



**Ms. Grace Madden  
Kimberly Clark  
2001 East Orangethorpe Avenue  
Fullerton, California 92831**

RE: December 12, 2018  
**H2 Environmental Proposal No. 2069218 AS**  
Asbestos & XRF Lead Survey  
**Phase 2 - Fullerton Mill**  
2001 East Orangethorpe Avenue  
Fullerton, California

Dear Ms. Madden,

H2 Environmental received a request for a proposal on November 13, 2018 for an Asbestos & Lead XRF Survey of the Fullerton Mill located at 2001 East Orangethorpe Avenue, Fullerton, California. The investigation was requested by Ms. Grace Madden and began on November 19, 2018.

### **Asbestos**

The building materials that will be impacted during the Fullerton Mill demolition were sampled for asbestos as part of this survey. Analytical results of the **609 samples analyzed are summarized below:**

### **Building 2**

- **White Joint Compound – Positive (55,680 SF)**
- **Black Floor Tile Mastic Under Multi-Color Floor Tile Under Blue Carpet – Positive (5,100 SF)**
- **Black Floor Tile Mastic Under 12”x12” Gray/Blue Floor Tile – Positive (1,000 SF)**
- **Black Floor Tile Mastic Under 9”x9” Floor Tile – Positive (200 SF)**
- **Black Gasket at HVAC – Positive (300 SF)**
- **Black Mastic Behind Corkboard – Positive (1,800 SF)**
- **White Joint Compound (2<sup>nd</sup> Floor Mechanical Room) – Positive (1,000 SF)**
- **White Mastic Sandwiched Between 2 Layers of Drywall – Positive (1,000 SF)**
- **Black Floor Mastic Under 12”x12” White Floor Tile – Positive (210 SF)**
- **Black Floor Tile Mastic Under 12”x12” Brown/Tan Floor Tile – Positive (390 SF)**
- **Black Floor Tile Mastic Under Off-White Floor Tile Under Gray With Streaks and Cream Floor Tile – Positive (4,000 SF)**
- **White Drywall – Negative**
- **12”x12” White Ceiling Tile – Negative**
- **Brown Ceiling Tile Mastic Behind 12”x12” Ceiling Tile – Negative**



**Building 2, Cont'd.**

- White Drywall Behind 12"x12" Ceiling Tile – Negative
- 2'x4' White Ceiling Tile – Negative
- 4" Gray Cove Base – Negative
- Tan/Brown Cove Base Mastic – Negative
- 12"x12" Gray Floor Tile – Negative
- Yellow Floor Tile Glue – Negative
- Multi-Color Floor Tile Under Blue Carpet – Negative
- 12"x12" Gray/Blue Floor Tile – Negative
- Yellow Carpet Glue Under Blue Carpet – Negative
- 9"x9" Brown Floor Tile – Negative
- White Pipe Wrap – Negative
- Yellow Pipe Insulation – Negative
- Black/White Vibration Damper – Negative
- Tan Duct Work Wrap – Negative
- Brown Corkboard Under Duct Work Wrap – Negative
- White Drywall (Layer 1) – Negative
- White Drywall (Layer 2) – Negative
- Gray Plaster – Negative
- Yellow Carpet Glue Under Gray Carpet – Negative
- 4" Black Cove Base – Negative
- Brown/Tan Cove Base Mastic – Negative
- 12"x12" Tan Floor Tile – Negative
- Gray Floor Tile Glue – Negative
- White Floor Tile Under Tan Floor Tile – Negative
- Black Floor Mastic – Negative
- Gray Linoleum – Negative
- Yellow Linoleum Glue – Negative
- 12"x12" White Floor Tile – Negative
- 12"x12" Dark Gray Floor Tile – Negative
- Yellow/Black Floor Tile Glue – Negative
- 4" Brown Cove Base – Negative
- Brown Cove Base Glue – Negative
- Gray Linoleum – Negative
- Brown/White Linoleum Glue – Negative
- 12"x12" Brown/Tan Floor Tile – Negative
- 4" Gray Cove Base – Negative
- Tan/Brown Cove Base Mastic – Negative
- 12"x12" Cream Floor Tile – Negative
- Gray Floor Tile Glue – Negative

### **Building 2, Cont'd.**

- 12"x12" Gray With Streaks Floor Tile – Negative
- Yellow Floor Tile Glue – Negative
- Off-White Floor Tile Under Gray With Streaks and Cream Floor Tile – Negative
- 12"x12" Dark Gray With White Streaks Floor Tile – Negative
- White/Tan Floor Tile Glue – Negative

### **Building 2, Roof Air Washer Building**

- **Gray Panels – Positive (400 SF)**
- **Black Roof Mastic – Positive (100 SF)**
- **Silver/Black Mastic on Flashing – Positive (100 SF)**
- Brown Debris – Negative
- Black/White Caulk on Flashing – Negative
- White Caulking on Gable Vent – Negative

### **Building 3**

- 12"x12" Tan With Streaks Floor Tile – Negative
- Yellow Floor Tile Glue on Wood – Negative
- 4" Brown Cove Base – Negative
- Brown Cove Base Mastic – Negative

### **Building 6**

- 12"x12" White Ceiling Tile – Negative
- Brown Ceiling Tile Mastic – Negative
- White Drywall Behind 12"x12" Ceiling Tile – Negative
- 4" Black Cove Base – Negative
- Tan Cove Base Glue – Negative
- 12"x12" White With Gray Streaks Floor Tile – Negative
- Yellow Floor Tile Glue – Negative
- 4" Gray Cove Base – Negative
- Tan/Brown Cove Base Glue – Negative
- Yellow Carpet Glue Under Blue Carpet – Negative
- 12"x12" Gray/Blue Floor Tile – Negative
- Yellow Floor Tile Glue – Negative
- Brown Stair Flooring – Negative
- Brown Stair Flooring Mastic – Negative
- White Drywall – Negative
- White Joint Compound – Negative

### **Building 7**

**No suspected asbestos materials were sampled within Building 7**

### **Building 8**

- White Drywall – Negative
- White Joint Compound – Negative
- Brown Drywall – Negative
- White Joint Compound – Negative
- White Pipe Wrap – Negative
- Yellow Pipe Insulation – Negative
- Gray Floor Epoxy – Negative
- Tan Pipe Wrap – Negative
- Off-White Pipe Insulation – Negative

### **Building 8, Roof Air Washer Building North**

- **Black/White Pipe Wrap – Positive (10 SF)**
- **Gray Wall Panels – Positive (3,000 SF)**
- White Pipe Wrap – Negative
- Yellow Pipe Insulation – Negative
- Black Vibration Damper – Negative
- Brown Wall Insulation – Negative

### **Building 8, Roof Air Washer Building South**

- White Pipe Wrap – Negative
- Yellow Pipe Insulation – Negative
- White Vibration Damper – Negative
- Black Gasket Sealant – Negative
- Gray Caulking on Wall – Negative
- Black Foam Cover – Negative

### **Building 9**

**No suspected asbestos materials were sampled within Building 9**

### **Building 10 – Tractor Area**

- 12"x12" Tan Floor Tile – Negative
- Yellow Floor Tile Glue – Negative

**Building 10 – Tractor Area, Cont'd.**

- 4" Brown Cove Base – Negative
- Brown/Tan Cove Base Glue – Negative
- 12"x12" White Ceiling Tile – Negative
- Brown Ceiling Mastic – Negative
- White Drywall Behind 12"x12" Ceiling Tile – Negative
- White Ductwork Wrap – Negative
- Yellow Ductwork Insulation – Negative
- Green Ductwork Glue – Negative
- White Drywall – Negative
- White Joint Compound – Negative

**Building 10 – Battery Area**

**No suspected asbestos materials were sampled within the Building 10 Battery Area**

**Building 12**

**No suspected asbestos materials were sampled within Building 12**

**Building 13**

- White Drywall – Negative
- White Joint Compound – Negative
- 12"x12" White Ceiling Tile – Negative
- Tan/Gray Ceiling Mastic – Negative
- White Drywall Above 12"x12" Ceiling Tile – Negative
- 4" Gray Cove Base – Negative
- Off-White/Tan Cove Base Glue – Negative
- Yellow Carpet Glue – Negative
- 12"x12" Gray Floor Tile – Negative
- 12"x12" Off-White Floor Tile – Negative
- Yellow Floor Tile Glue – Negative

**Building 19**

- **Black Floor Mastic Under 12"x12" Tan Floor Tile – Positive (500 SF)**
- **Brown Linoleum – Positive (1,480 SF)**
- 12"x12" White Ceiling Tile – Negative
- Brown Ceiling Tile Mastic – Negative
- White Drywall Behind 12"x12" Ceiling Tile – Negative

### **Building 19, Cont'd.**

- 4" Grey Cove Base – Negative
- Off-White Cove Base Glue – Negative
- 12"x12" Gray Floor Tile – Negative
- Yellow Floor Tile Glue – Negative
- Gray Caulking on Fan Units – Negative
- White Pipe Wrap – Negative
- Yellow Pipe Insulation – Negative
- 12"x12" Tan Floor Tile – Negative
- 4" Brown Cove Base – Negative
- Brown Cove Base Mastic – Negative
- 2'x4' White Ceiling Tile – Negative
- Gray Linoleum – Negative
- Yellow Linoleum Glue – Negative
- Yellow/White Linoleum Glue – Negative
- Yellow Ceiling Insulation – Negative
- White Drywall – Negative
- White Joint Compound – Negative
- Black Foam Insulation on Motor Equipment – Negative
- Brown Glue On Foam Insulation – Negative

### **Building 20**

**No suspected asbestos materials were sampled within Building 20**

### **Building 21**

- **Black Floor Tile Mastic Under Off-White Floor Tile Under Light Gray/Blue 12"x12" Floor Tile – Positive (14,320 SF)**
- **12"x12" Tan With Brown Streaks Floor Tile Mastic – Positive (1,580 SF)**
- White Drywall – Negative
- White Joint Compound – Negative
- 4" Gray Cove Base – Negative
- Brown/Tan Cove Base Glue – Negative
- 4" Brown Cove Base – Negative
- Brown/Tan Cove Base Glue – Negative
- 4" Black Cove Base – Negative
- Brown/Tan Cove Base Glue – Negative
- 2'x4' White Ceiling Tile – Negative
- Yellow Carpet Glue Under Blue Carpet – Negative
- 12"x12" Light Gray/Blue Floor Tile – Negative

**Building 21, Cont'd.**

- Yellow/Gray Floor Tile Glue – Negative
- Off-White Floor Tile Under Light Gray/Blue 12"x12" Floor Tile – Negative
- 12"x12" Gray with Streaks Floor Tile – Negative
- Yellow Floor Tile Glue – Negative
- 12"x12" Tan With Brown Streaks Floor Tile – Negative
- Black Floor Mastic – Negative
- 12"x12" Brown Floor Tile – Negative
- Black/Brown Floor Tile Mastic – Negative
- Yellow Carpet Glue Under Gray Carpet – Negative
- 12"x12" Light Gray/Blue Floor Tile – Negative
- Yellow Floor Tile Glue – Negative
- White Pipe Wrap – Negative
- Yellow Pipe Insulation – Negative

**Building 22, Storage**

**No suspect asbestos materials were sampled within Building 22, Storage**

**Building 25, Chemical Storage**

**No suspect asbestos materials were sampled within Building 25, Chemical Storage**

**Building 28**

- White Drywall – Negative
- White Joint Compound – Negative
- 2'x4' White Ceiling Tile – Negative
- 4" Gray Cove Base – Negative
- Tan Cove Base Glue – Negative
- Yellow Carpet glue Under Blue Carpet – Negative
- 12"x12" Blue/Gray Floor Tile – Negative
- Yellow Floor Tile Glue – Negative

**Stores Storage/Office Area 2**

- 4" Brown Cove Base – Negative
- Tan Cove Base Glue – Negative
- 12"x12" Off-White With Tan Floor Tile – Negative
- Yellow Floor Tile Glue – Negative
- 12"x12" White Ceiling Tile – Negative



### **Stores Storage/Office Area 2, Cont'd.**

- Brown Ceiling Tile Mastic – Negative
- White Drywall Behind 12"x12" Ceiling Tile – Negative
- 2'x4' White Ceiling Tile – Negative
- White Plaster – Negative
- White Ductwork Wrap – Negative
- Brown Ductwork Insulation – Negative

### **Hardroll Area**

**No suspect asbestos materials were sampled within the Hardroll Area**

### **North Gate, Fire Pump House**

- White Caulking on Wall – Negative

### **North Gate, Guard Shack**

- 2'x4' White Ceiling Tile – Negative
- 4" Black Cove Base – Negative
- White Cove Base Glue – Negative
- 12"x12" Gray Floor Tile – Negative
- Off-White Floor Tile Under Gray Floor Tile – Negative
- Gray/Yellow Floor Tile Glue – Negative

### **Acacia Fire Pump Room**

**No suspect asbestos materials were sampled within the Acacia Fire Pump Room**

### **Outfall Samples Room**

**No suspect asbestos materials were sampled within the Outfall Sample Room**



### Lead

The building materials that will be impacted during the Fullerton Mill demolition were sampled for lead as part of this survey. Results of the **Positive Lead materials** are summarized below:

### Building 2

- 2<sup>nd</sup> Floor Landing Area (Stair Rail – Metal) – Positive (100 LF)
- 2<sup>nd</sup> Floor Landing Area (Stair Frame – Metal) – Positive (2 Each)
- 2<sup>nd</sup> Floor Men’s Restroom (4”x4” Wall Tile – Ceramic) – Positive (984 SF)
- 2<sup>nd</sup> Floor Men’s Restroom (4”x4” Wall Base Tile–Ceramic)–Positive (123 SF)
- 2<sup>nd</sup> Floor Men’s Shower (4”x4” Wall Tile – Ceramic) – Positive (288 SF)
- 2<sup>nd</sup> Floor Men’s Locker (I-Beam – Metal) – Positive (2 Each)
- 2<sup>nd</sup> Floor Hallway (I-Beam – Metal) – Positive (2 Each)
- 2<sup>nd</sup> Floor Hallway (I-Beam – Metal) – Positive (2 Each)
- 2<sup>nd</sup> Floor Hallway (Bracket – Metal) – Positive (3 Each)
- 2<sup>nd</sup> Floor Mechanical Room (Bracket – Metal) – Positive (1 Each)
- 1<sup>st</sup> Floor Kitchen Area (I-Beam – Metal) – Positive (1 Each)
- 1<sup>st</sup> Floor Health Service Restroom (Toilet – Ceramic) – Positive (1 Each)
- 1<sup>st</sup> Floor Open Conference Area (Stair Rail – Metal) – Positive (2 Each)
- 1<sup>st</sup> Floor Open Conference Area (I-Beam – Metal) – Positive (1 Each)
- 1<sup>st</sup> Floor Open Conference Area (Guard Rail – Metal) – Positive (1 Each)
- 1<sup>st</sup> Floor Open Conference Area (Ceiling I-Beam – Metal) – Positive (1,139 SF)
- 1<sup>st</sup> Floor Open Conference Area (Sliding Door – Metal) – Positive (1 Each)
- 1<sup>st</sup> Floor Open Conference Area (Wall I-Beam – Metal) – Positive (1 Each)
- 1<sup>st</sup> Floor Open Conference Area (Angle Bracket – Metal) – Positive (1,053 SF)
- 1<sup>st</sup> Floor Open Conference Area (Electrical Panel – Metal) – Positive (1 Each)
- 1<sup>st</sup> Floor Warehouse (Rail – Metal) – Positive (1 Each)
- 1<sup>st</sup> Floor Warehouse ( Red I-Beam – Metal) – Positive (25 Each)
- 1<sup>st</sup> Floor Warehouse (Yellow I-Beam – Metal) – Positive (5 Each)
- 1<sup>st</sup> Floor Warehouse (Shoot Ladder – Metal) – Positive (1 Each)
- 1<sup>st</sup> Floor Warehouse (White I-Beam – Metal) – Positive (5 Each)
- 1<sup>st</sup> Floor Warehouse (Stair Frame – Metal) – Positive (4 Each)
- 1<sup>st</sup> Floor Warehouse (Stair Rail – Metal) – Positive (4 Each)
- 1<sup>st</sup> Floor Warehouse (Ceiling I-Beam – Metal) – Positive (39,120 SF)
- 1<sup>st</sup> Floor Warehouse (Ceiling Angle Bracket – Metal) – Positive (39,120 SF)
- 1<sup>st</sup> Floor Warehouse (Catwalk Post – Metal) – Positive (100 SF)
- 1<sup>st</sup> Floor Warehouse (Orange Catwalk – Metal) – Positive (6,000 SF)
- 1<sup>st</sup> Floor Warehouse (Yellow Catwalk – Metal) – Positive (3,000 SF)
- 2<sup>nd</sup> Floor Warehouse (Orange Catwalk I-Beam – Metal) – Positive (200 SF)
- 2<sup>nd</sup> Floor Power Supply Room (Red I-Beam – Metal) – Positive (1,000 SF)
- 2<sup>nd</sup> Floor Power Supply Room (Ceiling I-Beam – Metal) – Positive (460 SF)
- 2<sup>nd</sup> Floor Power Supply Room (Angle Bracket – Metal) – Positive (800 SF)

### **Building 2, Roof Air Washer Building**

- Exterior (White I-Beam – Metal) – Positive (11 Each)
- Exterior (Louver Frame – Metal) – Positive (6 Each)
- Exterior (Blue I-Beam – Metal) – Positive (4 Each)
- Interior (I-Beam – Metal) – Positive (2,025 SF)
- Interior (Stair Rail – Metal) – Positive (1 Each)

### **Building 3**

- Converter Maintenance Storage (Sliding Door Frame–Metal)–Positive (2 Each)
- Converter Maintenance Storage (Bollard – Metal) – Positive (2 Each)
- Converter Maintenance Storage (White I-Beam – Metal) – Positive (100 SF)
- Converter Maintenance Storage (Red I-Beam – Metal) – Positive (100 SF)
- Warehouse Finished Stock (Sliding Door – Metal) – Positive (12 Each)
- Warehouse Finished Stock (Sliding Door Frame – Metal) – Positive (12 Each)
- Warehouse Finished Stock (Bollard – Metal) – Positive (100 SF)
- Warehouse Finished Stock (Rail – Metal) – Positive (235 LF)
- Warehouse Finished Stock (Red I-Beam – Metal) – Positive 100 SF)
- Warehouse Finished Stock (Yellow I-Beam – Metal) – Positive (100 SF)
- Warehouse Finished Stock (Bollard – Metal) – Positive (100 SF)
- Warehouse Finished Stock (Floor Strip – Metal) – Positive (381 LF)
- Warehouse Finished Stock (Platform Post – Metal) – Positive (6 Each)
- Warehouse Finished Stock (Stair Frame – Metal) – Positive (1 Each)
- Warehouse Finished Stock (Stair Case – Metal) – Positive (1 Each)
- Warehouse Finished Stock (Stair Rail– Metal) – Positive (1 Each)
- Warehouse Finished Stock (Platform Post – Metal) – Positive (4 Each)
- Warehouse Finished Stock (3 Step Frame – Metal) – Positive (2 Each)
- Warehouse Finished Stock (3 Step – Metal) – Positive (2 Each)
- Warehouse Finished Stock (Hydraulic System – Metal) – Positive (1 Each)
- Warehouse Finished Stock (Ceiling I-Beam– Metal) – Positive (9,047 SF)
- Warehouse Finished Stock (Angle Bracket – Metal) – Positive (90,475 SF)

### **Building 6**

- Warehouse (Yellow Bollard – Metal) – Positive (100 SF)
- Warehouse (Sliding Door – Metal) – Positive (7 Each)
- Warehouse (I-Beam – Metal) – Positive (1,000 SF)
- Warehouse (Stair Rail – Metal) – Positive (2 Each)
- Warehouse (Stair Case – Metal) – Positive (1 Each)
- Warehouse (Red Bollard – Metal) – Positive (1,000 SF)

### **Building 7**

- Warehouse (Bollard – Metal) – Positive (100 SF)
- Warehouse (Panel – Metal) – Positive (1 Each)

### **Building 8**

- OLP Room (Colum – Metal) – Positive (10 Each)
- OLP Room (Barrier – Metal) – Positive (5 Each)
- OLP Room (I-Beam – Metal) – Positive (6 Each)
- OLP Room (Ceiling I-Beam – Metal) – Positive (7,936 SF)
- OLP Room (Angle Bracket – Metal) – Positive (7,936 SF)
- OLP Room (Shoot Ladder Rail – Metal) – Positive (2 Each)
- OLP Room (Shoot Ladder – Metal) – Positive (2 Each)
- Lift Tank Room (White Shoot Ladder – Metal) – Positive (1 Each)
- Lift Tank Room (White Shoot Ladder Rail – Metal) – Positive (1 Each)
- Lift Tank Room (Yellow Shoot Ladder – Metal) – Positive (2 Each)
- Lift Tank Room (Yellow Shoot Ladder Rail – Metal) – Positive (2 Each)
- Lift Tank Room (Ceiling I-Beam – Metal) – Positive (533 SF)
- Lift Tank Room (Angle Bracket – Metal) – Positive (533 SF)
- Dust Collecting Room (Stair Rail – Metal) – Positive (1 Each)
- Dust Collecting Room (Stair Frame – Metal) – Positive (1 Each)
- Dust Collecting Room (Platform Frame – Metal) – Positive (1 Each)
- Dust Collecting Room (Ceiling I-Beam – Metal) – Positive (870 SF)
- Dust Collecting Room (Angle Bracket – Metal) – Positive (870 SF)
- Dust Collecting Room (Platform Rail – Metal) – Positive (2 Each)
- Open Storage Area (Column – Metal) – Positive (15 Each)
- Open Storage Area (Sliding Door – Metal) – Positive (3 Each)
- Open Storage Area (I-Beam – Metal) – Positive (12 Each)
- Open Storage Area (Sliding Door – Metal) – Positive (3 Each)
- Bath, Formerly Towels Area (I- Beam – Metal) – Positive (20 Each)
- Bath, Formerly Towels Area (Rail – Metal) – Positive (10 Each)
- Bath, Formerly Towels Area (Stair Rail – Metal) – Positive (2 Each)
- Bath, Formerly Towels Area (Colum – Metal) – Positive (5 Each)
- Bath, Formerly Towels Area (Sliding Door – Metal) – Positive (7 Each)
- Bath, Formerly Towels Area (Floor – Concrete) – Positive (167 LF)
- Bath, Formerly Towels Area (Ceiling I-Beam – Metal) – Positive (31,879 SF)
- Bath, Formerly Towels Area (Ceiling Angele Bracket – Metal) – Positive (31,879 SF)

### Building 8, Roof Air Washer Building

- Air Washer Building South (Stair Rail – Metal) – Positive (1 Each)
- Air Washer Building South (Staircase – Metal) – Positive (1 Each)
- Air Washer Building South (Louver Frame – Metal) – Positive (6 Each)
- Air Washer Building South (Stair Rail – Metal) – Positive (6 Each)
- Air Washer Building South (I-Beam – Metal) – Positive (4 Each)
- Air Washer Building South (Ceiling I-Beam – Metal) – Positive (150 SF)
- Air Washer Building North (Louver Frame – Metal) – Positive (3 Each)
- Air Washer Building North (Stair Rail – Metal) – Positive (1 Each)
- Air Washer Building North (Rail – Metal) – Positive (1 Each)
- Air Washer Building North (I-Beam – Metal) – Positive (225 SF)

### Building 9

- Platform Area ( White Staircase – Metal) – Positive (1 Each)
- Platform Area (White Stair Rail – Metal) – Positive (1 Each)
- Platform Area (Ceiling I-Beam – Metal) – Positive (4,000 SF)
- Platform Area (Ceiling Angle Bracket – Metal) – Positive (4,000 SF)
- Platform Area (Stair Frame – Metal) – Positive (1 Each)
- Platform Area (Yellow Staircase – Metal) – Positive (1 Each)
- Platform Area (Yellow Stair Rail – Metal) – Positive (1 Each)
- Platform Area (Column – Metal) – Positive (60 Each)
- Platform Area (I-Beam – Metal) – Positive (20 Each)
- Platform (Platform Rail – Metal) – Positive (1 Each)
- 1<sup>st</sup> Floor Warehouse (Red I-Beam – Metal) – Positive (10 Each)
- 1<sup>st</sup> Floor Warehouse (White I-Beam – Metal) – Positive (10 Each)
- 1<sup>st</sup> Floor Warehouse (Light Stand – Metal) – Positive (1 Each)

### Building 10 – Tractor Area

- Tractor Area (Ladder – Metal) – Positive (10 SF)
- Tractor Area (Handrail – Metal) – Positive (200 SF)
- Tractor Area (Handrail – Metal) – Positive (100 SF)
- Tractor Area (Bollards – Metal) – Positive (2 Each)

### Building 10 – Battery Area

- Battery Area (Yellow I-Beam – Metal) – Positive (300 SF)
- Battery Area (Red I-Beam – Metal) – Positive (300 SF)
- Battery Area (White I-Beam – Metal) – Positive (1,000 SF)
- Battery Area (Sliding Door – Metal) – Positive (1 Each)
- Battery Area (Hand Railing – Metal) – Positive (300 SF)
- Battery Area (Wall – Wood) – Positive (300 SF)
- Battery Area (Hand Railing – Metal) – Positive (50 SF)

### Building 12

- Warehouse (Sliding Door – Metal) – Positive (2 Each)
- Warehouse (Floor Rail – Metal) – Positive (1,132 LF)
- Warehouse (Floor – Concrete) – Positive (20 SF)

### Building 13

- Warehouse (Sprinkler Head Panel – Metal) – Positive (1 Each)
- Warehouse (Yellow Bollard – Metal) – Positive (100 SF)
- Warehouse (Floor – Concrete) – Positive (1,000 LF)
- Warehouse (Red Bollard – Metal) – Positive (100 SF)
- Warehouse (Post – Metal) – Positive (4 Each)
- Warehouse (Bollard Rail – Metal) – Positive (100 SF)
- Warehouse (Floor Rail – Metal) – Positive (307 LF)
- Warehouse (Bollard/I-Beam – Metal) – Positive (4 Each)
- Warehouse (Ramp Rail – Metal) – Positive (2 Each)
- Warehouse (Sliding Door – Metal) – Positive (6 Each)
- Men's Restroom 2 (4"x4" Wall Tile – Ceramic) – Positive (266 SF)
- Men's Restroom 2 (Toilet – Ceramic) – Positive (1 Each)

### Building 19

- Storage (Sliding Door – Metal) – Positive (2 Each)
- Storage (Ceiling I-Beam – Metal) – Positive (9 Each)
- Warehouse (Stair Frame – Metal) – Positive (2 Each)
- Warehouse (Floor - Concrete) – Positive (456 LF)
- Warehouse (Stair Brace – Metal) – Positive (2 Each)
- Warehouse (Yellow Column – Metal) – Positive (20 Each)
- Warehouse (White I-Beam – Metal) – Positive (10 Each)
- Warehouse (Red I-Beam – Metal) – Positive (10 Each)
- Warehouse (Yellow Column – Metal) – Positive (4 Each)
- Warehouse (Tan I-Beam – Metal) – Positive (6,840 SF)
- Warehouse (Angle Bracket – Metal) – Positive (6,840 SF)
- Warehouse (Platform Frame – Metal) – Positive (1 Each)
- Refrigerant Area (Sliding Door – Metal) – Positive (2 Each)
- Refrigerant Area (Ceiling I-Beam – Metal) – Positive (144 SF)
- Warehouse 2 (Sliding Door – Wood) – Positive (1 Each)
- Warehouse 2 (Ceiling I-Beam – Wood) – Positive (8,983 SF)
- Warehouse 2 (Ceiling Angle Bracket – Wood) – Positive (8,983 SF)
- Warehouse 2 (I-Beam – Metal) – Positive (200 SF)
- Warehouse 2 (Column – Metal) – Positive (30 Each)

### Building 20

- Warehouse (I-Beam – Metal) – Positive (1,000 SF)
- Warehouse (Ceiling I-Beam – Metal) – Positive (4,181 SF)
- Warehouse (Ceiling Angle Bracket – Metal) – Positive (41,810SF)
- Warehouse (Bollard – Metal) – Positive (1,000 SF)
- Warehouse (Sliding Door – Metal) – Positive (6 Each)
- Warehouse (Floor – Concrete) – Positive (100 LF)

### Building 21

- Building 21, 3<sup>rd</sup> Floor (Shelf – Metal) – Positive (2 Each)
- Warehouse (Sliding Door – Metal) – Positive (1 Each)
- Warehouse (Guard Rail – Metal) – Positive (4 Each)
- Warehouse (Shoot Ladder – Metal) – Positive (6 Each)
- Warehouse (Platform – Metal) – Positive (4 Each)
- Warehouse (I-Beam – Metal) – Positive (12 Each)
- Warehouse, 1<sup>st</sup> Floor (Ceiling I-Beam – Metal) – Positive (20 Each)
- Warehouse, 1<sup>st</sup> Floor (Ceiling Angle Bracket – Metal) – Positive (40,470 SF)

### Building 22

- Storage (Bollard Rail – Metal) – Positive (100 SF)

### Building 25

- Warehouse Storage 2 (Floor – Concrete) – Positive (100 LF)
- Warehouse Storage (Bollard – Metal) – Positive (7 Each)
- Warehouse Storage (Bollard Rail – Metal) – Positive (50 SF)

### Building 28

No Positive Lead Material was detected during the Building 28 Lead XRF Survey.

### Stores Storage/Office Area 2

- Warehouse (Sliding Door – Metal) – Positive (3 Each)
- Warehouse (Wall – Metal) – Positive (2,300 SF)
- Warehouse (Ceiling I-Beam – Metal) – Positive (13,923 SF)
- Warehouse (Cross Beam – Metal) – Positive (13,923 SF)

### Hardroll Area

- Hardroll Area (Red I-Beam – Metal) – Positive (300 SF)
- Hardroll Area (Yellow I-Beam – Metal) – Positive (300 SF)
- Hardroll Area (Door Frame – Metal) – Positive (2 Each)
- Hardroll Area (Sliding Door Frame – Metal) – Positive (2 Each)
- Hardroll Area (Bollards – Metal) – Positive (4 Each)

### North Gate, Fire Pump House

- Exterior (Water Tank – Metal) – Positive (2 Each)
- Exterior (Shoot Ladder – Metal) – Positive (2 Each)

### North Gate, Guard Shack

- Exterior (Bollard – Metal) – Positive (4 Each)

### Acacia Northwest Fire Pump Building

- Interior (Door – Metal) – Positive (2 Each)
- Interior (Door Frame – Metal) – Positive (2 Each)
- Interior (I-Beam – Metal) – Positive (6 Each)
- Interior (Ceiling I-Beam – Metal) – Positive (100 SF)
- Exterior (Door Frame – Metal) – Positive (2 Each)
- Exterior (Door – Metal) – Positive (2 Each)
- Exterior (I-Beam – Metal) – Positive (4 Each)

### Outfall Sample Room

**No Positive Lead Material was detected during the Outfall Sample Room Lead XRF Survey.**

Since there is asbestos & lead containing materials the removal of any asbestos & lead containing materials will need to be performed by a California Licensed Asbestos & Lead Abatement Contractor, and should be handled, stored and disposed of according to all local, state and federal regulations.



H2 Environmental Consulting Services, Inc. (H2 Environmental) received a written authorization from Ms. Grace Madden, to proceed on November 19, 2018. The scope of work consisted of an asbestos & lead XRF survey, specifically related to the planned demolition. The asbestos & lead XRF survey was performed by Mr. Alberto Sanchez who is a Certified Site Surveillance Technician (CSST No. 03-3511), Mr. Jason Ortiz who is a Certified Lead Sampling Technician, and Mr. W. Thomas Haley who is a Certified Indoor Environmental Consultant (CIEC No. 0703144) and a Certified Asbestos Consultant (CAC No. 95-1702).

H2 Environmental appreciates the opportunity to provide environmental services for this important project. If after your review you have any questions or require additional assistance, please do not hesitate to call our office at (909) 628-0369.

Respectfully submitted,  
***H2 Environmental Consulting Services, Inc.***

A handwritten signature in blue ink, appearing to read 'W. Thomas Haley', is placed over a light blue rectangular background.

W. Thomas Haley  
Vice President





## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509341  
**Samples Submitted:** 174  
**Sample Collection Date:** 11/19/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #2  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 1 of 44

### TEST DATA

**Laboratory ID#:** 1509341-001 **Client Sample #:** 1

**Sample Material and Location:** White Drywall 2nd Floor Laundry Locker Room - South End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509341-002 **Client Sample #:** 2

**Sample Material and Location:** White Drywall Maintenance Department - North End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509341-003 **Client Sample #:** 3

**Sample Material and Location:** White Drywall 1st Floor Hallway - West End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509341-004 **Client Sample #:** 4

**Sample Material and Location:** White Joint Compound 2nd Floor Laundry Locker Room - South End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 98% Non-Fibrous Material  
**Asbestos Observed (%):** Chrysotile 2%  
**Analyst:** Chris Turton **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** 2%



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509341  
**Samples Submitted:** 174  
**Sample Collection Date:** 11/19/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #2  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 2 of 44

### TEST DATA

**Laboratory ID#:** 1509341-005      **Client Sample #:** 5

**Sample Material and Location:** White Joint Compound Maintenance Department - North End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 98% Non-Fibrous Material  
**Asbestos Observed (%):** Chrysotile      2%      **Total Asbestos (%)**      2%  
**Analyst:** Chris Turton      **Date Analyzed:** 11/27/2018

### TEST DATA

**Laboratory ID#:** 1509341-006      **Client Sample #:** 6

**Sample Material and Location:** White Joint Compound 1st Floor Hallway - West End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 98% Non-Fibrous Material  
**Asbestos Observed (%):** Chrysotile      2%      **Total Asbestos (%)**      2%  
**Analyst:** Chris Turton      **Date Analyzed:** 11/27/2018

### TEST DATA

**Laboratory ID#:** 1509341-007      **Client Sample #:** 7

**Sample Material and Location:** White 12" x 12" Ceiling Tile 1st Floor Hallway - West End

**Sample Characteristics:** White Gray Fibrous Inhomogenous  
**Misc. Components Observed:** 64% Non-Fibrous Material  
6% Fibrous Glass  
30% Cellulose  
**Asbestos Observed (%):**      **Total Asbestos (%)**      None Detected  
**Analyst:** Chris Turton      **Date Analyzed:** 11/27/2018

### TEST DATA

**Laboratory ID#:** 1509341-008      **Client Sample #:** 8

**Sample Material and Location:** White 12" x 12" Ceiling Tile 2nd Floor Gym - N.W. End

**Sample Characteristics:** White Gray Fibrous Inhomogenous  
**Misc. Components Observed:** 64% Non-Fibrous Material 35% Cellulose  
6% Fibrous Glass  
30% Cellulose  
**Asbestos Observed (%):**      **Total Asbestos (%)**      None Detected  
**Analyst:** Chris Turton      **Date Analyzed:** 11/27/2018



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509341  
**Samples Submitted:** 174  
**Sample Collection Date:** 11/19/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #2  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 3 of 44

### TEST DATA

**Laboratory ID#:** 1509341-009      **Client Sample #:** 9

**Sample Material and Location:** White 12" x 12" Ceiling Tile Maintenance Department - East End

**Sample Characteristics:** White Gray Fibrous Inhomogenous  
**Misc. Components Observed:** 64% Non-Fibrous Material  
6% Fibrous Glass  
30% Cellulose

**Asbestos Observed (%):**      **Date Analyzed:** 11/27/2018      **Total Asbestos (%)** None Detected  
**Analyst:** Chris Turton

### TEST DATA

**Laboratory ID#:** 1509341-010      **Client Sample #:** 10

**Sample Material and Location:** Brown Ceiling Tile Mastic (12" x 12" C.T.) 1st Floor Hallway - West End

**Sample Characteristics:** Brown Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**      **Date Analyzed:** 11/27/2018      **Total Asbestos (%)** None Detected  
**Analyst:** Chris Turton

### TEST DATA

**Laboratory ID#:** 1509341-011      **Client Sample #:** 11

**Sample Material and Location:** Brown Ceiling Tile Mastic (12" x 12" C.T.) 2nd Floor Gym - N.W. End

**Sample Characteristics:** Brown Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**      **Date Analyzed:** 11/27/2018      **Total Asbestos (%)** None Detected  
**Analyst:** Chris Turton

### TEST DATA

**Laboratory ID#:** 1509341-012      **Client Sample #:** 12

**Sample Material and Location:** Brown Ceiling Tile Mastic (12" x 12" C.T.) Maintenance Department - East End

**Sample Characteristics:** Brown Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**      **Date Analyzed:** 11/27/2018      **Total Asbestos (%)** None Detected  
**Analyst:** Chris Turton



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509341  
**Samples Submitted:** 174  
**Sample Collection Date:** 11/19/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #2  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 4 of 44

### TEST DATA

**Laboratory ID#:** 1509341-013      **Client Sample #:** 13

**Sample Material and Location:** White Drywall behind 12" x 12" Ceiling Tile 1st Floor Hallway - West End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509341-014      **Client Sample #:** 14

**Sample Material and Location:** White Drywall behind 12" x 12" Ceiling Tile 2nd Floor Gym - N.W. End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509341-015      **Client Sample #:** 15

**Sample Material and Location:** White Drywall behind 12" x 12" Ceiling Tile Maintenance Department - East End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509341-016      **Client Sample #:** 16

**Sample Material and Location:** White 2' x 4' Ceiling Tile 2nd Floor Hallway - Center

**Sample Characteristics:** White Gray Fibrous Inhomogenous  
**Misc. Components Observed:** 55% Non-Fibrous Material  
5% Fibrous Glass  
40% Cellulose

**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509341  
**Samples Submitted:** 174  
**Sample Collection Date:** 11/19/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #2  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 5 of 44

### TEST DATA

**Laboratory ID#:** 1509341-017      **Client Sample #:** 17

**Sample Material and Location:** White 2' x 4' Ceiling Tile Maintenance Department Hallway - Center

**Sample Characteristics:** White Fibrous Inhomogenous  
**Misc. Components Observed:** 55% Non-Fibrous Material  
5% Fibrous Glass  
40% Cellulose

**Asbestos Observed (%):**      **Date Analyzed:** 11/27/2018      **Total Asbestos (%)** None Detected  
**Analyst:** Chris Turton

### TEST DATA

**Laboratory ID#:** 1509341-018      **Client Sample #:** 18

**Sample Material and Location:** White 2' x 4' Ceiling Tile Lab Data Room - Center

**Sample Characteristics:** White Gray Fibrous Inhomogenous  
**Misc. Components Observed:** 55% Non-Fibrous Material  
5% Fibrous Glass  
40% Cellulose

**Asbestos Observed (%):**      **Date Analyzed:** 11/27/2018      **Total Asbestos (%)** None Detected  
**Analyst:** Chris Turton

### TEST DATA

**Laboratory ID#:** 1509341-019      **Client Sample #:** 19

**Sample Material and Location:** Gray 4" Covebase 2nd Floor Laundry Locker Room - South End

**Sample Characteristics:** Gray Smooth Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**      **Date Analyzed:** 11/27/2018      **Total Asbestos (%)** None Detected  
**Analyst:** Chris Turton

### TEST DATA

**Laboratory ID#:** 1509341-020      **Client Sample #:** 20

**Sample Material and Location:** Gray 4" Covebase 2nd Floor Hallway - East End

**Sample Characteristics:** Gray Smooth Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**      **Date Analyzed:** 11/27/2018      **Total Asbestos (%)** None Detected  
**Analyst:** Chris Turton



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509341  
**Samples Submitted:** 174  
**Sample Collection Date:** 11/19/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #2  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 6 of 44

### TEST DATA

---

**Laboratory ID#:** 1509341-021      **Client Sample #:** 21

**Sample Material and Location:** Gray 4" Covebase 1st Floor Hallway - S.W. End

**Sample Characteristics:** Gray Smooth Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509341-022      **Client Sample #:** 22

**Sample Material and Location:** Tan/Brown Covebase Mastic 2nd Floor Laundry Locker Room - South End

**Sample Characteristics:** Tan Brown Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509341-023      **Client Sample #:** 23

**Sample Material and Location:** Tan/Brown Covebase Mastic 2nd Floor Hallway - East End

**Sample Characteristics:** Tan Brown Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509341-024      **Client Sample #:** 24

**Sample Material and Location:** Tan/Brown Covebase Mastic 1st Floor Hallway - S.W. End

**Sample Characteristics:** Tan Brown Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509341  
**Samples Submitted:** 174  
**Sample Collection Date:** 11/19/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #2  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 7 of 44

### TEST DATA

**Laboratory ID#:** 1509341-025      **Client Sample #:** 25

**Sample Material and Location:** Gray 12 x 12 Floor Tile 2nd Floor Laundry Locker Room - South End

**Sample Characteristics:** Gray White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**

**Analyst:** Chris Turton

**Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509341-026      **Client Sample #:** 26

**Sample Material and Location:** Gray 12 x 12 Floor Tile 2nd Floor Hallway - N.W. End

**Sample Characteristics:** Gray White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**

**Analyst:** Chris Turton

**Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509341-027      **Client Sample #:** 27

**Sample Material and Location:** Gray 12 x 12 Floor Tile 2nd Floor Hallway - South End

**Sample Characteristics:** Gray White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**

**Analyst:** Chris Turton

**Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509341-028      **Client Sample #:** 28

**Sample Material and Location:** Yellow Floor Tile Glue 2nd Floor Laundry Locker Room - South End

**Sample Characteristics:** Yellow Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**

**Analyst:** Chris Turton

**Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509341  
**Samples Submitted:** 174  
**Sample Collection Date:** 11/19/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #2  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 8 of 44

### TEST DATA

**Laboratory ID#:** 1509341-029      **Client Sample #:** 29

**Sample Material and Location:** Yellow Floor Tile Glue 2nd Floor Hallway - N.W. End

**Sample Characteristics:** Yellow Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509341-030      **Client Sample #:** 30

**Sample Material and Location:** Yellow Floor Tile Glue 2nd Floor Hallway - South End

**Sample Characteristics:** Yellow Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509341-031      **Client Sample #:** 31

**Sample Material and Location:** Multi Color Floor Tile under Blue Carpet VCC Conference Room - North End

**Sample Characteristics:** White Gray Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509341-032      **Client Sample #:** 32

**Sample Material and Location:** Multi Color Floor Tile under Blue Carpet IT Storage Closet - West End

**Sample Characteristics:** White Blue Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected





## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509341  
**Samples Submitted:** 174  
**Sample Collection Date:** 11/19/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #2  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 9 of 44

### TEST DATA

**Laboratory ID#:** 1509341-033      **Client Sample #:** 33

**Sample Material and Location:** Multi Color Floor Tile under Blue Carpet Human Resources Office - North End

**Sample Characteristics:** White Blue Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**      **Total Asbestos (%)** None Detected  
**Analyst:** Chris Turton      **Date Analyzed:** 11/27/2018

### TEST DATA

**Laboratory ID#:** 1509341-034      **Client Sample #:** 34

**Sample Material and Location:** Black Floor Tile Mastic VCC Conference Room - North End

**Sample Characteristics:** Black Non-Fibrous Homogenous  
**Misc. Components Observed:** 95% Non-Fibrous Material

**Asbestos Observed (%):** Chrysotile 5%      **Total Asbestos (%)** 5%  
**Analyst:** Chris Turton      **Date Analyzed:** 11/27/2018

### TEST DATA

**Laboratory ID#:** 1509341-035      **Client Sample #:** 35

**Sample Material and Location:** Black Floor Tile Mastic IT Storage Closet - West End

**Sample Characteristics:** Black Non-Fibrous Homogenous  
**Misc. Components Observed:** 95% Non-Fibrous Material

**Asbestos Observed (%):** Chrysotile 5%      **Total Asbestos (%)** 5%  
**Analyst:** Chris Turton      **Date Analyzed:** 11/27/2018

### TEST DATA

**Laboratory ID#:** 1509341-036      **Client Sample #:** 36

**Sample Material and Location:** Black Floor Tile Mastic Human Resources Office - North End

**Sample Characteristics:** Black Non-Fibrous Homogenous  
**Misc. Components Observed:** 95% Non-Fibrous Material

**Asbestos Observed (%):** Chrysotile 5%      **Total Asbestos (%)** 5%  
**Analyst:** Chris Turton      **Date Analyzed:** 11/27/2018



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509341  
**Samples Submitted:** 174  
**Sample Collection Date:** 11/19/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #2  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 10 of 44

### TEST DATA

**Laboratory ID#:** 1509341-037      **Client Sample #:** 37

**Sample Material and Location:** Gray/Blue 12 x12 Floor Tile 2nd Floor Hallway - East End

**Sample Characteristics:** Gray White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**

**Analyst:** Chris Turton

**Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509341-038      **Client Sample #:** 38

**Sample Material and Location:** Gray/Blue 12 x12 Floor Tile 2nd Floor Lounge Area - South End

**Sample Characteristics:** Gray White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**

**Analyst:** Chris Turton

**Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509341-039      **Client Sample #:** 39

**Sample Material and Location:** Gray/Blue 12 x12 Floor Tile 2nd Floor Hallway - West End

**Sample Characteristics:** Gray White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**

**Analyst:** Chris Turton

**Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509341-040      **Client Sample #:** 40

**Sample Material and Location:** Black Floor Tile Mastic 2nd Floor Hallway - East End

**Sample Characteristics:** Black Non-Fibrous Homogenous  
**Misc. Components Observed:** 95% Non-Fibrous Material

**Asbestos Observed (%):** Chrysotile 5%

**Analyst:** Chris Turton

**Date Analyzed:** 11/27/2018

**Total Asbestos (%)** 5%



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509341  
**Samples Submitted:** 174  
**Sample Collection Date:** 11/19/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #2  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 11 of 44

### TEST DATA

**Laboratory ID#:** 1509341-041      **Client Sample #:** 41

**Sample Material and Location:** Black Floor Tile Mastic 2nd Floor Lounge Area - South End

<b>Sample Characteristics:</b>	Black Non-Fibrous Homogenous		
<b>Misc. Components Observed:</b>	95% Non-Fibrous Material		
<b>Asbestos Observed (%):</b>	Chrysotile      5%	<b>Total Asbestos (%)</b>	5%
<b>Analyst:</b> Chris Turton	<b>Date Analyzed:</b> 11/27/2018		

### TEST DATA

**Laboratory ID#:** 1509341-042      **Client Sample #:** 42

**Sample Material and Location:** Black Floor Tile Mastic 2nd Floor Hallway - West End

<b>Sample Characteristics:</b>	Black Non-Fibrous Homogenous		
<b>Misc. Components Observed:</b>	95% Non-Fibrous Material		
<b>Asbestos Observed (%):</b>	Chrysotile      5%	<b>Total Asbestos (%)</b>	5%
<b>Analyst:</b> Chris Turton	<b>Date Analyzed:</b> 11/27/2018		

### TEST DATA

**Laboratory ID#:** 1509341-043      **Client Sample #:** 43

**Sample Material and Location:** Yellow Carpet Glue under Blue Carpet Main Mill Conference Room - S.W. End

<b>Sample Characteristics:</b>	Yellow Non-Fibrous Homogenous		
<b>Misc. Components Observed:</b>	100% Non-Fibrous Material		
<b>Asbestos Observed (%):</b>		<b>Total Asbestos (%)</b>	None Detected
<b>Analyst:</b> Chris Turton	<b>Date Analyzed:</b> 11/27/2018		

### TEST DATA

**Laboratory ID#:** 1509341-044      **Client Sample #:** 44

**Sample Material and Location:** Yellow Carpet Glue under Blue Carpet Safety & Training - South End

<b>Sample Characteristics:</b>	Yellow Non-Fibrous Homogenous		
<b>Misc. Components Observed:</b>	100% Non-Fibrous Material		
<b>Asbestos Observed (%):</b>		<b>Total Asbestos (%)</b>	None Detected
<b>Analyst:</b> Chris Turton	<b>Date Analyzed:</b> 11/27/2018		



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509341  
**Samples Submitted:** 174  
**Sample Collection Date:** 11/19/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #2  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 12 of 44

### TEST DATA

---

**Laboratory ID#:** 1509341-045      **Client Sample #:** 45

**Sample Material and Location:** Yellow Carpet Glue under Blue Carpet Safety & Training - North End

**Sample Characteristics:** Yellow Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509341-046      **Client Sample #:** 46

**Sample Material and Location:** Brown 9 x 9 Floor Tile 2nd Floor Women's R/R Hallway - North End

**Sample Characteristics:** Brown Gray Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509341-047      **Client Sample #:** 47

**Sample Material and Location:** Brown 9 x 9 Floor Tile 2nd Floor Women's R/R Hallway - S.W. End

**Sample Characteristics:** Brown Gray Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509341-048      **Client Sample #:** 48

**Sample Material and Location:** Brown 9 x 9 Floor Tile 2nd Floor Women's Lounge - East End

**Sample Characteristics:** Brown Gray Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509341  
**Samples Submitted:** 174  
**Sample Collection Date:** 11/19/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #2  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 13 of 44

### TEST DATA

**Laboratory ID#:** 1509341-049      **Client Sample #:** 49

**Sample Material and Location:** Black Floor Tile Mastic 2nd Floor Women's R/R Hallway - North End

<b>Sample Characteristics:</b>	Black Non-Fibrous Homogenous		
<b>Misc. Components Observed:</b>	95% Non-Fibrous Material		
<b>Asbestos Observed (%):</b>	Chrysotile	5%	<b>Total Asbestos (%)</b> 5%
<b>Analyst:</b> Chris Turton	<b>Date Analyzed:</b>	11/27/2018	

### TEST DATA

**Laboratory ID#:** 1509341-050      **Client Sample #:** 50

**Sample Material and Location:** Black Floor Tile Mastic 2nd Floor Women's R/R Hallway - S.W. End

<b>Sample Characteristics:</b>	Black Non-Fibrous Homogenous		
<b>Misc. Components Observed:</b>	95% Non-Fibrous Material		
<b>Asbestos Observed (%):</b>	Chrysotile	5%	<b>Total Asbestos (%)</b> 5%
<b>Analyst:</b> Chris Turton	<b>Date Analyzed:</b>	11/27/2018	

### TEST DATA

**Laboratory ID#:** 1509341-051      **Client Sample #:** 51

**Sample Material and Location:** Black Floor Tile Mastic 2nd Floor Women's Lounge - East End

<b>Sample Characteristics:</b>	Black Non-Fibrous Homogenous		
<b>Misc. Components Observed:</b>	95% Non-Fibrous Material		
<b>Asbestos Observed (%):</b>	Chrysotile	5%	<b>Total Asbestos (%)</b> 5%
<b>Analyst:</b> Chris Turton	<b>Date Analyzed:</b>	11/27/2018	

### TEST DATA

**Laboratory ID#:** 1509341-052      **Client Sample #:** 52

**Sample Material and Location:** White Pipe Wrap 2nd Floor Mech. Room - East End

<b>Sample Characteristics:</b>	White Fibrous Inhomogenous		
<b>Misc. Components Observed:</b>	60% Non-Fibrous Material 10% Fibrous Glass 30% Cellulose		
<b>Asbestos Observed (%):</b>			<b>Total Asbestos (%)</b> None Detected
<b>Analyst:</b> Chris Turton	<b>Date Analyzed:</b>	11/27/2018	



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509341  
**Samples Submitted:** 174  
**Sample Collection Date:** 11/19/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #2  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 14 of 44

### TEST DATA

**Laboratory ID#:** 1509341-053      **Client Sample #:** 53

**Sample Material and Location:** White Pipe Wrap 2nd Floor Mech. Room - West End

**Sample Characteristics:** White Fibrous Inhomogenous  
**Misc. Components Observed:** 60% Non-Fibrous Material  
10% Fibrous Glass  
30% Cellulose

**Asbestos Observed (%):**      **Date Analyzed:** 11/27/2018      **Total Asbestos (%)** None Detected  
**Analyst:** Chris Turton

### TEST DATA

**Laboratory ID#:** 1509341-054      **Client Sample #:** 54

**Sample Material and Location:** White Pipe Wrap 2nd Floor Power Supply Room - West End

**Sample Characteristics:** White Fibrous Inhomogenous  
**Misc. Components Observed:** 60% Non-Fibrous Material  
10% Fibrous Glass  
30% Cellulose

**Asbestos Observed (%):**      **Date Analyzed:** 11/27/2018      **Total Asbestos (%)** None Detected  
**Analyst:** Chris Turton

### TEST DATA

**Laboratory ID#:** 1509341-055      **Client Sample #:** 55

**Sample Material and Location:** Yellow Pipe Insulation 2nd Floor Mech. Room - East End

**Sample Characteristics:** Yellow Fibrous Homogenous  
**Misc. Components Observed:** 3% Non-Fibrous Material  
97% Fibrous Glass

**Asbestos Observed (%):**      **Date Analyzed:** 11/27/2018      **Total Asbestos (%)** None Detected  
**Analyst:** Chris Turton

### TEST DATA

**Laboratory ID#:** 1509341-056      **Client Sample #:** 56

**Sample Material and Location:** Yellow Pipe Insulation 2nd Floor Mech. Room - West End

**Sample Characteristics:** Yellow Fibrous Homogenous  
**Misc. Components Observed:** 3% Non-Fibrous Material  
97% Fibrous Glass

**Asbestos Observed (%):**      **Date Analyzed:** 11/27/2018      **Total Asbestos (%)** None Detected  
**Analyst:** Chris Turton



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509341  
**Samples Submitted:** 174  
**Sample Collection Date:** 11/19/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #2  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 15 of 44

### TEST DATA

**Laboratory ID#:** 1509341-057      **Client Sample #:** 57

**Sample Material and Location:** Yellow Pipe Insulation 2nd Floor Power Supply Room - West End

**Sample Characteristics:** Yellow Fibrous Inhomogenous  
**Misc. Components Observed:** 3% Non-Fibrous Material  
97% Fibrous Glass

**Asbestos Observed (%):**      **Date Analyzed:** 11/27/2018      **Total Asbestos (%)** None Detected  
**Analyst:** Chris Turton

### TEST DATA

**Laboratory ID#:** 1509341-058      **Client Sample #:** 58

**Sample Material and Location:** Black Gasket at HVAC 2nd Floor Mech. Room at HVAC - S.E. End

**Sample Characteristics:** Black Non-Fibrous Homogenous  
**Misc. Components Observed:** 95% Non-Fibrous Material  
**Asbestos Observed (%):** Chrysotile 5%  
**Analyst:** Chris Turton      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** 5%

### TEST DATA

**Laboratory ID#:** 1509341-059      **Client Sample #:** 59

**Sample Material and Location:** Black Gasket at HVAC 2nd Floor Power Supply Room - N.E. End

**Sample Characteristics:** Black Non-Fibrous Homogenous  
**Misc. Components Observed:** 95% Non-Fibrous Material  
**Asbestos Observed (%):** Chrysotile 5%  
**Analyst:** Chris Turton      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** 5%

### TEST DATA

**Laboratory ID#:** 1509341-060      **Client Sample #:** 60

**Sample Material and Location:** Black Gasket at HVAC 2nd Floor Power Supply Room - West End

**Sample Characteristics:** Black Non-Fibrous Homogenous  
**Misc. Components Observed:** 95% Non-Fibrous Material  
**Asbestos Observed (%):** Chrysotile 5%  
**Analyst:** Chris Turton      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** 5%



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509341  
**Samples Submitted:** 174  
**Sample Collection Date:** 11/19/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #2  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 16 of 44

### TEST DATA

**Laboratory ID#:** 1509341-061 **Client Sample #:** 61

**Sample Material and Location:** Black/White Vibration Damper 2nd Floor Mech. Room - East End

**Sample Characteristics:** Brown Fibrous Inhomogenous  
**Misc. Components Observed:** 30% Non-Fibrous Material  
70% Cellulose

**Asbestos Observed (%):** **Total Asbestos (%)** None Detected  
**Analyst:** Chris Turton **Date Analyzed:** 11/27/2018

### TEST DATA

**Laboratory ID#:** 1509341-062 **Client Sample #:** 62

**Sample Material and Location:** Black/White Vibration Damper 2nd Floor Power Supply Room - Center

**Sample Characteristics:** Brown Fibrous Inhomogenous  
**Misc. Components Observed:** 30% Non-Fibrous Material  
70% Cellulose

**Asbestos Observed (%):** **Total Asbestos (%)** None Detected  
**Analyst:** Chris Turton **Date Analyzed:** 11/27/2018

### TEST DATA

**Laboratory ID#:** 1509341-063 **Client Sample #:** 63

**Sample Material and Location:** Black/White Vibration Damper 2nd Floor Power Supply Room - West End

**Sample Characteristics:** Brown Fibrous Inhomogenous  
**Misc. Components Observed:** 30% Non-Fibrous Material  
70% Cellulose

**Asbestos Observed (%):** **Total Asbestos (%)** None Detected  
**Analyst:** Chris Turton **Date Analyzed:** 11/27/2018

### TEST DATA

**Laboratory ID#:** 1509341-064 **Client Sample #:** 64

**Sample Material and Location:** Tan Ductwork Wrap 2nd Floor Mech. Room Ductwork - West End

**Sample Characteristics:** Brown Fibrous Homogenous  
**Misc. Components Observed:** 20% Non-Fibrous Material  
80% Cellulose

**Asbestos Observed (%):** **Total Asbestos (%)** None Detected  
**Analyst:** Chris Turton **Date Analyzed:** 11/27/2018





## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509341  
**Samples Submitted:** 174  
**Sample Collection Date:** 11/19/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #2  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 17 of 44

### TEST DATA

---

**Laboratory ID#:** 1509341-065      **Client Sample #:** 65

**Sample Material and Location:** Tan Ductwork Wrap 2nd Floor Power Supply Room - West End

**Sample Characteristics:** Brown Fibrous Homogenous  
**Misc. Components Observed:** 20% Non-Fibrous Material  
80% Cellulose

**Asbestos Observed (%):**      **Date Analyzed:** 11/27/2018      **Total Asbestos (%)** None Detected  
**Analyst:** Chris Turton

### TEST DATA

---

**Laboratory ID#:** 1509341-066      **Client Sample #:** 66

**Sample Material and Location:** Tan Ductwork Wrap 2nd Floor Power Supply Room - North End

**Sample Characteristics:** Brown Fibrous Inhomogenous  
**Misc. Components Observed:** 20% Non-Fibrous Material  
80% Cellulose

**Asbestos Observed (%):**      **Date Analyzed:** 11/27/2018      **Total Asbestos (%)** None Detected  
**Analyst:** Chris Turton

### TEST DATA

---

**Laboratory ID#:** 1509341-067      **Client Sample #:** 67

**Sample Material and Location:** Brown Cork Board under Duct Work Wrap 2nd Floor Mech. Room Ductwork - West End

**Sample Characteristics:** Brown Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**      **Date Analyzed:** 11/27/2018      **Total Asbestos (%)** None Detected  
**Analyst:** Chris Turton

### TEST DATA

---

**Laboratory ID#:** 1509341-068      **Client Sample #:** 68

**Sample Material and Location:** Brown Cork Board under Duct Work Wra 2nd Floor Power Supply Room - West End

**Sample Characteristics:** Brown Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**      **Date Analyzed:** 11/27/2018      **Total Asbestos (%)** None Detected  
**Analyst:** Chris Turton



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509341  
**Samples Submitted:** 174  
**Sample Collection Date:** 11/19/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #2  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 18 of 44

### TEST DATA

**Laboratory ID#:** 1509341-069      **Client Sample #:** 69

**Sample Material and Location:** Brown Cork Board under Duct Work Wra 2nd Floor Power Supply Room - North End

**Sample Characteristics:** Brown Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)**    None Detected

### TEST DATA

**Laboratory ID#:** 1509341-070      **Client Sample #:** 70

**Sample Material and Location:** Black Mastic behind Cork Board 2nd Floor Mech. Room Ductwork - West End

**Sample Characteristics:** Black Non-Fibrous Homogenous  
**Misc. Components Observed:** 95% Non-Fibrous Material  
**Asbestos Observed (%):** Chrysotile      5%  
**Analyst:** Chris Turton      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)**      5%

### TEST DATA

**Laboratory ID#:** 1509341-071      **Client Sample #:** 71

**Sample Material and Location:** Black Mastic behind Cork Board 2nd Floor Power Supply Room - West End

**Sample Characteristics:** Black Non-Fibrous Homogenous  
**Misc. Components Observed:** 95% Non-Fibrous Material  
**Asbestos Observed (%):** Chrysotile      5%  
**Analyst:** Chris Turton      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)**      5%

### TEST DATA

**Laboratory ID#:** 1509341-072      **Client Sample #:** 72

**Sample Material and Location:** Black Mastic behind Cork Board 2nd Floor Power Supply Room - North End

**Sample Characteristics:** Black Non-Fibrous Homogenous  
**Misc. Components Observed:** 95% Non-Fibrous Material  
**Asbestos Observed (%):** Chrysotile      5%  
**Analyst:** Chris Turton      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)**      5%



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509341  
**Samples Submitted:** 174  
**Sample Collection Date:** 11/19/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #2  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 19 of 44

### TEST DATA

**Laboratory ID#:** 1509341-073      **Client Sample #:** 73

**Sample Material and Location:** White Joint Compound 2nd Floor Mech. Room - West End

<b>Sample Characteristics:</b>	White Non-Fibrous Homogenous		
<b>Misc. Components Observed:</b>	98% Non-Fibrous Material		
<b>Asbestos Observed (%):</b>	Chrysotile	2%	<b>Total Asbestos (%)</b> 2%
<b>Analyst:</b> Chris Turton	<b>Date Analyzed:</b>	11/27/2018	

### TEST DATA

**Laboratory ID#:** 1509341-074      **Client Sample #:** 74

**Sample Material and Location:** White Joint Compound 2nd Floor Mech. Room - North End

<b>Sample Characteristics:</b>	White Non-Fibrous Homogenous		
<b>Misc. Components Observed:</b>	98% Non-Fibrous Material		
<b>Asbestos Observed (%):</b>	Chrysotile	2%	<b>Total Asbestos (%)</b> 2%
<b>Analyst:</b> Chris Turton	<b>Date Analyzed:</b>	11/27/2018	

### TEST DATA

**Laboratory ID#:** 1509341-075      **Client Sample #:** 75

**Sample Material and Location:** White Joint Compound 2nd Floor Mech. Room - East End

<b>Sample Characteristics:</b>	White Non-Fibrous Homogenous		
<b>Misc. Components Observed:</b>	98% Non-Fibrous Material		
<b>Asbestos Observed (%):</b>	Chrysotile	2%	<b>Total Asbestos (%)</b> 2%
<b>Analyst:</b> Chris Turton	<b>Date Analyzed:</b>	11/27/2018	

### TEST DATA

**Laboratory ID#:** 1509341-076      **Client Sample #:** 76

**Sample Material and Location:** White Drywall Layer 1 2nd Floor Mech. Room - West End

<b>Sample Characteristics:</b>	White Non-Fibrous Homogenous		
<b>Misc. Components Observed:</b>	95% Non-Fibrous Material 5% Cellulose		
<b>Asbestos Observed (%):</b>			<b>Total Asbestos (%)</b> None Detected
<b>Analyst:</b> Chris Turton	<b>Date Analyzed:</b>	11/28/2018	



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509341  
**Samples Submitted:** 174  
**Sample Collection Date:** 11/19/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #2  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 20 of 44

### TEST DATA

**Laboratory ID#:** 1509341-077      **Client Sample #:** 77

**Sample Material and Location:** White Drywall Layer 1 2nd Floor Mech. Room - North End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 95% Non-Fibrous Material  
5% Cellulose

**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509341-078      **Client Sample #:** 78

**Sample Material and Location:** White Drywall Layer 1 2nd Floor Mech. Room - East End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 95% Non-Fibrous Material  
5% Cellulose

**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509341-079      **Client Sample #:** 79

**Sample Material and Location:** White Mastic Sandwiched between 2 Layers of Drywall 2nd Floor Mech. Room - West End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 98% Non-Fibrous Material  
**Asbestos Observed (%):** Chrysotile 2%  
**Analyst:** Chris Turton      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** 2%

### TEST DATA

**Laboratory ID#:** 1509341-080      **Client Sample #:** 80

**Sample Material and Location:** White Mastic Sandwiched between 2 Layers of Drywall 2nd Floor Mech. Room - North End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 98% Non-Fibrous Material  
**Asbestos Observed (%):** Chrysotile 2%  
**Analyst:** Chris Turton      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** 2%



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509341  
**Samples Submitted:** 174  
**Sample Collection Date:** 11/19/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #2  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 21 of 44

### TEST DATA

**Laboratory ID#:** 1509341-081      **Client Sample #:** 81

**Sample Material and Location:** White Mastic Sandwiched between 2 Layers of Drywall 2nd Floor Mech. Room - East End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 98% Non-Fibrous Material  
**Asbestos Observed (%):** Chrysotile      2%      **Total Asbestos (%)**      2%  
**Analyst:** Chris Turton      **Date Analyzed:** 11/28/2018

### TEST DATA

**Laboratory ID#:** 1509341-082      **Client Sample #:** 82

**Sample Material and Location:** White Drywall Layer 2 2nd Floor Mech. Room - West End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 95% Non-Fibrous Material  
5% Cellulose  
**Asbestos Observed (%):**      **Total Asbestos (%)**      None Detected  
**Analyst:** Chris Turton      **Date Analyzed:** 11/28/2018

### TEST DATA

**Laboratory ID#:** 1509341-083      **Client Sample #:** 83

**Sample Material and Location:** White Drywall Layer 2 2nd Floor Mech. Room - North End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 95% Non-Fibrous Material  
5% Cellulose  
**Asbestos Observed (%):**      **Total Asbestos (%)**      None Detected  
**Analyst:** Chris Turton      **Date Analyzed:** 11/28/2018

### TEST DATA

**Laboratory ID#:** 1509341-084      **Client Sample #:** 84

**Sample Material and Location:** White Drywall Layer 2 2nd Floor Mech. Room - East End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 95% Non-Fibrous Material  
5% Cellulose  
**Asbestos Observed (%):**      **Total Asbestos (%)**      None Detected  
**Analyst:** Chris Turton      **Date Analyzed:** 11/28/2018



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509341  
**Samples Submitted:** 174  
**Sample Collection Date:** 11/19/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #2  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 22 of 44

### TEST DATA

**Laboratory ID#:** 1509341-085      **Client Sample #:** 85

**Sample Material and Location:** Gray Plaster 1st Floor Hallway - North End

**Sample Characteristics:** Grey Grainy Inhomogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**

**Analyst:** Chris Turton      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509341-086      **Client Sample #:** 86

**Sample Material and Location:** Gray Plaster 2nd Floor Landing - East End

**Sample Characteristics:** Grey Grainy Inhomogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**

**Analyst:** Chris Turton      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509341-087      **Client Sample #:** 87

**Sample Material and Location:** Gray Plaster 2nd Floor Ceiling - S.W. End

**Sample Characteristics:** Grey Grainy Inhomogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**

**Analyst:** Chris Turton      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509341-088      **Client Sample #:** 88

**Sample Material and Location:** Yellow Carpet Glue under Gray Carpet 2nd Floor Gym - N.E. End

**Sample Characteristics:** Yellow Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**

**Analyst:** Chris Turton      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509341  
**Samples Submitted:** 174  
**Sample Collection Date:** 11/19/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #2  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 23 of 44

### TEST DATA

---

**Laboratory ID#:** 1509341-089      **Client Sample #:** 89

**Sample Material and Location:** Yellow Carpet Glue under Gray Carpet 2nd Floor Gym - N.W. End

**Sample Characteristics:** Yellow Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509341-090      **Client Sample #:** 90

**Sample Material and Location:** Yellow Carpet Glue under Gray Carpet 2nd Floor Gym - S.E. End

**Sample Characteristics:** Yellow Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509341-091      **Client Sample #:** 91

**Sample Material and Location:** Black 4" Covebase 2nd Floor Landing - S.W. End

**Sample Characteristics:** Black Smooth Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509341-092      **Client Sample #:** 92

**Sample Material and Location:** Black 4" Covebase 1st Floor Hallway - N.E. End

**Sample Characteristics:** Black Smooth Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509341  
**Samples Submitted:** 174  
**Sample Collection Date:** 11/19/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #2  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 24 of 44

### TEST DATA

---

**Laboratory ID#:** 1509341-093      **Client Sample #:** 93

**Sample Material and Location:** Black 4" Covebase 1st Floor Hallway - S.E. End

**Sample Characteristics:** Black Smooth Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509341-094      **Client Sample #:** 94

**Sample Material and Location:** Brown/Tan Covebase Mastic 2nd Floor Landing - S.W. End

**Sample Characteristics:** Brown Tan Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509341-095      **Client Sample #:** 95

**Sample Material and Location:** Brown/Tan Covebase Mastic 1st Floor Hallway - N.E. End

**Sample Characteristics:** Brown Tan Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509341-096      **Client Sample #:** 96

**Sample Material and Location:** Brown/Tan Covebase Mastic 1st Floor Hallway - S.E. End

**Sample Characteristics:** Brown Tan Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected





## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509341  
**Samples Submitted:** 174  
**Sample Collection Date:** 11/19/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #2  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 25 of 44

### TEST DATA

**Laboratory ID#:** 1509341-097 **Client Sample #:** 97

**Sample Material and Location:** Tan 12 x 12 Floor Tile Café - North End

**Sample Characteristics:** Tan White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509341-098 **Client Sample #:** 98

**Sample Material and Location:** Tan 12 x 12 Floor Tile Café - S.E. End

**Sample Characteristics:** Tan White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509341-099 **Client Sample #:** 99

**Sample Material and Location:** Tan 12 x 12 Floor Tile Kitchen - East End

**Sample Characteristics:** Tan White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509341-100 **Client Sample #:** 100

**Sample Material and Location:** Gray Floor Tile Glue Café - North End

**Sample Characteristics:** Gray Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509341  
**Samples Submitted:** 174  
**Sample Collection Date:** 11/19/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #2  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 26 of 44

### TEST DATA

---

**Laboratory ID#:** 1509341-101      **Client Sample #:** 101

**Sample Material and Location:** Gray Floor Tile Glue Café - S.E. End

**Sample Characteristics:** Gray Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509341-102      **Client Sample #:** 102

**Sample Material and Location:** Gray Floor Tile Glue Kitchen - East End

**Sample Characteristics:** Gray Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509341-103      **Client Sample #:** 103

**Sample Material and Location:** White Floor Tile under Tan Floor Tile Café - North End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509341-104      **Client Sample #:** 104

**Sample Material and Location:** White Floor Tile under Tan Floor Tile Café - S.E. End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509341  
**Samples Submitted:** 174  
**Sample Collection Date:** 11/19/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #2  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 27 of 44

### TEST DATA

---

**Laboratory ID#:** 1509341-105      **Client Sample #:** 105

**Sample Material and Location:** White Floor Tile under Tan Floor Tile Kitchen - East End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509341-106      **Client Sample #:** 106

**Sample Material and Location:** Black Floor Mastic Café - North End

**Sample Characteristics:** Black Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509341-107      **Client Sample #:** 107

**Sample Material and Location:** Black Floor Mastic Café - S.E. End End

**Sample Characteristics:** Black Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509341-108      **Client Sample #:** 108

**Sample Material and Location:** Black Floor Mastic Kitchen - East End

**Sample Characteristics:** Black Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509341  
**Samples Submitted:** 174  
**Sample Collection Date:** 11/19/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #2  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 28 of 44

### TEST DATA

**Laboratory ID#:** 1509341-109      **Client Sample #:** 109

**Sample Material and Location:** Gray Linoleum Janitors Closet - North End

**Sample Characteristics:** Grey Fibrous Inhomogenous  
**Misc. Components Observed:** 67% Non-Fibrous Material  
3% Fibrous Glass  
30% Cellulose

**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509341-110      **Client Sample #:** 110

**Sample Material and Location:** Gray Linoleum Food Pantry - South End

**Sample Characteristics:** Grey Fibrous Inhomogenous  
**Misc. Components Observed:** 67% Non-Fibrous Material  
3% Fibrous Glass  
30% Cellulose

**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509341-111      **Client Sample #:** 111

**Sample Material and Location:** Gray Linoleum Storage Closet - West End

**Sample Characteristics:** Grey Fibrous Inhomogenous  
**Misc. Components Observed:** 67% Non-Fibrous Material  
3% Fibrous Glass  
30% Cellulose

**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509341-112      **Client Sample #:** 112

**Sample Material and Location:** Yellow Linoleum Glue Janitors Closet - North End

**Sample Characteristics:** Yellow Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509341  
**Samples Submitted:** 174  
**Sample Collection Date:** 11/19/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #2  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 29 of 44

### TEST DATA

---

**Laboratory ID#:** 1509341-113      **Client Sample #:** 113

**Sample Material and Location:** Yellow Linoleum Glue Food Pantry - South End

**Sample Characteristics:** Yellow Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509341-114      **Client Sample #:** 114

**Sample Material and Location:** Yellow Linoleum Glue Storage Closet - West End

**Sample Characteristics:** Yellow Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509341-115      **Client Sample #:** 115

**Sample Material and Location:** White 12 x 12 Floor Tile Patient Room - East End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509341-116      **Client Sample #:** 116

**Sample Material and Location:** White 12 x 12 Floor Tile Patient Room - South End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected



**Analytical Report**

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509341  
**Samples Submitted:** 174  
**Sample Collection Date:** 11/19/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #2  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 30 of 44

**TEST DATA**

**Laboratory ID#:** 1509341-117      **Client Sample #:** 117

**Sample Material and Location:** White 12 x 12 Floor Tile Hearing Room - North End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**      **Total Asbestos (%)** None Detected  
**Analyst:** Chris Turton      **Date Analyzed:** 11/28/2018

**TEST DATA**

**Laboratory ID#:** 1509341-118      **Client Sample #:** 118

**Sample Material and Location:** Black Floor Mastic Patient Room - East End

**Sample Characteristics:** Black Non-Fibrous Homogenous  
**Misc. Components Observed:** 95% Non-Fibrous Material

**Asbestos Observed (%):** Chrysotile 5%      **Total Asbestos (%)** 5%  
**Analyst:** Chris Turton      **Date Analyzed:** 11/28/2018

**TEST DATA**

**Laboratory ID#:** 1509341-119      **Client Sample #:** 119

**Sample Material and Location:** Black Floor Mastic Patient Room - South End

**Sample Characteristics:** Black Non-Fibrous Homogenous  
**Misc. Components Observed:** 95% Non-Fibrous Material

**Asbestos Observed (%):** Chrysotile 5%      **Total Asbestos (%)** 5%  
**Analyst:** Chris Turton      **Date Analyzed:** 11/28/2018

**TEST DATA**

**Laboratory ID#:** 1509341-120      **Client Sample #:** 120

**Sample Material and Location:** Black Floor Mastic Hearing Room - North End

**Sample Characteristics:** Black Non-Fibrous Homogenous  
**Misc. Components Observed:** 95% Non-Fibrous Material

**Asbestos Observed (%):** Chrysotile 5%      **Total Asbestos (%)** 5%  
**Analyst:** Chris Turton      **Date Analyzed:** 11/28/2018



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509341  
**Samples Submitted:** 174  
**Sample Collection Date:** 11/19/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #2  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 31 of 44

### TEST DATA

---

**Laboratory ID#:** 1509341-121      **Client Sample #:** 121

**Sample Material and Location:** Dark Gray 12 x 12 Floor Tile Health Service - West End

**Sample Characteristics:** Gray White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**

**Analyst:** Chris Turton

**Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509341-122      **Client Sample #:** 122

**Sample Material and Location:** Dark Gray 12 x 12 Floor Tile Hallway - East End

**Sample Characteristics:** Gray White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**

**Analyst:** Chris Turton

**Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509341-123      **Client Sample #:** 123

**Sample Material and Location:** Dark Gray 12 x 12 Floor Tile Storage Room - North End

**Sample Characteristics:** Gray White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**

**Analyst:** Chris Turton

**Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509341-124      **Client Sample #:** 124

**Sample Material and Location:** Yellow Floor Tile Glue Health Service - West End

**Sample Characteristics:** Yellow Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**

**Analyst:** Chris Turton

**Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509341  
**Samples Submitted:** 174  
**Sample Collection Date:** 11/19/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #2  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 32 of 44

### TEST DATA

---

**Laboratory ID#:** 1509341-125      **Client Sample #:** 125

**Sample Material and Location:** Yellow Floor Tile Glue Hallway - East End

**Sample Characteristics:** Yellow Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509341-126      **Client Sample #:** 126

**Sample Material and Location:** Yellow Floor Tile Glue Storage Room - North End

**Sample Characteristics:** Yellow Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509341-127      **Client Sample #:** 127

**Sample Material and Location:** Brown 4" Covebase Lab #1 - East End

**Sample Characteristics:** Brown Gray Smooth Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509341-128      **Client Sample #:** 128

**Sample Material and Location:** Brown 4" Covebase Office #6 - West End

**Sample Characteristics:** Brown Gray Smooth Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected





## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509341  
**Samples Submitted:** 174  
**Sample Collection Date:** 11/19/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #2  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 33 of 44

### TEST DATA

---

**Laboratory ID#:** 1509341-129      **Client Sample #:** 129

**Sample Material and Location:** Brown 4" Covebase Maintenance Department Hallway - North End

**Sample Characteristics:** Brown Smooth Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509341-130      **Client Sample #:** 130

**Sample Material and Location:** Brown Covebase Glue Lab #1 - East End

**Sample Characteristics:** Brown Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509341-131      **Client Sample #:** 131

**Sample Material and Location:** Brown Covebase Glue Office #6 - West End

**Sample Characteristics:** Brown Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509341-132      **Client Sample #:** 132

**Sample Material and Location:** Brown Covebase Glue Maintenance Department Hallway - North End

**Sample Characteristics:** Brown Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509341  
**Samples Submitted:** 174  
**Sample Collection Date:** 11/19/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #2  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 34 of 44

### TEST DATA

**Laboratory ID#:** 1509341-133      **Client Sample #:** 133

**Sample Material and Location:** Gray Linoleum Lab #2 - South End

**Sample Characteristics:** Beige Fibrous Inhomogenous  
**Misc. Components Observed:** 67% Non-Fibrous Material  
3% Fibrous Glass  
30% Cellulose

**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509341-134      **Client Sample #:** 134

**Sample Material and Location:** Gray Linoleum Lab #2 - West End

**Sample Characteristics:** Beige Fibrous Inhomogenous  
**Misc. Components Observed:** 67% Non-Fibrous Material  
3% Fibrous Glass  
30% Cellulose

**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509341-135      **Client Sample #:** 135

**Sample Material and Location:** Gray Linoleum Lab Data Room - Center

**Sample Characteristics:** Beige Non-Fibrous Inhomogenous  
**Misc. Components Observed:** 67% Non-Fibrous Material  
3% Fibrous Glass  
30% Cellulose

**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509341-136      **Client Sample #:** 136

**Sample Material and Location:** Brown/White Linoleum Glue Lab #2 - South End

**Sample Characteristics:** Brown Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509341  
**Samples Submitted:** 174  
**Sample Collection Date:** 11/19/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #2  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 35 of 44

### TEST DATA

**Laboratory ID#:** 1509341-137      **Client Sample #:** 137

**Sample Material and Location:** Brown/White Linoleum Glue Lab #2 - West End

**Sample Characteristics:** Brown Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509341-138      **Client Sample #:** 138

**Sample Material and Location:** Brown/White Linoleum Glue Lab Data Room - Center

**Sample Characteristics:** Brown Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509341-139      **Client Sample #:** 139

**Sample Material and Location:** Brown/Tan 12 x 12 Floor Tile Lab Office - South End

**Sample Characteristics:** Brown Tan Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509341-140      **Client Sample #:** 140

**Sample Material and Location:** Brown/Tan 12 x 12 Floor Tile Lab Office - East End

**Sample Characteristics:** Brown Tan Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509341  
**Samples Submitted:** 174  
**Sample Collection Date:** 11/19/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #2  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 36 of 44

### TEST DATA

**Laboratory ID#:** 1509341-141      **Client Sample #:** 141

**Sample Material and Location:** Brown/Tan 12 x 12 Floor Tile Lab Office - North End

**Sample Characteristics:** Brown Tan Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**

**Analyst:** Chris Turton

**Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509341-142      **Client Sample #:** 142

**Sample Material and Location:** Black Floor Tile Mastic Lab Office - South End

**Sample Characteristics:** Black Non-Fibrous Homogenous

**Misc. Components Observed:** 95% Non-Fibrous Material

**Asbestos Observed (%):** Chrysotile 5%

**Analyst:** Chris Turton

**Date Analyzed:** 11/28/2018

**Total Asbestos (%)** 5%

### TEST DATA

**Laboratory ID#:** 1509341-143      **Client Sample #:** 143

**Sample Material and Location:** Black Floor Tile Mastic Lab Office - East End

**Sample Characteristics:** Black Non-Fibrous Homogenous

**Misc. Components Observed:** 95% Non-Fibrous Material

**Asbestos Observed (%):** Chrysotile 5%

**Analyst:** Chris Turton

**Date Analyzed:** 11/28/2018

**Total Asbestos (%)** 5%

### TEST DATA

**Laboratory ID#:** 1509341-144      **Client Sample #:** 144

**Sample Material and Location:** Black Floor Tile Mastic Lab Office - North End

**Sample Characteristics:** Black Non-Fibrous Homogenous

**Misc. Components Observed:** 95% Non-Fibrous Material

**Asbestos Observed (%):** Chrysotile 5%

**Analyst:** Chris Turton

**Date Analyzed:** 11/28/2018

**Total Asbestos (%)** 5%



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509341  
**Samples Submitted:** 174  
**Sample Collection Date:** 11/19/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #2  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 37 of 44

### TEST DATA

---

**Laboratory ID#:** 1509341-145      **Client Sample #:** 145

**Sample Material and Location:** Gray 4" Covebase Lab Office - South End

**Sample Characteristics:** Gray Smooth Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509341-146      **Client Sample #:** 146

**Sample Material and Location:** Gray 4" Covebase Lab Office - East End

**Sample Characteristics:** Gray Smooth Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509341-147      **Client Sample #:** 147

**Sample Material and Location:** Gray 4" Covebase Copy Room - West End

**Sample Characteristics:** Gray Smooth Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509341-148      **Client Sample #:** 148

**Sample Material and Location:** Tan/Brown Covebase Mastic Lab Office - South End

**Sample Characteristics:** Tan Brown Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509341  
**Samples Submitted:** 174  
**Sample Collection Date:** 11/19/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #2  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 38 of 44

### TEST DATA

**Laboratory ID#:** 1509341-149      **Client Sample #:** 149

**Sample Material and Location:** Tan/Brown Covebase Mastic Lab Office - East End

**Sample Characteristics:** Tan Brown Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**

**Analyst:** Chris Turton

**Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509341-150      **Client Sample #:** 150

**Sample Material and Location:** Tan/Brown Covebase Mastic Copy Room - West End

**Sample Characteristics:** Tan Brown Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**

**Analyst:** Chris Turton

**Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509341-151      **Client Sample #:** 151

**Sample Material and Location:** Cream 12 x 12 Floor Tile Operations Center - South End

**Sample Characteristics:** Cream White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**

**Analyst:** Chris Turton

**Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509341-152      **Client Sample #:** 152

**Sample Material and Location:** Cream 12 x 12 Floor Tile Operations Center - N.E. End

**Sample Characteristics:** Cream White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**

**Analyst:** Chris Turton

**Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509341  
**Samples Submitted:** 174  
**Sample Collection Date:** 11/19/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #2  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 39 of 44

### TEST DATA

---

**Laboratory ID#:** 1509341-153      **Client Sample #:** 153

**Sample Material and Location:** Cream 12 x 12 Floor Tile Operations Center - S.E. End

**Sample Characteristics:** Cream White Non-Fibrous Homogenous

**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**

**Analyst:** Chris Turton

**Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509341-154      **Client Sample #:** 154

**Sample Material and Location:** Gray Floor Tile Glue Operations Center - South End

**Sample Characteristics:** Gray Non-Fibrous Homogenous

**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**

**Analyst:** Chris Turton

**Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509341-155      **Client Sample #:** 155

**Sample Material and Location:** Gray Floor Tile Glue Operations Center - N.E. End

**Sample Characteristics:** Gray Non-Fibrous Homogenous

**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**

**Analyst:** Chris Turton

**Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509341-156      **Client Sample #:** 156

**Sample Material and Location:** Gray Floor Tile Glue Operations Center - S.E. End

**Sample Characteristics:** Gray Non-Fibrous Homogenous

**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**

**Analyst:** Chris Turton

**Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509341  
**Samples Submitted:** 174  
**Sample Collection Date:** 11/19/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #2  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 40 of 44

### TEST DATA

**Laboratory ID#:** 1509341-157      **Client Sample #:** 157

**Sample Material and Location:** Gray w/Streaks 12 x 12 Floor Tile Operations Center - S.E. End

**Sample Characteristics:** Gray White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**

**Analyst:** Chris Turton      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509341-158      **Client Sample #:** 158

**Sample Material and Location:** Gray w/Streaks 12 x 12 Floor Tile Office #6 - West End

**Sample Characteristics:** Gray White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**

**Analyst:** Chris Turton      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509341-159      **Client Sample #:** 159

**Sample Material and Location:** Gray w/Streaks 12 x 12 Floor Tile Hallway - South End

**Sample Characteristics:** Gray White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**

**Analyst:** Chris Turton      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509341-160      **Client Sample #:** 160

**Sample Material and Location:** Yellow Floor Tile Glue Operations Center - S.E. End

**Sample Characteristics:** Yellow Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**

**Analyst:** Chris Turton      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected





## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509341  
**Samples Submitted:** 174  
**Sample Collection Date:** 11/19/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #2  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 41 of 44

### TEST DATA

---

**Laboratory ID#:** 1509341-161      **Client Sample #:** 161

**Sample Material and Location:** Yellow Floor Tile Glue Office #6 - West End

**Sample Characteristics:** Yellow Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509341-162      **Client Sample #:** 162

**Sample Material and Location:** Yellow Floor Tile Glue Hallway - South End

**Sample Characteristics:** Yellow Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509341-163      **Client Sample #:** 163

**Sample Material and Location:** Offwhite Floor Tile under Gray w/Streaks and Cream F.T. Operations Center - S.E. End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509341-164      **Client Sample #:** 164

**Sample Material and Location:** Offwhite Floor Tile under Gray w/Streaks and Cream F.T. Office #6 - West End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509341  
**Samples Submitted:** 174  
**Sample Collection Date:** 11/19/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #2  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 42 of 44

### TEST DATA

**Laboratory ID#:** 1509341-165      **Client Sample #:** 165

**Sample Material and Location:** Offwhite Floor Tile under Gray w/Streaks and Cream F.T. Hallway - South End

**Sample Characteristics:** White Non-Fibrous Homogenous

**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**

**Analyst:** Chris Turton

**Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509341-166      **Client Sample #:** 166

**Sample Material and Location:** Black Floor Tile Mastic Operations Center - S.E. End

**Sample Characteristics:** Black Non-Fibrous Homogenous

**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**

**Analyst:** Chris Turton

**Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509341-167      **Client Sample #:** 167

**Sample Material and Location:** Black Floor Tile Mastic Office #6 - West End

**Sample Characteristics:** Black Non-Fibrous Homogenous

**Misc. Components Observed:** 95% Non-Fibrous Material

**Asbestos Observed (%):** Chrysotile 5%

**Analyst:** Chris Turton

**Date Analyzed:** 11/28/2018

**Total Asbestos (%)** 5%

### TEST DATA

**Laboratory ID#:** 1509341-168      **Client Sample #:** 168

**Sample Material and Location:** Black Floor Tile Mastic Hallway - South End

**Sample Characteristics:** Black Non-Fibrous Homogenous

**Misc. Components Observed:** 95% Non-Fibrous Material

**Asbestos Observed (%):** Chrysotile 5%

**Analyst:** Chris Turton

**Date Analyzed:** 11/28/2018

**Total Asbestos (%)** 5%



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509341  
**Samples Submitted:** 174  
**Sample Collection Date:** 11/19/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #2  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 43 of 44

### TEST DATA

**Laboratory ID#:** 1509341-169      **Client Sample #:** 169

**Sample Material and Location:** Dark Gray w/White Streaks 12 x 12 Floor Tile Lab Hallway - West End

**Sample Characteristics:** Grey Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509341-170      **Client Sample #:** 170

**Sample Material and Location:** Dark Gray w/White Streaks 12 x 12 Floor Tile Lab Hallway - North End

**Sample Characteristics:** Grey Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509341-171      **Client Sample #:** 171

**Sample Material and Location:** Dark Gray w/White Streaks 12 x 12 Floor Tile Lab Hallway - South End

**Sample Characteristics:** Grey Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509341-172      **Client Sample #:** 172

**Sample Material and Location:** White/Tan Floor Tile Glue Lab Hallway - West End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509341  
**Samples Submitted:** 174  
**Sample Collection Date:** 11/19/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #2  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 44 of 44

### TEST DATA

**Laboratory ID#:** 1509341-173      **Client Sample #:** 173

**Sample Material and Location:** White/Tan Floor Tile Glue Lab Hallway - North End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509341-174      **Client Sample #:** 174

**Sample Material and Location:** White/Tan Floor Tile Glue Lab Hallway - South End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

Samples were analyzed by Calibrated Visual Estimation (CVE). Analyses by CVE have a detection limit of 1% asbestos by relative area and may not be consistently reliable below this limit or for asbestos with fiber diameter thinner than the resolving capacity of PLM without further analysis by another independent method. A test result of less than (<) 1% by CVE means asbestos was observed in the sample but is visually estimated to be below the reportable limit of 1%. The laboratory references interim method EPA 600/M4-82-020 (Interim Method) for fiber identification, 400 point counts, and composite reporting. EPA method 600/R-93/116 is referenced for analysis of non-insulation materials, sub-layers, expanded and modified point counts, CVE and subsequent data reporting. Samples containing distinct layers that can be reliably separated are analyzed and reported as separate unless requested in writing. The test data presented apply only to the items submitted. Count for samples submitted is indicative of total layers observed and may vary from actual analysis for positive stop requests. ATEL, LLC is a NIST-NVLAP and CA-ELAP Accredited laboratory (ID# 201073-0 and #2971, respectively). This report must not be reproduced, unless in its entirety, without the written consent of ATEL, LLC. Per NIST-NVLAP 150 Annex A: This report shall not be used to claim product certification, approval or endorsement by NVLAP, NIST, or any agency of the federal government.

Unless indicated, samples were received in acceptable condition. Sample retention time is 30 days from issuing this report unless requested otherwise.

**Analyst Signature:**  -Chris Turton

**Approved Signatory:**  -Dennis Liu

**Reported On:** 11/28/2018



1509341

Analytical Services Request v.112414

Pg 1 of 1

Asbestos Laboratory

**Your Contact Information**

Company Name (if by company): H2 Environmental Consulting Services, Inc.  
 Personal/Company Address: 13122 6th Street, Chino, CA 91710  
 Contact Person: Amy De Santiago  
 Contact Information: Main: 909-628-0369 E-Mail: labresults@h2env.com  
 Mobile: \_\_\_\_\_ Fax: 909-613-5845  
 How should we send your result Verbal  Verbal  E-mail  Fax   
*\*If verbal results are requested, you must also select a second form of delivery.*

**Project Information**

Project Name: Kimberly Clark  
 Project #: 2069218.45  
 Project Location: 2001 E. Orangewood Ave, Fullerton, CA - Bldg #2  
 PO#: \_\_\_\_\_ Claim# \_\_\_\_\_  
 Date Sampled: 11/19/18 Time Sampled: 3pm

**Analytical Type(s) Requested**

Asbestos In Bulk Materials, EPA 600/R-93/116, 600/M4-82-020  
 Routine, Calibrated Visual Estimation   
 Point Count: 400pts   
 1000pts   
 Gravimetric Reduction (72hr Minimum)   
 Fiber Count in Sampling Cartridge (25mm MCE)  
 Asbestos-like, NIOSH 7400 A Rules   
 Rotometer Calibration (Low and High Flow Rotometers)

**Turnaround Time\***

\*Business Hrs: 0800-1700 Mon-Fri.  
 Rush 3 Business Hrs\*   
 8 Business Hrs\*   
 Expedited 24 Business Hrs   
 Routine 48 Business Hrs   
 72 Business Hrs   
 Standard 5 Business Days

\*3hr TAT: Samples must be submitted by 2pm for same day results  
 \*8hr TAT: Samples must be submitted by 9am for same day results

Special Instructions: \_\_\_\_\_

**Sample Information**

Sample ID #	Description/Material Type	Location	Flow Rate	Start Time	Stop Time	Volume (L)
	Please See Attached					

For more samples, please continue onto supplemental form. Page # Indication in upper-right-hand of form.

**Chain of Custody**

Relinquished By: Alberto Sanchez Date and Time: 11/19/18 3pm  
 Received By: \_\_\_\_\_ Date and Time: \_\_\_\_\_  
 Relinquished By: [Signature] Date and Time: \_\_\_\_\_  
 Received By: \_\_\_\_\_ Date and Time: 11/27/18 2:50pm



# ENVIRONMENTAL CONSULTING SERVICES, INC.


## Bulk Sampling Form

Stop at First Positive  
  24 Hour turn around  
  Rush turn around (4 Hours)  
 Do Not Layer Samples

CLIENT <i>Kimberly Clark</i>	PROJECT NO. <i>2069218AS</i>
PROJECT ID <i>Bldg #2</i>	DATE <i>11/19/18</i> PAGE <i>1</i> OF <i>9</i>
PROJECT LOCATION <i>2001 E. Orange Ave, Fullerton, CA</i>	INSPECTOR <i>A. Sanchez, J. Ortiz</i>

GRP. NO.	SAMP. NO.	MATERIAL DESCRIPTION	LOCATION OF SAMPLE	QTY	% POS
01	01	white Drywall	2nd Flr. Laundry Locker Room - South end		
↓	02	↓	2nd Flr. Laundry Locker Room - North end		
↓	03	↓	1st Flr. Hallway - west end		
02	04	white joint compound	2nd Flr. Laundry Locker Room - South end		
↓	05	↓	2nd Flr. Laundry Locker Room - North end		
↓	06	↓	1st Flr. Hallway - west end		
03	07	wh. tile 12x12"	1st Flr. Hallway - west end		
↓	08	ceiling tile	2nd Flr. Gym - N.W. end		
↓	09	↓	Maintenance Department - east end		
04	10	Ben. ceiling tile	1st Flr. Hallway - west end		
↓	11	maskie	2nd Flr. Gym - N.W. end		
↓	12	(12x12" C.T.)	Maintenance Dept. - East end		
05	13	white Drywall	1st Flr. Hallway - west end		
↓	14	behind 12x12"	2nd Flr. Gym - N.W. end		
↓	15	ceiling tile	Maintenance Dept. - East end		
06	16	white zinc	2nd Flr. Hallway - Center		
↓	17	ceiling tile	Maintenance Dept. Hallway - Center		
↓	18	↓	Lab DATA Room - Center		
07	19	Army 4" concrete	2nd Flr. Laundry Locker Room - South end		
↓	20	↓	2nd Flr. Hallway - East end		
↓	21	↓	1st Flr. Hallway - S.W. end		

Notes:



**ENVIRONMENTAL CONSULTING SERVICES, INC.**

**Bulk Sampling Form**

Stop at First Positive  
  24 Hour turn around  
  Rush turn around (4 Hours)  
 Do Not Layer Samples

CLIENT <i>Kimberly Clark</i>	PROJECT NO. <i>2069218AS</i>
PROJECT ID <i>Bldg #2</i>	DATE <i>11/19/18</i>
PROJECT LOCATION <i>20011 F. Orange Street, Fullerton, CA</i>	INSPECTOR <i>A. Sanchez, J. Ortiz</i>
PAGE <i>2</i>	OF <i>9</i>

GRP. NO.	SAMP. NO.	MATERIAL DESCRIPTION	LOCATION OF SAMPLE	QTY	% POS
<i>08</i>	<i>22</i>	<i>Tan/Brown Coarse</i>	<i>2nd Flr. Laundry Locker Area - South end</i>		
	<i>23</i>	<i>marble</i>	<i>2nd flr. Hallway - East end</i>		
	<i>24</i>		<i>1st flr. Hallway - SW end</i>		
<i>09</i>	<i>25</i>	<i>Gray 12x12 Floor tile</i>	<i>2nd flr. Laundry Locker Area - South end</i>		
	<i>26</i>		<i>2nd flr. Hallway - North end</i>		
	<i>27</i>		<i>2nd flr. Hallway - South end</i>		
<i>10</i>	<i>28</i>	<i>yellow floor tile</i>	<i>2nd flr. Laundry Locker Area - South end</i>		
	<i>29</i>	<i>glass</i>	<i>2nd flr. Hallway - North end</i>		
	<i>30</i>		<i>2nd flr. Hallway - South end</i>		
<i>11</i>	<i>31</i>	<i>Multi color floor tile</i>	<i>VCC Conf. Room - North end</i>		
	<i>32</i>	<i>under Blue carpet</i>	<i>IT storage closet - West end</i>		
	<i>33</i>		<i>Human Resources office - North end</i>		
<i>12</i>	<i>34</i>	<i>Blue Floor tile</i>	<i>VCC Conf. Room - North end</i>		
	<i>35</i>	<i>marble</i>	<i>IT storage Area - West end</i>		
	<i>36</i>		<i>Human Resources office - North end</i>		
<i>13</i>	<i>37</i>	<i>Gray/Blue 12x12</i>	<i>2nd flr. Hallway - East end</i>		
	<i>38</i>	<i>Floor tile</i>	<i>2nd flr. Lavatory Area - South end</i>		
	<i>39</i>		<i>2nd flr. Hallway - North end</i>		
<i>14</i>	<i>40</i>	<i>Blue Floor tile</i>	<i>2nd flr. Hallway - East end</i>		
	<i>41</i>	<i>marble</i>	<i>2nd flr. Lavatory Area - South end</i>		
	<i>42</i>		<i>2nd flr. Hallway - West end</i>		

Notes:



**ENVIRONMENTAL CONSULTING SERVICES, INC.**

**Bulk Sampling Form**

Stop at First Positive  24 Hour turn around  Rush turn around (4 Hours)  
 Do Not Layer Samples

CLIENT Kimberly Clark	PROJECT NO. 206921845		
PROJECT ID Bldg #12	DATE 11/19/18	PAGE 3	OF 9
PROJECT LOCATION 2001 E. Orange Avenue, Fullerton, CA	INSPECTOR A. Sanchez, J. Ortiz		

GRP. NO.	SAMP. NO.	MATERIAL DESCRIPTION	LOCATION OF SAMPLE	QTY	% POS
15	43	Yellow Gasket glue	Main mill Conf. Rm. - S.W. end		
↓	44	under Blk gasket	Safety & Training - South end		
↓	45	↓	Safety & Training - North end		
16	46	Bea. 9x9 Floor tile	2nd Flr. women's RR Hallway - North end		
↓	47	↓	2nd Flr. women's RR Hallway - S.W. end		
↓	48	↓	2nd Flr. women's lounge - East end		
17	49	Blk Floor tile	2nd Flr. women's RR Hallway - North end		
↓	50	mark -	2nd Flr. women's RR Hallway - S.W. end		
↓	51	↓	2nd Flr. women's lounge - East end		
18	52	white pipe wrap	2nd Flr. Mech. Rm. - East end		
↓	53	↓	↓ - West end		
↓	54	↓	2nd Flr. Power supply Rm - West end		
19	55	Yellow pipe	2nd Flr. mech. Rm. - East end		
↓	56	Insulation	↓ - West end		
↓	57	↓	2nd Flr. Power supply Rm - West end		
20	58	Blk gasket at HVAC	2nd Flr. mech. Rm. at HVAC - SE		
↓	59	HVAC	2nd Flr. Power supply Rm. N.E. end		
↓	60	↓	↓ West end		
21	61	white Blk vibration	2nd Flr. Mech. Rm. - East end		
↓	62	Dumper	2nd Flr. Power supply Rm. Center		
↓	63	↓	↓ West end		

Notes:





**H2 ENVIRONMENTAL CONSULTING SERVICES, INC.**

**Bulk Sampling Form**


Stop at First Positive 
  24 Hour turn around 
  Rush turn around (4 Hours)

Do Not Layer Samples

CLIENT <i>Kimberly Clark</i>	PROJECT NO. <i>2069218 AS</i>		
PROJECT ID <i>Bldg # 2</i>	DATE <i>11/19/18</i>	PAGE <i>1</i>	OF <i>9</i>
PROJECT LOCATION <i>2001 E. Orange Avenue, Fullerton, CA</i>	INSPECTOR <i>A. Sanchez, J. Ortiz</i>		

GRP. NO.	SAMP. NO.	MATERIAL DESCRIPTION	LOCATION OF SAMPLE	QTY	% POS
22	64	TAN Ductwork wrap	2nd fl. mech. Rm. Ductwork - <sup>West</sup> End		
↓	65	↓	2nd floor supply Rm. - <sup>West</sup> End		
↓	66	↓	↓ - North end		
23	67	Ben. cork Board	2nd fl. mech. Rm. Ductwork - <sup>West</sup> End		
↓	68	under Duct work wrap	2nd fl. power supply Rm. - <sup>West</sup> End		
↓	69	↓	↓ - North end		
24	70	Blk mastic behind	2nd fl. mech. Rm. Ductwork - <sup>West</sup> End		
↓	71	Cork Board	2nd fl. power supply Rm. - <sup>West</sup> End		
↓	72	↓	↓ - North end		
25	73	white joint	2nd fl. mech. Rm. - <sup>West</sup> End		
↓	74	Compound	↓ - North end		
↓	75	↓	↓ - East end		
26	76	white Drywall	2nd fl. mech. Rm. - <sup>West</sup> End		
↓	77	layer 1 ↓	↓ - North end		
↓	78	↓	↓ - East end		
27	79	white mastic	2nd fl. mech. Rm. - <sup>West</sup> End		
↓	80	Sandwiched between	↓ - North end		
↓	81	2 layers of drywall	↓ - East end		
28	82	white Drywall	2nd fl. mech. Rm. - <sup>West</sup> End		
↓	83	layer 2 ↓	↓ - North end		
↓	84	↓	↓ - East end		

Notes:



**ENVIRONMENTAL CONSULTING SERVICES, INC.**


**Bulk Sampling Form**

Stop at First Positive  24 Hour turn around  Rush turn around (4 Hours)  
 Do Not Layer Samples

CLIENT Kimberly Clark	PROJECT NO. 2069218AS		
PROJECT ID Bids #12	DATE 11/19/18	PAGE 5	OF 9
PROJECT LOCATION 2001 E. Umpathorne Ave, Fullerton, CA	INSPECTOR A. Sanchez, J. Ortiz		

GRP. NO.	SAMP. NO.	MATERIAL DESCRIPTION	LOCATION OF SAMPLE	QTY	% POS
29	85	gray plaster	1st Flr. Hallway - North end		
↓	86	↓	2nd Flr. Landing - East end		
↓	87	↓	2nd Flr. Ceiling - S.W. end		
30	88	yellow carpet glue	2nd Flr. Atrium - N.E. End		
↓	89	under gray carpet	↓ - N.W. end		
↓	90	↓	↓ - S.E. end		
31	91	Black 4" carpet	2nd Flr. Landing - S.W. end		
↓	92	↓	1st Flr. Hallway - N.E. End		
↓	93	↓	1st Flr. Hallway - S.E. end		
32	94	Tan Brown Carpet	2nd Flr. Landing - S.W. end		
↓	95	maastic	1st Flr. Hallway - N.E. end		
↓	96	↓	1st Flr. Hallway - S.W. end		
33	97	TAN 12x12 floor	Carpa - North end		
↓	98	tile	Carpa - S.E. end		
↓	99	↓	Carpa - East end		
34	100	Gray Floor tile glue	Carpa - North end		
↓	101	↓	Carpa - S.E. end		
↓	102	↓	Carpa - East end		
35	103	white Floor tile	Carpa - North end		
↓	104	under TAN Floor	Carpa - S.E. end		
↓	105	tile	Carpa - East end		

Notes:



**H2 ENVIRONMENTAL CONSULTING SERVICES, INC.**

**Bulk Sampling Form**

Stop at First Positive    24 Hour turn around    Rush turn around (4 Hours)  
 Do Not Layer Samples

CLIENT <i>Kimberly Clark</i>	PROJECT NO. <i>2069218AS</i>		
PROJECT ID <i>Blk #2</i>	DATE <i>11/19/14</i>	PAGE <i>6</i>	OF <i>9</i>
PROJECT LOCATION <i>2001 E. Orange Ave. Fullerton, CA</i>	INSPECTOR <i>A Sanchez, J. Ortiz</i>		

GRP. NO.	SAMP. NO.	MATERIAL DESCRIPTION	LOCATION OF SAMPLE	QTY	% POS
36	106	Blk Floor mastic	Ceiling - North end		
↓	107	↓	ceiling - S.E. end		
↓	108	↓	ceiling - east end		
37	109	gray linoleum	Janitors closet - North end		
↓	110	↓	Food pantry - South end		
↓	111	↓	Storage closet - West end		
38	112	yellow linoleum	Janitors closet - North end		
↓	113	glue ↓	Food pantry - South end		
↓	114	↓	Storage closet - West end		
39	115	white 12x12	patient Rm. - East end		
↓	116	Floor tile	patient Rm. - South end		
↓	117	↓	Hearing Rm. - North end		
40	118	Blk Floor mastic	patient Rm. - East end		
↓	119	↓	patient Rm. - South end		
↓	120	↓	Hearing Rm. - North end		
41	121	Dark gray 12x12	Health Services - west end		
↓	122	Floor tile	Hallway - east end		
↓	123	↓	Storage Rm. - North end		
42	124	Yellow <sup>blk</sup> Floor tile	Health Services - west end		
↓	125	glue ↓	Hallway - East end		
↓	126	↓	Storage Rm. - North end		

Notes:



**ENVIRONMENTAL CONSULTING SERVICES, INC.**


**Bulk Sampling Form**

Stop at First Positive     24 Hour turn around     Rush turn around (4 Hours)  
 Do Not Layer Samples

CLIENT Kimberly Clark	PROJECT NO. 2069218 AS		
PROJECT ID Blde # 2	DATE 11/19/14	PAGE 7	OF 8
PROJECT LOCATION 2001 E. Orangeburg Ave, Fullerton, CA	INSPECTOR A. Sanchez, J. Ortiz		

GRP. NO.	SAMP. NO.	MATERIAL DESCRIPTION	LOCATION OF SAMPLE	QTY	% POS
43	127	Brn. 4" Covebase	Lab #1 - east end		
	128	↓	Office #6 - west end		
	129	↓	Maintenance Dept Hallway - <sup>North</sup> end		
44	130	Brn Covebase	Lab #1 - east end		
	131	glue	Office #6 - west end		
	132	↓	Maintenance Dept Hallway - <sup>North</sup> end		
45	133	gray Linoleum	Lab #2 - South end		
	134	↓	Lab #2 - west end		
	135	↓	Lab #2 - <del>west end</del>		
46	136	Brn. white Linoleum	Lab #2 - South end		
	137	glue	Lab #2 - west end		
	138	↓	Lab #2 - <del>west end</del>		
47	139	Br/TAN 12x12 Floor	Lab office - South end		
	140	tile	↓ - East end		
	141	↓	↓ - North end		
48	142	Blk Floor tile	Lab office - South end		
	143	music	↓ - East end		
	144	↓	↓ - North end		
49	145	gray 4" Covebase	Lab office - South end		
	146	↓	Lab #1 - East end		
	147	↓	Lab #1 - <del>west end</del>		

Notes:



**H2 ENVIRONMENTAL CONSULTING SERVICES, INC.**

**Bulk Sampling Form**

Stop at First Positive    24 Hour turn around    Rush turn around (4 Hours)  
 Do Not Layer Samples

CLIENT <i>Kimberly Clark</i>	PROJECT NO. <i>2069218AS</i>
PROJECT ID <i>Bldg #2</i>	DATE <i>11/19/18</i>
PROJECT LOCATION <i>2001 E Orangeburg Ave. Fullerton</i>	INSPECTOR <i>A. Sanchez, J. Ortiz</i>

GRP. NO.	SAMP. NO.	MATERIAL DESCRIPTION	LOCATION OF SAMPLE	QTY	% POS
50	148	TAN/BRN concrete	lab office - South end		
↓	149	music ↓	↓ - east end		
↓	150	↓	concrete - West end		
51	151	cream 12x12	operations center - South end		
↓	152	Floor tile ↓	↓ - N.E. end		
↓	153	↓	↓ - S.E. end		
52	154	gray floor tile	operations center - South end		
↓	155	glue ↓	↓ - N.E. end		
↓	156	↓	↓ - S.E. end		
53	157	gray w/strakes	operations center - S.E. end		
↓	158	12x12 floor tile	office #6 - west end		
↓	159	↓	Hallway - South end		
54	160	yellow floor tile	operations center - S.E. end		
↓	161	glue ↓	office #6 - west end		
↓	162	↓	Hallway - South end		
55	163	offwhite floor tile	operations center - S.E. end		
↓	164	under gray w/strakes	office #6 - west end		
↓	165	and cream F.T.	Hallway - South end		
56	166	Blk floor tile	operations center - S.E. end		
↓	167	music ↓	office #6 - west end		
↓	168	↓	Hallway - South end		

Notes:



**SECTION 2**  
**SURVEY SUMMARY**

**LEAD XRF SURVEY RESULTS**  
**BUILDING 2**

**Phase 2 - Fullerton Mill - 2069218 AS**  
**2001 East Orangethorpe Avenue**  
**Fullerton, California**

The list materials and their components where Lead Based Paint (LBP) was detected at or in excess of the HUD/EPA standards of 1.0 mg/cm<sup>2</sup> (Los Angeles County has established a more stringent standard for lead-based paint at 0.7mg/cm<sup>2</sup>) by XRF method which is listed in the table below. All XRF readings below the regulatory defined action level are considered negative and all readings at and above these levels are considered positive.

Shot #	Unit	Room Tested	Wall	Color	Component	Substrate	Quantity	Paint Condition	Result	Neg/Pos
01	1 <sup>st</sup> Floor	Hallway	North	White	Wall	Drywall	210 SF	Intact	0.00	Negative
02	1 <sup>st</sup> Floor	Hallway	North	White	Door Frame	Metal	8 Each	Intact	0.00	Negative
03	1 <sup>st</sup> Floor	Hallway	North	Blue	Door Frame	Metal	2 Each	Intact	0.00	Negative
04	1 <sup>st</sup> Floor	Hallway	North	Blue	Door	Wood	2 Each	Intact	0.00	Negative
05	1 <sup>st</sup> Floor	Mail Room	North	White	Wall	Drywall	800 SF	Intact	0.00	Negative
06	1 <sup>st</sup> Floor	IT Storage	South	Blue	Door Frame	Metal	1 Each	Intact	0.00	Negative
07	1 <sup>st</sup> Floor	IT Storage	South	Blue	Door	Wood	1 Each	Intact	0.00	Negative
08	1 <sup>st</sup> Floor	IT Storage	South	White	Wall	Drywall	320 SF	Intact	0.00	Negative
09	1 <sup>st</sup> Floor	Video Conference Room	East	Blue	Door Frame	Metal	1 Each	Intact	0.00	Negative
10	1 <sup>st</sup> Floor	Video Conference Room	East	Blue	Door	Metal	1 Each	Intact	0.00	Negative
11	1 <sup>st</sup> Floor	Video Conference Room	East	Grey	Wall	Drywall	640 SF	Intact	0.00	Negative
12	1 <sup>st</sup> Floor	Hallway	South	Blue	Window Frame	Wood	1 Each	Intact	0.00	Negative
13	1 <sup>st</sup> Floor	Hallway	South	Blue	Panel	Wood	1 Each	Intact	0.00	Negative
14	1 <sup>st</sup> Floor	Hallway	West	Grey	Stair Landing	Metal	18 SF	Intact	0.00	Negative
15	1 <sup>st</sup> Floor	Hallway	West	White	Wall	Concrete	138 SF	Intact	0.00	Negative
16	1 <sup>st</sup> Floor	Hallway	West	White	Door	Wood	1 Each	Intact	0.00	Negative

**SECTION 2  
SURVEY SUMMARY**

**LEAD XRF SURVEY RESULTS  
BUILDING 2**

**Phase 2 - Fullerton Mill - 2069218 AS  
2001 East Orangethorpe Avenue  
Fullerton, California**

The list materials and their components where Lead Based Paint (LBP) was detected at or in excess of the HUD/EPA standards of 1.0 mg/cm<sup>2</sup> (Los Angeles County has established a more stringent standard for lead-based paint at 0.7mg/cm<sup>2</sup>) by XRF method which is listed in the table below. All XRF readings below the regulatory defined action level are considered negative and all readings at and above these levels are considered positive.

Shot #	Unit	Room Tested	Wall	Color	Component	Substrate	Quantity	Paint Condition	Result	Neg/Pos
17	1 <sup>st</sup> Floor	Hallway	East	Red	Wall	Concrete	5 SF	Intact	0.01	Negative
18	2 <sup>nd</sup> Floor	Landing Area	East	White	Ceiling	Plaster	176 SF	Intact	0.01	Negative
19	2 <sup>nd</sup> Floor	Landing Area	East	White	Wall	Drywall	304 SF	Intact	0.00	Negative
20	2 <sup>nd</sup> Floor	Landing Area	West	Blue	Door Frame	Metal	2 Each	Intact	0.01	Negative
21	2 <sup>nd</sup> Floor	Landing Area	West	Blue	Door	Wood	4 Each	Intact	0.01	Negative
22	2 <sup>nd</sup> Floor	Landing Area	West	Blue	Door Window Frame	Metal	2 Each	Intact	0.05	Negative
<b>23</b>	<b>2<sup>nd</sup> Floor</b>	<b>Landing Area</b>	<b>East</b>	<b>Yellow</b>	<b>Stair Rail</b>	<b>Metal</b>	<b>100 LF</b>	<b>Intact</b>	<b>5.80</b>	<b>Positive</b>
<b>24</b>	<b>2<sup>nd</sup> Floor</b>	<b>Landing Area</b>	<b>East</b>	<b>Blue</b>	<b>Stair Frame</b>	<b>Metal</b>	<b>2 Each</b>	<b>Intact</b>	<b>1.80</b>	<b>Positive</b>
25	2 <sup>nd</sup> Floor	Area 2	West	Blue	Door Frame	Metal	4 Each	Intact	0.01	Negative
26	2 <sup>nd</sup> Floor	Area 2	West	Blue	Door	Wood	5 Each	Intact	0.05	Negative
27	2 <sup>nd</sup> Floor	Mechanical Room	North	Grey	Door Frame	Metal	1 Each	Intact	0.05	Negative
28	2 <sup>nd</sup> Floor	Mechanical Room	North	Grey	Door	Wood	2 Each	Intact	0.05	Negative
29	2 <sup>nd</sup> Floor	Mechanical Room	South	Grey	Floor	Concrete	100 SF	Intact	0.00	Negative
30	2 <sup>nd</sup> Floor	Mechanical Room	North	Grey	Wall	Drywall	592 SF	Intact	0.09	Negative
31	2 <sup>nd</sup> Floor	Area 2	West	White	Wall	Drywall	424 SF	Intact	0.10	Negative
32	2 <sup>nd</sup> Floor	Hallway	East	White	Wall	Drywall	1,216 SF	Intact	0.01	Negative



**SECTION 2  
SURVEY SUMMARY**

**LEAD XRF SURVEY RESULTS  
BUILDING 2**

**Phase 2 - Fullerton Mill - 2069218 AS  
2001 East Orangethorpe Avenue  
Fullerton, California**

The list materials and their components where Lead Based Paint (LBP) was detected at or in excess of the HUD/EPA standards of 1.0 mg/cm<sup>2</sup> (Los Angeles County has established a more stringent standard for lead-based paint at 0.7mg/cm<sup>2</sup>) by XRF method which is listed in the table below. All XRF readings below the regulatory defined action level are considered negative and all readings at and above these levels are considered positive.

Shot #	Unit	Room Tested	Wall	Color	Component	Substrate	Quantity	Paint Condition	Result	Neg/Pos
33	2 <sup>nd</sup> Floor	Hallway	East	Blue	Running Board	Wood	39 LF	Intact	0.05	Negative
34	2 <sup>nd</sup> Floor	Hallway	South	White	Ceiling	Drywall	190 SF	Intact	0.10	Negative
35	2 <sup>nd</sup> Floor	Hallway	South	Blue	Door Frame	Metal	9 Each	Intact	0.01	Negative
36	2 <sup>nd</sup> Floor	Hallway	South	Blue	Door	Wood	5 Each	Intact	0.01	Negative
<b>37</b>	<b>2<sup>nd</sup> Floor</b>	<b>Men's Restroom</b>	<b>South</b>	<b>Tan</b>	<b>4"x4" Wall Tile</b>	<b>Ceramic</b>	<b>984 SF</b>	<b>Intact</b>	<b>8.50</b>	<b>Positive</b>
<b>38</b>	<b>2<sup>nd</sup> Floor</b>	<b>Men's Restroom</b>	<b>South</b>	<b>Tan</b>	<b>4"x4" Base Tile</b>	<b>Ceramic</b>	<b>123 SF</b>	<b>Intact</b>	<b>8.50</b>	<b>Positive</b>
39	2 <sup>nd</sup> Floor	Men's Restroom	South	Tan	Ceiling	Drywall	165 SF	Intact	0.01	Negative
40	2 <sup>nd</sup> Floor	Men's Restroom	South	Brown	Ceiling	Drywall	165 SF	Intact	0.02	Negative
41	2 <sup>nd</sup> Floor	Men's Restroom	South	Brown	2'x2' Floor Tile	Ceramic	165 SF	Intact	0.01	Negative
42	2 <sup>nd</sup> Floor	Men's Restroom	East	White	Urinal	Ceramic	3 Each	Intact	0.01	Negative
43	2 <sup>nd</sup> Floor	Men's Restroom	East	White	Toilet	Ceramic	4 Each	Intact	0.01	Negative
44	2 <sup>nd</sup> Floor	Men's Restroom	East	Tan	Partician	Metal	4 Each	Intact	0.01	Negative
<b>45</b>	<b>2<sup>nd</sup> Floor</b>	<b>Men's Shower</b>	<b>East</b>	<b>Tan</b>	<b>4"x4" Wall Tile</b>	<b>Ceramic</b>	<b>288 SF</b>	<b>Intact</b>	<b>8.90</b>	<b>Positive</b>
46	2 <sup>nd</sup> Floor	Men's Shower	East	Brown	3"x3" Floor Tile	Ceramic	77 SF	Intact	0.00	Negative
47	2 <sup>nd</sup> Floor	Men's Shower	East	White	Ceiling	Drywall	77 SF	Intact	0.00	Negative
48	2 <sup>nd</sup> Floor	Men's Locker 1	East	Brown	2'x2' Floor Tile	Ceramic	2,856 SF	Intact	0.00	Negative

**SECTION 2  
SURVEY SUMMARY**

**LEAD XRF SURVEY RESULTS  
BUILDING 2**

**Phase 2 - Fullerton Mill - 2069218 AS  
2001 East Orangethorpe Avenue  
Fullerton, California**

The list materials and their components where Lead Based Paint (LBP) was detected at or in excess of the HUD/EPA standards of 1.0 mg/cm<sup>2</sup> (Los Angeles County has established a more stringent standard for lead-based paint at 0.7mg/cm<sup>2</sup>) by XRF method which is listed in the table below. All XRF readings below the regulatory defined action level are considered negative and all readings at and above these levels are considered positive.

Shot #	Unit	Room Tested	Wall	Color	Component	Substrate	Quantity	Paint Condition	Result	Neg/Pos
49	2 <sup>nd</sup> Floor	Men's Locker	North	Coffee	4"x4" Wall Tile	Ceramic	1,552 SF	Intact	0.03	Negative
50	2 <sup>nd</sup> Floor	Men's Locker	North	Coffee	4"x4" Base Tile	Ceramic	194 SF	Intact	0.03	Negative
51	2 <sup>nd</sup> Floor	Men's Locker	East	Tan	Locker	Metal	1,148 SF	Intact	0.02	Negative
52	2 <sup>nd</sup> Floor	Men's Locker	East	White	Wall	Drywall	784 SF	Intact	0.00	Negative
<b>53</b>	<b>2<sup>nd</sup> Floor</b>	<b>Men's Locker</b>	<b>South</b>	<b>White</b>	<b>I-Beam</b>	<b>Metal</b>	<b>2 Each</b>	<b>Intact</b>	<b>2.80</b>	<b>Positive</b>
54	2 <sup>nd</sup> Floor	Men's Locker	East	Tan	Locker Panel	Metal	123 SF	Intact	0.08	Negative
55	2 <sup>nd</sup> Floor	Men's Locker	West	Burgundy	2'x2' Floor Tile	Ceramic	15 SF	Intact	0.00	Negative
56	2 <sup>nd</sup> Floor	Men's Locker	North	Tan	Door Frame	Metal	1 Each	Intact	0.00	Negative
57	2 <sup>nd</sup> Floor	Laundry	South	White	Door Frame	Metal	1 Each	Intact	0.05	Negative
58	2 <sup>nd</sup> Floor	Locker Room	South	White	Wall	Drywall	832 SF	Intact	0.04	Negative
59	2 <sup>nd</sup> Floor	Women's Lounge	South	Blue	Door Frame	Metal	1 Each	Intact	0.01	Negative
60	2 <sup>nd</sup> Floor	Women's Lounge	South	Blue	Door	Wood	1 Each	Intact	0.00	Negative
61	2 <sup>nd</sup> Floor	Women's Lounge	South	White	Wall	Drywall	288 SF	Intact	0.01	Negative
62	2 <sup>nd</sup> Floor	Women's Lounge	South	White	Ceiling	Drywall	77 SF	Intact	0.00	Negative
63	2 <sup>nd</sup> Floor	Woman's Restroom	West	Tan	4"x4" Wall Tile	Ceramic	800 SF	Intact	0.00	Negative
64	2 <sup>nd</sup> Floor	Woman's Restroom	West	Tan	4"x4" Base Tile	Ceramic	100 SF	Intact	0.05	Negative

**SECTION 2  
SURVEY SUMMARY**

**LEAD XRF SURVEY RESULTS  
BUILDING 2**

**Phase 2 - Fullerton Mill - 2069218 AS  
2001 East Orangethorpe Avenue  
Fullerton, California**

The list materials and their components where Lead Based Paint (LBP) was detected at or in excess of the HUD/EPA standards of 1.0 mg/cm<sup>2</sup> (Los Angeles County has established a more stringent standard for lead-based paint at 0.7mg/cm<sup>2</sup>) by XRF method which is listed in the table below. All XRF readings below the regulatory defined action level are considered negative and all readings at and above these levels are considered positive.

Shot #	Unit	Room Tested	Wall	Color	Component	Substrate	Quantity	Paint Condition	Result	Neg/Pos
65	2 <sup>nd</sup> Floor	Women's Restroom	West	White	Sink	Ceramic	2 Each	Intact	0.05	Negative
66	2 <sup>nd</sup> Floor	Women's Restroom	West	White	Toilet	Ceramic	3 Each	Intact	0.05	Negative
67	2 <sup>nd</sup> Floor	Women's Restroom	West	Pink	Partition	Metal	3 Each	Intact	0.01	Negative
68	2 <sup>nd</sup> Floor	Women's Shower	West	Tan	4"x4" Wall Tile	Ceramic	512 SF	Intact	0.00	Negative
69	2 <sup>nd</sup> Floor	Women's Shower	West	Brown	2'x2' Wall Tile	Ceramic	256 SF	Intact	0.00	Negative
70	2 <sup>nd</sup> Floor	Women's Shower	West	Brown	2'x2' Floor Tile	Ceramic	64 SF	Intact	0.00	Negative
71	2 <sup>nd</sup> Floor	Women's Shower	West	Tan	Ceiling	Drywall	207 SF	Intact	0.00	Negative
72	2 <sup>nd</sup> Floor	Women's Shower	West	Brown	2'x2' Floor Tile	Ceramic	207 SF	Intact	0.00	Negative
73	2 <sup>nd</sup> Floor	Women's Locker 1	North	Tan	Door Frame	Metal	1 Each	Intact	0.00	Negative
74	2 <sup>nd</sup> Floor	Women's Locker 1	North	Tan	Door	Metal	1 Each	Intact	0.00	Negative
75	2 <sup>nd</sup> Floor	Women's Locker 1	North	Tan	4"x4" Wall Tile	Metal	832 SF	Intact	0.00	Negative
76	2 <sup>nd</sup> Floor	Women's Locker 1	East	Tan	Wall	Drywall	416 SF	Intact	0.00	Negative
77	2 <sup>nd</sup> Floor	Women's Locker 1	East	Red	2'x2' Floor Tile	Ceramic	451 SF	Intact	0.01	Negative
78	2 <sup>nd</sup> Floor	Women's Locker 1	East	Tan	Ceiling	Drywall	451 SF	Intact	0.01	Negative
79	2 <sup>nd</sup> Floor	Women's Locker 2	North	Coffee	4"x4" Wall Tile	Ceramic	800 SF	Intact	0.01	Negative
80	2 <sup>nd</sup> Floor	Women's Locker 2	North	Tan	Wall	Drywall	400 SF	Intact	0.01	Negative

**SECTION 2  
SURVEY SUMMARY**

**LEAD XRF SURVEY RESULTS  
BUILDING 2**

**Phase 2 - Fullerton Mill - 2069218 AS  
2001 East Orangethorpe Avenue  
Fullerton, California**

The list materials and their components where Lead Based Paint (LBP) was detected at or in excess of the HUD/EPA standards of 1.0 mg/cm<sup>2</sup> (Los Angeles County has established a more stringent standard for lead-based paint at 0.7mg/cm<sup>2</sup>) by XRF method which is listed in the table below. All XRF readings below the regulatory defined action level are considered negative and all readings at and above these levels are considered positive.

Shot #	Unit	Room Tested	Wall	Color	Component	Substrate	Quantity	Paint Condition	Result	Neg/Pos
81	2 <sup>nd</sup> Floor	Fitness Center	South	Blue	Door Frame	Metal	3 Each	Intact	0.19	Negative
82	2 <sup>nd</sup> Floor	Fitness Center	South	Blue	Door	Metal	3 Each	Intact	0.15	Negative
83	2 <sup>nd</sup> Floor	Fitness Center	South	White	Wall	Drywall	1,120 SF	Intact	0.10	Negative
84	2 <sup>nd</sup> Floor	Fitness Center	South	Red	Wall	Drywall	4 SF	Intact	0.22	Negative
<b>85</b>	<b>2<sup>nd</sup> Floor</b>	<b>Hallway</b>	<b>North</b>	<b>White</b>	<b>I-Beam</b>	<b>Metal</b>	<b>2 Each</b>	<b>Intact</b>	<b>3.80</b>	<b>Positive</b>
<b>86</b>	<b>2<sup>nd</sup> Floor</b>	<b>Hallway</b>	<b>North</b>	<b>White</b>	<b>I-Beam</b>	<b>Metal</b>	<b>2 Each</b>	<b>Intact</b>	<b>4.10</b>	<b>Positive</b>
<b>87</b>	<b>2<sup>nd</sup> Floor</b>	<b>Hallway</b>	<b>North</b>	<b>White</b>	<b>Bracket</b>	<b>Metal</b>	<b>3 Each</b>	<b>Intact</b>	<b>15.0</b>	<b>Positive</b>
<b>88</b>	<b>2<sup>nd</sup> Floor</b>	<b>Mechanical Room</b>	<b>South</b>	<b>White</b>	<b>Bracket</b>	<b>Metal</b>	<b>1 Each</b>	<b>Intact</b>	<b>15.0</b>	<b>Positive</b>
89	2 <sup>nd</sup> Floor	Hallway	North	White	Panel	Metal	140 SF	Intact	0.10	Negative
90	1 <sup>st</sup> Floor	Cafeteria	North	Tan	Wall	Drywall	2,280 SF	Intact	0.00	Negative
91	1 <sup>st</sup> Floor	Open Area	North	Red	Wall	Drywall	1,140 SF	Intact	0.00	Negative
<b>92</b>	<b>1<sup>st</sup> Floor</b>	<b>Kitchen Area</b>	<b>East</b>	<b>Red</b>	<b>I-Beam</b>	<b>Metal</b>	<b>1 Each</b>	<b>Intact</b>	<b>2.30</b>	<b>Positive</b>
93	1 <sup>st</sup> Floor	Kitchen Area	North	Red	Wall	Plaster	736 SF	Intact	0.00	Negative
94	1 <sup>st</sup> Floor	Kitchen Area	East	Grey	4"x4" Wall Tile	Ceramic	368 SF	Intact	0.01	Negative
95	1 <sup>st</sup> Floor	Kitchen Prep	East	Grey	4"x4" Wall Tile	Ceramic	368 SF	Intact	0.01	Negative
96	1 <sup>st</sup> Floor	Kitchen Prep	South	Red	6"x6" Wall Tile	Ceramic	368 SF	Intact	0.02	Negative

**SECTION 2  
SURVEY SUMMARY**

**LEAD XRF SURVEY RESULTS  
BUILDING 2**

**Phase 2 - Fullerton Mill - 2069218 AS  
2001 East Orangethorpe Avenue  
Fullerton, California**

The list materials and their components where Lead Based Paint (LBP) was detected at or in excess of the HUD/EPA standards of 1.0 mg/cm<sup>2</sup> (Los Angeles County has established a more stringent standard for lead-based paint at 0.7mg/cm<sup>2</sup>) by XRF method which is listed in the table below. All XRF readings below the regulatory defined action level are considered negative and all readings at and above these levels are considered positive.

Shot #	Unit	Room Tested	Wall	Color	Component	Substrate	Quantity	Paint Condition	Result	Neg/Pos
97	1 <sup>st</sup> Floor	Kitchen Prep	South	Tan	Door Frame	Metal	2 Each	Intact	0.01	Negative
98	1 <sup>st</sup> Floor	Kitchen Prep	South	Tan	Door	Wood	2 Each	Intact	0.01	Negative
99	1 <sup>st</sup> Floor	Kitchen Prep	North	Red	Door	Wood	1 Each	Intact	0.00	Negative
100	1 <sup>st</sup> Floor	Cafeteria Hallway	West	Tan	Door Entryway	Drywall	1 Each	Intact	0.01	Negative
101	1 <sup>st</sup> Floor	Cafeteria Hallway	North	Tan	Door Frame	Metal	4 Each	Intact	0.00	Negative
102	1 <sup>st</sup> Floor	Cafeteria Hallway	North	Tan	Door	Metal	4 Each	Intact	0.00	Negative
103	1 <sup>st</sup> Floor	Cafeteria Hallway	North	Tan	Wall	Drywall	240 SF	Intact	0.00	Negative
104	1 <sup>st</sup> Floor	Hallway	West	White	Wall	Plaster	1,605 SF	Intact	0.11	Negative
105	1 <sup>st</sup> Floor	Hallway	West	White	Wall	Drywall	802 SF	Intact	0.10	Negative
106	1 <sup>st</sup> Floor	Hallway	West	Blue	Door Frame	Metal	4 Each	Intact	0.01	Negative
107	1 <sup>st</sup> Floor	Hallway	West	Blue	Door	Metal	2 Each	Intact	0.05	Negative
108	1 <sup>st</sup> Floor	Hallway	West	Blue	Window Frame	Metal	1 Each	Intact	0.05	Negative
109	1 <sup>st</sup> Floor	Men's Restroom	North	Blue	Door Frame	Metal	1 Each	Intact	0.01	Negative
110	1 <sup>st</sup> Floor	Men's Restroom	North	Blue	Door	Metal	1 Each	Intact	0.01	Negative
111	1 <sup>st</sup> Floor	Men's Restroom	North	White	Wall	Drywall	184 SF	Intact	0.00	Negative
112	1 <sup>st</sup> Floor	Men's Restroom	North	Grey	6"x6" Wall Tile	Ceramic	92 SF	Intact	0.01	Negative

**SECTION 2  
SURVEY SUMMARY**

**LEAD XRF SURVEY RESULTS  
BUILDING 2**

**Phase 2 - Fullerton Mill - 2069218 AS  
2001 East Orangethorpe Avenue  
Fullerton, California**

The list materials and their components where Lead Based Paint (LBP) was detected at or in excess of the HUD/EPA standards of 1.0 mg/cm<sup>2</sup> (Los Angeles County has established a more stringent standard for lead-based paint at 0.7mg/cm<sup>2</sup>) by XRF method which is listed in the table below. All XRF readings below the regulatory defined action level are considered negative and all readings at and above these levels are considered positive.

Shot #	Unit	Room Tested	Wall	Color	Component	Substrate	Quantity	Paint Condition	Result	Neg/Pos
113	1 <sup>st</sup> Floor	Men's Restroom	North	Blue	6"x6" Wall Tile	Ceramic	92 SF	Intact	0.00	Negative
114	1 <sup>st</sup> Floor	Men's Restroom	North	White	Urinal	Ceramic	2 Each	Intact	0.00	Negative
115	1 <sup>st</sup> Floor	Men's Restroom	East	White	Toilet	Ceramic	1 Each	Intact	0.00	Negative
116	1 <sup>st</sup> Floor	Men's Restroom	North	Grey	Partician	Wood	2 Each	Intact	0.00	Negative
117	1 <sup>st</sup> Floor	Men's Restroom	South	White	Sink	Ceramic	2 Each	Intact	0.00	Negative
118	1 <sup>st</sup> Floor	Men's Restroom	South	White	Ceiling	Drywall	102 SF	Intact	0.00	Negative
119	1 <sup>st</sup> Floor	Men's Restroom	South	Grey	6"X6" Floor Tile	Ceramic	51 SF	Intact	0.00	Negative
120	1 <sup>st</sup> Floor	Men's Restroom	South	Blue	6"x6" Floor Tile	Ceramic	51 SF	Intact	0.00	Negative
121	1 <sup>st</sup> Floor	Men's Restroom	South	Grey	3"x6" Base Tile	Ceramic	102 SF	Intact	0.01	Negative
122	1 <sup>st</sup> Floor	Health Service	North	Grey	Wall	Drywall	1,604 SF	Intact	0.00	Negative
123	1 <sup>st</sup> Floor	Health Service	North	Grey	Cabinet	Wood	3 Each	Intact	0.05	Negative
124	1 <sup>st</sup> Floor	Health Service	West	Grey	Door Frame	Metal	6 Each	Intact	0.00	Negative
125	1 <sup>st</sup> Floor	Health Service	West	Grey	Door	Wood	2 Each	Intact	0.00	Negative
126	1 <sup>st</sup> Floor	Health Service Restroom	North	Pink	4"x4" Wall Tile	Ceramic	160 SF	Intact	0.00	Negative
127	1 <sup>st</sup> Floor	Health Service Restroom	West	White	Sink	Ceramic	1 Each	Intact	0.00	Negative
<b>128</b>	<b>1<sup>st</sup> Floor</b>	<b>Health Service Restroom</b>	<b>West</b>	<b>White</b>	<b>Toilet</b>	<b>Ceramic</b>	<b>1 Each</b>	<b>Intact</b>	<b>4.80</b>	<b>Positive</b>

**SECTION 2  
SURVEY SUMMARY**

**LEAD XRF SURVEY RESULTS  
BUILDING 2**

**Phase 2 - Fullerton Mill - 2069218 AS  
2001 East Orangethorpe Avenue  
Fullerton, California**

The list materials and their components where Lead Based Paint (LBP) was detected at or in excess of the HUD/EPA standards of 1.0 mg/cm<sup>2</sup> (Los Angeles County has established a more stringent standard for lead-based paint at 0.7mg/cm<sup>2</sup>) by XRF method which is listed in the table below. All XRF readings below the regulatory defined action level are considered negative and all readings at and above these levels are considered positive.

Shot #	Unit	Room Tested	Wall	Color	Component	Substrate	Quantity	Paint Condition	Result	Neg/Pos
129	1 <sup>st</sup> Floor	Health Service Restroom	West	White	Ceiling	Drywall	20 SF	Intact	0.00	Negative
130	1 <sup>st</sup> Floor	Health Service Restroom	West	Brown	1'x1' Floor Tile	Ceramic	20 SF	Intact	0.05	Negative
131	1 <sup>st</sup> Floor	Heath Service	North	Grey	Ceiling	Drywall	416 SF	Intact	0.00	Negative
132	1 <sup>st</sup> Floor	Safety Supply Room	North	White	Wall	Concrete	738 SF	Intact	0.01	Negative
133	1 <sup>st</sup> Floor	Safety Supply Room	North	White	Wall	Drywall	384 SF	Intact	0.01	Negative
134	1 <sup>st</sup> Floor	Safety Supply Room	North	White	Pipe	Metal	40 LF	Intact	0.01	Negative
135	1 <sup>st</sup> Floor	Safety Supply Room	East	Blue	Door Frame	Metal	1 Each	Intact	0.00	Negative
136	1 <sup>st</sup> Floor	Safety Supply Room	East	Blue	Door	Wood	1 Each	Intact	0.00	Negative
137	1 <sup>st</sup> Floor	Safety Supply Room	East	Blue	2'x6' Board	Wood	2 Each	Intact	0.00	Negative
138	1 <sup>st</sup> Floor	Safety Supply Room	East	Red	Floor	Concrete	512 SF	Intact	0.00	Negative
139	1 <sup>st</sup> Floor	Open Conference Area	North	White	Wall	Drywall	1,704 SF	Intact	0.00	Negative
140	1 <sup>st</sup> Floor	Open Conference Area	South	White	Wall	Concrete	205 SF	Intact	0.00	Negative
141	1 <sup>st</sup> Floor	Open Conference Area	South	Blue	Door Frame	Metal	5 Each	Intact	0.00	Negative
142	1 <sup>st</sup> Floor	Open Conference Area	South	Blue	Door	Metal	5 Each	Intact	0.00	Negative
143	1 <sup>st</sup> Floor	Open Conference Area	South	Blue	Stair Frame	Metal	1 Each	Intact	0.00	Negative
144	1 <sup>st</sup> Floor	Open Conference Area	South	Blue	Stair Case	Metal	1 Each	Intact	0.00	Negative

**SECTION 2  
SURVEY SUMMARY**

**LEAD XRF SURVEY RESULTS  
BUILDING 2**

**Phase 2 - Fullerton Mill - 2069218 AS  
2001 East Orangethorpe Avenue  
Fullerton, California**

The list materials and their components where Lead Based Paint (LBP) was detected at or in excess of the HUD/EPA standards of 1.0 mg/cm<sup>2</sup> (Los Angeles County has established a more stringent standard for lead-based paint at 0.7mg/cm<sup>2</sup>) by XRF method which is listed in the table below. All XRF readings below the regulatory defined action level are considered negative and all readings at and above these levels are considered positive.

Shot #	Unit	Room Tested	Wall	Color	Component	Substrate	Quantity	Paint Condition	Result	Neg/Pos
145	1 <sup>st</sup> Floor	Open Conference Area	South	Yellow	Stair Rail	Metal	2 Each	Intact	1.80	Positive
146	1 <sup>st</sup> Floor	Open Conference Area	South	Red	I-Beam	Metal	1 Each	Intact	5.60	Positive
147	1 <sup>st</sup> Floor	Open Conference Area	South	Yellow	Guard Rail	Metal	1 Each	Intact	4.30	Positive
148	1 <sup>st</sup> Floor	Open Conference Area	North	White	Ceiling I-Beam	Metal	1,139 SF	Intact	4.80	Positive
149	1 <sup>st</sup> Floor	Open Conference Area	North	White	Ceiling Pipe	Metal	66 LF	Intact	0.14	Negative
150	1 <sup>st</sup> Floor	Open Conference Area	North	White	Ceiling	Metal	1139 SF	Intact	0.10	Negative
151	1 <sup>st</sup> Floor	Open Conference Area	North	Blue	Floor	Concrete	1139 SF	Intact	0.01	Negative
152	1 <sup>st</sup> Floor	Open Conference Area	West	Blue	Sliding Door	Metal	1 Each	Intact	6.50	Positive
153	1 <sup>st</sup> Floor	Open Conference Area	West	Blue	Door Frame	Metal	1 Each	Intact	0.08	Negative
154	1 <sup>st</sup> Floor	Open Conference Area	West	White	Wall I-Beam	Metal	1 Each	Intact	4.80	Positive
155	1 <sup>st</sup> Floor	Open Conference Area	West	White	Wall	Metal	310 SF	Intact	0.10	Negative
156	1 <sup>st</sup> Floor	Maintenance Department	East	Tan	Wall	Drywall	768 SF	Intact	0.00	Negative
157	1 <sup>st</sup> Floor	Hallway 1	East	Brown	Door Frame	Metal	6 Each	Intact	0.00	Negative
158	1 <sup>st</sup> Floor	Hallway 1	East	Brown	Door	Metal	6 Each	Intact	0.00	Negative
159	1 <sup>st</sup> Floor	Breakroom	East	Grey	Wall	Drywall	304 SF	Intact	0.01	Negative
160	1 <sup>st</sup> Floor	Hallway 2	East	Tan	Wall	Drywall	768 SF	Intact	0.00	Negative



**SECTION 2  
SURVEY SUMMARY**

**LEAD XRF SURVEY RESULTS  
BUILDING 2**

**Phase 2 - Fullerton Mill - 2069218 AS  
2001 East Orangethorpe Avenue  
Fullerton, California**

The list materials and their components where Lead Based Paint (LBP) was detected at or in excess of the HUD/EPA standards of 1.0 mg/cm<sup>2</sup> (Los Angeles County has established a more stringent standard for lead-based paint at 0.7mg/cm<sup>2</sup>) by XRF method which is listed in the table below. All XRF readings below the regulatory defined action level are considered negative and all readings at and above these levels are considered positive.

Shot #	Unit	Room Tested	Wall	Color	Component	Substrate	Quantity	Paint Condition	Result	Neg/Pos
161	1 <sup>st</sup> Floor	Maintenance Department	East	White	Wall	Drywall	448 SF	Intact	0.50	Negative
162	1 <sup>st</sup> Floor	Copy Room	South	White	Wall	Concrete	234 SF	Intact	0.50	Negative
163	1 <sup>st</sup> Floor	Copy Room	West	Blue	Door Frame	Metal	2 Each	Intact	0.00	Negative
164	1 <sup>st</sup> Floor	Copy Room	West	Blue	Door	Wood	2 Each	Intact	0.00	Negative
165	1 <sup>st</sup> Floor	Maintenance Department	South	Brown	Window Frame	Metal	1 Each	Intact	0.00	Negative
166	1 <sup>st</sup> Floor	Open Area	East	Brown	Door Frame	Metal	10 Each	Intact	0.00	Negative
167	1 <sup>st</sup> Floor	Open Area	East	Brown	Door	Metal	10 Each	Intact	0.00	Negative
168	1 <sup>st</sup> Floor	Open Area	South	Blue	Door Frame	Metal	1 Each	Intact	0.00	Negative
169	1 <sup>st</sup> Floor	Open Area	South	Blue	Door	Wood	1 Each	Intact	0.00	Negative
<b>170</b>	<b>1<sup>st</sup> Floor</b>	<b>Open Conference Area</b>	<b>South</b>	<b>White</b>	<b>Angle Bracket</b>	<b>Metal</b>	<b>1,053 SF</b>	<b>Intact</b>	<b>4.80</b>	<b>Positive</b>
171	1 <sup>st</sup> Floor	Operations Center	North	Tan	Wall	Concrete	1,648 SF	Intact	0.00	Negative
172	1 <sup>st</sup> Floor	Operations Center	East	Brown	Door Frame	Metal	2 Each	Intact	0.00	Negative
173	1 <sup>st</sup> Floor	Operations Center	East	Brown	Door	Wood	2 Each	Intact	0.00	Negative
174	1 <sup>st</sup> Floor	Operations Center	South	Tan	Wall	Drywall	824 SF	Intact	0.00	Negative
175	1 <sup>st</sup> Floor	Operations Center	South	White	Ceiling	Drywall	1,022 SF	Intact	0.00	Negative
176	1 <sup>st</sup> Floor	Hallway	East	Red	Hydrant Pipe	Metal	1 Each	Intact	0.80	Negative

**SECTION 2  
SURVEY SUMMARY**

**LEAD XRF SURVEY RESULTS  
BUILDING 2**

**Phase 2 - Fullerton Mill - 2069218 AS  
2001 East Orangethorpe Avenue  
Fullerton, California**

The list materials and their components where Lead Based Paint (LBP) was detected at or in excess of the HUD/EPA standards of 1.0 mg/cm<sup>2</sup> (Los Angeles County has established a more stringent standard for lead-based paint at 0.7mg/cm<sup>2</sup>) by XRF method which is listed in the table below. All XRF readings below the regulatory defined action level are considered negative and all readings at and above these levels are considered positive.

Shot #	Unit	Room Tested	Wall	Color	Component	Substrate	Quantity	Paint Condition	Result	Neg/Pos
<b>177</b>	<b>1<sup>st</sup> Floor</b>	<b>Open Conference Area</b>	<b>South</b>	<b>Yellow</b>	<b>Electrical Panel</b>	<b>Metal</b>	<b>1 Each</b>	<b>Intact</b>	<b>1.00</b>	<b>Positive</b>
178	1 <sup>st</sup> Floor	Hallway	West	Blue	Wall	Concrete	150 SF	Intact	0.00	Negative
<b>179</b>	<b>1<sup>st</sup> Floor</b>	<b>Warehouse</b>	<b>East</b>	<b>Yellow</b>	<b>Rail</b>	<b>Metal</b>	<b>1 Each</b>	<b>Intact</b>	<b>4.80</b>	<b>Positive</b>
180	1 <sup>st</sup> Floor	Warehouse	East	Yellow	Floor Rail	Metal	200 LF	Intact	0.80	Negative
<b>181</b>	<b>1<sup>st</sup> Floor</b>	<b>Warehouse</b>	<b>East</b>	<b>Red</b>	<b>I-Beam</b>	<b>Metal</b>	<b>25 Each</b>	<b>Intact</b>	<b>8.40</b>	<b>Positive</b>
182	1 <sup>st</sup> Floor	Warehouse	East	Yellow	Column	Concrete	4,260 SF	Intact	0.01	Negative
<b>183</b>	<b>1<sup>st</sup> Floor</b>	<b>Warehouse</b>	<b>East</b>	<b>Yellow</b>	<b>I-Beam</b>	<b>Metal</b>	<b>5 Each</b>	<b>Intact</b>	<b>3.00</b>	<b>Positive</b>
<b>184</b>	<b>1<sup>st</sup> Floor</b>	<b>Warehouse</b>	<b>North</b>	<b>Yellow</b>	<b>Shoot Ladder</b>	<b>Metal</b>	<b>1 Each</b>	<b>Intact</b>	<b>1.90</b>	<b>Positive</b>
<b>185</b>	<b>1<sup>st</sup> Floor</b>	<b>Warehouse</b>	<b>North</b>	<b>White</b>	<b>I-Beam</b>	<b>Metal</b>	<b>5 Each</b>	<b>Intact</b>	<b>7.30</b>	<b>Positive</b>
186	1 <sup>st</sup> Floor	Warehouse	North	White	Wall	Metal	10 SF	Intact	0.03	Negative
187	1 <sup>st</sup> Floor	Warehouse	North	Gray	Stairwell	Metal	4 Each	Intact	0.01	Negative
<b>188</b>	<b>1<sup>st</sup> Floor</b>	<b>Warehouse</b>	<b>North</b>	<b>Yellow</b>	<b>Stair Frame</b>	<b>Metal</b>	<b>4 Each</b>	<b>Intact</b>	<b>1.90</b>	<b>Positive</b>
<b>189</b>	<b>1<sup>st</sup> Floor</b>	<b>Warehouse</b>	<b>North</b>	<b>Yellow</b>	<b>Stair Rail</b>	<b>Metal</b>	<b>4 Each</b>	<b>Intact</b>	<b>1.90</b>	<b>Positive</b>
190	1 <sup>st</sup> Floor	Warehouse	West	Red	Hydrant Hose Door	Metal	1 Each	Intact	0.01	Negative
<b>191</b>	<b>1<sup>st</sup> Floor</b>	<b>Warehouse</b>	<b>West</b>	<b>White</b>	<b>Ceiling I-Beam</b>	<b>Metal</b>	<b>39,120 SF</b>	<b>Intact</b>	<b>4.80</b>	<b>Positive</b>
<b>192</b>	<b>1<sup>st</sup> Floor</b>	<b>Warehouse</b>	<b>West</b>	<b>White</b>	<b>Ceiling Angle Bracket</b>	<b>Metal</b>	<b>39,120 SF</b>	<b>Intact</b>	<b>4.80</b>	<b>Positive</b>

**SECTION 2  
SURVEY SUMMARY**

**LEAD XRF SURVEY RESULTS  
BUILDING 2**

**Phase 2 - Fullerton Mill - 2069218 AS  
2001 East Orangethorpe Avenue  
Fullerton, California**

The list materials and their components where Lead Based Paint (LBP) was detected at or in excess of the HUD/EPA standards of 1.0 mg/cm<sup>2</sup> (Los Angeles County has established a more stringent standard for lead-based paint at 0.7mg/cm<sup>2</sup>) by XRF method which is listed in the table below. All XRF readings below the regulatory defined action level are considered negative and all readings at and above these levels are considered positive.

Shot #	Unit	Room Tested	Wall	Color	Component	Substrate	Quantity	Paint Condition	Result	Neg/Pos
193	1 <sup>st</sup> Floor	Warehouse	West	White	Ceiling	Metal	39,120 SF	Intact	0.01	Negative
194	1 <sup>st</sup> Floor	Warehouse	West	Red	Ceiling Pipe	Metal	326 LF	Intact	0.08	Negative
195	1 <sup>st</sup> Floor	Warehouse	West	White	Duct	Metal	7,824 LF	Intact	0.00	Negative
196	1 <sup>st</sup> Floor	Warehouse	West	Yellow	Floor	Concrete	7,824 LF	Intact	0.00	Negative
<b>197</b>	<b>1<sup>st</sup> Floor</b>	<b>Warehouse</b>	<b>North</b>	<b>White</b>	<b>Catwalk Post</b>	<b>Metal</b>	<b>100 SF</b>	<b>Intact</b>	<b>2.00</b>	<b>Positive</b>
<b>198</b>	<b>1<sup>st</sup> Floor</b>	<b>Warehouse</b>	<b>North</b>	<b>Orange</b>	<b>Catwalk</b>	<b>Metal</b>	<b>6,000 SF</b>	<b>Intact</b>	<b>1.30</b>	<b>Positive</b>
199	1 <sup>st</sup> Floor	Warehouse	North	Yellow	Catwalk Rail	Metal	100 LF	Intact	0.50	Negative
<b>200</b>	<b>1<sup>st</sup> Floor</b>	<b>Warehouse</b>	<b>North</b>	<b>Yellow</b>	<b>Catwalk</b>	<b>Metal</b>	<b>3,000 SF</b>	<b>Intact</b>	<b>2.80</b>	<b>Positive</b>
<b>201</b>	<b>2<sup>nd</sup> Floor</b>	<b>Warehouse</b>	<b>North</b>	<b>Orange</b>	<b>Catwalk I-Beam</b>	<b>Metal</b>	<b>200 SF</b>	<b>Intact</b>	<b>2.80</b>	<b>Positive</b>
<b>202</b>	<b>2<sup>nd</sup> Floor</b>	<b>Power Supply Room</b>	<b>East</b>	<b>Red</b>	<b>I-Beam</b>	<b>Metal</b>	<b>1,000 SF</b>	<b>Intact</b>	<b>4.80</b>	<b>Positive</b>
203	2 <sup>nd</sup> Floor	Power Supply Room	West	White	Door Frame	Metal	1 Each	Intact	0.00	Negative
204	2 <sup>nd</sup> Floor	Power Supply Room	West	Tan	Door	Metal	2 Each	Intact	0.00	Negative
205	2 <sup>nd</sup> Floor	Power Supply Room	West	White	Ceiling	Metal	920 SF	Intact	0.00	Negative
<b>206</b>	<b>2<sup>nd</sup> Floor</b>	<b>Power Supply Room</b>	<b>West</b>	<b>White</b>	<b>Ceiling I-Beam</b>	<b>Metal</b>	<b>460 SF</b>	<b>Intact</b>	<b>4.80</b>	<b>Positive</b>
207	2 <sup>nd</sup> Floor	Power Supply Room	West	White	Pipe	Metal	9,202 LF	Intact	0.00	Negative
<b>208</b>	<b>2<sup>nd</sup> Floor</b>	<b>Power Supply Room</b>	<b>West</b>	<b>White</b>	<b>Angle Bracket</b>	<b>Metal</b>	<b>800 SF</b>	<b>Intact</b>	<b>4.80</b>	<b>Positive</b>



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509372  
**Samples Submitted:** 18  
**Sample Collection Date:** 11/26/2018  
**Laboratory Receipt Date:** 11/30/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #2 Roof Air Washer Bldg  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 1 of 5

### TEST DATA

**Laboratory ID#:** 1509372-001 **Client Sample #:** 1

**Sample Material and Location:** Gray Panels Air Washer Bldg - North End

**Sample Characteristics:** Grey Fibrous Inhomogenous  
**Misc. Components Observed:** 55% Non-Fibrous Material  
20% Cellulose

**Asbestos Observed (%):** Chrysotile 25% **Total Asbestos (%)** 25%  
**Analyst:** Dennis Liu **Date Analyzed:** 11/30/2018

### TEST DATA

**Laboratory ID#:** 1509372-002 **Client Sample #:** 2

**Sample Material and Location:** Gray Panels Air Washer Bldg - East End

**Sample Characteristics:** Grey Fibrous Inhomogenous  
**Misc. Components Observed:** 55% Non-Fibrous Material  
20% Cellulose

**Asbestos Observed (%):** Chrysotile 25% **Total Asbestos (%)** 25%  
**Analyst:** Dennis Liu **Date Analyzed:** 11/30/2018

### TEST DATA

**Laboratory ID#:** 1509372-003 **Client Sample #:** 3

**Sample Material and Location:** Gray Panels Air Washer Bldg - South End

**Sample Characteristics:** Grey Fibrous Inhomogenous  
**Misc. Components Observed:** 55% Non-Fibrous Material  
20% Cellulose

**Asbestos Observed (%):** Chrysotile 25% **Total Asbestos (%)** 25%  
**Analyst:** Dennis Liu **Date Analyzed:** 11/30/2018

### TEST DATA

**Laboratory ID#:** 1509372-004 **Client Sample #:** 4

**Sample Material and Location:** Black Roof Mastic Air Washer Bldg - S.W. End End

**Sample Characteristics:** Black Grey Fibrous Inhomogenous  
**Misc. Components Observed:** 75% Non-Fibrous Material  
20% Cellulose

**Asbestos Observed (%):** Chrysotile 5% **Total Asbestos (%)** 5%  
**Analyst:** Dennis Liu **Date Analyzed:** 11/30/2018



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509372  
**Samples Submitted:** 18  
**Sample Collection Date:** 11/26/2018  
**Laboratory Receipt Date:** 11/30/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #2 Roof Air Washer Bldg  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 2 of 5

### TEST DATA

**Laboratory ID#:** 1509372-005      **Client Sample #:** 5

**Sample Material and Location:** Black Roof Mastic Air Washer Bldg - S.E. End End

**Sample Characteristics:** Black Grey Fibrous Inhomogenous  
**Misc. Components Observed:** 75% Non-Fibrous Material  
20% Cellulose

**Asbestos Observed (%):** Chrysotile      5%      **Total Asbestos (%)**      5%  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/30/2018

### TEST DATA

**Laboratory ID#:** 1509372-006      **Client Sample #:** 6

**Sample Material and Location:** Black Roof Mastic Air Washer Bldg - N.E. End End

**Sample Characteristics:** Black Grey Fibrous Inhomogenous  
**Misc. Components Observed:** 75% Non-Fibrous Material  
20% Cellulose

**Asbestos Observed (%):** Chrysotile      5%      **Total Asbestos (%)**      5%  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/30/2018

### TEST DATA

**Laboratory ID#:** 1509372-007      **Client Sample #:** 7

**Sample Material and Location:** Brown Debris Air Washer Bldg - S.W. End End

**Sample Characteristics:** Brown Non-Fibrous Inhomogenous  
**Misc. Components Observed:** 90% Non-Fibrous Material  
10% Cellulose

**Asbestos Observed (%):**      **Total Asbestos (%)**      None Detected  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/30/2018

### TEST DATA

**Laboratory ID#:** 1509372-008      **Client Sample #:** 8

**Sample Material and Location:** Brown Debris Air Washer Bldg - Center

**Sample Characteristics:** Brown Non-Fibrous Inhomogenous  
**Misc. Components Observed:** 90% Non-Fibrous Material  
10% Cellulose

**Asbestos Observed (%):**      **Total Asbestos (%)**      None Detected  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/30/2018



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509372  
**Samples Submitted:** 18  
**Sample Collection Date:** 11/26/2018  
**Laboratory Receipt Date:** 11/30/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #2 Roof Air Washer Bldg  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 3 of 5

### TEST DATA

**Laboratory ID#:** 1509372-009      **Client Sample #:** 9

**Sample Material and Location:** Brown Debris Air Washer Bldg - N.E. End

**Sample Characteristics:** Brown Non-Fibrous Inhomogenous  
**Misc. Components Observed:** 90% Non-Fibrous Material  
10% Cellulose

**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/30/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509372-010      **Client Sample #:** 10

**Sample Material and Location:** Black/White Caulk on Flashing Air Washer Bldg - S.W. End

**Sample Characteristics:** Black White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/30/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509372-011      **Client Sample #:** 11

**Sample Material and Location:** Black/White Caulk on Flashing Air Washer Bldg - North End

**Sample Characteristics:** Black White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/30/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509372-012      **Client Sample #:** 12

**Sample Material and Location:** Black/White Caulk on Flashing Air Washer Bldg - S.E. End

**Sample Characteristics:** Black White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/30/2018

**Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
 Chino, CA 91710

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #2 Roof Air Washer Bldg  
**Project Location:** 2001 E. Orangethorpe Ave  
 Fullerton, CA

**Report Number:** 1509372  
**Samples Submitted:** 18  
**Sample Collection Date:** 11/26/2018  
**Laboratory Receipt Date:** 11/30/2018

**Page:** 4 of 5

### TEST DATA

**Laboratory ID#:** 1509372-013      **Client Sample #:** 13

**Sample Material and Location:** Silver/Black Mastic on Flashing Air Washer Bldg - South End

**Sample Characteristics:** Black Silver Fibrous Inhomogenous  
**Misc. Components Observed:** 60% Non-Fibrous Material  
 5% Fibrous Glass  
 30% Cellulose

**Asbestos Observed (%):** Chrysotile      5%      **Total Asbestos (%)**      5%  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/30/2018

### TEST DATA

**Laboratory ID#:** 1509372-014      **Client Sample #:** 14

**Sample Material and Location:** Silver/Black Mastic on Flashing Air Washer Bldg - East End

**Sample Characteristics:** Black Silver Fibrous Inhomogenous  
**Misc. Components Observed:** 60% Non-Fibrous Material  
 5% Fibrous Glass  
 30% Cellulose

**Asbestos Observed (%):** Chrysotile      5%      **Total Asbestos (%)**      5%  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/30/2018

### TEST DATA

**Laboratory ID#:** 1509372-015      **Client Sample #:** 15

**Sample Material and Location:** Silver/Black Mastic on Flashing Air Washer Bldg - North End

**Sample Characteristics:** Black Silver Fibrous Inhomogenous  
**Misc. Components Observed:** 60% Non-Fibrous Material  
 5% Fibrous Glass  
 30% Cellulose

**Asbestos Observed (%):** Chrysotile      5%      **Total Asbestos (%)**      5%  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/30/2018

### TEST DATA

**Laboratory ID#:** 1509372-016      **Client Sample #:** 16

**Sample Material and Location:** White Caulking on Gable Vent Air Washer Bldg - South End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**      **Total Asbestos (%)**      None Detected  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/30/2018



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509372  
**Samples Submitted:** 18  
**Sample Collection Date:** 11/26/2018  
**Laboratory Receipt Date:** 11/30/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #2 Roof Air Washer Bldg  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 5 of 5

### TEST DATA

**Laboratory ID#:** 1509372-017      **Client Sample #:** 17

**Sample Material and Location:** White Caulking on Gable Vent Air Washer Bldg - N.E. End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/30/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509372-018      **Client Sample #:** 18

**Sample Material and Location:** White Caulking on Gable Vent Air Washer Bldg - N.W. End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/30/2018

**Total Asbestos (%)** None Detected

Samples were analyzed by Calibrated Visual Estimation (CVE). Analyses by CVE have a detection limit of 1% asbestos by relative area and may not be consistently reliable below this limit or for asbestos with fiber diameter thinner than the resolving capacity of PLM without further analysis by another independent method. A test result of less than (<) 1% by CVE means asbestos was observed in the sample but is visually estimated to be below the reportable limit of 1%. The laboratory references interim method EPA 600/M4-82-020 (Interim Method) for fiber identification, 400 point counts, and composite reporting. EPA method 600/R-93/116 is referenced for analysis of non-insulation materials, sub-layers, expanded and modified point counts, CVE and subsequent data reporting. Samples containing distinct layers that can be reliably separated are analyzed and reported as separate unless requested in writing. The test data presented apply only to the items submitted. Count for samples submitted is indicative of total layers observed and may vary from actual analysis for positive stop requests. ATEL, LLC is a NIST-NVLAP and CA-ELAP Accredited laboratory (ID# 201073-0 and #2971, respectively). This report must not be reproduced, unless in its entirety, without the written consent of ATEL, LLC. Per NIST-NVLAP 150 Annex A: This report shall not be used to claim product certification, approval or endorsement by NVLAP, NIST, or any agency of the federal government.

Unless indicated, samples were received in acceptable condition. Sample retention time is 30 days from issuing this report unless requested otherwise.

**Analyst Signature:**  -Dennis Liu

**Approved Signatory:**  -Chris Turton

**Reported On:** 12/3/2018





1509372

Analytical Services Request v.112414

Pg 1 of 1

Asbestos Laboratory

**Your Contact Information**

Company Name (if by company): H2 Environmental Consulting Services, Inc.  
 Personal/Company Address: 13122 6th Street, Chino, CA 91710  
 Contact Person: Amy De Santiago  
 Contact Information: Main: 909-628-0369 E-Mail: labresults@h2env.com  
 Mobile: \_\_\_\_\_ Fax: 909-613-5845  
 How should we send your result Verbal  Verbal  E-mail  Fax

\*If verbal results are requested, you must also select a second form of delivery.

**Project Information**

Project Name: Kimberly Clark  
 Project #: 2069218 AS  
 Project Location: 2001 E Orange Ave, Fullerton, CA - Bldg 2 Roof  
 PO#: \_\_\_\_\_ Claim# \_\_\_\_\_  
 Date Sampled: 11/26/18 Time Sampled: 10 AM

**Analytical Type(s) Requested**

Asbestos in Bulk Materials, EPA 600/R-93/116, 600/M4-82-020  
 Routine, Calibrated Visual Estimation   
 Point Count: 400pts   
 1000pts   
 Gravimetric Reduction (72hr Minimum)   
 Fiber Count in Sampling Cartridge (25mm MCE)  
 Asbestos-like, NIOSH 7400 A Rules   
 Rotometer Calibration (Low and High Flow Rotometers)

**Turnaround Time\***

\*Business Hrs: 0800-1700 Mon-Fri.  
 Rush 3 Business Hrs\*   
 8 Business Hrs\*   
 Expedited 24 Business Hrs   
 Routine 48 Business Hrs   
 72 Business Hrs   
 Standard 5 Business Days

\*3hr TAT: Samples must be submitted by 2pm for same day results  
 \*8hr TAT: Samples must be submitted by 9am for same day results

Special Instructions: \_\_\_\_\_

**Sample Information**

Sample ID #	Description/Material Type	Location	Flow Rate	Start Time	Stop Time	Volume (L)
	Please See Attached					

For more samples, please continue onto supplemental form. Page # indication in upper-right-hand of form.

**Chain of Custody**

Relinquished By: Alberto Sanchez Date and Time: 11/26/18  
 Received By: \_\_\_\_\_ Date and Time: \_\_\_\_\_  
 Relinquished By: \_\_\_\_\_ Date and Time: \_\_\_\_\_  
 Received By: Alberto Sanchez Date and Time: 11/30/18 8:15 AM



**ENVIRONMENTAL CONSULTING SERVICES, INC.**

**Bulk Sampling Form**

Stop at First Positive    24 Hour turn around    Rush turn around (4 Hours)  
 Do Not Layer Samples

CLIENT <i>Kimberly Clark</i>	PROJECT NO. <i>2069218AS</i>	
PROJECT ID <i>Bldg 2 Roof Air washer Bldg.</i>	DATE <i>11/26/18</i>	PAGE OF <i>1 1</i>
PROJECT LOCATION <i>2001 E. Orange Avenue, Anaheim, Fullerton, CA</i>	INSPECTOR <i>Albert Sanchez</i>	

GRP. NO.	SAMP. NO.	MATERIAL DESCRIPTION	LOCATION OF SAMPLE	QTY	% POS
01	01	Gray panels	Air washer Bldg. - North end		
	02	↓	↓ - east end		
	03	↓	↓ - south end		
02	04	Blk Roof mastic	Air washer Bldg - S.W. end		
	05	↓	↓ - S.E. end		
	06	↓	↓ - N.E. end		
03	07	Brn. Debris	Air washer Bldg. - S.W. end		
	08	↓	↓ - center		
	09	↓	↓ - N.E. end		
04	10	Blk/white caulk	Air washer Bldg - S.W. end		
	11	↓ on flashing	↓ - North End		
	12	↓	↓ - S.E. end		
05	13	Silver/Blk mastic	Air washer Bldg - South end		
	14	↓ on flashing	↓ - east end		
	15	↓	↓ - North end		
06	16	white caulking	Air washer Bldg. - South end		
	17	↓ on gable vent	↓ - N.E. end		
	18	↓	↓ - N.W. end		

Notes:

**SECTION 2  
SURVEY SUMMARY**

**LEAD XRF SURVEY RESULTS  
BUILDING 2, ROOF AIR WASHER BUILDING**

**Phase 2 - Fullerton Mill - 2069218 AS  
2001 East Orangethorpe Avenue  
Fullerton, California**

The list materials and their components where Lead Based Paint (LBP) was detected at or in excess of the HUD/EPA standards of 1.0 mg/cm<sup>2</sup> (Los Angeles County has established a more stringent standard for lead-based paint at 0.7mg/cm<sup>2</sup>) by XRF method which is listed in the table below. All XRF readings below the regulatory defined action level are considered negative and all readings at and above these levels are considered positive.

Shot #	Unit	Room Tested	Wall	Color	Component	Substrate	Quantity	Paint Condition	Result	Neg/Pos
<b>01</b>	<b>Air Washer Bldg.</b>	<b>Exterior</b>	<b>West</b>	<b>White</b>	<b>I-Beam</b>	<b>Metal</b>	<b>11 Each</b>	<b>Intact</b>	<b>10.70</b>	<b>Positive</b>
02	Air Washer Bldg.	Exterior	South	White	Wall	Metal	5,400 SF	Intact	0.01	Negative
03	Air Washer Bldg.	Exterior	South	Blue	Louver	Metal	2,000 SF	Intact	0.01	Negative
<b>04</b>	<b>Air Washer Bldg.</b>	<b>Exterior</b>	<b>South</b>	<b>Blue</b>	<b>Louver Frame</b>	<b>Metal</b>	<b>6 Each</b>	<b>Intact</b>	<b>6.80</b>	<b>Positive</b>
05	Air Washer Bldg.	Exterior	North	Blue	Door	Metal	1 Each	Intact	0.01	Negative
<b>06</b>	<b>Air Washer Bldg.</b>	<b>Exterior</b>	<b>North</b>	<b>Blue</b>	<b>I-Beam</b>	<b>Metal</b>	<b>4 Each</b>	<b>Intact</b>	<b>4.60</b>	<b>Positive</b>
07	Air Washer Bldg.	Exterior	North	Red	Fire Hydrant Panel	Metal	1 Each	Intact	0.08	Negative
08	Air Washer Bldg.	Exterior	North	White	Pipe	Metal	4 Each	Intact	0.01	Negative
09	Air Washer Bldg.	Exterior	North	Blue	Edge Metal	Metal	480 LF	Intact	0.01	Negative
10	Air Washer Bldg.	Interior	North	Gray	Wall	Metal	5,400 SF	Intact	0.00	Negative
11	Air Washer Bldg.	Interior	North	Gray	Ceiling	Metal	810 SF	Intact	0.00	Negative
<b>12</b>	<b>Air Washer Bldg.</b>	<b>Interior</b>	<b>North</b>	<b>Gray</b>	<b>I-Beam</b>	<b>Metal</b>	<b>2,025 SF</b>	<b>Intact</b>	<b>4.60</b>	<b>Positive</b>
<b>13</b>	<b>Air Washer Bldg.</b>	<b>Interior</b>	<b>North</b>	<b>Yellow</b>	<b>Stair Rail</b>	<b>Metal</b>	<b>1 Each</b>	<b>Intact</b>	<b>1.80</b>	<b>Positive</b>
14	Air Washer Bldg.	Interior	North	Yellow	Staircase	Metal	1 Each	Intact	0.00	Negative



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509515  
**Samples Submitted:** 12  
**Sample Collection Date:** 12/7/2018  
**Laboratory Receipt Date:** 12/7/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #3  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 1 of 4

### TEST DATA

**Laboratory ID#:** 1509515-001      **Client Sample #:** 1

**Sample Material and Location:** Tan w/Streaks 12 x 12 Floor Tile Break Room - South End

**Sample Characteristics:** Tan Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**

**Analyst:** Dennis Liu

**Date Analyzed:** 12/7/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509515-002      **Client Sample #:** 2

**Sample Material and Location:** Tan w/Streaks 12 x 12 Floor Tile Break Room - West End

**Sample Characteristics:** Tan Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**

**Analyst:** Dennis Liu

**Date Analyzed:** 12/7/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509515-003      **Client Sample #:** 3

**Sample Material and Location:** Tan w/Streaks 12 x 12 Floor Tile Break Room - North End

**Sample Characteristics:** Tan Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**

**Analyst:** Dennis Liu

**Date Analyzed:** 12/7/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509515-004      **Client Sample #:** 4

**Sample Material and Location:** Yellow Floor Tile Glue on Wood Break Room - South End

**Sample Characteristics:** Yellow Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**

**Analyst:** Dennis Liu

**Date Analyzed:** 12/7/2018

**Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509515  
**Samples Submitted:** 12  
**Sample Collection Date:** 12/7/2018  
**Laboratory Receipt Date:** 12/7/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #3  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 2 of 4

### TEST DATA

---

**Laboratory ID#:** 1509515-005      **Client Sample #:** 5

**Sample Material and Location:** Yellow Floor Tile Glue on Wood Break Room - West End

**Sample Characteristics:** Yellow Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 12/7/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509515-006      **Client Sample #:** 6

**Sample Material and Location:** Yellow Floor Tile Glue on Wood Break Room - North End

**Sample Characteristics:** Yellow Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 12/7/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509515-007      **Client Sample #:** 7

**Sample Material and Location:** Brown 4" Covebase Break Room - South End

**Sample Characteristics:** Brown Smooth Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 12/7/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509515-008      **Client Sample #:** 8

**Sample Material and Location:** Brown 4" Covebase Break Room - West End

**Sample Characteristics:** Brown Smooth Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 12/7/2018

**Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509515  
**Samples Submitted:** 12  
**Sample Collection Date:** 12/7/2018  
**Laboratory Receipt Date:** 12/7/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #3  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 3 of 4

### TEST DATA

---

**Laboratory ID#:** 1509515-009      **Client Sample #:** 9

**Sample Material and Location:** Brown 4" Covebase Break Room - North End

**Sample Characteristics:** Brown Smooth Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 12/7/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509515-010      **Client Sample #:** 10

**Sample Material and Location:** Brown Covebase Mastic Break Room - South End

**Sample Characteristics:** Brown Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 12/7/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509515-011      **Client Sample #:** 11

**Sample Material and Location:** Brown Covebase Mastic Break Room - West End

**Sample Characteristics:** Brown Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 12/7/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509515-012      **Client Sample #:** 12

**Sample Material and Location:** Brown Covebase Mastic Break Room - North End

**Sample Characteristics:** Brown Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 12/7/2018

**Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509515  
**Samples Submitted:** 12  
**Sample Collection Date:** 12/7/2018  
**Laboratory Receipt Date:** 12/7/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #3  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 4 of 4

Samples were analyzed by Calibrated Visual Estimation (CVE). Analyses by CVE have a detection limit of 1% asbestos by relative area and may not be consistently reliable below this limit or for asbestos with fiber diameter thinner than the resolving capacity of PLM without further analysis by another independent method. A test result of less than (<) 1% by CVE means asbestos was observed in the sample but is visually estimated to be below the reportable limit of 1%. The laboratory references interim method EPA 600/M4-82-020 (Interim Method) for fiber identification, 400 point counts, and composite reporting. EPA method 600/R-93/116 is referenced for analysis of non-insulation materials, sub-layers, expanded and modified point counts, CVE and subsequent data reporting. Samples containing distinct layers that can be reliably separated are analyzed and reported as separate unless requested in writing. The test data presented apply only to the items submitted. Count for samples submitted is indicative of total layers observed and may vary from actual analysis for positive stop requests. ATEL, LLC is a NIST-NVLAP and CA-ELAP Accredited laboratory (ID# 201073-0 and #2971, respectively). This report must not be reproduced, unless in its entirety, without the written consent of ATEL, LLC. Per NIST-NVLAP 150 Annex A: This report shall not be used to claim product certification, approval or endorsement by NVLAP, NIST, or any agency of the federal government.

Unless indicated, samples were received in acceptable condition. Sample retention time is 30 days from issuing this report unless requested otherwise.

Analyst Signature:

Handwritten signature of Dennis Liu in black ink.

-Dennis Liu

Approved Signatory:

Handwritten signature of Chris Turton in black ink.

-Chris Turton

Reported On: 12/8/2018







**SECTION 2**  
**SURVEY SUMMARY**

**LEAD XRF SURVEY RESULTS**  
**BUILDING 3**

**Phase 2 - Fullerton Mill - 2069218 AS**  
**2001 East Orangethorpe Avenue**  
**Fullerton, California**

The list materials and their components where Lead Based Paint (LBP) was detected at or in excess of the HUD/EPA standards of 1.0 mg/cm<sup>2</sup> (Los Angeles County has established a more stringent standard for lead-based paint at 0.7mg/cm<sup>2</sup>) by XRF method which is listed in the table below. All XRF readings below the regulatory defined action level are considered negative and all readings at and above these levels are considered positive.

Shot #	Unit	Room Tested	Wall	Color	Component	Substrate	Quantity	Paint Condition	Result	Neg/Pos
01	Building 3	Converter Maintenance Storage	North	Blue	Wall	Concrete	1,650 SF	Intact	0.00	Negative
02	Building 3	Converter Maintenance Storage	North	White	Wall	Concrete	1,650 SF	Intact	0.00	Negative
<b>03</b>	<b>Building 3</b>	<b>Converter Maintenance Storage</b>	<b>North</b>	<b>Blue</b>	<b>Sliding Door Frame</b>	<b>Metal</b>	<b>2 Each</b>	<b>Intact</b>	<b>5.80</b>	<b>Positive</b>
04	Building 3	Converter Maintenance Storage	North	Blue	Sliding Door	Metal	2 Each	Intact	0.00	Negative
<b>05</b>	<b>Building 3</b>	<b>Converter Maintenance Storage</b>	<b>North</b>	<b>Yellow</b>	<b>Bollard</b>	<b>Metal</b>	<b>2 Each</b>	<b>Intact</b>	<b>9.80</b>	<b>Positive</b>
06	Building 3	Converter Maintenance Storage	East	Red	Wall	Concrete	8 SF	Intact	0.00	Negative
<b>07</b>	<b>Building 3</b>	<b>Converter Maintenance Storage</b>	<b>East</b>	<b>White</b>	<b>I-Beam</b>	<b>Metal</b>	<b>100 SF</b>	<b>Intact</b>	<b>6.80</b>	<b>Positive</b>
<b>08</b>	<b>Building 3</b>	<b>Converter Maintenance Storage</b>	<b>East</b>	<b>Red</b>	<b>I-Beam</b>	<b>Metal</b>	<b>100 SF</b>	<b>Intact</b>	<b>6.70</b>	<b>Positive</b>
09	Building 3	Converter Maintenance Storage	South	Blue	Door Frame	Metal	2 Each	Intact	0.00	Negative
10	Building 3	Converter Maintenance Storage	South	Blue	Door	Wood	2 Each	Intact	0.00	Negative
11	Building 3	Warehouse Finished Stock	South	Blue	Wall	Concrete	8,213 SF	Intact	0.00	Negative
12	Building 3	Warehouse Finished Stock	South	White	Wall	Concrete	8213 SF	Intact	0.00	Negative
<b>13</b>	<b>Building 3</b>	<b>Warehouse Finished Stock</b>	<b>South</b>	<b>Blue</b>	<b>Sliding Door</b>	<b>Metal</b>	<b>12 Each</b>	<b>Intact</b>	<b>2.20</b>	<b>Positive</b>
<b>14</b>	<b>Building 3</b>	<b>Warehouse Finished Stock</b>	<b>South</b>	<b>Blue</b>	<b>Sliding Door Frame</b>	<b>Metal</b>	<b>12 Each</b>	<b>Intact</b>	<b>5.80</b>	<b>Positive</b>
15	Building 3	Warehouse Finished Stock	South	Blue	Column	Concrete	100 SF	Intact	0.00	Negative
<b>16</b>	<b>Building 3</b>	<b>Warehouse Finished Stock</b>	<b>South</b>	<b>Yellow</b>	<b>Bollard</b>	<b>Metal</b>	<b>100 SF</b>	<b>Intact</b>	<b>9.70</b>	<b>Positive</b>

**SECTION 2  
SURVEY SUMMARY**

**LEAD XRF SURVEY RESULTS  
BUILDING 3**

**Phase 2 - Fullerton Mill - 2069218 AS  
2001 East Orangethorpe Avenue  
Fullerton, California**

The list materials and their components where Lead Based Paint (LBP) was detected at or in excess of the HUD/EPA standards of 1.0 mg/cm<sup>2</sup> (Los Angeles County has established a more stringent standard for lead-based paint at 0.7mg/cm<sup>2</sup>) by XRF method which is listed in the table below. All XRF readings below the regulatory defined action level are considered negative and all readings at and above these levels are considered positive.

Shot #	Unit	Room Tested	Wall	Color	Component	Substrate	Quantity	Paint Condition	Result	Neg/Pos
17	Building 3	Warehouse Finished Stock	South	Yellow	Floor, Rail	Metal	235 LF	Intact	0.60	Negative
18	Building 3	Warehouse Finished Stock	South	Yellow	Barrier	Metal	100 LF	Intact	0.00	Negative
19	Building 3	Warehouse Finished Stock	South	Yellow	Floor	Concrete	100 LF	Intact	0.01	Negative
<b>20</b>	<b>Building 3</b>	<b>Warehouse Finished Stock</b>	<b>South</b>	<b>Yellow</b>	<b>Rail</b>	<b>Metal</b>	<b>235 LF</b>	<b>Intact</b>	<b>9.80</b>	<b>Positive</b>
21	Building 3	Warehouse Finished Stock	South	Yellow	Swing Door	Metal	1 Each	Intact	0.01	Negative
22	Building 3	Warehouse Finished Stock	South	Yellow	Shoot Ladder	Metal	2 Each	Intact	0.00	Negative
23	Building 3	Warehouse Finished Stock	South	Yellow	Shoot Ladder Rail	Metal	2 Each	Intact	0.00	Negative
24	Building 3	Warehouse Finished Stock	South	White	Platform I-Beam	Metal	100 SF	Intact	0.00	Negative
25	Building 3	Warehouse Finished Stock	South	Yellow	Platform Rail	Metal	2 Each	Intact	0.00	Negative
<b>26</b>	<b>Building 3</b>	<b>Warehouse Finished Stock</b>	<b>West</b>	<b>Red</b>	<b>I-Beam</b>	<b>Metal</b>	<b>100 SF</b>	<b>Intact</b>	<b>5.80</b>	<b>Positive</b>
<b>27</b>	<b>Building 3</b>	<b>Warehouse Finished Stock</b>	<b>West</b>	<b>Yellow</b>	<b>I-Beam</b>	<b>Metal</b>	<b>100 SF</b>	<b>Intact</b>	<b>6.70</b>	<b>Positive</b>
28	Building 3	Warehouse Finished Stock	North	White	Pipe	Metal	2 Each	Intact	0.00	Negative
<b>29</b>	<b>Building 3</b>	<b>Warehouse Finished Stock</b>	<b>North</b>	<b>Red</b>	<b>Bollard</b>	<b>Metal</b>	<b>100 SF</b>	<b>Intact</b>	<b>9.20</b>	<b>Positive</b>
30	Building 3	Warehouse Finished Stock	North	Red	Floor	Concrete	100 SF	Intact	0.00	Negative
<b>31</b>	<b>Building 3</b>	<b>Warehouse Finished Stock</b>	<b>North</b>	<b>Orange</b>	<b>Floor, Strip</b>	<b>Metal</b>	<b>38 LF</b>	<b>Intact</b>	<b>1.30</b>	<b>Positive</b>
<b>32</b>	<b>Building 3</b>	<b>Warehouse Finished Stock</b>	<b>North</b>	<b>Yellow</b>	<b>Platform Post</b>	<b>Metal</b>	<b>4 Each</b>	<b>Intact</b>	<b>1.00</b>	<b>Positive</b>

**SECTION 2  
SURVEY SUMMARY**

**LEAD XRF SURVEY RESULTS  
BUILDING 3**

**Phase 2 - Fullerton Mill - 2069218 AS  
2001 East Orangethorpe Avenue  
Fullerton, California**

The list materials and their components where Lead Based Paint (LBP) was detected at or in excess of the HUD/EPA standards of 1.0 mg/cm<sup>2</sup> (Los Angeles County has established a more stringent standard for lead-based paint at 0.7mg/cm<sup>2</sup>) by XRF method which is listed in the table below. All XRF readings below the regulatory defined action level are considered negative and all readings at and above these levels are considered positive.

Shot #	Unit	Room Tested	Wall	Color	Component	Substrate	Quantity	Paint Condition	Result	Neg/Pos
33	Building 3	Warehouse Finished Stock	North	White	Stair Frame	Metal	1 Each	Intact	2.20	Positive
34	Building 3	Warehouse Finished Stock	North	White	Staircase	Metal	1 Each	Intact	2.20	Positive
35	Building 3	Warehouse Finished Stock	North	Yellow	Stair Rail	Metal	1 Each	Intact	2.20	Positive
36	Building 3	Warehouse Finished Stock	North	White	Electrical Panel	Metal	2 Each	Intact	0.20	Negative
37	Building 3	Warehouse Finished Stock	North	White	Platform Post	Metal	4 Each	Intact	3.00	Positive
38	Building 3	Warehouse Finished Stock	North	Yellow	3 Step Frame	Metal	2 Each	Intact	3.30	Positive
39	Building 3	Warehouse Finished Stock	North	Yellow	3 Step	Metal	2 Each	Intact	3.80	Positive
40	Building 3	Warehouse Finished Stock	North	Yellow	3 Step Rail	Metal	2 Each	Intact	0.00	Negative
41	Building 3	Warehouse Finished Stock	North	White	Electrical Panel	Metal	4 Each	Intact	0.00	Negative
42	Building 3	Warehouse Finished Stock	North	White	Hydraulic System	Metal	1 Each	Intact	1.00	Positive
43	Building 3	Warehouse Finished Stock	North	White	Conveyor Gate	Metal	1 Each	Intact	0.01	Negative
44	Building 3	Warehouse Finished Stock	North	Yellow	Roll Table Frame	Metal	3 Each	Intact	0.00	Negative
45	Building 3	Warehouse Finished Stock	East	White	Ceiling	Metal	90,475 SF	Intact	0.00	Negative
46	Building 3	Warehouse Finished Stock	East	White	Ceiling I-Beam	Metal	9,047 SF	Intact	6.80	Positive
47	Building 3	Warehouse Finished Stock	East	White	Angle Bracket	Metal	90,475 SF	Intact	9.70	Positive
48	Building 3	Warehouse Finished Stock	East	White	Ceiling Pipe	Metal	1,000 SF	Intact	0.00	Negative

**SECTION 2**  
**SURVEY SUMMARY**

**LEAD XRF SURVEY RESULTS**  
**BUILDING 3**

**Phase 2 - Fullerton Mill - 2069218 AS**  
**2001 East Orangethorpe Avenue**  
**Fullerton, California**

The list materials and their components where Lead Based Paint (LBP) was detected at or in excess of the HUD/EPA standards of 1.0 mg/cm<sup>2</sup> (Los Angeles County has established a more stringent standard for lead-based paint at 0.7mg/cm<sup>2</sup>) by XRF method which is listed in the table below. All XRF readings below the regulatory defined action level are considered negative and all readings at and above these levels are considered positive.

Shot #	Unit	Room Tested	Wall	Color	Component	Substrate	Quantity	Paint Condition	Result	Neg/Pos
49	Building 3	Breakroom	North	White	Wall	Metal	312 SF	Intact	0.08	Negative
50	Building 3	Breakroom	North	White	Panel	Metal	4 Each	Intact	0.06	Negative
51	Building 3	Breakroom	North	White	Ceiling	Metal	190 SF	Intact	0.00	Negative
52	Building 3	Breakroom	East	White	Wall	Wood	190 SF	Intact	0.00	Negative
53	Building 3	Breakroom	South	Blue	Door Frame	Metal	1 Each	Intact	0.00	Negative
54	Building 3	Breakroom	South	Blue	Door	Metal	1 Each	Intact	0.00	Negative



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509521  
**Samples Submitted:** 48  
**Sample Collection Date:** 12/7/2018  
**Laboratory Receipt Date:** 12/7/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #6  
**Project Location:** 2001 E. Orangethorpe  
Fullerton, CA

**Page:** 1 of 13

### TEST DATA

**Laboratory ID#:** 1509521-001      **Client Sample #:** 1

**Sample Material and Location:** White 12" x 12" Ceiling Tile Break Room 2 - Center

**Sample Characteristics:** White Gray Fibrous Inhomogenous  
**Misc. Components Observed:** 60% Non-Fibrous Material  
10% Fibrous Glass  
30% Cellulose

**Asbestos Observed (%):**      **Date Analyzed:** 12/8/2018      **Total Asbestos (%)** None Detected  
**Analyst:** Chris Turton

### TEST DATA

**Laboratory ID#:** 1509521-002      **Client Sample #:** 2

**Sample Material and Location:** White 12" x 12" Ceiling Tile Break Room 1 - N.E. End

**Sample Characteristics:** White Grey Fibrous Inhomogenous  
**Misc. Components Observed:** 60% Non-Fibrous Material  
10% Fibrous Glass  
30% Cellulose

**Asbestos Observed (%):**      **Date Analyzed:** 12/8/2018      **Total Asbestos (%)** None Detected  
**Analyst:** Chris Turton

### TEST DATA

**Laboratory ID#:** 1509521-003      **Client Sample #:** 3

**Sample Material and Location:** White 12" x 12" Ceiling Tile Office #4 Center -

**Sample Characteristics:** White Grey Fibrous Inhomogenous  
**Misc. Components Observed:** 60% Non-Fibrous Material  
10% Fibrous Glass  
30% Cellulose

**Asbestos Observed (%):**      **Date Analyzed:** 12/8/2018      **Total Asbestos (%)** None Detected  
**Analyst:** Chris Turton

### TEST DATA

**Laboratory ID#:** 1509521-004      **Client Sample #:** 4

**Sample Material and Location:** Brown Ceiling Tile Mastic Break Room 2 - Center

**Sample Characteristics:** Brown Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**      **Date Analyzed:** 12/8/2018      **Total Asbestos (%)** None Detected  
**Analyst:** Chris Turton



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509521  
**Samples Submitted:** 48  
**Sample Collection Date:** 12/7/2018  
**Laboratory Receipt Date:** 12/7/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #6  
**Project Location:** 2001 E. Orangethorpe  
Fullerton, CA

**Page:** 2 of 13

### TEST DATA

---

**Laboratory ID#:** 1509521-005      **Client Sample #:** 5

**Sample Material and Location:** Brown Ceiling Tile Mastic Break Room 2 - Center

**Sample Characteristics:** Brown Non-Fibrous Homogenous

**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**

**Analyst:** Chris Turton

**Date Analyzed:** 12/8/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509521-006      **Client Sample #:** 6

**Sample Material and Location:** Brown Ceiling Tile Mastic Office #4 - Center

**Sample Characteristics:** Brown Non-Fibrous Homogenous

**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**

**Analyst:** Chris Turton

**Date Analyzed:** 12/8/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509521-007      **Client Sample #:** 7

**Sample Material and Location:** White Drywall behind 12" x 12" Ceiling Tile Break Room 2 - Center

**Sample Characteristics:** White Non-Fibrous Homogenous

**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**

**Analyst:** Chris Turton

**Date Analyzed:** 12/8/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509521-008      **Client Sample #:** 8

**Sample Material and Location:** White Drywall behind 12" x 12" Ceiling Tile Break Room 1 - N.E. End

**Sample Characteristics:** White Non-Fibrous Homogenous

**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**

**Analyst:** Chris Turton

**Date Analyzed:** 12/8/2018

**Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509521  
**Samples Submitted:** 48  
**Sample Collection Date:** 12/7/2018  
**Laboratory Receipt Date:** 12/7/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #6  
**Project Location:** 2001 E. Orangethorpe  
Fullerton, CA

**Page:** 3 of 13

### TEST DATA

**Laboratory ID#:** 1509521-009      **Client Sample #:** 9

**Sample Material and Location:** White Drywall behind 12" x 12" Ceiling Tile Office #4 - Center

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 12/8/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509521-010      **Client Sample #:** 10

**Sample Material and Location:** Black 4" Covebase Break Room 2 - West End

**Sample Characteristics:** Black Smooth Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 12/8/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509521-011      **Client Sample #:** 11

**Sample Material and Location:** Black 4" Covebase Break Room 1 - North End

**Sample Characteristics:** Black Smooth Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 12/8/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509521-012      **Client Sample #:** 12

**Sample Material and Location:** Black 4" Covebase Break Room 1 - West End

**Sample Characteristics:** Black Smooth Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 12/8/2018

**Total Asbestos (%)** None Detected





**Analytical Report**

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509521  
**Samples Submitted:** 48  
**Sample Collection Date:** 12/7/2018  
**Laboratory Receipt Date:** 12/7/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #6  
**Project Location:** 2001 E. Orangethorpe  
Fullerton, CA

**Page:** 4 of 13

**TEST DATA**

---

**Laboratory ID#:** 1509521-013                      **Client Sample #:** 13

**Sample Material and Location:** Tan Covebase Glue Break Room 2 - West End

**Sample Characteristics:** Tan Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton                      **Date Analyzed:** 12/8/2018

**Total Asbestos (%)** None Detected

**TEST DATA**

---

**Laboratory ID#:** 1509521-014                      **Client Sample #:** 14

**Sample Material and Location:** Tan Covebase Glue Break Room 1 - North End

**Sample Characteristics:** Tan Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton                      **Date Analyzed:** 12/8/2018

**Total Asbestos (%)** None Detected

**TEST DATA**

---

**Laboratory ID#:** 1509521-015                      **Client Sample #:** 15

**Sample Material and Location:** Tan Covebase Glue Break Room 1 - West End

**Sample Characteristics:** Tan Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton                      **Date Analyzed:** 12/8/2018

**Total Asbestos (%)** None Detected

**TEST DATA**

---

**Laboratory ID#:** 1509521-016                      **Client Sample #:** 16

**Sample Material and Location:** White w/Gray Streaks 12 x 12 Floor Tile Break Room 2 - West End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton                      **Date Analyzed:** 12/8/2018

**Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509521  
**Samples Submitted:** 48  
**Sample Collection Date:** 12/7/2018  
**Laboratory Receipt Date:** 12/7/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #6  
**Project Location:** 2001 E. Orangethorpe  
Fullerton, CA

**Page:** 5 of 13

### TEST DATA

---

**Laboratory ID#:** 1509521-017      **Client Sample #:** 17

**Sample Material and Location:** White w/Gray Streaks 12 x 12 Floor Tile Break Room 2 - South End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 12/8/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509521-018      **Client Sample #:** 18

**Sample Material and Location:** White w/Gray Streaks 12 x 12 Floor Tile Break Room 1 - West End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 12/8/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509521-019      **Client Sample #:** 19

**Sample Material and Location:** Yellow Floor Tile Glue Break Room 2 - West End

**Sample Characteristics:** Yellow Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 12/8/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509521-020      **Client Sample #:** 20

**Sample Material and Location:** Yellow Floor Tile Glue Break Room 2 - South End

**Sample Characteristics:** Yellow Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 12/8/2018

**Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509521  
**Samples Submitted:** 48  
**Sample Collection Date:** 12/7/2018  
**Laboratory Receipt Date:** 12/7/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #6  
**Project Location:** 2001 E. Orangethorpe  
Fullerton, CA

**Page:** 6 of 13

### TEST DATA

---

**Laboratory ID#:** 1509521-021      **Client Sample #:** 21

**Sample Material and Location:** Yellow Floor Tile Glue Break Room 1 - West End

**Sample Characteristics:** Yellow Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 12/8/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509521-022      **Client Sample #:** 22

**Sample Material and Location:** Gray 4" Covebase Office #4 - North End

**Sample Characteristics:** Gray Smooth Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 12/8/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509521-023      **Client Sample #:** 23

**Sample Material and Location:** Gray 4" Covebase Office #3 - North End

**Sample Characteristics:** Gray Smooth Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 12/8/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509521-024      **Client Sample #:** 24

**Sample Material and Location:** Gray 4" Covebase 2nd Floor Hallway - N.W. End

**Sample Characteristics:** Gray Smooth Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 12/8/2018

**Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509521  
**Samples Submitted:** 48  
**Sample Collection Date:** 12/7/2018  
**Laboratory Receipt Date:** 12/7/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #6  
**Project Location:** 2001 E. Orangethorpe  
Fullerton, CA

**Page:** 7 of 13

### TEST DATA

---

**Laboratory ID#:** 1509521-025      **Client Sample #:** 25

**Sample Material and Location:** Tan/Brown Covebase Glue Office #4 - North End

**Sample Characteristics:** Tan Brown Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 12/8/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509521-026      **Client Sample #:** 26

**Sample Material and Location:** Tan/Brown Covebase Glue Office #3 - North End

**Sample Characteristics:** Tan Brown Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 12/8/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509521-027      **Client Sample #:** 27

**Sample Material and Location:** Tan/Brown Covebase Glue 2nd Floor Hallway - N.W. End

**Sample Characteristics:** Tan Brown Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 12/8/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509521-028      **Client Sample #:** 28

**Sample Material and Location:** Yellow Carpet Glue (Blue Carpet) Office #1 - North End

**Sample Characteristics:** Yellow Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 12/8/2018

**Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509521  
**Samples Submitted:** 48  
**Sample Collection Date:** 12/7/2018  
**Laboratory Receipt Date:** 12/7/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #6  
**Project Location:** 2001 E. Orangethorpe  
Fullerton, CA

**Page:** 8 of 13

### TEST DATA

---

**Laboratory ID#:** 1509521-029      **Client Sample #:** 29

**Sample Material and Location:** Yellow Carpet Glue (Blue Carpet) Office #2 - North End

**Sample Characteristics:** Yellow Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 12/8/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509521-030      **Client Sample #:** 30

**Sample Material and Location:** Yellow Carpet Glue (Blue Carpet) Office #1 - South End

**Sample Characteristics:** Yellow Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 12/8/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509521-031      **Client Sample #:** 31

**Sample Material and Location:** Gray/Blue 12 x 12 Floor Tile Office #4 - East End

**Sample Characteristics:** Blue Gray Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 12/8/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509521-032      **Client Sample #:** 32

**Sample Material and Location:** Gray/Blue 12 x 12 Floor Tile Office #3 - North End

**Sample Characteristics:** Gray Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 12/8/2018

**Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509521  
**Samples Submitted:** 48  
**Sample Collection Date:** 12/7/2018  
**Laboratory Receipt Date:** 12/7/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #6  
**Project Location:** 2001 E. Orangethorpe  
Fullerton, CA

**Page:** 9 of 13

### TEST DATA

---

**Laboratory ID#:** 1509521-033      **Client Sample #:** 33

**Sample Material and Location:** Gray/Blue 12 x 12 Floor Tile 2nd Floor Hallway - N.W. End

**Sample Characteristics:** Gray Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 12/8/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509521-034      **Client Sample #:** 34

**Sample Material and Location:** Yellow Floor Tile Glue Office #4 - East End

**Sample Characteristics:** Yellow Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 12/8/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509521-035      **Client Sample #:** 35

**Sample Material and Location:** Yellow Floor Tile Glue Office #3 - North End

**Sample Characteristics:** Yellow Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 12/8/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509521-036      **Client Sample #:** 36

**Sample Material and Location:** Yellow Floor Tile Glue 2nd Floor Hallway - N.W. End

**Sample Characteristics:** Yellow Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 12/8/2018

**Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509521  
**Samples Submitted:** 48  
**Sample Collection Date:** 12/7/2018  
**Laboratory Receipt Date:** 12/7/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #6  
**Project Location:** 2001 E. Orangethorpe  
Fullerton, CA

**Page:** 10 of 13

### TEST DATA

---

**Laboratory ID#:** 1509521-037      **Client Sample #:** 37

**Sample Material and Location:** Brown Stair Flooring Stairs - North End

**Sample Characteristics:** Brown Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 12/8/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509521-038      **Client Sample #:** 38

**Sample Material and Location:** Brown Stair Flooring Stairs - Center

**Sample Characteristics:** Brown Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 12/8/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509521-039      **Client Sample #:** 39

**Sample Material and Location:** Brown Stair Flooring Stairs - South End

**Sample Characteristics:** Brown Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 12/8/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509521-040      **Client Sample #:** 40

**Sample Material and Location:** Brown Stair Flooring Mastic Stairs - North End

**Sample Characteristics:** Brown Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 12/8/2018

**Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509521  
**Samples Submitted:** 48  
**Sample Collection Date:** 12/7/2018  
**Laboratory Receipt Date:** 12/7/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #6  
**Project Location:** 2001 E. Orangethorpe  
Fullerton, CA

**Page:** 11 of 13

### TEST DATA

---

**Laboratory ID#:** 1509521-041      **Client Sample #:** 41

**Sample Material and Location:** Brown Stair Flooring Mastic Stairs - Center

**Sample Characteristics:** Brown Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 12/8/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509521-042      **Client Sample #:** 42

**Sample Material and Location:** Brown Stair Flooring Mastic Stairs - South End

**Sample Characteristics:** Brown Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 12/8/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509521-043      **Client Sample #:** 43

**Sample Material and Location:** White Drywall Office #7 - North End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 12/8/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509521-044      **Client Sample #:** 44

**Sample Material and Location:** White Drywall Office #6 - North End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 12/8/2018

**Total Asbestos (%)** None Detected





## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509521  
**Samples Submitted:** 48  
**Sample Collection Date:** 12/7/2018  
**Laboratory Receipt Date:** 12/7/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #6  
**Project Location:** 2001 E. Orangethorpe  
Fullerton, CA

**Page:** 12 of 13

### TEST DATA

---

**Laboratory ID#:** 1509521-045      **Client Sample #:** 45

**Sample Material and Location:** White Drywall Office #5 - North End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 12/8/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509521-046      **Client Sample #:** 46

**Sample Material and Location:** White Joint Compound Office #7 - North End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 12/8/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509521-047      **Client Sample #:** 47

**Sample Material and Location:** White Joint Compound Office #6 - North End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 12/8/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509521-048      **Client Sample #:** 48

**Sample Material and Location:** White Joint Compound Office #5 - North End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 12/8/2018

**Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509521  
**Samples Submitted:** 48  
**Sample Collection Date:** 12/7/2018  
**Laboratory Receipt Date:** 12/7/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #6  
**Project Location:** 2001 E. Orangethorpe  
Fullerton, CA

**Page:** 13 of 13

Samples were analyzed by Calibrated Visual Estimation (CVE). Analyses by CVE have a detection limit of 1% asbestos by relative area and may not be consistently reliable below this limit or for asbestos with fiber diameter thinner than the resolving capacity of PLM without further analysis by another independent method. A test result of less than (<) 1% by CVE means asbestos was observed in the sample but is visually estimated to be below the reportable limit of 1%. The laboratory references interim method EPA 600/M4-82-020 (Interim Method) for fiber identification, 400 point counts, and composite reporting. EPA method 600/R-93/116 is referenced for analysis of non-insulation materials, sub-layers, expanded and modified point counts, CVE and subsequent data reporting. Samples containing distinct layers that can be reliably separated are analyzed and reported as separate unless requested in writing. The test data presented apply only to the items submitted. Count for samples submitted is indicative of total layers observed and may vary from actual analysis for positive stop requests. ATEL, LLC is a NIST-NVLAP and CA-ELAP Accredited laboratory (ID# 201073-0 and #2971, respectively). This report must not be reproduced, unless in its entirety, without the written consent of ATEL, LLC. Per NIST-NVLAP 150 Annex A: This report shall not be used to claim product certification, approval or endorsement by NVLAP, NIST, or any agency of the federal government.

Unless indicated, samples were received in acceptable condition. Sample retention time is 30 days from issuing this report unless requested otherwise.

Analyst Signature:

Handwritten signature of Chris Turton in black ink.

-Chris Turton

Approved Signatory:

Handwritten signature of Dennis Liu in black ink.

-Dennis Liu

Reported On: 12/8/2018



1509521

Asbestos Laboratory

**Your Contact Information**

Company Name (if by company): H2 Environmental Consulting Services, Inc.

Personal/Company Address: 13122 6th Street, Chino, CA 91710

Contact Person: Amy De Santiago

Contact Information: Main: 909-628-0369 E-Mail: labresults@h2env.com

Mobile: \_\_\_\_\_ Fax: 909-613-5845

How should we send your result Verbal  Verbal  E-mail  Fax

*\*If verbal results are requested, you must also select a second form of delivery.*

**Project Information**

Project Name: Kimberly Clark

Project #: 2069218AS

Project Location: 2001 E. Commonwealth Ave, Fullerton, CA - Bldg # 6

PO#: \_\_\_\_\_ Claim# \_\_\_\_\_

Date Sampled: 12/6/18 Time Sampled: 10am

Analytical Type(s) Requested	Turnaround Time*
Asbestos in Bulk Materials, EPA 600/R-93/116, 600/M4-82-020	*Business Hrs: 0800-1700 Mon-Fri.
Routine, Calibrated Visual Estimation <input checked="" type="checkbox"/>	Rush 3 Business Hrs* <input type="checkbox"/>
Point Count: 400pts <input type="checkbox"/>	8 Business Hrs* <input type="checkbox"/>
1000pts <input type="checkbox"/>	
Gravimetric Reduction (72hr Minimum) <input type="checkbox"/>	Expedited 24 Business Hrs <input checked="" type="checkbox"/>
	Routine 48 Business Hrs <input type="checkbox"/>
Fiber Count in Sampling Cartridge (25mm MCE)	72 Business Hrs <input type="checkbox"/>
Asbestos-like, NIOSH 7400 A Rules <input type="checkbox"/>	
	Standard 5 Business Days <input type="checkbox"/>
Rotometer Calibration (Low and High Flow Rotometers) <input type="checkbox"/>	*3hr TAT: Samples must be submitted by 2pm for same day results
	*8hr TAT: Samples must be submitted by 9am for same day results

Special Instructions: \_\_\_\_\_

**Sample Information**

Sample ID #	Description/Material Type	Location	Flow Rate	Start Time	Stop Time	Volume (L)
	Please See Attached					

For more samples, please continue onto supplemental form. Page # Indication in upper-right-hand of form.

**Chain of Custody**

Relinquished By: Amy De Santiago Date and Time: 12/6/18 10am

Received By: \_\_\_\_\_ Date and Time: \_\_\_\_\_

Relinquished By: \_\_\_\_\_ Date and Time: \_\_\_\_\_

Received By: Chris Tutton Date and Time: 12/7/18 3:40pm



# ENVIRONMENTAL CONSULTING SERVICES, INC.


## Bulk Sampling Form

Stop at First Positive   
 24 Hour turn around   
 Rush turn around (4 Hours)  
 Do Not Layer Samples

CLIENT <i>Kimberly Clark</i>	PROJECT NO. <i>2069218AS</i>		
PROJECT ID <i>Bldg. C</i>	DATE <i>12/6/18</i>	PAGE <i>1</i>	OF <i>3</i>
PROJECT LOCATION <i>2001 E. Orangeburg Ave., Fullerton, CA</i>	INSPECTOR <i>A. Sanchez, J. Ortiz</i>		

GRP. NO.	SAMP. NO.	MATERIAL DESCRIPTION	LOCATION OF SAMPLE	QTY	% POS
U1	U1	white 12x12	Break Room 2 - Center	1,100#	
↓	U2	ceiling tile	Break Room 1 - N.E. end	↓	
	U3	↓	Office #4 - Center	↓	
U2	U4	Bea ceiling tile	Break Room 2 - Center	1,100#	
↓	U5	music	Break Room 1 - N.E. end	↓	
	U6	↓	Office #4 - Center	↓	
U3	U7	white Downer	Break Room 2 - Center	1,100#	
↓	U8	beige 12x12	Break Room 1 - N.E. end	↓	
	U9	ceiling tile	Office #4 - Center	↓	
U4	U10	BLK 4" lumber	Break Room 2 - West end	150Lb.	
↓	U11	↓	Break Room 1 - North end	↓	
	U12	↓	Break Room 1 - West end	↓	
U5	U13	TAN Lumber slat	Break Room 2 - West end	150Lb.	
↓	U14	↓	Break Room 1 - North end	↓	
	U15	↓	Break Room 1 - West end	↓	
U6	U16	white w/gray streaks	Break Room 2 - West end	640#	
↓	U17	12x12 floor tile	Break Room 2 - South end	↓	
	U18	↓	Break Room 1 - West end	↓	
U7	U19	yellow floor tile	Break Room 2 - West end	640#	
↓	U20	slat	Break Room 2 - South end	↓	
	U21	↓	Break Room 1 - West end	↓	

Notes:



**H2 ENVIRONMENTAL**  
CONSULTING SERVICES, INC.

**Bulk Sampling Form**

Stop at First Positive  24 Hour turn around  Rush turn around (4 Hours)  
 Do Not Layer Samples

CLIENT <i>Kimberly Clark</i>	PROJECT NO. <i>2069218AS</i>		
PROJECT ID <i>Bldg 6</i>	DATE <i>12/6/18</i>	PAGE <i>2</i>	OF <i>3</i>
PROJECT LOCATION <i>2001 E. Orangeburg Ave, Fullerton, CA</i>	INSPECTOR <i>A. Sanchez, J. Ortiz</i>		

GRP. NO.	SAMP. NO.	MATERIAL DESCRIPTION	LOCATION OF SAMPLE	QTY	% POS
08	22	gray 4" lumber	OFFICE #4 - North end	200lb	
	23	↓	OFFICE #3 - North end	↓	
	24	↓	2nd Flr. Hallway - North end	↓	
09	25	TAN/Ber. Lumber	OFFICE #4 - North end	200lb	
	26	↓	OFFICE #3 - North end	↓	
	27	↓	2nd Flr. Hallway - N.W. End	↓	
10	28	Yellow carpet glue	OFFICE #1 - North end	100lb	
	29	(Blue carpet)	OFFICE #2 - North end	↓	
	30	↓	OFFICE #3 - South end	↓	
11	31	gray/Blue 12x12	OFFICE #4 - East end	550lb	
	32	↓	OFFICE #3 - North end	↓	
	33	↓	2nd Flr. Hallway - N.W. end	↓	
12	34	yellow floor tile	OFFICE #4 - East end	550lb	
	35	↓	OFFICE #3 - North end	↓	
	36	↓	2nd Flr. Hallway - N.W. end	↓	
13	37	Ber. stair Flooring	stairs - North end	600lb	
	38	↓	↓ - Center	↓	
	39	↓	↓ - South end	↓	
14	40	Ber. stair Flooring	stairs - North end	600lb	
	41	↓	↓ - Center	↓	
	42	↓	↓ - South end	↓	

Notes:



**SECTION 2**  
**SURVEY SUMMARY**

**LEAD XRF SURVEY RESULTS**  
**BUILDING 6**

**Phase 2 - Fullerton Mill - 2069218 AS**  
**2001 East Orangethorpe Avenue**  
**Fullerton, California**

The list materials and their components where Lead Based Paint (LBP) was detected at or in excess of the HUD/EPA standards of 1.0 mg/cm<sup>2</sup> (Los Angeles County has established a more stringent standard for lead-based paint at 0.7mg/cm<sup>2</sup>) by XRF method which is listed in the table below. All XRF readings below the regulatory defined action level are considered negative and all readings at and above these levels are considered positive.

Shot #	Unit	Room Tested	Wall	Color	Component	Substrate	Quantity	Paint Condition	Result	Neg/Pos
01	1 <sup>st</sup> Floor	Breakroom 1	North	Blue	Door Frame	Metal	2 Each	Intact	0.00	Negative
02	1 <sup>st</sup> Floor	Breakroom 1	North	Blue	Door	Wood	2 Each	Intact	0.00	Negative
03	1 <sup>st</sup> Floor	Breakroom 1	North	Blue	Window Frame	Metal	3 Each	Intact	0.00	Negative
04	1 <sup>st</sup> Floor	Breakroom 1	North	White	Wall	Metal	736 SF	Intact	0.00	Negative
05	1 <sup>st</sup> Floor	Office 4	North	Blue	Door Frame	Metal	4 Each	Intact	0.00	Negative
06	1 <sup>st</sup> Floor	Office 4	North	Blue	Door	Wood	4 Each	Intact	0.00	Negative
07	1 <sup>st</sup> Floor	Office 4	North	Blue	Window Frame	Metal	7 Each	Intact	0.00	Negative
08	1 <sup>st</sup> Floor	Office 4	North	Grey	Wall	Wood	1,088 SF	Intact	0.00	Negative
09	1 <sup>st</sup> Floor	Warehouse	South	Blue	Stair Rail	Wood	1 Each	Intact	0.00	Negative
10	2 <sup>nd</sup> Floor	Office 6	South	Blue	Door Frame	Metal	4 Each	Intact	0.00	Negative
11	2 <sup>nd</sup> Floor	Office 6	South	Blue	Door	Wood	4 Each	Intact	0.00	Negative
12	2 <sup>nd</sup> Floor	Office 6	North	White	Wall	Drywall	1,152 SF	Intact	0.00	Negative
13	2 <sup>nd</sup> Floor	Office 6	North	White	Window Frame	Drywall	4 Each	Intact	0.00	Negative
14	1 <sup>st</sup> Floor	Warehouse	South	Blue	Door Frame	Metal	10 Each	Intact	0.00	Negative
15	1 <sup>st</sup> Floor	Warehouse	South	Blue	Door	Wood	10 Each	Intact	0.00	Negative
16	1 <sup>st</sup> Floor	Warehouse	South	Blue	Wall	Metal	20,900 SF	Intact	0.00	Negative

**SECTION 2  
SURVEY SUMMARY**

**LEAD XRF SURVEY RESULTS  
BUILDING 6**

**Phase 2 - Fullerton Mill - 2069218 AS  
2001 East Orangethorpe Avenue  
Fullerton, California**

The list materials and their components where Lead Based Paint (LBP) was detected at or in excess of the HUD/EPA standards of 1.0 mg/cm<sup>2</sup> (Los Angeles County has established a more stringent standard for lead-based paint at 0.7mg/cm<sup>2</sup>) by XRF method which is listed in the table below. All XRF readings below the regulatory defined action level are considered negative and all readings at and above these levels are considered positive.

Shot #	Unit	Room Tested	Wall	Color	Component	Substrate	Quantity	Paint Condition	Result	Neg/Pos
17	1 <sup>st</sup> Floor	Warehouse	North	White	Wall	Concrete	20,900 SF	Intact	0.00	Negative
18	1 <sup>st</sup> Floor	Warehouse	North	White	Door Frame	Metal	2 Each	Intact	0.00	Negative
19	1 <sup>st</sup> Floor	Warehouse	North	Blue	Door	Metal	2 Each	Intact	0.00	Negative
<b>20</b>	<b>1<sup>st</sup> Floor</b>	<b>Warehouse</b>	<b>North</b>	<b>Yellow</b>	<b>Bollard</b>	<b>Metal</b>	<b>100 SF</b>	<b>Intact</b>	<b>6.80</b>	<b>Positive</b>
21	1 <sup>st</sup> Floor	Warehouse	North	Yellow	Floor	Concrete	100 Each	Intact	0.01	Negative
22	1 <sup>st</sup> Floor	Warehouse	South	Blue	Sliding Door Frame	Metal	7 Each	Intact	0.01	Negative
<b>23</b>	<b>1<sup>st</sup> Floor</b>	<b>Warehouse</b>	<b>South</b>	<b>Blue</b>	<b>Sliding Door</b>	<b>Metal</b>	<b>7 Each</b>	<b>Intact</b>	<b>5.80</b>	<b>Positive</b>
<b>24</b>	<b>1<sup>st</sup> Floor</b>	<b>Warehouse</b>	<b>North</b>	<b>Red</b>	<b>I-Beam</b>	<b>Metal</b>	<b>1000 SF</b>	<b>Intact</b>	<b>6.80</b>	<b>Positive</b>
25	1 <sup>st</sup> Floor	Warehouse	North	Red	Floor	Concrete	100 SF	Intact	0.01	Negative
26	1 <sup>st</sup> Floor	Warehouse	North	Yellow	Rail	Metal	100 SF	Intact	0.01	Negative
<b>27</b>	<b>1<sup>st</sup> Floor</b>	<b>Warehouse</b>	<b>North</b>	<b>Yellow</b>	<b>Stair Rail</b>	<b>Metal</b>	<b>2 Each</b>	<b>Intact</b>	<b>4.80</b>	<b>Positive</b>
28	1 <sup>st</sup> Floor	Warehouse	South	White	Ceiling	Metal	143,040 SF	Intact	0.00	Negative
29	1 <sup>st</sup> Floor	Warehouse	South	White	Ceiling I-Beam	Metal	14,304 SF	Intact	0.00	Negative
30	1 <sup>st</sup> Floor	Warehouse	South	White	Angle Bracket	Metal	143,040 SF	Intact	0.01	Negative
31	1 <sup>st</sup> Floor	Warehouse	South	White	Ceiling Pipe	Metal	1,000 SF	Intact	0.01	Negative
32	1 <sup>st</sup> Floor	Warehouse	South	Yellow	Shoot Ladder	Metal	1 Each	Intact	0.00	Negative



**SECTION 2  
SURVEY SUMMARY**

**LEAD XRF SURVEY RESULTS  
BUILDING 6**

**Phase 2 - Fullerton Mill - 2069218 AS  
2001 East Orangethorpe Avenue  
Fullerton, California**

The list materials and their components where Lead Based Paint (LBP) was detected at or in excess of the HUD/EPA standards of 1.0 mg/cm<sup>2</sup> (Los Angeles County has established a more stringent standard for lead-based paint at 0.7mg/cm<sup>2</sup>) by XRF method which is listed in the table below. All XRF readings below the regulatory defined action level are considered negative and all readings at and above these levels are considered positive.

Shot #	Unit	Room Tested	Wall	Color	Component	Substrate	Quantity	Paint Condition	Result	Neg/Pos
33	1 <sup>st</sup> Floor	Warehouse	North	Blue	Cable Vent	Metal	2 Each	Intact	-0.70	Negative
34	1 <sup>st</sup> Floor	Warehouse	North	Yellow	Floor	Concrete	1,000 LF	Intact	0.00	Negative
35	1 <sup>st</sup> Floor	Warehouse	North	Yellow	Floor Edge Metal	Metal	147 LF	Intact	0.01	Negative
36	1 <sup>st</sup> Floor	Warehouse	East	Blue	Loading Back Door	Metal	4 Each	Intact	0.01	Negative
37	1 <sup>st</sup> Floor	Warehouse	East	Blue	Dock Door Frame	Metal	4 Each	Intact	0.01	Negative
38	1 <sup>st</sup> Floor	Warehouse	South	Red	Plate	Metal	10 SF	Intact	0.00	Negative
39	1 <sup>st</sup> Floor	Warehouse	South	Red	Pipe	Metal	1,000 LF	Intact	0.00	Negative
40	1 <sup>st</sup> Floor	Warehouse	West	Yellow	Door	Metal	1 Each	Intact	0.00	Negative
41	1 <sup>st</sup> Floor	Warehouse	West	White	Door Frame	Metal	1 Each	Intact	0.10	Negative
<b>42</b>	<b>1<sup>st</sup> Floor</b>	<b>Warehouse</b>	<b>East</b>	<b>Yellow</b>	<b>Stair Case</b>	<b>Metal</b>	<b>1 Each</b>	<b>Intact</b>	<b>1.50</b>	<b>Positive</b>
<b>43</b>	<b>1<sup>st</sup> Floor</b>	<b>Warehouse</b>	<b>West</b>	<b>Red</b>	<b>Bollard</b>	<b>Metal</b>	<b>1,000 SF</b>	<b>Intact</b>	<b>6.80</b>	<b>Positive</b>
44	2 <sup>nd</sup> Floor	Warehouse	South	Blue	Guard Rail	Wood	100 SF	Intact	0.00	Negative

**SECTION 2  
SURVEY SUMMARY**

**LEAD XRF SURVEY RESULTS  
BUILDING 7**

**Phase 2 - Fullerton Mill - 2069218 AS  
2001 East Orangethorpe Avenue  
Fullerton, California**

The list materials and their components where Lead Based Paint (LBP) was detected at or in excess of the HUD/EPA standards of 1.0 mg/cm<sup>2</sup> (Los Angeles County has established a more stringent standard for lead-based paint at 0.7mg/cm<sup>2</sup>) by XRF method which is listed in the table below. All XRF readings below the regulatory defined action level are considered negative and all readings at and above these levels are considered positive.

Shot #	Unit	Room Tested	Wall	Color	Component	Substrate	Quantity	Paint Condition	Result	Neg/Pos
01	1 <sup>st</sup> Floor	Warehouse	North	White	Wall	Concrete	14,480 SF	Intact	0.00	Negative
02	1 <sup>st</sup> Floor	Warehouse	North	Blue	Wall	Concrete	14,480 SF	Intact	0.00	Negative
03	1 <sup>st</sup> Floor	Warehouse	North	Red	Pipe	Metal	100 SF	Intact	0.01	Negative
04	1 <sup>st</sup> Floor	Warehouse	West	Red	I-Beam	Metal	1,000 SF	Intact	0.01	Negative
05	1 <sup>st</sup> Floor	Warehouse	West	Yellow	I-Beam	Metal	1,000 SF	Intact	0.01	Negative
06	1 <sup>st</sup> Floor	Warehouse	West	Blue	Sliding Door	Metal	13 Each	Intact	0.10	Negative
<b>07</b>	<b>1<sup>st</sup> Floor</b>	<b>Warehouse</b>	<b>West</b>	<b>Yellow</b>	<b>Bollard</b>	<b>Metal</b>	<b>100 SF</b>	<b>Intact</b>	<b>7.90</b>	<b>Positive</b>
08	1 <sup>st</sup> Floor	Warehouse	West	Red	Floor	Concrete	100 SF	Intact	0.01	Negative
09	1 <sup>st</sup> Floor	Warehouse	West	Yellow	Floor	Concrete	1,000 LF	Intact	0.01	Negative
10	1 <sup>st</sup> Floor	Warehouse	West	Gray	Ceiling	Metal	126,150 SF	Intact	0.00	Negative
11	1 <sup>st</sup> Floor	Warehouse	West	Gray	Ceiling I-Beam	Metal	12,615 SF	Intact	0.01	Negative
12	1 <sup>st</sup> Floor	Warehouse	West	Gray	Ceiling Angle Bracket	Metal	126,150 SF	Intact	0.01	Negative
13	1 <sup>st</sup> Floor	Warehouse	West	Gray	Ceiling Pipe	Metal	1,000 LF	Intact	0.00	Negative
14	1 <sup>st</sup> Floor	Warehouse	South	Blue	Door Frame	Metal	12 Each	Intact	0.00	Negative
15	1 <sup>st</sup> Floor	Warehouse	South	Blue	Door	Metal	12 Each	Intact	0.00	Negative
16	1 <sup>st</sup> Floor	Warehouse	North	Yellow	Floor Rail	Metal	290 LF	Intact	0.00	Negative
<b>17</b>	<b>Bldg. 7</b>	<b>Warehouse</b>	<b>East</b>	<b>Yellow</b>	<b>Panel</b>	<b>Metal</b>	<b>1 Each</b>	<b>Intact</b>	<b>5.00</b>	<b>Positive</b>



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509334  
**Samples Submitted:** 27  
**Sample Collection Date:** 11/19/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #8  
**Project Location:** 2001 E. Orangethorpe  
Fullerton, CA

**Page:** 1 of 7

### TEST DATA

**Laboratory ID#:** 1509334-001      **Client Sample #:** 1

**Sample Material and Location:** White Drywall Lift Tank Room - West End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 95% Non-Fibrous Material  
5% Cellulose

**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509334-002      **Client Sample #:** 2

**Sample Material and Location:** White Drywall Lift Tank Room - South End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 95% Non-Fibrous Material  
5% Cellulose

**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509334-003      **Client Sample #:** 3

**Sample Material and Location:** White Drywall Lift Tank Room - East End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 95% Non-Fibrous Material  
5% Cellulose

**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509334-004      **Client Sample #:** 4

**Sample Material and Location:** White Joint Compound Lift Tank Room - West End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509334  
**Samples Submitted:** 27  
**Sample Collection Date:** 11/19/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #8  
**Project Location:** 2001 E. Orangethorpe  
Fullerton, CA

**Page:** 2 of 7

### TEST DATA

---

**Laboratory ID#:** 1509334-005      **Client Sample #:** 5

**Sample Material and Location:** White Joint Compound Lift Tank Room - South End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509334-006      **Client Sample #:** 6

**Sample Material and Location:** White Joint Compound Lift Tank Room - East End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509334-007      **Client Sample #:** 7

**Sample Material and Location:** Brown Drywall Room #1 - West End

**Sample Characteristics:** Brown Non-Fibrous Homogenous  
**Misc. Components Observed:** 95% Non-Fibrous Material  
5% Cellulose  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509334-008      **Client Sample #:** 8

**Sample Material and Location:** Brown Drywall Room #1 - South End

**Sample Characteristics:** Brown Non-Fibrous Homogenous  
**Misc. Components Observed:** 95% Non-Fibrous Material  
5% Cellulose  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509334  
**Samples Submitted:** 27  
**Sample Collection Date:** 11/19/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #8  
**Project Location:** 2001 E. Orangethorpe  
Fullerton, CA

**Page:** 3 of 7

### TEST DATA

---

**Laboratory ID#:** 1509334-009      **Client Sample #:** 9

**Sample Material and Location:** Brown Drywall Room #1 - North End

**Sample Characteristics:** Brown Non-Fibrous Homogenous  
**Misc. Components Observed:** 95% Non-Fibrous Material  
5% Cellulose

**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509334-010      **Client Sample #:** 10

**Sample Material and Location:** White Joint Compound Room #1 - West End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509334-011      **Client Sample #:** 11

**Sample Material and Location:** White Joint Compound Room #1 - South End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509334-012      **Client Sample #:** 12

**Sample Material and Location:** White Joint Compound Room #1 - North End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509334  
**Samples Submitted:** 27  
**Sample Collection Date:** 11/19/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #8  
**Project Location:** 2001 E. Orangethorpe  
Fullerton, CA

**Page:** 4 of 7

### TEST DATA

**Laboratory ID#:** 1509334-013 **Client Sample #:** 13

**Sample Material and Location:** White Pipe Wrap Bath Open Storage Area - N.W. End

**Sample Characteristics:** White Fibrous Inhomogenous  
**Misc. Components Observed:** 60% Non-Fibrous Material  
10% Fibrous Glass  
30% Cellulose

**Asbestos Observed (%):**  
**Analyst:** Dennis Liu **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509334-014 **Client Sample #:** 14

**Sample Material and Location:** White Pipe Wrap Bath Open Storage Area - North End

**Sample Characteristics:** White Fibrous Inhomogenous  
**Misc. Components Observed:** 60% Non-Fibrous Material  
10% Fibrous Glass  
30% Cellulose

**Asbestos Observed (%):**  
**Analyst:** Dennis Liu **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509334-015 **Client Sample #:** 15

**Sample Material and Location:** White Pipe Wrap Bath Open Storage Area - N.E. End

**Sample Characteristics:** White Fibrous Inhomogenous  
**Misc. Components Observed:** 60% Non-Fibrous Material  
10% Fibrous Glass  
30% Cellulose

**Asbestos Observed (%):**  
**Analyst:** Dennis Liu **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509334-016 **Client Sample #:** 16

**Sample Material and Location:** Yellow Pipe Insulation Bath Open Storage Area - N.W. End

**Sample Characteristics:** Yellow Fibrous Homogenous  
**Misc. Components Observed:** 5% Non-Fibrous Material  
95% Fibrous Glass

**Asbestos Observed (%):**  
**Analyst:** Dennis Liu **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509334  
**Samples Submitted:** 27  
**Sample Collection Date:** 11/19/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #8  
**Project Location:** 2001 E. Orangethorpe  
Fullerton, CA

**Page:** 5 of 7

### TEST DATA

---

**Laboratory ID#:** 1509334-017      **Client Sample #:** 17

**Sample Material and Location:** Yellow Pipe Insulation Bath Open Storage Area - North End

**Sample Characteristics:** Yellow Fibrous Inhomogenous  
**Misc. Components Observed:** 5% Non-Fibrous Material  
95% Fibrous Glass

**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509334-018      **Client Sample #:** 18

**Sample Material and Location:** Yellow Pipe Insulation Bath Open Storage Area - N.E. End

**Sample Characteristics:** Yellow Fibrous Inhomogenous  
**Misc. Components Observed:** 5% Non-Fibrous Material  
95% Fibrous Glass

**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509334-019      **Client Sample #:** 19

**Sample Material and Location:** Gray Floor Epoxy Room #1 - West End

**Sample Characteristics:** Grey Grainy Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509334-020      **Client Sample #:** 20

**Sample Material and Location:** Gray Floor Epoxy Room #1 - North End

**Sample Characteristics:** Grey Grainy Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509334  
**Samples Submitted:** 27  
**Sample Collection Date:** 11/19/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #8  
**Project Location:** 2001 E. Orangethorpe  
Fullerton, CA

**Page:** 6 of 7

### TEST DATA

**Laboratory ID#:** 1509334-021      **Client Sample #:** 21

**Sample Material and Location:** Gray Floor Epoxy Room #1 - East End

**Sample Characteristics:** Grey Grainy Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**

**Analyst:** Dennis Liu

**Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509334-022      **Client Sample #:** 22

**Sample Material and Location:** Tan Pipe Wrap Lift Tank Room at Tank - N.W. End

**Sample Characteristics:** Tan Fibrous Homogenous  
**Misc. Components Observed:** 5% Non-Fibrous Material  
95% Cellulose

**Asbestos Observed (%):**

**Analyst:** Dennis Liu

**Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509334-023      **Client Sample #:** 23

**Sample Material and Location:** Tan Pipe Wrap Lift Tank Room at Tank - North End

**Sample Characteristics:** Tan Fibrous Homogenous  
**Misc. Components Observed:** 5% Non-Fibrous Material  
95% Cellulose

**Asbestos Observed (%):**

**Analyst:** Dennis Liu

**Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509334-024      **Client Sample #:** 24

**Sample Material and Location:** Tan Pipe Wrap Lift Tank Room at Tank - N.E. End

**Sample Characteristics:** Tan Fibrous Homogenous  
**Misc. Components Observed:** 5% Non-Fibrous Material  
95% Cellulose

**Asbestos Observed (%):**

**Analyst:** Dennis Liu

**Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected





## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509334  
**Samples Submitted:** 27  
**Sample Collection Date:** 11/19/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #8  
**Project Location:** 2001 E. Orangethorpe  
Fullerton, CA

**Page:** 7 of 7

### TEST DATA

**Laboratory ID#:** 1509334-025      **Client Sample #:** 25

**Sample Material and Location:** Offwhite Pipe Insulation Lift Tank Room at Tank - N.W. End

**Sample Characteristics:** Yellow Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509334-026      **Client Sample #:** 26

**Sample Material and Location:** Offwhite Pipe Insulation Lift Tank Room at Tank - North End

**Sample Characteristics:** Yellow Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509334-027      **Client Sample #:** 27

**Sample Material and Location:** Offwhite Pipe Insulation Lift Tank Room at Tank - N.E. End

**Sample Characteristics:** Yellow Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

Samples were analyzed by Calibrated Visual Estimation (CVE). Analyses by CVE have a detection limit of 1% asbestos by relative area and may not be consistently reliable below this limit or for asbestos with fiber diameter thinner than the resolving capacity of PLM without further analysis by another independent method. A test result of less than (<) 1% by CVE means asbestos was observed in the sample but is visually estimated to be below the reportable limit of 1%. The laboratory references interim method EPA 600/M4-82-020 (Interim Method) for fiber identification, 400 point counts, and composite reporting. EPA method 600/R-93/116 is referenced for analysis of non-insulation materials, sub-layers, expanded and modified point counts, CVE and subsequent data reporting. Samples containing distinct layers that can be reliably separated are analyzed and reported as separate unless requested in writing. The test data presented apply only to the items submitted. Count for samples submitted is indicative of total layers observed and may vary from actual analysis for positive stop requests. ATEL, LLC is a NIST-NVLAP and CA-ELAP Accredited laboratory (ID# 201073-0 and #2971, respectively). This report must not be reproduced, unless in its entirety, without the written consent of ATEL, LLC. Per NIST-NVLAP 150 Annex A: This report shall not be used to claim product certification, approval or endorsement by NVLAP, NIST, or any agency of the federal government.

Unless indicated, samples were received in acceptable condition. Sample retention time is 30 days from issuing this report unless requested otherwise.

**Analyst Signature:**

-Dennis Liu

**Approved Signatory:**

-Chris Turton

**Reported On:** 11/28/2018



1509334

Analytical Services Request v.112414

Pg 1 of 1

Asbestos Laboratory

**Your Contact Information**

Company Name (if by company): H2 Environmental Consulting Services, Inc.  
 Personal/Company Address: 13122 6th Street, Chino, CA 91710  
 Contact Person: Amy De Santiago  
 Contact Information: Main: 909-628-0369 E-Mail: labresults@h2env.com  
 Mobile: \_\_\_\_\_ Fax: 909-613-5845  
 How should we send your result Verbal  Verbal  E-mail  Fax

*\*If verbal results are requested, you must also select a second form of delivery.*

**Project Information**

Project Name: Kimberly Clark  
 Project #: 2069218AS  
 Project Location: 2011 E. Washington, Fullerton, CA - Bldg 58  
 PO#: \_\_\_\_\_ Claim# \_\_\_\_\_  
 Date Sampled: 11/19/18 Time Sampled: 8:45am

Analytical Type(s) Requested	Turnaround Time*
Asbestos in Bulk Materials, EPA 600/R-93/116, 600/M4-82-020	*Business Hrs: 0800-1700 Mon-Fri.
Routine, Calibrated <u>Visual Estimation</u> <input checked="" type="checkbox"/>	Rush 3 Business Hrs* <input type="checkbox"/>
Point Count: 400pts <input type="checkbox"/>	8 Business Hrs* <input type="checkbox"/>
1000pts <input type="checkbox"/>	Expedited 24 Business Hrs <input checked="" type="checkbox"/>
Gravimetric Reduction (72hr Minimum) <input type="checkbox"/>	Routine 48 Business Hrs <input type="checkbox"/>
Fiber Count in Sampling Cartridge (25mm MCE)	72 Business Hrs <input type="checkbox"/>
Asbestos-like, NIOSH 7400 A Rules <input type="checkbox"/>	Standard 5 Business Days <input type="checkbox"/>
Rotometer Calibration (Low and High Flow Rotometers) <input type="checkbox"/>	*3hr TAT: Samples must be submitted by 2pm for same day results
Special Instructions: _____	*8hr TAT: Samples must be submitted by 9am for same day results

**Sample Information**

Sample ID #	Description/Material Type	Location	Flow Rate	Start Time	Stop Time	Volume (L)
	Please See Attached					

For more samples, please continue onto supplemental form. Page # indication in upper-right-hand of form.

**Chain of Custody**

Relinquished By: Alberto Sanchez Date and Time: 11/19/18 8:45am  
 Received By: \_\_\_\_\_ Date and Time: \_\_\_\_\_  
 Relinquished By: \_\_\_\_\_ Date and Time: \_\_\_\_\_  
 Received By: Chris Smith Date and Time: 11/27/18 2:50pm



**H2 ENVIRONMENTAL CONSULTING SERVICES, INC.**

**Bulk Sampling Form**

Stop at First Positive  24 Hour turn around  Rush turn around (4 Hours)  
 Do Not Layer Samples

CLIENT Kimberly Clark	PROJECT NO. 206921845		
PROJECT ID Bldg #8	DATE	PAGE 1	OF 2
PROJECT LOCATION 2001 E. Orange Highway, Fullerton, CA	INSPECTOR A. Sanchez, J. Ortiz		

GRP. NO.	SAMP. NO.	MATERIAL DESCRIPTION	LOCATION OF SAMPLE	QTY	% POS
01	01	White Drywall	lift tank room - west end	2,820 lb	
↓	02	↓	↓ - south end	↓	
↓	03	↓	↓ - east end	↓	
02	04	white joint	lift tank room - west end	1,820 lb	
↓	05	compound	↓ - south end	↓	
↓	06	↓	↓ - east end	↓	
03	07	Red Drywall	Room #11 - west end	1,650 lb	
↓	08	↓	↓ - south end	↓	
↓	09	↓	↓ - north end	↓	
04	10	white joint	Room #11 - west end	1,650 lb	
↓	11	compound	↓ - south end	↓	
↓	12	↓	↓ - north end	↓	
05	13	white pipe wrap	Bath upon storage area - NW end	600 lb	
↓	14	↓	↓ - north end	↓	
↓	15	↓	↓ - N.E. end	↓	
06	16	yellow pipe	Bath upon storage area - NW end	600 lb	
↓	17	Insulation	↓ - north end	↓	
↓	18	↓	↓ - N.E. end	↓	
07	19	gray floor epoxy	Room #11 - west end	600 lb	
↓	20	↓	↓ - north end	↓	
↓	21	↓	↓ - east end	↓	

Notes:



**SECTION 2  
SURVEY SUMMARY**

**LEAD XRF SURVEY RESULTS  
BUILDING 8**

**Phase 2 - Fullerton Mill - 2069218 AS  
2001 East Orangethorpe Avenue  
Fullerton, California**

The list materials and their components where Lead Based Paint (LBP) was detected at or in excess of the HUD/EPA standards of 1.0 mg/cm<sup>2</sup> (Los Angeles County has established a more stringent standard for lead-based paint at 0.7mg/cm<sup>2</sup>) by XRF method which is listed in the table below. All XRF readings below the regulatory defined action level are considered negative and all readings at and above these levels are considered positive.

Shot #	Unit	Room Tested	Wall	Color	Component	Substrate	Quantity	Paint Condition	Result	Neg/Pos
01	Bldg. 8	OLP Room	North	White	Wall	Metal	7,600 SF	Intact	0.00	Negative
02	Bldg. 8	OLP Room	North	White	Door Frame	Metal	1 Each	Intact	0.00	Negative
<b>03</b>	<b>Bldg. 8</b>	<b>OLP Room</b>	<b>North</b>	<b>Yellow</b>	<b>Column</b>	<b>Metal</b>	<b>10 Each</b>	<b>Intact</b>	<b>4.80</b>	<b>Positive</b>
04	Bldg. 8	OLP Room	East	Yellow	Floor Rail	Metal	380 LF	Intact	0.00	Negative
05	Bldg. 8	OLP Room	East	Blue	Door Frame	Metal	4 Each	Intact	0.00	Negative
06	Bldg. 8	OLP Room	East	Blue	Door	Metal	4 Each	Intact	0.00	Negative
<b>07</b>	<b>Bldg. 8</b>	<b>OLP Room</b>	<b>North</b>	<b>Yellow</b>	<b>Barrier</b>	<b>Metal</b>	<b>5 Each</b>	<b>Intact</b>	<b>4.80</b>	<b>Positive</b>
<b>08</b>	<b>Bldg. 8</b>	<b>OLP Room</b>	<b>North</b>	<b>Red</b>	<b>I-Beam</b>	<b>Metal</b>	<b>6 Each</b>	<b>Intact</b>	<b>4.80</b>	<b>Positive</b>
09	Bldg. 8	OLP Room	West	White	Duct	Metal	380 SF	Intact	0.00	Negative
10	Bldg. 8	OLP Room	West	White	Ceiling	Metal	7,936 SF	Intact	0.00	Negative
<b>11</b>	<b>Bldg. 8</b>	<b>OLP Room</b>	<b>West</b>	<b>White</b>	<b>Ceiling I-Beam</b>	<b>Metal</b>	<b>7,936 SF</b>	<b>Intact</b>	<b>4.80</b>	<b>Positive</b>
<b>12</b>	<b>Bldg. 8</b>	<b>OLP Room</b>	<b>West</b>	<b>White</b>	<b>Angle Bracket</b>	<b>Metal</b>	<b>7,936 SF</b>	<b>Intact</b>	<b>6.80</b>	<b>Positive</b>
13	Bldg. 8	OLP Room	West	Blue	Pipe	Metal	190 LF	Intact	0.01	Negative
14	Bldg. 8	OLP Room	South	White	Conveyor	Metal	1 Each	Intact	0.00	Negative
<b>15</b>	<b>Bldg. 8</b>	<b>OLP Room</b>	<b>South</b>	<b>Yellow</b>	<b>Shoot Ladder Rail</b>	<b>Metal</b>	<b>2 Each</b>	<b>Intact</b>	<b>4.80</b>	<b>Positive</b>
<b>16</b>	<b>Bldg. 8</b>	<b>OLP Room</b>	<b>South</b>	<b>Yellow</b>	<b>Shoot Ladder</b>	<b>Metal</b>	<b>2 Each</b>	<b>Intact</b>	<b>1.00</b>	<b>Positive</b>

**SECTION 2  
SURVEY SUMMARY**

**LEAD XRF SURVEY RESULTS  
BUILDING 8**

**Phase 2 - Fullerton Mill - 2069218 AS  
2001 East Orangethorpe Avenue  
Fullerton, California**

The list materials and their components where Lead Based Paint (LBP) was detected at or in excess of the HUD/EPA standards of 1.0 mg/cm<sup>2</sup> (Los Angeles County has established a more stringent standard for lead-based paint at 0.7mg/cm<sup>2</sup>) by XRF method which is listed in the table below. All XRF readings below the regulatory defined action level are considered negative and all readings at and above these levels are considered positive.

Shot #	Unit	Room Tested	Wall	Color	Component	Substrate	Quantity	Paint Condition	Result	Neg/Pos
17	Bldg. 8	Lift Tank Room	North	White	Tank	Metal	1 Each	Intact	0.00	Negative
<b>18</b>	<b>Bldg. 8</b>	<b>Lift Tank Room</b>	<b>North</b>	<b>White</b>	<b>Shoot Ladder</b>	<b>Metal</b>	<b>1 Each</b>	<b>Intact</b>	<b>4.80</b>	<b>Positive</b>
<b>19</b>	<b>Bldg. 8</b>	<b>Lift Tank Room</b>	<b>North</b>	<b>White</b>	<b>Shoot Ladder Rail</b>	<b>Metal</b>	<b>1 Each</b>	<b>Intact</b>	<b>1.80</b>	<b>Positive</b>
<b>20</b>	<b>Bldg. 8</b>	<b>Lift Tank Room</b>	<b>North</b>	<b>Yellow</b>	<b>Shoot Ladder</b>	<b>Metal</b>	<b>2 Each</b>	<b>Intact</b>	<b>1.40</b>	<b>Positive</b>
<b>21</b>	<b>Bldg. 8</b>	<b>Lift Tank Room</b>	<b>North</b>	<b>Yellow</b>	<b>Shoot Ladder Rail</b>	<b>Metal</b>	<b>2 Each</b>	<b>Intact</b>	<b>1.80</b>	<b>Positive</b>
22	Bldg. 8	Lift Tank Room	North	Yellow	Rail	Metal	1 Each	Intact	0.08	Negative
23	Bldg. 8	Lift Tank Room	East	Blue	Door Frame	Metal	1 Each	Intact	0.00	Negative
24	Bldg. 8	Lift Tank Room	East	Blue	Door	Metal	1 Each	Intact	0.00	Negative
25	Bldg. 8	Lift Tank Room	South	Blue	Door Frame	Metal	1 Each	Intact	0.01	Negative
26	Bldg. 8	Lift Tank Room	East	White	Ceiling	Metal	533 SF	Intact	0.00	Negative
<b>27</b>	<b>Bldg. 8</b>	<b>Lift Tank Room</b>	<b>East</b>	<b>White</b>	<b>Ceiling I-Beam</b>	<b>Metal</b>	<b>533 SF</b>	<b>Intact</b>	<b>4.80</b>	<b>Positive</b>
28	Bldg. 8	Lift Tank Room	East	White	Ceiling Pipe	Metal	54 LF	Intact	0.00	Negative
<b>29</b>	<b>Bldg. 8</b>	<b>Lift Tank Room</b>	<b>East</b>	<b>White</b>	<b>Angle Bracket</b>	<b>Metal</b>	<b>533 SF</b>	<b>Intact</b>	<b>4.80</b>	<b>Positive</b>
30	Bldg. 8	Dust Collection Room	North	White	Wall	Concrete	2,360 SF	Intact	0.00	Negative
31	Bldg. 8	Dust Collection Room	North	White	Door Frame	Metal	2 Each	Intact	0.00	Negative
32	Bldg. 8	Dust Collection Room	North	White	Door	Metal	2 Each	Intact	0.00	Negative

**SECTION 2  
SURVEY SUMMARY**

**LEAD XRF SURVEY RESULTS  
BUILDING 8**

**Phase 2 - Fullerton Mill - 2069218 AS  
2001 East Orangethorpe Avenue  
Fullerton, California**

The list materials and their components where Lead Based Paint (LBP) was detected at or in excess of the HUD/EPA standards of 1.0 mg/cm<sup>2</sup> (Los Angeles County has established a more stringent standard for lead-based paint at 0.7mg/cm<sup>2</sup>) by XRF method which is listed in the table below. All XRF readings below the regulatory defined action level are considered negative and all readings at and above these levels are considered positive.

Shot #	Unit	Room Tested	Wall	Color	Component	Substrate	Quantity	Paint Condition	Result	Neg/Pos
33	Bldg. 8	Dust Collecting Room	West	White	Door Frame	Metal	1 Each	Intact	0.00	Negative
34	Bldg. 8	Dust Collecting Room	West	White	Shoot Ladder	Metal	1 Each	Intact	0.00	Negative
<b>35</b>	<b>Bldg. 8</b>	<b>Dust Collecting Room</b>	<b>West</b>	<b>White</b>	<b>Stair Rail</b>	<b>Metal</b>	<b>1 Each</b>	<b>Intact</b>	<b>4.80</b>	<b>Positive</b>
<b>36</b>	<b>Bldg. 8</b>	<b>Dust Collecting Room</b>	<b>West</b>	<b>White</b>	<b>Stair Frame</b>	<b>Metal</b>	<b>1 Each</b>	<b>Intact</b>	<b>3.90</b>	<b>Positive</b>
<b>37</b>	<b>Bldg. 8</b>	<b>Dust Collecting Room</b>	<b>West</b>	<b>White</b>	<b>Platform Frame</b>	<b>Metal</b>	<b>1 Each</b>	<b>Intact</b>	<b>4.70</b>	<b>Positive</b>
38	Bldg. 8	Dust Collecting Room	West	White	Ceiling	Metal	870 SF	Intact	0.01	Negative
<b>39</b>	<b>Bldg. 8</b>	<b>Dust Collecting Room</b>	<b>West</b>	<b>White</b>	<b>Ceiling I-Beam</b>	<b>Metal</b>	<b>870 SF</b>	<b>Intact</b>	<b>4.70</b>	<b>Positive</b>
<b>40</b>	<b>Bldg. 8</b>	<b>Dust Collecting Room</b>	<b>West</b>	<b>White</b>	<b>Angel Bracket</b>	<b>Metal</b>	<b>870 SF</b>	<b>Intact</b>	<b>5.80</b>	<b>Positive</b>
<b>41</b>	<b>Bldg. 8</b>	<b>Dust Collecting Room</b>	<b>West</b>	<b>White</b>	<b>Platform Rail</b>	<b>Metal</b>	<b>2 Each</b>	<b>Intact</b>	<b>1.70</b>	<b>Positive</b>
42	Bldg. 8	Open Storage Area	North	White	Wall	Concrete	14,840 SF	Intact	0.00	Negative
<b>43</b>	<b>Bldg. 8</b>	<b>Open Storage Area</b>	<b>North</b>	<b>Yellow</b>	<b>Column</b>	<b>Metal</b>	<b>15 Each</b>	<b>Intact</b>	<b>4.90</b>	<b>Positive</b>
<b>44</b>	<b>Bldg. 8</b>	<b>Open Storage Area</b>	<b>North</b>	<b>Blue</b>	<b>Sliding Door</b>	<b>Metal</b>	<b>3 Each</b>	<b>Intact</b>	<b>7.90</b>	<b>Positive</b>
<b>45</b>	<b>Bldg. 8</b>	<b>Open Storage Area</b>	<b>East</b>	<b>Red</b>	<b>I-Beam</b>	<b>Metal</b>	<b>12 Each</b>	<b>Intact</b>	<b>4.90</b>	<b>Positive</b>
46	Bldg. 8	Open Storage Area	East	Yellow	Floor Rail	Metal	740 LF	Intact	0.01	Negative
47	Bldg. 8	Open Storage Area	South	Gray	Ceiling	Metal	34,200 SF	Intact	0.00	Negative
48	Bldg. 8	Open Storage Area	South	Gray	Ceiling I-Beam	Metal	34,200 SF	Intact	0.01	Negative

**SECTION 2  
SURVEY SUMMARY**

**LEAD XRF SURVEY RESULTS  
BUILDING 8**

**Phase 2 - Fullerton Mill - 2069218 AS  
2001 East Orangethorpe Avenue  
Fullerton, California**

The list materials and their components where Lead Based Paint (LBP) was detected at or in excess of the HUD/EPA standards of 1.0 mg/cm<sup>2</sup> (Los Angeles County has established a more stringent standard for lead-based paint at 0.7mg/cm<sup>2</sup>) by XRF method which is listed in the table below. All XRF readings below the regulatory defined action level are considered negative and all readings at and above these levels are considered positive.

Shot #	Unit	Room Tested	Wall	Color	Component	Substrate	Quantity	Paint Condition	Result	Neg/Pos
49	Bldg. 8	Open Storage Area	South	Grey	Ceiling Angle Bracket	Metal	34,200 SF	Intact	0.01	Negative
50	Bldg. 8	Open Storage Area	South	Grey	Pipe	Metal	100 LF	Intact	0.01	Negative
<b>52</b>	<b>Bldg. 8</b>	<b>Open Storage Area</b>	<b>East</b>	<b>Blue</b>	<b>Sliding Door</b>	<b>Metal</b>	<b>3 Each</b>	<b>Intact</b>	<b>4.80</b>	<b>Positive</b>
52	Bldg. 8	Open Storage Area	South	Yellow	Floor Rail	Metal	180 LF	Intact	0.01	Negative
53	Bldg. 8	Bath	North	White	Wall	Concrete	14,320 SF	Intact	0.01	Negative
<b>54</b>	<b>Bldg. 8</b>	<b>Bath</b>	<b>North</b>	<b>Red</b>	<b>I-Beam</b>	<b>Metal</b>	<b>20 Each</b>	<b>Intact</b>	<b>4.90</b>	<b>Positive</b>
55	Bldg. 8	Bath	North	Yellow	Barrier	Metal	1 Each	Intact	0.01	Negative
<b>56</b>	<b>Bldg. 8</b>	<b>Bath</b>	<b>North</b>	<b>Yellow</b>	<b>Rail</b>	<b>Metal</b>	<b>10 Each</b>	<b>Intact</b>	<b>6.80</b>	<b>Positive</b>
<b>57</b>	<b>Bldg. 8</b>	<b>Bath</b>	<b>East</b>	<b>Yellow</b>	<b>Stair Rail</b>	<b>Metal</b>	<b>2 Each</b>	<b>Intact</b>	<b>4.90</b>	<b>Positive</b>
58	Bldg. 8	Bath	East	White	Stair Frame	Metal	2 Each	Intact	0.01	Negative
<b>59</b>	<b>Bldg. 8</b>	<b>Bath</b>	<b>South</b>	<b>Yellow</b>	<b>Column</b>	<b>Metal</b>	<b>5 Each</b>	<b>Intact</b>	<b>4.90</b>	<b>Positive</b>
<b>60</b>	<b>Bldg. 8</b>	<b>Bath</b>	<b>East</b>	<b>Blue</b>	<b>Sliding Door</b>	<b>Metal</b>	<b>7 Each</b>	<b>Intact</b>	<b>5.70</b>	<b>Positive</b>
<b>61</b>	<b>Bldg. 8</b>	<b>Bath</b>	<b>East</b>	<b>Yellow</b>	<b>Floor</b>	<b>Concrete</b>	<b>167 LF</b>	<b>Intact</b>	<b>1.80</b>	<b>Positive</b>
62	Bldg. 8	Bath	East	White	Ceiling	Metal	31,987 SF	Intact	0.01	Negative
<b>63</b>	<b>Bldg. 8</b>	<b>Bath</b>	<b>East</b>	<b>White</b>	<b>Ceiling I-Beam</b>	<b>Metal</b>	<b>31,987 SF</b>	<b>Intact</b>	<b>4.90</b>	<b>Positive</b>
<b>64</b>	<b>Bldg. 8</b>	<b>Bath</b>	<b>East</b>	<b>White</b>	<b>Ceiling Angle Bracket</b>	<b>Metal</b>	<b>31,987 SF</b>	<b>Intact</b>	<b>5.80</b>	<b>Positive</b>



**SECTION 2**  
**SURVEY SUMMARY**

---

**LEAD XRF SURVEY RESULTS**  
**BUILDING 8**

**Phase 2 - Fullerton Mill - 2069218 AS**  
**2001 East Orangethorpe Avenue**  
**Fullerton, California**

The list materials and their components where Lead Based Paint (LBP) was detected at or in excess of the HUD/EPA standards of 1.0 mg/cm<sup>2</sup> (Los Angeles County has established a more stringent standard for lead-based paint at 0.7mg/cm<sup>2</sup>) by XRF method which is listed in the table below. All XRF readings below the regulatory defined action level are considered negative and all readings at and above these levels are considered positive.

Shot #	Unit	Room Tested	Wall	Color	Component	Substrate	Quantity	Paint Condition	Result	Neg/Pos
65	Bldg. 8	Bath	East	White	Duct	Metal	358 LF	Intact	0.01	Negative
66	Bldg. 8	Bath	East	Red	Pipe	Metal	358 LF	Intact	0.01	Negative





## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509518  
**Samples Submitted:** 18  
**Sample Collection Date:** 12/7/2018  
**Laboratory Receipt Date:** 12/7/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #8 Roof Air Washer Bldg - N.  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 2 of 5

### TEST DATA

**Laboratory ID#:** 1509518-005      **Client Sample #:** 5

**Sample Material and Location:** Yellow Pipe Insulation Air Washer Room - S.W. End

**Sample Characteristics:** Yellow Fibrous Homogenous  
**Misc. Components Observed:** 5% Non-Fibrous Material  
95% Non-Fibrous Material Fibrous Glass

**Asbestos Observed (%):**      **Date Analyzed:** 12/7/2018      **Total Asbestos (%)** None Detected  
**Analyst:** Dennis Liu

### TEST DATA

**Laboratory ID#:** 1509518-006      **Client Sample #:** 6

**Sample Material and Location:** Yellow Pipe Insulation Air Washer Room - N.W. End

**Sample Characteristics:** Yellow Fibrous Inhomogenous  
**Misc. Components Observed:** 5% Non-Fibrous Material  
95% Fibrous Glass

**Asbestos Observed (%):**      **Date Analyzed:** 12/7/2018      **Total Asbestos (%)** None Detected  
**Analyst:** Dennis Liu

### TEST DATA

**Laboratory ID#:** 1509518-007      **Client Sample #:** 7

**Sample Material and Location:** Black/White Pipe Wrap Air Washer Room - East End

**Sample Characteristics:** Black White Fibrous Inhomogenous  
**Misc. Components Observed:** 55% Non-Fibrous Material  
40% Cellulose

**Asbestos Observed (%):**      **Date Analyzed:** 12/7/2018      **Total Asbestos (%)** 5%  
**Analyst:** Dennis Liu      Chrysotile 5%

### TEST DATA

**Laboratory ID#:** 1509518-008      **Client Sample #:** 8

**Sample Material and Location:** Black/White Pipe Wrap Air Washer Room - S.W. End

**Sample Characteristics:** Black White Fibrous Inhomogenous  
**Misc. Components Observed:** 55% Non-Fibrous Material  
40% Cellulose

**Asbestos Observed (%):**      **Date Analyzed:** 12/7/2018      **Total Asbestos (%)** 5%  
**Analyst:** Dennis Liu      Chrysotile 5%



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509518  
**Samples Submitted:** 18  
**Sample Collection Date:** 12/7/2018  
**Laboratory Receipt Date:** 12/7/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #8 Roof Air Washer Bldg - N.  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 3 of 5

### TEST DATA

**Laboratory ID#:** 1509518-009      **Client Sample #:** 9

**Sample Material and Location:** Black/White Pipe Wrap Air Washer Room - N.W. End

**Sample Characteristics:** Black White Fibrous Inhomogenous  
**Misc. Components Observed:** 55% Non-Fibrous Material  
40% Cellulose

**Asbestos Observed (%):** Chrysotile      5%      **Total Asbestos (%)**      5%  
**Analyst:** Dennis Liu      **Date Analyzed:** 12/7/2018

### TEST DATA

**Laboratory ID#:** 1509518-010      **Client Sample #:** 10

**Sample Material and Location:** Black Vibration Damper Air Washer Room - S.E. End

**Sample Characteristics:** Black Fibrous Inhomogenous  
**Misc. Components Observed:** 80% Non-Fibrous Material  
20% Synthetic

**Asbestos Observed (%):**      **Total Asbestos (%)**      None Detected  
**Analyst:** Dennis Liu      **Date Analyzed:** 12/7/2018

### TEST DATA

**Laboratory ID#:** 1509518-011      **Client Sample #:** 11

**Sample Material and Location:** Black Vibration Damper Air Washer Room - South End

**Sample Characteristics:** Black Fibrous Inhomogenous  
**Misc. Components Observed:** 80% Non-Fibrous Material  
20% Synthetic

**Asbestos Observed (%):**      **Total Asbestos (%)**      None Detected  
**Analyst:** Dennis Liu      **Date Analyzed:** 12/7/2018

### TEST DATA

**Laboratory ID#:** 1509518-012      **Client Sample #:** 12

**Sample Material and Location:** Black Vibration Damper Air Washer Room - S.W. End

**Sample Characteristics:** Black Fibrous Inhomogenous  
**Misc. Components Observed:** 80% Non-Fibrous Material  
20% Synthetic

**Asbestos Observed (%):**      **Total Asbestos (%)**      None Detected  
**Analyst:** Dennis Liu      **Date Analyzed:** 12/7/2018



**Analytical Report**

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509518  
**Samples Submitted:** 18  
**Sample Collection Date:** 12/7/2018  
**Laboratory Receipt Date:** 12/7/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #8 Roof Air Washer Bldg - N.  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 4 of 5

**TEST DATA**

---

**Laboratory ID#:** 1509518-013                      **Client Sample #:** 13

**Sample Material and Location:** Gray Wall Panels Air Washer Room - North End

**Sample Characteristics:** Grey Fibrous Inhomogenous  
**Misc. Components Observed:** 40% Non-Fibrous Material  
40% Cellulose

**Asbestos Observed (%):** Chrysotile                      20%                      **Total Asbestos (%)**                      20%  
**Analyst:** Dennis Liu                      **Date Analyzed:** 12/7/2018

**TEST DATA**

---

**Laboratory ID#:** 1509518-014                      **Client Sample #:** 14

**Sample Material and Location:** Gray Wall Panels Air Washer Room - West End

**Sample Characteristics:** Grey Fibrous Inhomogenous  
**Misc. Components Observed:** 40% Non-Fibrous Material  
40% Cellulose

**Asbestos Observed (%):** Chrysotile                      20%                      **Total Asbestos (%)**                      20%  
**Analyst:** Dennis Liu                      **Date Analyzed:** 12/7/2018

**TEST DATA**

---

**Laboratory ID#:** 1509518-015                      **Client Sample #:** 15

**Sample Material and Location:** Gray Wall Panels Air Washer Room - South End

**Sample Characteristics:** Grey Fibrous Inhomogenous  
**Misc. Components Observed:** 40% Non-Fibrous Material  
40% Cellulose

**Asbestos Observed (%):** Chrysotile                      20%                      **Total Asbestos (%)**                      20%  
**Analyst:** Dennis Liu                      **Date Analyzed:** 12/7/2018

**TEST DATA**

---

**Laboratory ID#:** 1509518-016                      **Client Sample #:** 16

**Sample Material and Location:** Brown Wall Insulation Air Washer Room - North End

**Sample Characteristics:** Brown Fibrous Inhomogenous  
**Misc. Components Observed:** 60% Non-Fibrous Material  
40% Cellulose

**Asbestos Observed (%):**                      **Total Asbestos (%)**                      None Detected  
**Analyst:** Dennis Liu                      **Date Analyzed:** 12/7/2018



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509518  
**Samples Submitted:** 18  
**Sample Collection Date:** 12/7/2018  
**Laboratory Receipt Date:** 12/7/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #8 Roof Air Washer Bldg - N.  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 5 of 5

### TEST DATA

**Laboratory ID#:** 1509518-017      **Client Sample #:** 17

**Sample Material and Location:** Brown Wall Insulation Air Washer Room - West End

**Sample Characteristics:** Brown Fibrous Inhomogenous  
**Misc. Components Observed:** 60% Non-Fibrous Material  
40% Cellulose

**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 12/7/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509518-018      **Client Sample #:** 18

**Sample Material and Location:** Brown Wall Insulation Air Washer Room - South End

**Sample Characteristics:** Brown Fibrous Inhomogenous  
**Misc. Components Observed:** 60% Non-Fibrous Material  
40% Cellulose

**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 12/7/2018

**Total Asbestos (%)** None Detected

Samples were analyzed by Calibrated Visual Estimation (CVE). Analyses by CVE have a detection limit of 1% asbestos by relative area and may not be consistently reliable below this limit or for asbestos with fiber diameter thinner than the resolving capacity of PLM without further analysis by another independent method. A test result of less than (<) 1% by CVE means asbestos was observed in the sample but is visually estimated to be below the reportable limit of 1%. The laboratory references interim method EPA 600/M4-82-020 (Interim Method) for fiber identification, 400 point counts, and composite reporting. EPA method 600/R-93/116 is referenced for analysis of non-insulation materials, sub-layers, expanded and modified point counts, CVE and subsequent data reporting. Samples containing distinct layers that can be reliably separated are analyzed and reported as separate unless requested in writing. The test data presented apply only to the items submitted. Count for samples submitted is indicative of total layers observed and may vary from actual analysis for positive stop requests. ATEL, LLC is a NIST-NVLAP and CA-ELAP Accredited laboratory (ID# 201073-0 and #2971, respectively). This report must not be reproduced, unless in its entirety, without the written consent of ATEL, LLC. Per NIST-NVLAP 150 Annex A: This report shall not be used to claim product certification, approval or endorsement by NVLAP, NIST, or any agency of the federal government.

Unless indicated, samples were received in acceptable condition. Sample retention time is 30 days from issuing this report unless requested otherwise.

**Analyst Signature:**

-Dennis Liu

**Approved Signatory:**

-Chris Turton

**Reported On:** 12/8/2018



1509518

Asbestos Laboratory

**Your Contact Information**

Company Name (if by company): H2 Environmental Consulting Services, Inc.  
 Personal/Company Address: 13122 6th Street, Chino, CA 91710  
 Contact Person: Amy De Santiago  
 Contact Information: Main: 909-628-0369 E-Mail: labresults@h2env.com  
 Mobile: \_\_\_\_\_ Fax: 909-613-5845  
 How should we send your result Verbal  Verbal  E-mail  Fax

*\*If verbal results are requested, you must also select a second form of delivery.*

**Project Information**

Project Name: Limberly Clark  
 Project #: 2069218.45  
 Project Location: Bldg 8 Roof Air washer Bldg North  
 PO#: \_\_\_\_\_ Claim#: \_\_\_\_\_  
 Date Sampled: 12/7/18 Time Sampled: 8am

Analytical Type(s) Requested	Turnaround Time*
Asbestos in Bulk Materials, EPA 600/R-93/116, 600/M4-82-020	*Business Hrs: 0800-1700 Mon-Fri.
Routine, Calibrated Visual Estimation <input checked="" type="checkbox"/>	Rush 3 Business Hrs* <input type="checkbox"/>
Point Count: 400pts <input type="checkbox"/>	8 Business Hrs* <input type="checkbox"/>
1000pts <input type="checkbox"/>	Expedited 24 Business Hrs <input checked="" type="checkbox"/>
Gravimetric Reduction (72hr Minimum) <input type="checkbox"/>	Routine 48 Business Hrs <input type="checkbox"/>
Fiber Count In Sampling Cartridge (25mm MCE)	72 Business Hrs <input type="checkbox"/>
Asbestos-like, NIOSH 7400 A Rules <input type="checkbox"/>	Standard 5 Business Days <input type="checkbox"/>
Rotometer Calibration (Low and High Flow Rotometers) <input type="checkbox"/>	*3hr TAT: Samples must be submitted by 2pm for same day results
	*8hr TAT: Samples must be submitted by 9am for same day results

Special Instructions: \_\_\_\_\_

**Sample Information**

Sample ID #	Description/Material Type	Location	Flow Rate	Start Time	Stop Time	Volume (L)
	Please See Attached					

For more samples, please continue onto supplemental form. Page # Indication in upper-right-hand of form.

**Chain of Custody**

Relinquished By: Albert Sanchez Date and Time: 12/7/18 8:41  
 Received By: \_\_\_\_\_ Date and Time: \_\_\_\_\_  
 Relinquished By: [Signature] Date and Time: \_\_\_\_\_  
 Received By: \_\_\_\_\_ Date and Time: 12/7/18 3:40 pm



**H2 ENVIRONMENTAL CONSULTING SERVICES, INC.**

**Bulk Sampling Form**

Stop at First Positive    24 Hour turn around    Rush turn around (4 Hours)  
 Do Not Layer Samples

CLIENT Kimberly Clark	PROJECT NO. 2069218 AS		
PROJECT ID Bldg #18 Roof Air washer Bldg. - North	DATE 12/11/18	PAGE 1	OF 1
PROJECT LOCATION 2001 E. Orange Avenue, Fullerton, CA	INSPECTOR A Sanchez		

GRP. NO.	SAMP. NO.	MATERIAL DESCRIPTION	LOCATION OF SAMPLE	QTY	% POS
01	01	white pipe wrap	Air washer Rm. - East end	100φ	
↓	02	↓	↓ - S.W. end	↓	
↓	03	↓	↓ - N.W. end	↓	
02	04	yellow pipe insulation	Air washer Rm. - East end	100φ	
↓	05	↓	↓ - S.W. end	↓	
↓	06	↓	↓ - N.W. end	↓	
03	07	Blk/white pipe	Air washer Rm. - East end	100φ	
↓	08	wrap	↓ - S.W. end	↓	
↓	09	↓	↓ - N.W. end	↓	
04	10	Blk vibration	Air washer Rm. - S.E. end	50φ	
↓	11	Damper	↓ - South end	↓	
↓	12	↓	↓ - S.W. end	↓	
05	13	gray wall panels	Air washer Rm. - North end	3,000φ	
↓	14	↓	↓ - West end	↓	
↓	15	↓	↓ - South end	↓	
06	16	Brn. wall insulation	Air washer Rm. - North end	3,000φ	
↓	17	↓	↓ - West end	↓	
↓	18	↓	↓ - South end	↓	

Notes:





## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

<b>Client Name:</b>	H2 Environmental Consulting Services	<b>Report Number:</b>	1509519
<b>Client Address:</b>	13122 6th Street Chino, CA 91710	<b>Samples Submitted:</b>	18
<b>Project ID:</b>	2069218AS	<b>Sample Collection Date:</b>	12/7/2018
<b>Project Name:</b>	Kimberly Clark - Bldg #8 Roof Air Washer Bldg - S.	<b>Laboratory Receipt Date:</b>	12/7/2018
<b>Project Location:</b>	2001 E. Orangethorpe Ave Fullerton, CA	<b>Page:</b>	1 of 5

### TEST DATA

<b>Laboratory ID#:</b>	1509519-001	<b>Client Sample #:</b>	1
<b>Sample Material and Location:</b>	White Pipe Wrap Air Washer Room - South End		
<b>Sample Characteristics:</b>	White Fibrous Inhomogenous		
<b>Misc. Components Observed:</b>	40% Non-Fibrous Material 20% Fibrous Glass 40% Cellulose		
<b>Asbestos Observed (%):</b>		<b>Date Analyzed:</b>	12/7/2018
<b>Analyst:</b>	Chris Turton	<b>Total Asbestos (%):</b>	None Detected

### TEST DATA

<b>Laboratory ID#:</b>	1509519-002	<b>Client Sample #:</b>	2
<b>Sample Material and Location:</b>	White Pipe Wrap Air Washer Room - S.W. End		
<b>Sample Characteristics:</b>	White Fibrous Inhomogenous		
<b>Misc. Components Observed:</b>	40% Non-Fibrous Material 20% Fibrous Glass 40% Cellulose		
<b>Asbestos Observed (%):</b>		<b>Date Analyzed:</b>	12/7/2018
<b>Analyst:</b>	Chris Turton	<b>Total Asbestos (%):</b>	None Detected

### TEST DATA

<b>Laboratory ID#:</b>	1509519-003	<b>Client Sample #:</b>	3
<b>Sample Material and Location:</b>	White Pipe Wrap Air Washer Room - N.W. End		
<b>Sample Characteristics:</b>	White Fibrous Inhomogenous		
<b>Misc. Components Observed:</b>	40% Non-Fibrous Material 20% Fibrous Glass 40% Cellulose		
<b>Asbestos Observed (%):</b>		<b>Date Analyzed:</b>	12/7/2018
<b>Analyst:</b>	Chris Turton	<b>Total Asbestos (%):</b>	None Detected

### TEST DATA

<b>Laboratory ID#:</b>	1509519-004	<b>Client Sample #:</b>	4
<b>Sample Material and Location:</b>	Yellow Pipe Insulation Air Washer Room - South End		
<b>Sample Characteristics:</b>	Yellow Fibrous Homogenous		
<b>Misc. Components Observed:</b>	5% Non-Fibrous Material 95% Fibrous Glass		
<b>Asbestos Observed (%):</b>		<b>Date Analyzed:</b>	12/7/2018
<b>Analyst:</b>	Chris Turton	<b>Total Asbestos (%):</b>	None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509519  
**Samples Submitted:** 18  
**Sample Collection Date:** 12/7/2018  
**Laboratory Receipt Date:** 12/7/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #8 Roof Air Washer Bldg - S.  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 2 of 5

### TEST DATA

**Laboratory ID#:** 1509519-005      **Client Sample #:** 5

**Sample Material and Location:** Yellow Pipe Insulation Air Washer Room - S.W. End

**Sample Characteristics:** Yellow Fibrous Homogenous  
**Misc. Components Observed:** 5% Non-Fibrous Material  
95% Fibrous Glass

**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 12/7/2018      **Total Asbestos (%):** None Detected

### TEST DATA

**Laboratory ID#:** 1509519-006      **Client Sample #:** 6

**Sample Material and Location:** Yellow Pipe Insulation Air Washer Room - N.W. End

**Sample Characteristics:** Yellow Fibrous Homogenous  
**Misc. Components Observed:** 5% Non-Fibrous Material  
95% Fibrous Glass

**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 12/7/2018      **Total Asbestos (%):** None Detected

### TEST DATA

**Laboratory ID#:** 1509519-007      **Client Sample #:** 7

**Sample Material and Location:** White Vibration Damper Air Washer Room - N.E. End

**Sample Characteristics:** White Fibrous Inhomogenous  
**Misc. Components Observed:** 80% Non-Fibrous Material  
20% Synthetic

**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 12/7/2018      **Total Asbestos (%):** None Detected

### TEST DATA

**Laboratory ID#:** 1509519-008      **Client Sample #:** 8

**Sample Material and Location:** White Vibration Damper Air Washer Room - North Center

**Sample Characteristics:** White Fibrous Inhomogenous  
**Misc. Components Observed:** 80% Non-Fibrous Material  
20% Synthetic

**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 12/7/2018      **Total Asbestos (%):** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509519  
**Samples Submitted:** 18  
**Sample Collection Date:** 12/7/2018  
**Laboratory Receipt Date:** 12/7/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #8 Roof Air Washer Bldg - S.  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 3 of 5

### TEST DATA

---

**Laboratory ID#:** 1509519-009      **Client Sample #:** 9

**Sample Material and Location:** White Vibration Damper Air Washer Room - N.W. End

**Sample Characteristics:** White Fibrous Inhomogenous  
**Misc. Components Observed:** 80% Non-Fibrous Material  
20% Synthetic

**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 12/7/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509519-010      **Client Sample #:** 10

**Sample Material and Location:** Black Gasket Sealant Air Washer Room - N.End

**Sample Characteristics:** Black Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 12/7/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509519-011      **Client Sample #:** 11

**Sample Material and Location:** Black Gasket Sealant Air Washer Room - North End

**Sample Characteristics:** Black Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 12/7/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509519-012      **Client Sample #:** 12

**Sample Material and Location:** Black Gasket Sealant Air Washer Room - N.W. End

**Sample Characteristics:** Black Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 12/7/2018

**Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509519  
**Samples Submitted:** 18  
**Sample Collection Date:** 12/7/2018  
**Laboratory Receipt Date:** 12/7/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #8 Roof Air Washer Bldg - S.  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 4 of 5

### TEST DATA

---

**Laboratory ID#:** 1509519-013      **Client Sample #:** 13

**Sample Material and Location:** Gray Caulking on Wall Air Washer Room - N.W. End

**Sample Characteristics:** Gray Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 12/7/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509519-014      **Client Sample #:** 14

**Sample Material and Location:** Gray Caulking on Wall Air Washer Room - N.E. End

**Sample Characteristics:** Gray Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 12/7/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509519-015      **Client Sample #:** 15

**Sample Material and Location:** Gray Caulking on Wall Air Washer Room - S.W. End

**Sample Characteristics:** Gray Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 12/7/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509519-016      **Client Sample #:** 16

**Sample Material and Location:** Black Foam Cover Air Washer Room - East End

**Sample Characteristics:** Black Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 12/7/2018

**Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509519  
**Samples Submitted:** 18  
**Sample Collection Date:** 12/7/2018  
**Laboratory Receipt Date:** 12/7/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #8 Roof Air Washer Bldg - S.  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 5 of 5

### TEST DATA

**Laboratory ID#:** 1509519-017 **Client Sample #:** 17

**Sample Material and Location:** Black Foam Cover Air Washer Room - North End

**Sample Characteristics:** Black Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton **Date Analyzed:** 12/7/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509519-018 **Client Sample #:** 18

**Sample Material and Location:** Black Foam Cover Air Washer Room - West End

**Sample Characteristics:** Black Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton **Date Analyzed:** 12/7/2018

**Total Asbestos (%)** None Detected

Samples were analyzed by Calibrated Visual Estimation (CVE). Analyses by CVE have a detection limit of 1% asbestos by relative area and may not be consistently reliable below this limit or for asbestos with fiber diameter thinner than the resolving capacity of PLM without further analysis by another independent method. A test result of less than (<) 1% by CVE means asbestos was observed in the sample but is visually estimated to be below the reportable limit of 1%. The laboratory references interim method EPA 600/M4-82-020 (Interim Method) for fiber identification, 400 point counts, and composite reporting. EPA method 600/R-93/116 is referenced for analysis of non-insulation materials, sub-layers, expanded and modified point counts, CVE and subsequent data reporting. Samples containing distinct layers that can be reliably separated are analyzed and reported as separate unless requested in writing. The test data presented apply only to the items submitted. Count for samples submitted is indicative of total layers observed and may vary from actual analysis for positive stop requests. ATEL, LLC is a NIST-NVLAP and CA-ELAP Accredited laboratory (ID# 201073-0 and #2971, respectively). This report must not be reproduced, unless in its entirety, without the written consent of ATEL, LLC. Per NIST-NVLAP 150 Annex A: This report shall not be used to claim product certification, approval or endorsement by NVLAP, NIST, or any agency of the federal government.

Unless indicated, samples were received in acceptable condition. Sample retention time is 30 days from issuing this report unless requested otherwise.

**Analyst Signature:**  -Chris Turton

**Approved Signatory:**  -Dennis Liu

**Reported On:** 12/8/2018



# ENVIRONMENTAL CONSULTING SERVICES, INC.

## Bulk Sampling Form

Stop at First Positive  
  24 Hour turn around  
  Rush turn around (4 Hours)  
 Do Not Layer Samples

CLIENT <i>Kimberly Clark</i>	PROJECT NO. <i>2069218AS</i>
PROJECT ID <i>Bldg 9 Roof Air washer Bldg - South</i>	DATE <i>12/7/14</i>
PROJECT LOCATION <i>2001 E. Orange Avenue, Fullerton, CA</i>	INSPECTOR <i>A. Sanchez</i>

GRP. NO.	SAMP. NO.	MATERIAL DESCRIPTION	LOCATION OF SAMPLE	QTY	% POS
01	01	white pipe wrap	Air washer Rm - South end	100φ	
↓	02	↓	↓ - S.W. end	↓	
↓	03	↓	↓ - N.W. end	↓	
02	04	yellow pipe insulation	Air washer Rm - South end	100φ	
↓	05	↓	↓ - S.W. end	↓	
↓	06	↓	↓ - N.W. end	↓	
03	07	white vibration	Air washer Rm <del>N.E. end</del>	50φ	
↓	08	Dumper	↓ - <del>North end</del>	↓	
↓	09		↓ - <del>North end</del>	↓	
04	10	Blk Gasket Sealant	Air washer Rm - N. end	100φ	
↓	11	↓	↓ - North end	↓	
↓	12	↓	↓ - N.W. end	↓	
05	13	Grey caulking on	Air washer Rm - N.W. end	50φ	
↓	14	wall	↓ - N.E. end	↓	
↓	15	↓	↓ - S.W. end	↓	
06	16	Blk Foam Cover	Air washer Rm - East end	100φ	
↓	17	↓	↓ - North end	↓	
↓	18	↓	↓ - West end	↓	

Notes:



1509519

Asbestos Laboratory

**Your Contact Information**

Company Name (if by company): H2 Environmental Consulting Services, Inc.  
 Personal/Company Address: 13122 6th Street, Chino, CA 91710  
 Contact Person: Amy De Santiago  
 Contact Information: Main: 909-628-0369 E-Mail: labresults@h2env.com  
 Mobile: \_\_\_\_\_ Fax: 909-613-5845  
 How should we send your result Verbal  Verbal  E-mail  Fax

*\*If verbal results are requested, you must also select a second form of delivery.*

**Project Information**

Project Name: Kimberly Clark  
 Project #: 2069218AS  
 Project Location: Bldg 8 Roof Air Washer Bldg - South  
 PO#: \_\_\_\_\_ Claim# \_\_\_\_\_  
 Date Sampled: 12/7/18 Time Sampled: 1pm

Analytical Type(s) Requested	Turnaround Time*
Asbestos in Bulk Materials, EPA 600/R-93/116, 600/M4-82-020	*Business Hrs: 0800-1700 Mon-Fri.
Routine, Calibrated Visual Estimation <input checked="" type="checkbox"/>	Rush 3 Business Hrs* <input type="checkbox"/>
Point Count: 400pts <input type="checkbox"/>	8 Business Hrs* <input type="checkbox"/>
1000pts <input type="checkbox"/>	
Gravimetric Reduction (72hr Minimum) <input type="checkbox"/>	Expedited 24 Business Hrs <input checked="" type="checkbox"/>
	Routine 48 Business Hrs <input type="checkbox"/>
Fiber Count In Sampling Cartridge (25mm MCE)	72 Business Hrs <input type="checkbox"/>
Asbestos-like, NIOSH 7400 A Rules <input type="checkbox"/>	Standard 5 Business Days <input type="checkbox"/>
Rotometer Calibration (Low and High Flow Rotometers) <input type="checkbox"/>	*3hr TAT: Samples must be submitted by 2pm for same day results
	*8hr TAT: Samples must be submitted by 9am for same day results

Special Instructions: \_\_\_\_\_

**Sample Information**

Sample ID #	Description/Material Type	Location	Flow Rate	Start Time	Stop Time	Volume (L)
	Please See Attached					

For more samples, please continue onto supplemental form. Page # Indication in upper-right-hand of form.

**Chain of Custody**

Relinquished By: Alfredo Sanchez Date and Time: 12/7/18 1pm  
 Received By: \_\_\_\_\_ Date and Time: \_\_\_\_\_  
 Relinquished By: \_\_\_\_\_ Date and Time: \_\_\_\_\_  
 Received By: Chris Penta Date and Time: 12/7/18 3:40 pm

**SECTION 2**  
**SURVEY SUMMARY**

**LEAD XRF SURVEY RESULTS**  
**BUILDING 8, ROOF AIR WASHER BUILDING**

**Phase 2 - Fullerton Mill - 2069218 AS**  
**2001 East Orangethorpe Avenue**  
**Fullerton, California**

The list materials and their components where Lead Based Paint (LBP) was detected at or in excess of the HUD/EPA standards of 1.0 mg/cm<sup>2</sup> (Los Angeles County has established a more stringent standard for lead-based paint at 0.7mg/cm<sup>2</sup>) by XRF method which is listed in the table below. All XRF readings below the regulatory defined action level are considered negative and all readings at and above these levels are considered positive.

Shot #	Unit	Room Tested	Wall	Color	Component	Substrate	Quantity	Paint Condition	Result	Neg/Pos
<b>01</b>	<b>Air Washer Bldg. South</b>	<b>Exterior</b>	<b>North</b>	<b>Yellow</b>	<b>Stair Rail</b>	<b>Metal</b>	<b>1 Each</b>	<b>Intact</b>	<b>4.90</b>	<b>Positive</b>
<b>02</b>	<b>Air Washer Bldg. South</b>	<b>Exterior</b>	<b>North</b>	<b>Yellow</b>	<b>Staircase</b>	<b>Metal</b>	<b>1 Each</b>	<b>Intact</b>	<b>4.80</b>	<b>Positive</b>
03	Air Washer Bldg. South	Exterior	North	Blue	Wall	Metal	1,320 SF	Intact	0.00	Negative
04	Air Washer Bldg. South	Exterior	North	Blue	Door	Metal	1 Each	Intact	0.00	Negative
05	Air Washer Bldg. South	Exterior	South	Blue	Louver	Metal	6 Each	Intact	0.01	Negative
<b>06</b>	<b>Air Washer Bldg. South</b>	<b>Exterior</b>	<b>South</b>	<b>Blue</b>	<b>Louver Frame</b>	<b>Metal</b>	<b>6 Each</b>	<b>Intact</b>	<b>4.80</b>	<b>Positive</b>
07	Air Washer Bldg. South	Exterior	South	White	Duct	Metal	1 Each	Intact	0.00	Negative
<b>08</b>	<b>Air Washer Bldg. South</b>	<b>Interior</b>	<b>North</b>	<b>Yellow</b>	<b>Stair Rail</b>	<b>Metal</b>	<b>1 Each</b>	<b>Intact</b>	<b>1.80</b>	<b>Positive</b>
09	Air Washer Bldg. South	Interior	North	Yellow	Staircase	Metal	1 Each	Intact	0.01	Negative
10	Air Washer Bldg. South	Interior	North	Gray	Wall	Metal	1,650 SF	Intact	0.00	Negative
<b>11</b>	<b>Air Washer Bldg. South</b>	<b>Interior</b>	<b>North</b>	<b>Gray</b>	<b>I-Beam</b>	<b>Metal</b>	<b>4 Each</b>	<b>Intact</b>	<b>4.60</b>	<b>Positive</b>
12	Air Washer Bldg. South	Interior	South	Gray	Ceiling	Metal	600 SF	Intact	0.01	Negative
<b>13</b>	<b>Air Washer Bldg. South</b>	<b>Interior</b>	<b>South</b>	<b>Gray</b>	<b>Ceiling I-Beam</b>	<b>Metal</b>	<b>150 SF</b>	<b>Intact</b>	<b>4.90</b>	<b>Positive</b>
14	Air Washer Bldg. North	Exterior	North	Blue	Wall	Metal	960 SF	Intact	0.00	Negative
15	Air Washer Bldg. North	Exterior	North	Blue	Louver	Metal	3 Each	Intact	0.01	Negative
<b>16</b>	<b>Air Washer Bldg. North</b>	<b>Exterior</b>	<b>North</b>	<b>Blue</b>	<b>Louver Frame</b>	<b>Metal</b>	<b>3 Each</b>	<b>Intact</b>	<b>9.10</b>	<b>Positive</b>



**SECTION 2  
SURVEY SUMMARY**

**LEAD XRF SURVEY RESULTS  
BUILDING 8, ROOF AIR WASHER BUILDING**

**Phase 2 - Fullerton Mill - 2069218 AS  
2001 East Orangethorpe Avenue  
Fullerton, California**

The list materials and their components where Lead Based Paint (LBP) was detected at or in excess of the HUD/EPA standards of 1.0 mg/cm<sup>2</sup> (Los Angeles County has established a more stringent standard for lead-based paint at 0.7mg/cm<sup>2</sup>) by XRF method which is listed in the table below. All XRF readings below the regulatory defined action level are considered negative and all readings at and above these levels are considered positive.

Shot #	Unit	Room Tested	Wall	Color	Component	Substrate	Quantity	Paint Condition	Result	Neg/Pos
17	Air Washer Bldg. North	Exterior	North	Red	Fire Hydrant Door	Metal	1 Each	Intact	0.01	Negative
18	Air Washer Bldg. North	Exterior	North	Blue	Edge Metal	Metal	120 LF	Intact	0.01	Negative
19	Air Washer Bldg. North	Exterior	South	White	Duct	Metal	1 Each	Intact	0.00	Negative
<b>20</b>	<b>Air Washer Bldg. North</b>	<b>Interior</b>	<b>North</b>	<b>Yellow</b>	<b>Stair Rail</b>	<b>Metal</b>	<b>1 Each</b>	<b>Intact</b>	<b>4.80</b>	<b>Positive</b>
21	Air Washer Bldg. North	Interior	North	Yellow	Stair Case	Metal	1 Each	Intact	0.00	Negative
<b>22</b>	<b>Air Washer Bldg. North</b>	<b>Interior</b>	<b>North</b>	<b>Yellow</b>	<b>Rail</b>	<b>Metal</b>	<b>1 Each</b>	<b>Intact</b>	<b>1.80</b>	<b>Positive</b>
23	Air Washer Bldg. North	Interior	North	Gray	Wall	Metal	1,800 SF	Intact	0.00	Negative
24	Air Washer Bldg. North	Interior	South	Gray	Ceiling	Metal	900 SF	Intact	0.00	Negative
<b>25</b>	<b>Air Washer Bldg. North</b>	<b>Interior</b>	<b>South</b>	<b>Gray</b>	<b>I-Beam</b>	<b>Metal</b>	<b>225 SF</b>	<b>Intact</b>	<b>4.20</b>	<b>Positive</b>

**SECTION 2  
SURVEY SUMMARY**

**LEAD XRF SURVEY RESULTS  
BUILDING 9**

**Phase 2 - Fullerton Mill - 2069218 AS  
2001 East Orangethorpe Avenue  
Fullerton, California**

The list materials and their components where Lead Based Paint (LBP) was detected at or in excess of the HUD/EPA standards of 1.0 mg/cm<sup>2</sup> (Los Angeles County has established a more stringent standard for lead-based paint at 0.7mg/cm<sup>2</sup>) by XRF method which is listed in the table below. All XRF readings below the regulatory defined action level are considered negative and all readings at and above these levels are considered positive.

Shot #	Unit	Room Tested	Wall	Color	Component	Substrate	Quantity	Paint Condition	Result	Neg/Pos
<b>01</b>	<b>Bldg. 9</b>	<b>Platform Area</b>	<b>East</b>	<b>White</b>	<b>Staircase</b>	<b>Metal</b>	<b>1 Each</b>	<b>Intact</b>	<b>4.20</b>	<b>Positive</b>
<b>02</b>	<b>Bldg. 9</b>	<b>Platform Area</b>	<b>East</b>	<b>White</b>	<b>Stair Rail</b>	<b>Metal</b>	<b>1 Each</b>	<b>Intact</b>	<b>4.80</b>	<b>Positive</b>
03	Bldg. 9	Platform Area	East	White	Wall	Concrete	1,024 SF	Intact	0.01	Negative
04	Bldg. 9	Platform Area	East	White	Ceiling	Metal	80,000 SF	Intact	0.01	Negative
<b>05</b>	<b>Bldg. 9</b>	<b>Platform Area</b>	<b>East</b>	<b>White</b>	<b>Ceiling I-Beam</b>	<b>Metal</b>	<b>4,000 SF</b>	<b>Intact</b>	<b>4.80</b>	<b>Positive</b>
<b>06</b>	<b>Bldg. 9</b>	<b>Platform Area</b>	<b>East</b>	<b>White</b>	<b>Ceiling Angle Bracket</b>	<b>Metal</b>	<b>4,000 SF</b>	<b>Intact</b>	<b>5.60</b>	<b>Positive</b>
<b>07</b>	<b>Bldg. 9</b>	<b>Platform Area</b>	<b>East</b>	<b>Yellow</b>	<b>Stair Frame</b>	<b>Metal</b>	<b>1 Each</b>	<b>Intact</b>	<b>1.80</b>	<b>Positive</b>
<b>08</b>	<b>Bldg. 9</b>	<b>Platform Area</b>	<b>East</b>	<b>Yellow</b>	<b>Staircase</b>	<b>Metal</b>	<b>1 Each</b>	<b>Intact</b>	<b>1.70</b>	<b>Positive</b>
<b>09</b>	<b>Bldg. 9</b>	<b>Platform Area</b>	<b>East</b>	<b>Yellow</b>	<b>Stair Rail</b>	<b>Metal</b>	<b>1 Each</b>	<b>Intact</b>	<b>1.00</b>	<b>Positive</b>
<b>10</b>	<b>Bldg. 9</b>	<b>Platform Area</b>	<b>East</b>	<b>Yellow</b>	<b>Column</b>	<b>Metal</b>	<b>60 Each</b>	<b>Intact</b>	<b>4.80</b>	<b>Positive</b>
11	Bldg. 9	Platform Area	East	Yellow	Floor	Concrete	4,000 LF	Intact	0.01	Negative
<b>12</b>	<b>Bldg. 9</b>	<b>Platform Area</b>	<b>East</b>	<b>White</b>	<b>I-Beam</b>	<b>Metal</b>	<b>20 Each</b>	<b>Intact</b>	<b>5.80</b>	<b>Positive</b>
13	Bldg. 9	Platform Area	East	White	Duct	Metal	2,000 SF	Intact	0.01	Negative
14	Bldg. 9	Platform Area	East	White	Pipe	Metal	1,000 LF	Intact	0.01	Negative
15	Bldg. 9	Platform Area	East	Red	Pipe	Metal	1,000 LF	Intact	0.01	Negative
16	Bldg. 9	Platform Area	East	Blue	Door	Metal	3 Each	Intact	0.00	Negative

**SECTION 2  
SURVEY SUMMARY**

**LEAD XRF SURVEY RESULTS  
BUILDING 9**

**Phase 2 - Fullerton Mill - 2069218 AS  
2001 East Orangethorpe Avenue  
Fullerton, California**

The list materials and their components where Lead Based Paint (LBP) was detected at or in excess of the HUD/EPA standards of 1.0 mg/cm<sup>2</sup> (Los Angeles County has established a more stringent standard for lead-based paint at 0.7mg/cm<sup>2</sup>) by XRF method which is listed in the table below. All XRF readings below the regulatory defined action level are considered negative and all readings at and above these levels are considered positive.

Shot #	Unit	Room Tested	Wall	Color	Component	Substrate	Quantity	Paint Condition	Result	Neg/Pos
17	Bldg. 9	Platform	East	White	Wall	Metal	160 SF	Intact	0.00	Negative
<b>18</b>	<b>Bldg. 9</b>	<b>Platform</b>	<b>North</b>	<b>Yellow</b>	<b>Platform Rail</b>	<b>Metal</b>	<b>1 Each</b>	<b>Intact</b>	<b>1.80</b>	<b>Positive</b>
19	Bldg. 9	Platform	East	White	Machine	Metal	1 Each	Intact	0.01	Negative
<b>20</b>	<b>Bldg. 9</b>	<b>Warehouse</b>	<b>North</b>	<b>Red</b>	<b>I-Beam</b>	<b>Metal</b>	<b>10 Each</b>	<b>Intact</b>	<b>7.90</b>	<b>Positive</b>
21	Bldg. 9	Warehouse	North	Red	Floor	Concrete	10 SF	Intact	0.08	Negative
22	Bldg. 9, 1 <sup>st</sup> Floor	Warehouse	North	Yellow	Barrier	Metal	400 LF	Intact	0.01	Negative
23	Bldg. 9, 1 <sup>st</sup> Floor	Warehouse	West	Blue	Door	Metal	15 Each	Intact	0.00	Negative
<b>24</b>	<b>Bldg. 9, 1<sup>st</sup> Floor</b>	<b>Warehouse</b>	<b>West</b>	<b>White</b>	<b>I-Beam</b>	<b>Metal</b>	<b>10 Each</b>	<b>Intact</b>	<b>4.90</b>	<b>Positive</b>
<b>25</b>	<b>Bldg. 9, 1<sup>st</sup> Floor</b>	<b>Warehouse</b>	<b>West</b>	<b>Yellow</b>	<b>Light Stand</b>	<b>Metal</b>	<b>1 Each</b>	<b>Intact</b>	<b>1.70</b>	<b>Positive</b>
26	Bldg. 9	Platform Area	East	Blue	Door Frame	Metal	2 Each	Intact	0.00	Negative
27	Bldg. 9	Platform Area	East	Blue	Door	Metal	2 Each	Intact	0.00	Negative



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509410  
**Samples Submitted:** 36  
**Sample Collection Date:** 11/27/2018  
**Laboratory Receipt Date:** 12/3/2018

**Project ID:** 2069218AM  
**Project Name:** Kimberly Clark - Bldg #10 Tractor Area  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 1 of 10

### TEST DATA

---

**Laboratory ID#:** 1509410-001      **Client Sample #:** 1

**Sample Material and Location:** Tan 12 x 12 Floor Tile Office #2 - West End

**Sample Characteristics:** Tan Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 12/4/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509410-002      **Client Sample #:** 2

**Sample Material and Location:** Tan 12 x 12 Floor Tile Office #2 - East End

**Sample Characteristics:** Tan Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 12/3/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509410-003      **Client Sample #:** 3

**Sample Material and Location:** Tan 12 x 12 Floor Tile Office #1 - North End

**Sample Characteristics:** Tan Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 12/3/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509410-004      **Client Sample #:** 4

**Sample Material and Location:** Yellow Floor Tile Glue Office #2 - West End

**Sample Characteristics:** Yellow Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 12/3/2018

**Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509410  
**Samples Submitted:** 36  
**Sample Collection Date:** 11/27/2018  
**Laboratory Receipt Date:** 12/3/2018

**Project ID:** 2069218AM  
**Project Name:** Kimberly Clark - Bldg #10 Tractor Area  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 2 of 10

### TEST DATA

**Laboratory ID#:** 1509410-005 **Client Sample #:** 5

**Sample Material and Location:** Yellow Floor Tile Glue Office #2 - East End

**Sample Characteristics:** Yellow Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton **Date Analyzed:** 12/3/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509410-006 **Client Sample #:** 6

**Sample Material and Location:** Yellow Floor Tile Glue Office #1 - North End

**Sample Characteristics:** Yellow Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton **Date Analyzed:** 12/3/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509410-007 **Client Sample #:** 7

**Sample Material and Location:** Brown 4" Covebase Office #2 - East End

**Sample Characteristics:** Brown Grey Smooth Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton **Date Analyzed:** 12/3/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509410-008 **Client Sample #:** 8

**Sample Material and Location:** Brown 4" Covebase Office #1 - South End

**Sample Characteristics:** Brown Grey Smooth Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton **Date Analyzed:** 12/3/2018

**Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509410  
**Samples Submitted:** 36  
**Sample Collection Date:** 11/27/2018  
**Laboratory Receipt Date:** 12/3/2018

**Project ID:** 2069218AM  
**Project Name:** Kimberly Clark - Bldg #10 Tractor Area  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 3 of 10

### TEST DATA

**Laboratory ID#:** 1509410-009      **Client Sample #:** 9

**Sample Material and Location:** Brown 4" Covebase Office #1 - North End

**Sample Characteristics:** Brown Grey Smooth Homogenous

**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**

**Analyst:** Chris Turton

**Date Analyzed:** 12/3/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509410-010      **Client Sample #:** 10

**Sample Material and Location:** Brown/Tan Covebase Glue Office #2 - East End

**Sample Characteristics:** Brown Non-Fibrous Homogenous

**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**

**Analyst:** Chris Turton

**Date Analyzed:** 12/3/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509410-011      **Client Sample #:** 11

**Sample Material and Location:** Brown/Tan Covebase Glue Office #1 - South End

**Sample Characteristics:** Brown Non-Fibrous Homogenous

**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**

**Analyst:** Chris Turton

**Date Analyzed:** 12/3/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509410-012      **Client Sample #:** 12

**Sample Material and Location:** Brown/Tan Covebase Glue Office #1 - North End

**Sample Characteristics:** Brown Non-Fibrous Homogenous

**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**

**Analyst:** Chris Turton

**Date Analyzed:** 12/3/2018

**Total Asbestos (%)** None Detected



**Analytical Report**

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509410  
**Samples Submitted:** 36  
**Sample Collection Date:** 11/27/2018  
**Laboratory Receipt Date:** 12/3/2018

**Project ID:** 2069218AM  
**Project Name:** Kimberly Clark - Bldg #10 Tractor Area  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 4 of 10

**TEST DATA**

**Laboratory ID#:** 1509410-013 **Client Sample #:** 13

**Sample Material and Location:** White 12" x 12" Ceiling Tile Office #2 - South End

**Sample Characteristics:** White Brown Fibrous Inhomogenous  
**Misc. Components Observed:** 60% Non-Fibrous Material  
10% Fibrous Glass  
30% Cellulose

**Asbestos Observed (%):**  
**Analyst:** Chris Turton **Date Analyzed:** 12/3/2018 **Total Asbestos (%)** None Detected

**TEST DATA**

**Laboratory ID#:** 1509410-014 **Client Sample #:** 14

**Sample Material and Location:** White 12" x 12" Ceiling Tile Office #2 - East End

**Sample Characteristics:** White Brown Fibrous Inhomogenous  
**Misc. Components Observed:** 60% Non-Fibrous Material  
10% Fibrous Glass  
30% Cellulose

**Asbestos Observed (%):**  
**Analyst:** Chris Turton **Date Analyzed:** 12/3/2018 **Total Asbestos (%)** None Detected

**TEST DATA**

**Laboratory ID#:** 1509410-015 **Client Sample #:** 15

**Sample Material and Location:** White 12" x 12" Ceiling Tile Office #1 - North End

**Sample Characteristics:** White Brown Fibrous Inhomogenous  
**Misc. Components Observed:** 60% Non-Fibrous Material  
10% Fibrous Glass  
30% Cellulose

**Asbestos Observed (%):**  
**Analyst:** Chris Turton **Date Analyzed:** 12/3/2018 **Total Asbestos (%)** None Detected

**TEST DATA**

**Laboratory ID#:** 1509410-016 **Client Sample #:** 16

**Sample Material and Location:** Brown Ceiling Mastic Office #2 - South End

**Sample Characteristics:** Brown Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**  
**Analyst:** Chris Turton **Date Analyzed:** 12/3/2018 **Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509410  
**Samples Submitted:** 36  
**Sample Collection Date:** 11/27/2018  
**Laboratory Receipt Date:** 12/3/2018

**Project ID:** 2069218AM  
**Project Name:** Kimberly Clark - Bldg #10 Tractor Area  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 5 of 10

### TEST DATA

---

**Laboratory ID#:** 1509410-017 **Client Sample #:** 17

**Sample Material and Location:** Brown Ceiling Mastic Office #2 - East End

**Sample Characteristics:** Brown Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton **Date Analyzed:** 12/3/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509410-018 **Client Sample #:** 18

**Sample Material and Location:** Brown Ceiling Mastic Office #1 - North End

**Sample Characteristics:** Brown Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton **Date Analyzed:** 12/3/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509410-019 **Client Sample #:** 19

**Sample Material and Location:** White Drywall behind 12" x 12" C.T. Office #2 - South End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton **Date Analyzed:** 12/3/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509410-020 **Client Sample #:** 20

**Sample Material and Location:** White Drywall behind 12" x 12" C.T. Office #2 - East End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton **Date Analyzed:** 12/3/2018

**Total Asbestos (%)** None Detected





## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509410  
**Samples Submitted:** 36  
**Sample Collection Date:** 11/27/2018  
**Laboratory Receipt Date:** 12/3/2018

**Project ID:** 2069218AM  
**Project Name:** Kimberly Clark - Bldg #10 Tractor Area  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 6 of 10

### TEST DATA

**Laboratory ID#:** 1509410-021 **Client Sample #:** 21

**Sample Material and Location:** White Drywall behind 12" x 12" C.T. Office #1 - North End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton **Date Analyzed:** 12/3/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509410-022 **Client Sample #:** 22

**Sample Material and Location:** White Duct Work Wrap Sheet Metal - South End

**Sample Characteristics:** Brown White Fibrous Inhomogenous  
**Misc. Components Observed:** 50% Non-Fibrous Material  
10% Fibrous Glass  
40% Cellulose

**Asbestos Observed (%):**  
**Analyst:** Chris Turton **Date Analyzed:** 12/3/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509410-023 **Client Sample #:** 23

**Sample Material and Location:** White Duct Work Wrap Sheet Metal - East End

**Sample Characteristics:** Brown White Fibrous Inhomogenous  
**Misc. Components Observed:** 50% Non-Fibrous Material  
10% Fibrous Glass  
40% Cellulose

**Asbestos Observed (%):**  
**Analyst:** Chris Turton **Date Analyzed:** 12/3/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509410-024 **Client Sample #:** 24

**Sample Material and Location:** White Duct Work Wrap Area #1 - N.E. End

**Sample Characteristics:** Brown White Fibrous Inhomogenous  
**Misc. Components Observed:** 50% Non-Fibrous Material  
10% Fibrous Glass  
40% Cellulose

**Asbestos Observed (%):**  
**Analyst:** Chris Turton **Date Analyzed:** 12/3/2018

**Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509410  
**Samples Submitted:** 36  
**Sample Collection Date:** 11/27/2018  
**Laboratory Receipt Date:** 12/3/2018

**Project ID:** 2069218AM  
**Project Name:** Kimberly Clark - Bldg #10 Tractor Area  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 7 of 10

### TEST DATA

**Laboratory ID#:** 1509410-025      **Client Sample #:** 25

**Sample Material and Location:** Yellow Duct Work Insulation Sheet Metal - South End

**Sample Characteristics:** Yellow Fibrous Homogenous  
**Misc. Components Observed:** 5% Non-Fibrous Material  
95% Fibrous Glass

**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 12/3/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509410-026      **Client Sample #:** 26

**Sample Material and Location:** Yellow Duct Work Insulation Sheet Metal - East End

**Sample Characteristics:** Yellow Fibrous Homogenous  
**Misc. Components Observed:** 5% Non-Fibrous Material  
95% Fibrous Glass

**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 12/3/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509410-027      **Client Sample #:** 27

**Sample Material and Location:** Yellow Duct Work Insulation Area #1 - N.E. End

**Sample Characteristics:** Yellow Fibrous Homogenous  
**Misc. Components Observed:** 5% Non-Fibrous Material  
95% Fibrous Glass

**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 12/3/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509410-028      **Client Sample #:** 28

**Sample Material and Location:** Green Duct Work Glue Sheet Metal - South End

**Sample Characteristics:** Green Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 12/3/2018

**Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509410  
**Samples Submitted:** 36  
**Sample Collection Date:** 11/27/2018  
**Laboratory Receipt Date:** 12/3/2018

**Project ID:** 2069218AM  
**Project Name:** Kimberly Clark - Bldg #10 Tractor Area  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 8 of 10

### TEST DATA

---

**Laboratory ID#:** 1509410-029      **Client Sample #:** 29

**Sample Material and Location:** Green Duct Work Glue Sheet Metal - East End

**Sample Characteristics:** Green Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 12/3/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509410-030      **Client Sample #:** 30

**Sample Material and Location:** Green Duct Work Glue Area #1 - N.E. End

**Sample Characteristics:** Green Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 12/3/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509410-031      **Client Sample #:** 31

**Sample Material and Location:** White Drywall Storage #1 - S.E. End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 12/3/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509410-032      **Client Sample #:** 32

**Sample Material and Location:** White Drywall Storage #1 - East Center

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 12/3/2018

**Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509410  
**Samples Submitted:** 36  
**Sample Collection Date:** 11/27/2018  
**Laboratory Receipt Date:** 12/3/2018

**Project ID:** 2069218AM  
**Project Name:** Kimberly Clark - Bldg #10 Tractor Area  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 9 of 10

### TEST DATA

---

**Laboratory ID#:** 1509410-033      **Client Sample #:** 33

**Sample Material and Location:** White Drywall Storage #1 - N.E. End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 12/3/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509410-034      **Client Sample #:** 34

**Sample Material and Location:** White Joint Compound Storage #1 - S.E. End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 12/3/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509410-035      **Client Sample #:** 35

**Sample Material and Location:** White Joint Compound Storage #1 - East Center

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 12/3/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509410-036      **Client Sample #:** 36

**Sample Material and Location:** White Joint Compound Storage #1 - N.E. End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 12/3/2018

**Total Asbestos (%)** None Detected



### Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509410  
**Samples Submitted:** 36  
**Sample Collection Date:** 11/27/2018  
**Laboratory Receipt Date:** 12/3/2018

**Project ID:** 2069218AM  
**Project Name:** Kimberly Clark - Bldg #10 Tractor Area  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 10 of 10

Samples were analyzed by Calibrated Visual Estimation (CVE). Analyses by CVE have a detection limit of 1% asbestos by relative area and may not be consistently reliable below this limit or for asbestos with fiber diameter thinner than the resolving capacity of PLM without further analysis by another independent method. A test result of less than (<) 1% by CVE means asbestos was observed in the sample but is visually estimated to be below the reportable limit of 1%. The laboratory references interim method EPA 600/M4-82-020 (Interim Method) for fiber identification, 400 point counts, and composite reporting. EPA method 600/R-93/116 is referenced for analysis of non-insulation materials, sub-layers, expanded and modified point counts, CVE and subsequent data reporting. Samples containing distinct layers that can be reliably separated are analyzed and reported as separate unless requested in writing. The test data presented apply only to the items submitted. Count for samples submitted is indicative of total layers observed and may vary from actual analysis for positive stop requests. ATEL, LLC is a NIST-NVLAP and CA-ELAP Accredited laboratory (ID# 201073-0 and #2971, respectively). This report must not be reproduced, unless in its entirety, without the written consent of ATEL, LLC. Per NIST-NVLAP 150 Annex A: This report shall not be used to claim product certification, approval or endorsement by NVLAP, NIST, or any agency of the federal government.

Unless indicated, samples were received in acceptable condition. Sample retention time is 30 days from issuing this report unless requested otherwise.

Analyst Signature:

-Chris Turton

Approved Signatory:

-Dennis Liu

Reported On: 12/4/2018





**H2 ENVIRONMENTAL CONSULTING SERVICES, INC.**


**Bulk Sampling Form**

Stop at First Positive  24 Hour turn around  Rush turn around (4 Hours)  
 Do Not Layer Samples

CLIENT <i>Kimberly Clark</i>	PROJECT NO. <i>2069218A01</i>
PROJECT ID <i>Blk #10 Tractor Area</i>	DATE <i>11/27/18</i> PAGE <i>1</i> OF <i>2</i>
PROJECT LOCATION <i>2001 E. Orange Grove Ave., Fullerton, CA</i>	INSPECTOR <i>A. Sanchez</i>

GRP. NO.	SAMP. NO.	MATERIAL DESCRIPTION	LOCATION OF SAMPLE	QTY	% POS
01	01	TAN 12x12 FLOOR	OFFICE 2 - west end	2000	
↓	02	tile ↓	OFFICE 2 - east end	↓	
↓	03	↓	OFFICE 1 - North end	↓	
02	04	yellow Floor tile	OFFICE 2 - west end	2000	
↓	05	glue ↓	OFFICE 2 - east end	↓	
↓	06	↓	OFFICE 1 - North end	↓	
03	07	Bra. 4" Lumber	OFFICE 2 - east end	8000	
↓	08	↓	OFFICE 1 - South end	↓	
↓	09	↓	OFFICE 1 - North end	↓	
04	10	Bra./TAN Lumber	OFFICE 2 - east end	8000	
↓	11	glue ↓	OFFICE 1 - South end	↓	
↓	12	↓	OFFICE 1 - North end	↓	
05	13	white 12x12	OFFICE 2 - South end	2000	
↓	14	ceiling tile	OFFICE 2 - east end	↓	
↓	15	↓	OFFICE 1 - North end	↓	
06	16	Bra. ceiling music	OFFICE 2 - South end	2000	
↓	17	↓	OFFICE 2 - east end	↓	
↓	18	↓	OFFICE 1 - North end	↓	
07	19	white Drywall	OFFICE 2 - South end	2000	
↓	20	behind 12x12	OFFICE 2 - east end	↓	
↓	21	CT.	OFFICE 1 - North end	↓	

Notes:



**ENVIRONMENTAL CONSULTING SERVICES, INC.**

**Bulk Sampling Form**

Stop at First Positive     24 Hour turn around     Rush turn around (4 Hours)  
 Do Not Layer Samples

CLIENT Kimberly Clark	PROJECT NO. 2069218 Amy		
PROJECT ID Bldg. #10 Hunter Area	DATE 11/27/18	PAGE 2	OF 2
PROJECT LOCATION 2001 E. Orange Avenue, Fullerton, CA	INSPECTOR A. Sanchez		

GRP. NO.	SAMP. NO.	MATERIAL DESCRIPTION	LOCATION OF SAMPLE	QTY	% POS
08	22	white Deck work	Shant metal - South end	1,000φ	
↓	23	wrap	↓ - East end	↓	
↓	24	↓	Area #1 - N.E. end	↓	
09	25	Deckwork	Shant metal - South end	1,000φ	
↓	26	Insulation	↓ - East end	↓	
↓	27	↓	Area #1 - N.E. end	↓	
10	28	Green Deckwork	Shant metal - South end	1,000φ	
↓	29	glue	↓ - East end	↓	
↓	30	↓	Area #1 - N.E. end	↓	
11	31	white Drywall	Storage #1 - S.E. end	100φ	
↓	32	↓	↓ - East center	↓	
↓	33	↓	↓ - N.E. end	↓	
12	34	white joint	Storage #1 - S.E. end	100φ	
↓	35	compound	↓ - East center	↓	
↓	36	↓	↓ - N.E. end	↓	

Notes:



**SECTION 2  
SURVEY SUMMARY**

**LEAD XRF SURVEY RESULTS  
BUILDING 10, TRACTOR AREA**

**Phase 2 - Fullerton Mill - 2069218 AS  
2001 East Orangethorpe Avenue  
Fullerton, California**

The list materials and their components where Lead Based Paint (LBP) was detected at or in excess of the HUD/EPA standards of 1.0 mg/cm<sup>2</sup> (Los Angeles County has established a more stringent standard for lead-based paint at 0.7mg/cm<sup>2</sup>) by XRF method which is listed in the table below. All XRF readings below the regulatory defined action level are considered negative and all readings at and above these levels are considered positive.

Shot #	Unit	Room Tested	Wall	Color	Component	Substrate	Quantity	Paint Condition	Result	Neg/Pos
01	Bldg. 10	Tractor Area	East	White	Ceiling	Metal	5,670 SF	Intact	0.00	Negative
02	Bldg. 10	Tractor Area	East	White	Ceiling I-Beam	Metal	5,670 SF	Intact	0.05	Negative
03	Bldg. 10	Tractor Area	East	White	Cross Beam	Metal	5,670 SF	Intact	0.02	Negative
04	Bldg. 10	Tractor Area	South	White	Ductwork	Metal	1,000 SF	Intact	0.00	Negative
<b>05</b>	<b>Bldg. 10</b>	<b>Tractor Area</b>	<b>South</b>	<b>Yellow</b>	<b>Ladder</b>	<b>Metal</b>	<b>10 SF</b>	<b>Intact</b>	<b>3.90</b>	<b>Positive</b>
<b>06</b>	<b>Bldg. 10</b>	<b>Tractor Area</b>	<b>South</b>	<b>Yellow</b>	<b>Handrail</b>	<b>Metal</b>	<b>200 SF</b>	<b>Intact</b>	<b>7.50</b>	<b>Positive</b>
<b>07</b>	<b>Bldg. 10</b>	<b>Tractor Area</b>	<b>North</b>	<b>Yellow</b>	<b>Handrail</b>	<b>Metal</b>	<b>100 SF</b>	<b>Intact</b>	<b>5.30</b>	<b>Positive</b>
08	Bldg. 10	Tractor Area	South	White	Wall	Concrete	1,000 SF	Intact	0.00	Negative
09	Bldg. 10	Tractor Area	South	Gray	Door	Metal	3 Each	Intact	0.00	Negative
10	Bldg. 10	Tractor Area	South	Gray	Door Frame	Metal	3 Each	Intact	0.01	Negative
11	Bldg. 10	Tractor Area	West	White	Wall	Concrete	3,000 SF	Intact	0.01	Negative
<b>12</b>	<b>Bldg. 10</b>	<b>Tractor Area</b>	<b>West</b>	<b>Yellow</b>	<b>Bollards</b>	<b>Metal</b>	<b>2 Each</b>	<b>Intact</b>	<b>2.90</b>	<b>Positive</b>
13	Bldg. 10	Tractor Area	North	White	Wall	Wood	800 SF	Intact	0.00	Negative
14	Bldg. 10	Tractor Area	North	Gray	Wall	Wood	100 SF	Intact	0.00	Negative
15	Bldg. 10	Tractor Area	East	Brown	Door	Wood	2 Each	Intact	0.00	Negative
16	Bldg. 10	Tractor Area	East	Brown	Door Frame	Wood	2 Each	Intact	0.00	Negative

**SECTION 2**  
**SURVEY SUMMARY**

---

**LEAD XRF SURVEY RESULTS**  
**BUILDING 10, TRACTOR AREA**

**Phase 2 - Fullerton Mill - 2069218 AS**  
**2001 East Orangethorpe Avenue**  
**Fullerton, California**

The list materials and their components where Lead Based Paint (LBP) was detected at or in excess of the HUD/EPA standards of 1.0 mg/cm<sup>2</sup> (Los Angeles County has established a more stringent standard for lead-based paint at 0.7mg/cm<sup>2</sup>) by XRF method which is listed in the table below. All XRF readings below the regulatory defined action level are considered negative and all readings at and above these levels are considered positive.

Shot #	Unit	Room Tested	Wall	Color	Component	Substrate	Quantity	Paint Condition	Result	Neg/Pos
17	Bldg. 10	Tractor Area	West	Yellow	Floor	Concrete	100 SF	Intact	0.00	Negative
18	Bldg. 10	Tractor Area	West	Gray	Door	Metal	1 Each	Intact	0.00	Negative
19	Bldg. 10	Tractor Area	West	Gray	Door Frame	Metal	1 Each	Intact	0.00	Negative

**SECTION 2  
SURVEY SUMMARY**

**LEAD XRF SURVEY RESULTS  
BUILDING 10, BATTERY AREA**

**Phase 2 - Fullerton Mill - 2069218 AS  
2001 East Orangethorpe Avenue  
Fullerton, California**

The list materials and their components where Lead Based Paint (LBP) was detected at or in excess of the HUD/EPA standards of 1.0 mg/cm<sup>2</sup> (Los Angeles County has established a more stringent standard for lead-based paint at 0.7mg/cm<sup>2</sup>) by XRF method which is listed in the table below. All XRF readings below the regulatory defined action level are considered negative and all readings at and above these levels are considered positive.

Shot #	Unit	Room Tested	Wall	Color	Component	Substrate	Quantity	Paint Condition	Result	Neg/Pos
<b>01</b>	<b>Bldg. 10</b>	<b>Battery Area</b>	<b>East</b>	<b>Yellow</b>	<b>I-Beam</b>	<b>Metal</b>	<b>300 SF</b>	<b>Intact</b>	<b>1.90</b>	<b>Positive</b>
<b>02</b>	<b>Bldg. 10</b>	<b>Battery Area</b>	<b>East</b>	<b>Red</b>	<b>I-Beam</b>	<b>Metal</b>	<b>300 SF</b>	<b>Intact</b>	<b>3.20</b>	<b>Positive</b>
03	Bldg. 10	Battery Area	East	Gray	Wall	Ceramic	500 SF	Intact	0.00	Negative
04	Bldg. 10	Battery Area	East	White	Wall	Ceramic	1,500 SF	Intact	0.00	Negative
05	Bldg. 10	Battery Area	East	Yellow	Curb	Concrete	300 SF	Intact	0.10	Negative
<b>06</b>	<b>Bldg. 10</b>	<b>Battery Area</b>	<b>East</b>	<b>White</b>	<b>I-Beam</b>	<b>Metal</b>	<b>1,000 SF</b>	<b>Intact</b>	<b>3.00</b>	<b>Positive</b>
<b>07</b>	<b>Bldg. 10</b>	<b>Battery Area</b>	<b>East</b>	<b>Gray</b>	<b>Sliding Door</b>	<b>Metal</b>	<b>1 Each</b>	<b>Intact</b>	<b>6.70</b>	<b>Positive</b>
08	Bldg. 10	Battery Area	East	Gray	Sliding Door Frame	Metal	1 Each	Intact	0.00	Negative
09	Bldg. 10	Battery Area	North	Yellow	Post	Metal	50 SF	Intact	0.00	Negative
10	Bldg. 10	Battery Area	North	Yellow	Guardrail	Metal	100 SF	Intact	0.00	Negative
11	Bldg. 10	Battery Area	North	Yellow	Floor	Concrete	100 SF	Intact	0.00	Negative
12	Bldg. 10	Battery Area	North	Gray	Floor	Concrete	100 SF	Intact	0.00	Negative
<b>13</b>	<b>Bldg. 10</b>	<b>Battery Area</b>	<b>West</b>	<b>Yellow</b>	<b>Hand Railing</b>	<b>Metal</b>	<b>300 SF</b>	<b>Intact</b>	<b>5.90</b>	<b>Positive</b>
<b>14</b>	<b>Bldg. 10</b>	<b>Battery Area</b>	<b>West</b>	<b>Yellow</b>	<b>Wall</b>	<b>Wood</b>	<b>300 SF</b>	<b>Intact</b>	<b>3.20</b>	<b>Positive</b>
15	Bldg. 10	Battery Area	North	Yellow	Wall	Metal	100 SF	Intact	0.00	Negative
<b>16</b>	<b>Bldg. 10</b>	<b>Battery Area</b>	<b>North</b>	<b>Yellow</b>	<b>Hand Railing</b>	<b>Metal</b>	<b>50 SF</b>	<b>Intact</b>	<b>5.10</b>	<b>Positive</b>

**SECTION 2**  
**SURVEY SUMMARY**

**LEAD XRF SURVEY RESULTS**  
**BUILDING 12**

**Phase 2 - Fullerton Mill - 2069218 AS**  
**2001 East Orangethorpe Avenue**  
**Fullerton, California**

The list materials and their components where Lead Based Paint (LBP) was detected at or in excess of the HUD/EPA standards of 1.0 mg/cm<sup>2</sup> (Los Angeles County has established a more stringent standard for lead-based paint at 0.7mg/cm<sup>2</sup>) by XRF method which is listed in the table below. All XRF readings below the regulatory defined action level are considered negative and all readings at and above these levels are considered positive.

Shot #	Unit	Room Tested	Wall	Color	Component	Substrate	Quantity	Paint Condition	Result	Neg/Pos
01	Bldg. 12, 1 <sup>st</sup> Floor	Warehouse	North	White	Wall	Concrete	11,320 SF	Intact	0.00	Negative
02	Bldg. 12, 1 <sup>st</sup> Floor	Warehouse	North	Blue	Wall	Concrete	11,320 SF	Intact	0.00	Negative
03	Bldg. 12, 1 <sup>st</sup> Floor	Warehouse	North	Blue	Door Frame	Metal	5 Each	Intact	0.00	Negative
04	Bldg. 12, 1 <sup>st</sup> Floor	Warehouse	North	Blue	Door	Metal	5 Each	Intact	0.00	Negative
05	Bldg. 12, 1 <sup>st</sup> Floor	Warehouse	North	White	Column	Metal	500 SF	Intact	0.07	Negative
06	Bldg. 12, 1 <sup>st</sup> Floor	Warehouse	North	Red	Pipe	Metal	3,226 SF	Intact	0.01	Negative
07	Bldg. 12, 1 <sup>st</sup> Floor	Warehouse	East	Blue	Sliding Door Frame	Metal	2 Each	Intact	0.01	Negative
<b>08</b>	<b>Bldg. 12, 1<sup>st</sup> Floor</b>	<b>Warehouse</b>	<b>East</b>	<b>Blue</b>	<b>Sliding Door</b>	<b>Metal</b>	<b>2 Each</b>	<b>Intact</b>	<b>5.40</b>	<b>Positive</b>
<b>09</b>	<b>Bldg. 12, 1<sup>st</sup> Floor</b>	<b>Warehouse</b>	<b>East</b>	<b>Yellow</b>	<b>Floor Rail</b>	<b>Metal</b>	<b>1,132 SF</b>	<b>Intact</b>	<b>4.80</b>	<b>Positive</b>
<b>10</b>	<b>Bldg. 12, 1<sup>st</sup> Floor</b>	<b>Warehouse</b>	<b>East</b>	<b>Red</b>	<b>Floor</b>	<b>Concrete</b>	<b>20 SF</b>	<b>Intact</b>	<b>5.80</b>	<b>Positive</b>
11	Bldg. 12, 1 <sup>st</sup> Floor	Warehouse	East	White	Floor	Concrete	100 LF	Intact	0.08	Negative
12	Bldg. 12, 1 <sup>st</sup> Floor	Warehouse	South	Gray	Ceiling	Metal	70,240 SF	Intact	0.00	Negative
13	Bldg. 12, 1 <sup>st</sup> Floor	Warehouse	South	Gray	Ceiling I-Beam	Metal	19,560 SF	Intact	0.01	Negative
14	Bldg. 12, 1 <sup>st</sup> Floor	Warehouse	South	Gray	Angle Bracket	Metal	19,560 SF	Intact	0.01	Negative
15	Bldg. 12, 1 <sup>st</sup> Floor	Warehouse	South	Gray	Ceiling Pipe	Metal	1,304 LF	Intact	0.01	Negative
16	Bldg. 12, 1 <sup>st</sup> Floor	Warehouse	South	White	I-Beam	Metal	8 Each	Intact	0.01	Negative



**Analytical Report**

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #13  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Report Number:** 1509540  
**Samples Submitted:** 33  
**Sample Collection Date:** 12/7/2018  
**Laboratory Receipt Date:** 12/10/2018

**Page:** 1 of 9

**TEST DATA**

---

**Laboratory ID#:** 1509540-001      **Client Sample #:** 1

**Sample Material and Location:** White Drywall Office #1 - S.E. End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 95% Non-Fibrous Material  
5% Cellulose

**Asbestos Observed (%):**      **Date Analyzed:** 12/10/2018      **Total Asbestos (%)** None Detected  
**Analyst:** Dennis Liu

**TEST DATA**

---

**Laboratory ID#:** 1509540-002      **Client Sample #:** 2

**Sample Material and Location:** White Drywall Office #2 - East End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 95% Non-Fibrous Material  
5% Cellulose

**Asbestos Observed (%):**      **Date Analyzed:** 12/10/2018      **Total Asbestos (%)** None Detected  
**Analyst:** Dennis Liu

**TEST DATA**

---

**Laboratory ID#:** 1509540-003      **Client Sample #:** 3

**Sample Material and Location:** White Drywall Break Room - West End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 95% Non-Fibrous Material  
5% Cellulose

**Asbestos Observed (%):**      **Date Analyzed:** 12/10/2018      **Total Asbestos (%)** None Detected  
**Analyst:** Dennis Liu

**TEST DATA**

---

**Laboratory ID#:** 1509540-004      **Client Sample #:** 4

**Sample Material and Location:** White Joint Compound Office #1 - S.E. End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**      **Date Analyzed:** 12/10/2018      **Total Asbestos (%)** None Detected  
**Analyst:** Dennis Liu



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #13  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Report Number:** 1509540  
**Samples Submitted:** 33  
**Sample Collection Date:** 12/7/2018  
**Laboratory Receipt Date:** 12/10/2018

**Page:** 2 of 9

### TEST DATA

---

**Laboratory ID#:** 1509540-005      **Client Sample #:** 5

**Sample Material and Location:** White Joint Compound Office #2 - East End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**

**Analyst:** Dennis Liu      **Date Analyzed:** 12/10/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509540-006      **Client Sample #:** 6

**Sample Material and Location:** White Joint Compound Break Room - West End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**

**Analyst:** Dennis Liu      **Date Analyzed:** 12/10/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509540-007      **Client Sample #:** 7

**Sample Material and Location:** White 12 x 12 Ceiling Tile Office #2 - East End

**Sample Characteristics:** Grey Fibrous Inhomogenous  
**Misc. Components Observed:** 55% Non-Fibrous Material  
5% Fibrous Glass  
40% Cellulose

**Asbestos Observed (%):**

**Analyst:** Dennis Liu      **Date Analyzed:** 12/10/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509540-008      **Client Sample #:** 8

**Sample Material and Location:** White 12 x 12 Ceiling Tile Office #1 - East End

**Sample Characteristics:** Grey Fibrous Inhomogenous  
**Misc. Components Observed:** 55% Non-Fibrous Material  
5% Fibrous Glass  
40% Cellulose

**Asbestos Observed (%):**

**Analyst:** Dennis Liu      **Date Analyzed:** 12/10/2018

**Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509540  
**Samples Submitted:** 33  
**Sample Collection Date:** 12/7/2018  
**Laboratory Receipt Date:** 12/10/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #13  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 3 of 9

### TEST DATA

---

**Laboratory ID#:** 1509540-009      **Client Sample #:** 9

**Sample Material and Location:** White 12 x 12 Ceiling Tile File Room - South End

**Sample Characteristics:** Grey Fibrous Inhomogenous  
**Misc. Components Observed:** 55% Non-Fibrous Material  
5% Fibrous Glass  
40% Cellulose

**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 12/10/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509540-010      **Client Sample #:** 10

**Sample Material and Location:** Tan/Grey Ceiling Mastic Office #2 - East End

**Sample Characteristics:** Brown Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 12/10/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509540-011      **Client Sample #:** 11

**Sample Material and Location:** Tan/Grey Ceiling Mastic Office #1 - East End

**Sample Characteristics:** Brown Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 12/10/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509540-012      **Client Sample #:** 12

**Sample Material and Location:** Tan/Grey Ceiling Mastic File Room - South End

**Sample Characteristics:** Brown Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 12/10/2018

**Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509540  
**Samples Submitted:** 33  
**Sample Collection Date:** 12/7/2018  
**Laboratory Receipt Date:** 12/10/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #13  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 4 of 9

### TEST DATA

**Laboratory ID#:** 1509540-013      **Client Sample #:** 13

**Sample Material and Location:** White Drywall above 12 x 12 Ceiling Tile Office #2 - East End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 12/11/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509540-014      **Client Sample #:** 14

**Sample Material and Location:** White Drywall above 12 x 12 Ceiling Tile Office #1 - East End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 12/11/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509540-015      **Client Sample #:** 15

**Sample Material and Location:** White Drywall above 12 x 12 Ceiling Tile File Room - South End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 12/11/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509540-016      **Client Sample #:** 16

**Sample Material and Location:** Gray 4" Cove Base Office #3 - South End

**Sample Characteristics:** Gray Smooth Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 12/11/2018

**Total Asbestos (%)** None Detected





**Analytical Report**

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509540  
**Samples Submitted:** 33  
**Sample Collection Date:** 12/7/2018  
**Laboratory Receipt Date:** 12/10/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #13  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 5 of 9

**TEST DATA**

---

**Laboratory ID#:** 1509540-017                      **Client Sample #:** 17

**Sample Material and Location:** Gray 4" Cove Base File Room - East End

**Sample Characteristics:** Gray Smooth Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**

**Analyst:** Dennis Liu                      **Date Analyzed:** 12/11/2018

**Total Asbestos (%)** None Detected

**TEST DATA**

---

**Laboratory ID#:** 1509540-018                      **Client Sample #:** 18

**Sample Material and Location:** Gray 4" Cove Base Break Room - North End

**Sample Characteristics:** Gray Smooth Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**

**Analyst:** Dennis Liu                      **Date Analyzed:** 12/11/2018

**Total Asbestos (%)** None Detected

**TEST DATA**

---

**Laboratory ID#:** 1509540-019                      **Client Sample #:** 19

**Sample Material and Location:** Offwhite/Tan Covebase Glue Office #3 - South End

**Sample Characteristics:** Tan Beige Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**

**Analyst:** Dennis Liu                      **Date Analyzed:** 12/11/2018

**Total Asbestos (%)** None Detected

**TEST DATA**

---

**Laboratory ID#:** 1509540-020                      **Client Sample #:** 20

**Sample Material and Location:** Offwhite/Tan Covebase Glue File Room - East End

**Sample Characteristics:** Tan Beige Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**

**Analyst:** Dennis Liu                      **Date Analyzed:** 12/11/2018

**Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509540  
**Samples Submitted:** 33  
**Sample Collection Date:** 12/7/2018  
**Laboratory Receipt Date:** 12/10/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #13  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 6 of 9

### TEST DATA

---

**Laboratory ID#:** 1509540-021      **Client Sample #:** 21

**Sample Material and Location:** Offwhite/Tan Covebase Glue Break Room - North End

**Sample Characteristics:** Tan Beige Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 12/11/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509540-022      **Client Sample #:** 22

**Sample Material and Location:** Yellow Carpet Glue Office #3 - North End

**Sample Characteristics:** Yellow Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 12/11/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509540-023      **Client Sample #:** 23

**Sample Material and Location:** Yellow Carpet Glue Office #3 - South End

**Sample Characteristics:** Yellow Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 12/11/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509540-024      **Client Sample #:** 24

**Sample Material and Location:** Yellow Carpet Glue File Room - East End

**Sample Characteristics:** Yellow Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 12/11/2018

**Total Asbestos (%)** None Detected



**Analytical Report**

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509540  
**Samples Submitted:** 33  
**Sample Collection Date:** 12/7/2018  
**Laboratory Receipt Date:** 12/10/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #13  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 7 of 9

**TEST DATA**

---

**Laboratory ID#:** 1509540-025      **Client Sample #:** 25

**Sample Material and Location:** Gray 12 x 12 Floor Tile Room 3 - South End

**Sample Characteristics:** Gray Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 12/11/2018

**Total Asbestos (%)** None Detected

**TEST DATA**

---

**Laboratory ID#:** 1509540-026      **Client Sample #:** 26

**Sample Material and Location:** Gray 12 x 12 Floor Tile Office #2 - West End

**Sample Characteristics:** Gray Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 12/11/2018

**Total Asbestos (%)** None Detected

**TEST DATA**

---

**Laboratory ID#:** 1509540-027      **Client Sample #:** 27

**Sample Material and Location:** Gray 12 x 12 Floor Tile Break Room - North End

**Sample Characteristics:** Gray Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 12/11/2018

**Total Asbestos (%)** None Detected

**TEST DATA**

---

**Laboratory ID#:** 1509540-028      **Client Sample #:** 28

**Sample Material and Location:** Offwhite 12 x 12 Floor Tile Room 3 - South End

**Sample Characteristics:** Off-White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 12/11/2018

**Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509540  
**Samples Submitted:** 33  
**Sample Collection Date:** 12/7/2018  
**Laboratory Receipt Date:** 12/10/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #13  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 8 of 9

### TEST DATA

---

**Laboratory ID#:** 1509540-029      **Client Sample #:** 29

**Sample Material and Location:** Offwhite 12 x 12 Floor Tile Office #2 - West End

**Sample Characteristics:** Off-White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 12/11/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509540-030      **Client Sample #:** 30

**Sample Material and Location:** Offwhite 12 x 12 Floor Tile Break Room - North End

**Sample Characteristics:** Off-White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 12/11/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509540-031      **Client Sample #:** 31

**Sample Material and Location:** Yellow Floor Tile Glue Room 3 - South End

**Sample Characteristics:** Yellow Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 12/11/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509540-032      **Client Sample #:** 32

**Sample Material and Location:** Yellow Floor Tile Glue Office #2 - West End

**Sample Characteristics:** Yellow Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 12/11/2018

**Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509540  
**Samples Submitted:** 33  
**Sample Collection Date:** 12/7/2018  
**Laboratory Receipt Date:** 12/10/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #13  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 9 of 9

### TEST DATA

**Laboratory ID#:** 1509540-033      **Client Sample #:** 33

**Sample Material and Location:** Yellow Floor Tile Glue Break Room - North End


**Sample Characteristics:** Yellow Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 12/11/2018

**Total Asbestos (%)**    **None Detected**

Samples were analyzed by Calibrated Visual Estimation (CVE). Analyses by CVE have a detection limit of 1% asbestos by relative area and may not be consistently reliable below this limit or for asbestos with fiber diameter thinner than the resolving capacity of PLM without further analysis by another independent method. A test result of less than (<) 1% by CVE means asbestos was observed in the sample but is visually estimated to be below the reportable limit of 1%. The laboratory references interim method EPA 600/M4-82-020 (Interim Method) for fiber identification, 400 point counts, and composite reporting. EPA method 600/R-93/116 is referenced for analysis of non-insulation materials, sub-layers, expanded and modified point counts, CVE and subsequent data reporting. Samples containing distinct layers that can be reliably separated are analyzed and reported as separate unless requested in writing. The test data presented apply only to the items submitted. Count for samples submitted is indicative of total layers observed and may vary from actual analysis for positive stop requests. ATEL, LLC is a NIST-NVLAP and CA-ELAP Accredited laboratory (ID# 201073-0 and #2971, respectively). This report must not be reproduced, unless in its entirety, without the written consent of ATEL, LLC. Per NIST-NVLAP 150 Annex A: This report shall not be used to claim product certification, approval or endorsement by NVLAP, NIST, or any agency of the federal government.

Unless indicated, samples were received in acceptable condition. Sample retention time is 30 days from issuing this report unless requested otherwise.

**Analyst Signature:**  -Dennis Liu

**Approved Signatory:**  -Chris Turton

**Reported On:** 12/11/2018



1509540

Analytical Services Request v.112414

Pg 1 of 1

Asbestos Laboratory

**Your Contact Information**

Company Name (if by company): H2 Environmental Consulting Services, Inc.  
 Personal/Company Address: 13122 6th Street, Chino, CA 91710  
 Contact Person: Amy De Santiago  
 Contact Information: Main: 909-628-0369 E-Mail: labresults@h2env.com  
 Mobile: \_\_\_\_\_ Fax: 909-613-5845  
 How should we send your result Verbal  Verbal  E-mail  Fax

*\*If verbal results are requested, you must also select a second form of delivery.*

**Project Information**

Project Name: Kimberly Clark  
 Project #: 206921848  
 Project Location: 2001 E Orangeburg Ave, Fullerton, CA - Bldg 13  
 PO#: \_\_\_\_\_ Claim# \_\_\_\_\_  
 Date Sampled: 12/1/18 Time Sampled: 3pm

Analytical Type(s) Requested	Turnaround Time*
Asbestos in Bulk Materials, EPA 600/R-93/116, 600/M4-82-020	*Business Hrs: 0800-1700 Mon-Fri.
Routine, Calibrated Visual Estimation <input checked="" type="checkbox"/>	Rush 3 Business Hrs* <input type="checkbox"/>
Point Count: 400pts <input type="checkbox"/>	8 Business Hrs* <input type="checkbox"/>
1000pts <input type="checkbox"/>	Expedited 24 Business Hrs <input checked="" type="checkbox"/>
Gravimetric Reduction (72hr Minimum) <input type="checkbox"/>	Routine 48 Business Hrs <input type="checkbox"/>
Fiber Count in Sampling Cartridge (25mm MCE)	72 Business Hrs <input type="checkbox"/>
Asbestos-like, NIOSH 7400 A Rules <input type="checkbox"/>	Standard 5 Business Days <input type="checkbox"/>
Rotometer Calibration (Low and High Flow Rotometers) <input type="checkbox"/>	*3hr TAT: Samples must be submitted by 2pm for same day results
Special Instructions: _____	*8hr TAT: Samples must be submitted by 9am for same day results


**Sample Information**

Sample ID #	Description/Material Type	Location	Flow Rate	Start Time	Stop Time	Volume (L)
	Please See Attached					

For more samples, please continue onto supplemental form. Page # indication in upper-right-hand of form.

**Chain of Custody**

Relinquished By: Alberto Sanchez Date and Time: 12/1/18 3pm  
 Received By: \_\_\_\_\_ Date and Time: \_\_\_\_\_  
 Relinquished By: [Signature] Date and Time: \_\_\_\_\_  
 Received By: [Signature] Date and Time: 12/10/18 2:45pm



# ENVIRONMENTAL CONSULTING SERVICES, INC.

## Bulk Sampling Form

Stop at First Positive  
  24 Hour turn around  
  Rush turn around (4 Hours)  
 Do Not Layer Samples

CLIENT <i>Kimberly Clark</i>	PROJECT NO. <i>2069218AS</i>
PROJECT ID <i>Bldg # 13</i>	DATE <i>12/7/18</i>
PROJECT LOCATION <i>2001 E. Orange Ave, Fullerton, CA</i>	PAGE <i>1</i> OF <i>2</i>
INSPECTOR <i>A. Sanchez</i>	

GRP. NO.	SAMP. NO.	MATERIAL DESCRIPTION	LOCATION OF SAMPLE	QTY	% POS
01	01	white Drywall	OFFICE #1 - S.E. end	5,000#	
	02	↓	OFFICE #2 - East end	↓	
	03	↓	Break rm - west end	↓	
02	04	white joint	OFFICE #1 - S.E. end	5,000#	
	05	Compound	OFFICE #2 - East end	↓	
	06	↓	Break rm - west end	↓	
03	07	white 12x12	OFFICE #2 - East end	1,000#	
	08	ceiling tile	OFFICE #1 - East end	↓	
	09	↓	Film rm. - South end	↓	
04	10	<del>gray</del> / Army ceiling	OFFICE #2 - East end	1,000#	
	11	music	OFFICE #1 - East end	↓	
	12	↓	Film rm. - South end	↓	
05	13	white Drywall	OFFICE #2 - East end	1,000#	
	14	ceiling 12x12	OFFICE #1 - East end	↓	
	15	ceiling tile	Film rm. - South end	↓	
06	16	gray 4" concrete	OFFICE #3 - South end	4,000#	
	17	↓	Film rm - East end	↓	
	18	↓	Break rm - North end	↓	
07	19	offwhite / TAN	OFFICE #3 - South end	4,000#	
	20	concrete glaze	Film rm - East end	↓	
	21	↓	Break rm. - North end	↓	

Notes:





**SECTION 2  
SURVEY SUMMARY**

**LEAD XRF SURVEY RESULTS  
BUILDING 13**

**Phase 2 - Fullerton Mill - 2069218 AS  
2001 East Orangethorpe Avenue  
Fullerton, California**

The list materials and their components where Lead Based Paint (LBP) was detected at or in excess of the HUD/EPA standards of 1.0 mg/cm<sup>2</sup> (Los Angeles County has established a more stringent standard for lead-based paint at 0.7mg/cm<sup>2</sup>) by XRF method which is listed in the table below. All XRF readings below the regulatory defined action level are considered negative and all readings at and above these levels are considered positive.

Shot #	Unit	Room Tested	Wall	Color	Component	Substrate	Quantity	Paint Condition	Result	Neg/Pos
01	1 <sup>st</sup> Floor	Warehouse	North	White	Wall	Concrete	13362 SF	Intact	0.00	Negative
02	1 <sup>st</sup> Floor	Warehouse	North	Blue	Wall	Concrete	13362 SF	Intact	0.00	Negative
<b>03</b>	<b>1<sup>st</sup> Floor</b>	<b>Warehouse</b>	<b>North</b>	<b>Red</b>	<b>Sprinkler Head Panel</b>	<b>Metal</b>	<b>1 Each</b>	<b>Intact</b>	<b>1.00</b>	<b>Positive</b>
04	1 <sup>st</sup> Floor	Warehouse	North	Red	Pipe	Metal	3048 LF	Intact	0.00	Negative
<b>05</b>	<b>1<sup>st</sup> Floor</b>	<b>Warehouse</b>	<b>North</b>	<b>Yellow</b>	<b>Bollard</b>	<b>Metal</b>	<b>100 SF</b>	<b>Intact</b>	<b>5.80</b>	<b>Positive</b>
06	1 <sup>st</sup> Floor	Warehouse	North	Blue	Door Frame	Metal	9 Each	Intact	0.00	Negative
07	1 <sup>st</sup> Floor	Warehouse	North	Blue	Door	Metal	9 Each	Intact	0.00	Negative
<b>08</b>	<b>1<sup>st</sup> Floor</b>	<b>Warehouse</b>	<b>North</b>	<b>Yellow</b>	<b>Floor</b>	<b>Concrete</b>	<b>1000 LF</b>	<b>Intact</b>	<b>2.70</b>	<b>Positive</b>
09	1 <sup>st</sup> Floor	Warehouse	North	White	Floor	Concrete	1000 LF	Intact	0.01	Negative
<b>10</b>	<b>1<sup>st</sup> Floor</b>	<b>Warehouse</b>	<b>East</b>	<b>Red</b>	<b>Bollard</b>	<b>Metal</b>	<b>100 SF</b>	<b>Intact</b>	<b>8.00</b>	<b>Positive</b>
11	1 <sup>st</sup> Floor	Warehouse	East	Red	Column	Metal	2 Each	Intact	0.01	Negative
12	1 <sup>st</sup> Floor	Warehouse	East	Blue	Roll Up Door Frame	Metal	4 Each	Intact	0.08	Negative
<b>13</b>	<b>1<sup>st</sup> Floor</b>	<b>Warehouse</b>	<b>South</b>	<b>White</b>	<b>Post</b>	<b>Metal</b>	<b>4 Each</b>	<b>Intact</b>	<b>3.50</b>	<b>Positive</b>
<b>14</b>	<b>1<sup>st</sup> Floor</b>	<b>Warehouse</b>	<b>South</b>	<b>Yellow</b>	<b>Bollard Rail</b>	<b>Metal</b>	<b>100 SF</b>	<b>Intact</b>	<b>1.60</b>	<b>Positive</b>
<b>15</b>	<b>1<sup>st</sup> Floor</b>	<b>Warehouse</b>	<b>South</b>	<b>Yellow</b>	<b>Floor, Rail</b>	<b>Metal</b>	<b>307 LF</b>	<b>Intact</b>	<b>1.60</b>	<b>Positive</b>
<b>16</b>	<b>1<sup>st</sup> Floor</b>	<b>Warehouse</b>	<b>West</b>	<b>Yellow</b>	<b>Bollard/I-Beam</b>	<b>Metal</b>	<b>4 Each</b>	<b>Intact</b>	<b>5.60</b>	<b>Positive</b>

**SECTION 2**  
**SURVEY SUMMARY**

**LEAD XRF SURVEY RESULTS**  
**BUILDING 13**

**Phase 2 - Fullerton Mill - 2069218 AS**  
**2001 East Orangethorpe Avenue**  
**Fullerton, California**

The list materials and their components where Lead Based Paint (LBP) was detected at or in excess of the HUD/EPA standards of 1.0 mg/cm<sup>2</sup> (Los Angeles County has established a more stringent standard for lead-based paint at 0.7mg/cm<sup>2</sup>) by XRF method which is listed in the table below. All XRF readings below the regulatory defined action level are considered negative and all readings at and above these levels are considered positive.

Shot #	Unit	Room Tested	Wall	Color	Component	Substrate	Quantity	Paint Condition	Result	Neg/Pos
<b>17</b>	<b>1<sup>st</sup> Floor</b>	<b>Warehouse</b>	<b>West</b>	<b>Yellow</b>	<b>Ramp Rail</b>	<b>Metal</b>	<b>2 Each</b>	<b>Intact</b>	<b>2.20</b>	<b>Positive</b>
18	1 <sup>st</sup> Floor	Warehouse	West	Blue	Gable Ramp Vent	Metal	4 Each	Intact	0.01	Negative
<b>19</b>	<b>1<sup>st</sup> Floor</b>	<b>Warehouse</b>	<b>West</b>	<b>Blue</b>	<b>Sliding Door</b>	<b>Metal</b>	<b>6 Each</b>	<b>Intact</b>	<b>5.80</b>	<b>Positive</b>
20	1 <sup>st</sup> Floor	Warehouse	East	Blue	Dock Roll Up Door	Metal	4 Each	Intact	0.02	Negative
21	1 <sup>st</sup> Floor	Warehouse	East	Blue	Dock Door Frame	Metal	4 Each	Intact	0.02	Negative
22	1 <sup>st</sup> Floor	Office	South	Blue	Door Frame	Metal	7 Each	Intact	0.00	Negative
23	1 <sup>st</sup> Floor	Office	South	Blue	Door	Wood	7 Each	Intact	0.00	Negative
24	1 <sup>st</sup> Floor	Office	South	White	Wall	Wood	1,088 SF	Intact	0.00	Negative
25	1 <sup>st</sup> Floor	Office	South	White	Wall	Drywall	1,088 SF	Intact	0.00	Negative
26	1 <sup>st</sup> Floor	Office	North	Blue	Door Frame	Wood	2 Each	Intact	0.00	Negative
27	1 <sup>st</sup> Floor	Office	West	Blue	Window Frame	Wood	6 Each	Intact	0.00	Negative
28	1 <sup>st</sup> Floor	Men's Restroom	South	Blue	Door Frame	Metal	1 Each	Intact	0.00	Negative
29	1 <sup>st</sup> Floor	Men's Restroom	South	Blue	Door	Wood	1 Each	Intact	0.00	Negative
30	1 <sup>st</sup> Floor	Men's Restroom	West	White	Wall	Drywall	152 SF	Intact	0.00	Negative
31	1 <sup>st</sup> Floor	Men's Restroom	West	Grey	6"x6" Wall Tile	Ceramic	76 SF	Intact	0.00	Negative
32	1 <sup>st</sup> Floor	Men's Restroom	West	Blue	6"x6" Wall Tile	Ceramic	76 SF	Intact	0.00	Negative

**SECTION 2  
SURVEY SUMMARY**

**LEAD XRF SURVEY RESULTS  
BUILDING 13**

**Phase 2 - Fullerton Mill - 2069218 AS  
2001 East Orangethorpe Avenue  
Fullerton, California**

The list materials and their components where Lead Based Paint (LBP) was detected at or in excess of the HUD/EPA standards of 1.0 mg/cm<sup>2</sup> (Los Angeles County has established a more stringent standard for lead-based paint at 0.7mg/cm<sup>2</sup>) by XRF method which is listed in the table below. All XRF readings below the regulatory defined action level are considered negative and all readings at and above these levels are considered positive.

Shot #	Unit	Room Tested	Wall	Color	Component	Substrate	Quantity	Paint Condition	Result	Neg/Pos
33	1 <sup>st</sup> Floor	Men's Restroom	West	White	Sink	Ceramic	1 Each	Intact	0.00	Negative
34	1 <sup>st</sup> Floor	Men's Restroom	East	White	Toilet	Ceramic	1 Each	Intact	0.00	Negative
35	1 <sup>st</sup> Floor	Men's Restroom	East	White	Urinal	Ceramic	1 Each	Intact	0.00	Negative
36	1 <sup>st</sup> Floor	Men's Restroom	East	Grey	Partician	Metal	2 Each	Intact	0.00	Negative
37	1 <sup>st</sup> Floor	Men's Restroom	South	White	Ceiling	Drywall	88 SF	Intact	0.00	Negative
38	1 <sup>st</sup> Floor	Men's Restroom	South	Grey	6"x6" Floor Tile	Ceramic	44 SF	Intact	0.00	Negative
39	1 <sup>st</sup> Floor	Men's Restroom	South	Blue	6"x6" Floor Tile	Ceramic	44 SF	Intact	0.00	Negative
40	1 <sup>st</sup> Floor	Women's Restroom	West	Blue	Door Frame	Metal	1 Each	Intact	0.00	Negative
41	1 <sup>st</sup> Floor	Women's Restroom	West	Blue	Door	Wood	1 Each	Intact	0.00	Negative
42	1 <sup>st</sup> Floor	Women's Restroom	South	White	Wall	Drywall	112 SF	Intact	0.00	Negative
43	1 <sup>st</sup> Floor	Women's Restroom	South	Grey	6"x6" Wall Tile	Ceramic	56 SF	Intact	0.00	Negative
44	1 <sup>st</sup> Floor	Women's Restroom	South	Blue	6"x6" Wall Tile	Ceramic	56 SF	Intact	0.01	Negative
45	1 <sup>st</sup> Floor	Women's Restroom	East	White	Sink	Ceramic	1 Each	Intact	0.01	Negative
46	1 <sup>st</sup> Floor	Women's Restroom	East	White	Toilet	Ceramic	1 Each	Intact	0.01	Negative
47	1 <sup>st</sup> Floor	Women's Restroom	North	Grey	6"x6" Floor Tile	Ceramic	24 SF	Intact	0.00	Negative
48	1 <sup>st</sup> Floor	Women's Restroom	North	Blue	6"x6" Floor Tile	Ceramic	24 SF	Intact	0.00	Negative

**SECTION 2  
SURVEY SUMMARY**

**LEAD XRF SURVEY RESULTS  
BUILDING 13**

**Phase 2 - Fullerton Mill - 2069218 AS  
2001 East Orangethorpe Avenue  
Fullerton, California**

The list materials and their components where Lead Based Paint (LBP) was detected at or in excess of the HUD/EPA standards of 1.0 mg/cm<sup>2</sup> (Los Angeles County has established a more stringent standard for lead-based paint at 0.7mg/cm<sup>2</sup>) by XRF method which is listed in the table below. All XRF readings below the regulatory defined action level are considered negative and all readings at and above these levels are considered positive.

Shot #	Unit	Room Tested	Wall	Color	Component	Substrate	Quantity	Paint Condition	Result	Neg/Pos
49	1 <sup>st</sup> Floor	Women's Restroom	North	White	Ceiling	Drywall	48 SF	Intact	0.00	Negative
50	1 <sup>st</sup> Floor	Warehouse		White	Floor	Drywall	1,000 SF	Intact	0.00	Negative
51	1 <sup>st</sup> Floor	Men's Restroom 2	East	White	Wall	Drywall	38 SF	Intact	0.00	Negative
<b>52</b>	<b>1<sup>st</sup> Floor</b>	<b>Men's Restroom 2</b>	<b>East</b>	<b>Tan</b>	<b>4"x4" Wall Tile</b>	<b>Ceramic</b>	<b>266 SF</b>	<b>Intact</b>	<b>7.70</b>	<b>Positive</b>
53	1 <sup>st</sup> Floor	Men's Restroom 2	East	White	Sink	Ceramic	1 Each	Intact	0.01	Negative
54	1 <sup>st</sup> Floor	Men's Restroom 2	West	White	Urinal	Ceramic	1 Each	Intact	0.01	Negative
<b>55</b>	<b>1<sup>st</sup> Floor</b>	<b>Men's Restroom 2</b>	<b>West</b>	<b>White</b>	<b>Toilet</b>	<b>Ceramic</b>	<b>1 Each</b>	<b>Intact</b>	<b>3.30</b>	<b>Positive</b>
56	1 <sup>st</sup> Floor	Men's Restroom 2	West	Tan	Partician	Metal	2 Each	Intact	0.00	Negative
57	1 <sup>st</sup> Floor	Men's Restroom 2	North	White	Ceiling	Drywall	88 SF	Intact	0.00	Negative
58	1 <sup>st</sup> Floor	Men's Restroom 2	North	Brown	2'x2' Floor Tile	Ceramic	88 SF	Intact	0.00	Negative



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509363  
**Samples Submitted:** 72  
**Sample Collection Date:** 11/26/2018  
**Laboratory Receipt Date:** 11/29/2018

**Project ID:** 2069218AM  
**Project Name:** Kimberly Clark - Bldg #19  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 1 of 19

### TEST DATA

---

**Laboratory ID#:** 1509363-001                      **Client Sample #:** 1

**Sample Material and Location:** White 12" x 12" Ceiling Tile Warehouse Office - N.E. End

**Sample Characteristics:** Grey Fibrous Inhomogenous  
**Misc. Components Observed:** 60% Non-Fibrous Material  
10% Fibrous Glass  
30% Cellulose

**Asbestos Observed (%):**                      **Date Analyzed:** 11/29/2018                      **Total Asbestos (%)** None Detected  
**Analyst:** Dennis Liu

### TEST DATA

---

**Laboratory ID#:** 1509363-002                      **Client Sample #:** 2

**Sample Material and Location:** White 12" x 12" Ceiling Tile Warehouse Office - East End

**Sample Characteristics:** Grey Fibrous Inhomogenous  
**Misc. Components Observed:** 60% Non-Fibrous Material  
10% Fibrous Glass  
30% Cellulose

**Asbestos Observed (%):**                      **Date Analyzed:** 11/29/2018                      **Total Asbestos (%)** None Detected  
**Analyst:** Dennis Liu

### TEST DATA

---

**Laboratory ID#:** 1509363-003                      **Client Sample #:** 3

**Sample Material and Location:** White 12" x 12" Ceiling Tile Warehouse Office - S.E. End

**Sample Characteristics:** Grey Fibrous Inhomogenous  
**Misc. Components Observed:** 60% Non-Fibrous Material  
10% Fibrous Glass  
30% Cellulose

**Asbestos Observed (%):**                      **Date Analyzed:** 11/29/2018                      **Total Asbestos (%)** None Detected  
**Analyst:** Dennis Liu

### TEST DATA

---

**Laboratory ID#:** 1509363-004                      **Client Sample #:** 4

**Sample Material and Location:** Brown Ceiling Tile Mastic Warehouse Office - N.E. End

**Sample Characteristics:** Brown Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**                      **Date Analyzed:** 11/29/2018                      **Total Asbestos (%)** None Detected  
**Analyst:** Dennis Liu



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509363  
**Samples Submitted:** 72  
**Sample Collection Date:** 11/26/2018  
**Laboratory Receipt Date:** 11/29/2018

**Project ID:** 2069218AM  
**Project Name:** Kimberly Clark - Bldg #19  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 2 of 19

### TEST DATA

**Laboratory ID#:** 1509363-005      **Client Sample #:** 5

**Sample Material and Location:** Brown Ceiling Tile Mastic Warehouse Office - East End

**Sample Characteristics:** Brown Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/29/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509363-006      **Client Sample #:** 6

**Sample Material and Location:** Brown Ceiling Tile Mastic Warehouse Office - S.E. End

**Sample Characteristics:** Brown Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/29/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509363-007      **Client Sample #:** 7

**Sample Material and Location:** White Drywall behind 12" x 12" C.T. Warehouse Office - N.E. End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 95% Non-Fibrous Material  
5% Cellulose  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/29/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509363-008      **Client Sample #:** 8

**Sample Material and Location:** White Drywall behind 12" x 12" C.T. Warehouse Office - East End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 95% Non-Fibrous Material  
5% Cellulose  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/29/2018

**Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509363  
**Samples Submitted:** 72  
**Sample Collection Date:** 11/26/2018  
**Laboratory Receipt Date:** 11/29/2018

**Project ID:** 2069218AM  
**Project Name:** Kimberly Clark - Bldg #19  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 3 of 19

### TEST DATA

---

**Laboratory ID#:** 1509363-009      **Client Sample #:** 9

**Sample Material and Location:** White Drywall behind 12" x 12" C.T. Warehouse Office - S.E. End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 95% Non-Fibrous Material  
5% Cellulose

**Asbestos Observed (%):**      **Date Analyzed:** 11/29/2018      **Total Asbestos (%)** None Detected  
**Analyst:** Dennis Liu

### TEST DATA

---

**Laboratory ID#:** 1509363-010      **Client Sample #:** 10

**Sample Material and Location:** Gray 4" Covebase Warehouse Office - South End

**Sample Characteristics:** Grey Smooth Inhomogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**      **Date Analyzed:** 11/29/2018      **Total Asbestos (%)** None Detected  
**Analyst:** Dennis Liu

### TEST DATA

---

**Laboratory ID#:** 1509363-011      **Client Sample #:** 11

**Sample Material and Location:** Gray 4" Covebase Warehouse Office - West End

**Sample Characteristics:** Grey Smooth Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**      **Date Analyzed:** 11/29/2018      **Total Asbestos (%)** None Detected  
**Analyst:** Dennis Liu

### TEST DATA

---

**Laboratory ID#:** 1509363-012      **Client Sample #:** 12

**Sample Material and Location:** Gray 4" Covebase Warehouse Office - North End

**Sample Characteristics:** Grey Smooth Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**      **Date Analyzed:** 11/29/2018      **Total Asbestos (%)** None Detected  
**Analyst:** Dennis Liu



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509363  
**Samples Submitted:** 72  
**Sample Collection Date:** 11/26/2018  
**Laboratory Receipt Date:** 11/29/2018

**Project ID:** 2069218AM  
**Project Name:** Kimberly Clark - Bldg #19  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 4 of 19

### TEST DATA

**Laboratory ID#:** 1509363-013      **Client Sample #:** 13

**Sample Material and Location:** Offwhite Covebase Glue Warehouse Office - South End

**Sample Characteristics:** Off-White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**

**Analyst:** Dennis Liu

**Date Analyzed:** 11/29/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509363-014      **Client Sample #:** 14

**Sample Material and Location:** Offwhite Covebase Glue Warehouse Office - West End

**Sample Characteristics:** Off-White Non-Fibrous Homogenous

**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**

**Analyst:** Dennis Liu

**Date Analyzed:** 11/29/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509363-015      **Client Sample #:** 15

**Sample Material and Location:** Offwhite Covebase Glue Warehouse Office - North End

**Sample Characteristics:** Off-White Non-Fibrous Homogenous

**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**

**Analyst:** Dennis Liu

**Date Analyzed:** 11/29/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509363-016      **Client Sample #:** 16

**Sample Material and Location:** Gray 12 x 12 Floor Tile Warehouse Office - South End

**Sample Characteristics:** Grey Non-Fibrous Homogenous

**Misc. Components Observed:** 100% Fibrous Glass

100% Non-Fibrous Material Fibrous Glass

**Asbestos Observed (%):**

**Analyst:** Dennis Liu

**Date Analyzed:** 11/29/2018

**Total Asbestos (%)** None Detected





## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509363  
**Samples Submitted:** 72  
**Sample Collection Date:** 11/26/2018  
**Laboratory Receipt Date:** 11/29/2018

**Project ID:** 2069218AM  
**Project Name:** Kimberly Clark - Bldg #19  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 5 of 19

### TEST DATA

**Laboratory ID#:** 1509363-017      **Client Sample #:** 17

**Sample Material and Location:** Gray 12 x 12 Floor Tile Warehouse Office - West End

**Sample Characteristics:** Grey Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/29/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509363-018      **Client Sample #:** 18

**Sample Material and Location:** Gray 12 x 12 Floor Tile Warehouse Office - North End

**Sample Characteristics:** Grey Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/29/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509363-019      **Client Sample #:** 19

**Sample Material and Location:** Yellow Floor Tile Glue Warehouse Office - South End

**Sample Characteristics:** Yellow Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/29/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509363-020      **Client Sample #:** 20

**Sample Material and Location:** Yellow Floor Tile Glue Warehouse Office - West End

**Sample Characteristics:** Yellow Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/29/2018

**Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509363  
**Samples Submitted:** 72  
**Sample Collection Date:** 11/26/2018  
**Laboratory Receipt Date:** 11/29/2018

**Project ID:** 2069218AM  
**Project Name:** Kimberly Clark - Bldg #19  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 6 of 19

### TEST DATA

---

**Laboratory ID#:** 1509363-021      **Client Sample #:** 21

**Sample Material and Location:** Yellow Floor Tile Glue Warehouse Office - North End

**Sample Characteristics:** Yellow Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/29/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509363-022      **Client Sample #:** 22

**Sample Material and Location:** Gray Caulking on Fan Units Fan Unit #4 - S.W. End

**Sample Characteristics:** Grey Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/29/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509363-023      **Client Sample #:** 23

**Sample Material and Location:** Gray Caulking on Fan Units Fan Unit #4 - North End

**Sample Characteristics:** Grey Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/29/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509363-024      **Client Sample #:** 24

**Sample Material and Location:** Gray Caulking on Fan Units Fan Unit #5 - N.W. End

**Sample Characteristics:** Grey Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/29/2018

**Total Asbestos (%)** None Detected





## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509363  
**Samples Submitted:** 72  
**Sample Collection Date:** 11/26/2018  
**Laboratory Receipt Date:** 11/29/2018

**Project ID:** 2069218AM  
**Project Name:** Kimberly Clark - Bldg #19  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 8 of 19

### TEST DATA

**Laboratory ID#:** 1509363-029      **Client Sample #:** 29

**Sample Material and Location:** Yellow Pipe Insulation 2nd Floor - Center

**Sample Characteristics:** Yellow Fibrous Homogenous  
**Misc. Components Observed:** 3% Non-Fibrous Material  
97% Fibrous Glass

**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/29/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509363-030      **Client Sample #:** 30

**Sample Material and Location:** Yellow Pipe Insulation Mech. Room - Center

**Sample Characteristics:** Yellow Fibrous Homogenous  
**Misc. Components Observed:** 3% Non-Fibrous Material  
97% Fibrous Glass

**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/29/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509363-031      **Client Sample #:** 31

**Sample Material and Location:** Tan 12 x 12 Floor Tile 2nd Floor Break Room - N.E. End

**Sample Characteristics:** Tan Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/29/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509363-032      **Client Sample #:** 32

**Sample Material and Location:** Tan 12 x 12 Floor Tile 2nd Floor Office #4 - East End

**Sample Characteristics:** Tan Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/29/2018

**Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509363  
**Samples Submitted:** 72  
**Sample Collection Date:** 11/26/2018  
**Laboratory Receipt Date:** 11/29/2018

**Project ID:** 2069218AM  
**Project Name:** Kimberly Clark - Bldg #19  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 9 of 19

### TEST DATA

**Laboratory ID#:** 1509363-033      **Client Sample #:** 33

**Sample Material and Location:** Tan 12 x 12 Floor Tile 2nd Floor Janitors Closet - West End

**Sample Characteristics:** Tan Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/29/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509363-034      **Client Sample #:** 34

**Sample Material and Location:** Black Floor Tile Mastic 2nd Floor Break Room - N.E. End

**Sample Characteristics:** Black Non-Fibrous Homogenous  
**Misc. Components Observed:** 95% Non-Fibrous Material  
**Asbestos Observed (%):** Chrysotile 5%  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/29/2018

**Total Asbestos (%)** 5%

### TEST DATA

**Laboratory ID#:** 1509363-035      **Client Sample #:** 35

**Sample Material and Location:** Black Floor Tile Mastic 2nd Floor Office #4 - East End

**Sample Characteristics:** Black Non-Fibrous Homogenous  
**Misc. Components Observed:** 95% Non-Fibrous Material  
**Asbestos Observed (%):** Chrysotile 5%  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/29/2018

**Total Asbestos (%)** 5%

### TEST DATA

**Laboratory ID#:** 1509363-036      **Client Sample #:** 36

**Sample Material and Location:** Black Floor Tile Mastic 2nd Floor Janitors Closet - West End

**Sample Characteristics:** Black Non-Fibrous Homogenous  
**Misc. Components Observed:** 95% Non-Fibrous Material  
**Asbestos Observed (%):** Chrysotile 5%  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/29/2018

**Total Asbestos (%)** 5%



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509363  
**Samples Submitted:** 72  
**Sample Collection Date:** 11/26/2018  
**Laboratory Receipt Date:** 11/29/2018

**Project ID:** 2069218AM  
**Project Name:** Kimberly Clark - Bldg #19  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 10 of 19

### TEST DATA

---

**Laboratory ID#:** 1509363-037      **Client Sample #:** 37

**Sample Material and Location:** Brown 4" Covebase 2nd Floor Break Room - N.E. End

**Sample Characteristics:** Brown Smooth Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**

**Analyst:** Dennis Liu      **Date Analyzed:** 11/29/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509363-038      **Client Sample #:** 38

**Sample Material and Location:** Brown 4" Covebase 2nd Floor Office #4 - East End

**Sample Characteristics:** Brown Smooth Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**

**Analyst:** Dennis Liu      **Date Analyzed:** 11/29/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509363-039      **Client Sample #:** 39

**Sample Material and Location:** Brown 4" Covebase 2nd Floor Janitors Closet - West End

**Sample Characteristics:** Brown Smooth Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**

**Analyst:** Dennis Liu      **Date Analyzed:** 11/29/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509363-040      **Client Sample #:** 40

**Sample Material and Location:** Brown Covebase Mastic 2nd Floor Break Room - N.E. End

**Sample Characteristics:** Brown Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**

**Analyst:** Dennis Liu      **Date Analyzed:** 11/29/2018

**Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509363  
**Samples Submitted:** 72  
**Sample Collection Date:** 11/26/2018  
**Laboratory Receipt Date:** 11/29/2018

**Project ID:** 2069218AM  
**Project Name:** Kimberly Clark - Bldg #19  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 11 of 19

### TEST DATA

---

**Laboratory ID#:** 1509363-041      **Client Sample #:** 41

**Sample Material and Location:** Brown Covebase Mastic 2nd Floor Office #4 - East End

**Sample Characteristics:** Brown Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/29/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509363-042      **Client Sample #:** 42

**Sample Material and Location:** Brown Covebase Mastic 2nd Floor Janitors Closet - West End

**Sample Characteristics:** Brown Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/29/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509363-043      **Client Sample #:** 43

**Sample Material and Location:** White 2 x 4 Ceiling Tile 1st Floor Locker Room - East End

**Sample Characteristics:** Grey Fibrous Inhomogenous  
**Misc. Components Observed:** 60% Non-Fibrous Material  
10% Fibrous Glass  
30% Cellulose

**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/29/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509363-044      **Client Sample #:** 44

**Sample Material and Location:** White 2 x 4 Ceiling Tile 2nd Floor Break Room - N.E. End

**Sample Characteristics:** Grey Fibrous Inhomogenous  
**Misc. Components Observed:** 60% Non-Fibrous Material  
10% Fibrous Glass  
30% Cellulose

**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/29/2018

**Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509363  
**Samples Submitted:** 72  
**Sample Collection Date:** 11/26/2018  
**Laboratory Receipt Date:** 11/29/2018

**Project ID:** 2069218AM  
**Project Name:** Kimberly Clark - Bldg #19  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 12 of 19

### TEST DATA

**Laboratory ID#:** 1509363-045 **Client Sample #:** 45

**Sample Material and Location:** White 2 x 4 Ceiling Tile 2nd Floor Office #4 - East End

**Sample Characteristics:** Grey Fibrous Inhomogenous  
**Misc. Components Observed:** 60% Non-Fibrous Material  
10% Fibrous Glass  
30% Cellulose

**Asbestos Observed (%):**  
**Analyst:** Dennis Liu **Date Analyzed:** 11/29/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509363-046 **Client Sample #:** 46

**Sample Material and Location:** Gray Linoleum 1st Floor Breakroom - West End

**Sample Characteristics:** Grey Fibrous Inhomogenous  
**Misc. Components Observed:** 68% Non-Fibrous Material  
2% Fibrous Glass  
30% Cellulose

**Asbestos Observed (%):**  
**Analyst:** Dennis Liu **Date Analyzed:** 11/29/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509363-047 **Client Sample #:** 47

**Sample Material and Location:** Gray Linoleum 1st Floor Breakroom - North End

**Sample Characteristics:** Grey Fibrous Inhomogenous  
**Misc. Components Observed:** 68% Non-Fibrous Material  
2% Fibrous Glass  
30% Cellulose

**Asbestos Observed (%):**  
**Analyst:** Dennis Liu **Date Analyzed:** 11/29/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509363-048 **Client Sample #:** 48

**Sample Material and Location:** Gray Linoleum 1st Floor Breakroom - South End

**Sample Characteristics:** Grey Fibrous Inhomogenous  
**Misc. Components Observed:** 68% Non-Fibrous Material  
2% Fibrous Glass  
30% Cellulose

**Asbestos Observed (%):**  
**Analyst:** Dennis Liu **Date Analyzed:** 11/29/2018

**Total Asbestos (%)** None Detected





## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509363  
**Samples Submitted:** 72  
**Sample Collection Date:** 11/26/2018  
**Laboratory Receipt Date:** 11/29/2018

**Project ID:** 2069218AM  
**Project Name:** Kimberly Clark - Bldg #19  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 13 of 19

### TEST DATA

**Laboratory ID#:** 1509363-049      **Client Sample #:** 49

**Sample Material and Location:** Yellow Linoleum Glue 1st Floor Breakroom - West End

**Sample Characteristics:** Yellow Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/29/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509363-050      **Client Sample #:** 50

**Sample Material and Location:** Yellow Linoleum Glue 1st Floor Breakroom - North End

**Sample Characteristics:** Yellow Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/29/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509363-051      **Client Sample #:** 51

**Sample Material and Location:** Yellow Linoleum Glue 1st Floor Breakroom - South End

**Sample Characteristics:** Yellow Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/29/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509363-052      **Client Sample #:** 52

**Sample Material and Location:** Brown Linoleum 2nd Floor Locker Room - East End

**Sample Characteristics:** Beige Fibrous Inhomogenous  
**Misc. Components Observed:** 55% Non-Fibrous Material  
30% Cellulose  
**Asbestos Observed (%):** Chrysotile 15%  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/29/2018

**Total Asbestos (%)** 15%



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509363  
**Samples Submitted:** 72  
**Sample Collection Date:** 11/26/2018  
**Laboratory Receipt Date:** 11/29/2018

**Project ID:** 2069218AM  
**Project Name:** Kimberly Clark - Bldg #19  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 14 of 19

### TEST DATA

**Laboratory ID#:** 1509363-053      **Client Sample #:** 53

**Sample Material and Location:** Brown Linoleum 2nd Floor Locker Room - West End

**Sample Characteristics:** Beige Fibrous Inhomogenous  
**Misc. Components Observed:** 55% Non-Fibrous Material  
30% Cellulose

**Asbestos Observed (%):** **Chrysotile** 15%      **Total Asbestos (%)** 15%  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/29/2018

### TEST DATA

**Laboratory ID#:** 1509363-054      **Client Sample #:** 54

**Sample Material and Location:** Brown Linoleum 1st Floor Locker Room - East End

**Sample Characteristics:** Beige Fibrous Inhomogenous  
**Misc. Components Observed:** 55% Non-Fibrous Material  
30% Cellulose

**Asbestos Observed (%):** **Chrysotile** 15%      **Total Asbestos (%)** 15%  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/29/2018

### TEST DATA

**Laboratory ID#:** 1509363-055      **Client Sample #:** 55

**Sample Material and Location:** Yellow/White Linoleum Glue 2nd Floor Locker Room - East End

**Sample Characteristics:** Yellow Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**      **Date Analyzed:** 11/29/2018      **Total Asbestos (%)** None Detected  
**Analyst:** Dennis Liu

### TEST DATA

**Laboratory ID#:** 1509363-056      **Client Sample #:** 56

**Sample Material and Location:** Yellow/White Linoleum Glue 2nd Floor Locker Room - West End

**Sample Characteristics:** Yellow Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**      **Date Analyzed:** 11/29/2018      **Total Asbestos (%)** None Detected  
**Analyst:** Dennis Liu



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509363  
**Samples Submitted:** 72  
**Sample Collection Date:** 11/26/2018  
**Laboratory Receipt Date:** 11/29/2018

**Project ID:** 2069218AM  
**Project Name:** Kimberly Clark - Bldg #19  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 15 of 19

### TEST DATA

**Laboratory ID#:** 1509363-057      **Client Sample #:** 57

**Sample Material and Location:** Yellow/White Linoleum Glue 1st Floor Locker Room - East End

**Sample Characteristics:** Yellow Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**

**Analyst:** Dennis Liu

**Date Analyzed:** 11/29/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509363-058      **Client Sample #:** 58

**Sample Material and Location:** Yellow Ceiling Insulation 1st Floor Locker Room - East End

**Sample Characteristics:** Yellow Fibrous Homogenous  
**Misc. Components Observed:** 3% Non-Fibrous Material  
97% Fibrous Glass

**Asbestos Observed (%):**

**Analyst:** Dennis Liu

**Date Analyzed:** 11/29/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509363-059      **Client Sample #:** 59

**Sample Material and Location:** Yellow Ceiling Insulation 2nd Floor Break Room - N.E. End

**Sample Characteristics:** Yellow Fibrous Homogenous  
**Misc. Components Observed:** 3% Non-Fibrous Material  
97% Fibrous Glass

**Asbestos Observed (%):**

**Analyst:** Dennis Liu

**Date Analyzed:** 11/29/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509363-060      **Client Sample #:** 60

**Sample Material and Location:** Yellow Ceiling Insulation 2nd Floor Office #4 - East End

**Sample Characteristics:** Yellow Fibrous Homogenous  
**Misc. Components Observed:** 3% Non-Fibrous Material  
97% Fibrous Glass

**Asbestos Observed (%):**

**Analyst:** Dennis Liu

**Date Analyzed:** 11/29/2018

**Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509363  
**Samples Submitted:** 72  
**Sample Collection Date:** 11/26/2018  
**Laboratory Receipt Date:** 11/29/2018

**Project ID:** 2069218AM  
**Project Name:** Kimberly Clark - Bldg #19  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 16 of 19

### TEST DATA

**Laboratory ID#:** 1509363-061      **Client Sample #:** 61

**Sample Material and Location:** White Drywall 2nd Floor Office #4 - East End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 95% Non-Fibrous Material  
5% Cellulose

**Asbestos Observed (%):**      **Date Analyzed:** 11/29/2018      **Total Asbestos (%)** None Detected  
**Analyst:** Dennis Liu

### TEST DATA

**Laboratory ID#:** 1509363-062      **Client Sample #:** 62

**Sample Material and Location:** White Drywall 1st Floor Break Room - East End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 95% Non-Fibrous Material  
5% Cellulose

**Asbestos Observed (%):**      **Date Analyzed:** 11/29/2018      **Total Asbestos (%)** None Detected  
**Analyst:** Dennis Liu

### TEST DATA

**Laboratory ID#:** 1509363-063      **Client Sample #:** 63

**Sample Material and Location:** White Drywall 2nd Floor Janitors Closet - West End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 95% Non-Fibrous Material  
5% Cellulose

**Asbestos Observed (%):**      **Date Analyzed:** 11/29/2018      **Total Asbestos (%)** None Detected  
**Analyst:** Dennis Liu

### TEST DATA

**Laboratory ID#:** 1509363-064      **Client Sample #:** 64

**Sample Material and Location:** White Joint Compound 2nd Floor Office #4 - East End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**      **Date Analyzed:** 11/29/2018      **Total Asbestos (%)** None Detected  
**Analyst:** Dennis Liu



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509363  
**Samples Submitted:** 72  
**Sample Collection Date:** 11/26/2018  
**Laboratory Receipt Date:** 11/29/2018

**Project ID:** 2069218AM  
**Project Name:** Kimberly Clark - Bldg #19  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 17 of 19

### TEST DATA

**Laboratory ID#:** 1509363-065      **Client Sample #:** 65

**Sample Material and Location:** White Joint Compound 1st Floor Break Room - East End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/29/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509363-066      **Client Sample #:** 66

**Sample Material and Location:** White Joint Compound 2nd Floor Janitors Closet - West End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/29/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509363-067      **Client Sample #:** 67

**Sample Material and Location:** Black Foam Insulation on Motor Equipment Mech. Room - South End

**Sample Characteristics:** Black Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/29/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509363-068      **Client Sample #:** 68

**Sample Material and Location:** Black Foam Insulation on Motor Equipment Mech. Room - Center

**Sample Characteristics:** Black Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/29/2018

**Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509363  
**Samples Submitted:** 72  
**Sample Collection Date:** 11/26/2018  
**Laboratory Receipt Date:** 11/29/2018

**Project ID:** 2069218AM  
**Project Name:** Kimberly Clark - Bldg #19  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 18 of 19

### TEST DATA

**Laboratory ID#:** 1509363-069      **Client Sample #:** 69

**Sample Material and Location:** Black Foam Insulation on Motor Equipment Mech. Room - North End

**Sample Characteristics:** Black Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/29/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509363-070      **Client Sample #:** 70

**Sample Material and Location:** Brown Glue under Foam Insulation Mech. Room - South End

**Sample Characteristics:** Brown Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/29/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509363-071      **Client Sample #:** 71

**Sample Material and Location:** Brown Glue under Foam Insulation Mech. Room - Center

**Sample Characteristics:** Brown Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/29/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509363-072      **Client Sample #:** 72

**Sample Material and Location:** Brown Glue under Foam Insulation Mech. Room - North End

**Sample Characteristics:** Brown Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/29/2018

**Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509363  
**Samples Submitted:** 72  
**Sample Collection Date:** 11/26/2018  
**Laboratory Receipt Date:** 11/29/2018

**Project ID:** 2069218AM  
**Project Name:** Kimberly Clark - Bldg #19  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 19 of 19

Samples were analyzed by Calibrated Visual Estimation (CVE). Analyses by CVE have a detection limit of 1% asbestos by relative area and may not be consistently reliable below this limit or for asbestos with fiber diameter thinner than the resolving capacity of PLM without further analysis by another independent method. A test result of less than (<) 1% by CVE means asbestos was observed in the sample but is visually estimated to be below the reportable limit of 1%. The laboratory references interim method EPA 600/M4-82-020 (Interim Method) for fiber identification, 400 point counts, and composite reporting. EPA method 600/R-93/116 is referenced for analysis of non-insulation materials, sub-layers, expanded and modified point counts, CVE and subsequent data reporting. Samples containing distinct layers that can be reliably separated are analyzed and reported as separate unless requested in writing. The test data presented apply only to the items submitted. Count for samples submitted is indicative of total layers observed and may vary from actual analysis for positive stop requests. ATEL, LLC is a NIST-NVLAP and CA-ELAP Accredited laboratory (ID# 201073-0 and #2971, respectively). This report must not be reproduced, unless in its entirety, without the written consent of ATEL, LLC. Per NIST-NVLAP 150 Annex A: This report shall not be used to claim product certification, approval or endorsement by NVLAP, NIST, or any agency of the federal government.

Unless indicated, samples were received in acceptable condition. Sample retention time is 30 days from issuing this report unless requested otherwise.

Analyst Signature:

Handwritten signature of Dennis Liu in black ink.

-Dennis Liu

Approved Signatory:

Handwritten signature of Chris Turton in black ink.

-Chris Turton

Reported On: 11/30/2018







**H2 ENVIRONMENTAL**  
CONSULTING SERVICES, INC.

**Bulk Sampling Form**

Stop at First Positive    24 Hour turn around    Rush turn around (4 Hours)  
 Do Not Layer Samples

CLIENT <i>Kimberly Clark</i>	PROJECT NO. <i>2069218 AM</i>		
PROJECT ID <i>Bldg. #19</i>	DATE <i>11/26/18</i>	PAGE <i>1</i>	OF <i>4</i>
PROJECT LOCATION <i>2001 E. Orangewood Ave, Fullerton, CA</i>	INSPECTOR <i>A. Sanchez</i>		

GRP. NO.	SAMP. NO.	MATERIAL DESCRIPTION	LOCATION OF SAMPLE	QTY	% POS
01	01	white 12x17"	warehouse office - N.E. end	150φ	
↓	02	ceiling tile	↓ - east end	↓	
	03	↓	↓ - S.E. end	↓	
02	04	Ben. ceiling tile	warehouse office - N.E. end	150φ	
↓	05	mortar	↓ - east end	↓	
	06	↓	↓ - S.E. end	↓	
03	07	white Drywall	warehouse office - N.E. end	150φ	
↓	08	behind 12x12"	↓ - east end	↓	
	09	C.T.	↓ - S.E. end	↓	
04	10	gray 4" concrete	warehouse office - south end	506φ	
↓	11	↓	↓ - west end	↓	
	12	↓	↓ - north end	↓	
05	13	off-white concrete	warehouse office - south end	506φ	
↓	14	slur ↓	↓ - west end	↓	
	15	↓	↓ - north end	↓	
06	16	gray 12x12 Floor	warehouse office - south end	150φ	
↓	17	tile ↓	↓ - west end	↓	
	18	↓	↓ - north end	↓	
07	19	yellow floor tile	warehouse office - south end	150φ	
↓	20	glue ↓	↓ - west end	↓	
	21	↓	↓ - north end	↓	

Notes:



**H2 ENVIRONMENTAL CONSULTING SERVICES, INC.**


**Bulk Sampling Form**

Stop at First Positive     24 Hour turn around     Rush turn around (4 Hours)  
 Do Not Layer Samples

CLIENT <i>Kimberly Clark</i>	PROJECT NO. <i>2069218 Am</i>		
PROJECT ID <i>B16, #19</i>	DATE <i>11/26/18</i>	PAGE <i>2</i>	OF <i>4</i>
PROJECT LOCATION <i>2001 E. Ocean Blvd, Fullerton, CA</i>	INSPECTOR <i>A. Sanchez</i>		

GRP. NO.	SAMP. NO.	MATERIAL DESCRIPTION	LOCATION OF SAMPLE	QTY	% POS
08	22	Gray Caulking	FAN unit #14 - S.W. end	1000LF	
↓	23	on Fan units	↓ - North end	↓	
↓	24	↓	FAN unit #15 - N.W. end	↓	
09	25	white p.p.	2nd Flr. - South end	1000LF	
↓	26	wrap	↓ - Center	↓	
↓	27		Mech. Rm. Center	↓	
10	28	yellow p.p.	2nd Flr. - South end	1000LF	
↓	29	Insulation	↓ - Center	↓	
↓	30	↓	Mech. Rm. Center	↓	
11	31	TAN 12X12 FLOOR	2nd Flr. Break Rm - N.E. end	5,000SF	
↓	32	tile	2nd Flr. office #14 - East end	↓	
↓	33	↓	2nd Flr. Janitors closet - west end	↓	
12	34	BLK FLOOR tile	2nd Flr. Break Rm - N.E. end	500SF	
↓	35	marble	2nd Flr. office #14 - East end	↓	
↓	36	↓	2nd Flr. Janitors closet - west end	↓	
13	37	BRN. 4' Lumber	2nd Flr. Break Rm - N.E. end	1,975LF	
↓	38	↓	2nd Flr. office #14 - East end	↓	
↓	39	↓	2nd Flr. Janitors closet - west end	↓	
14	40	BRN. Lumber	2nd Flr. Break Rm - N.E. end	1,975LF	
↓	41	marble	2nd Flr. office #14 - East end	↓	
↓	42	↓	2nd Flr. Janitors closet - west end	↓	

Notes:



**ENVIRONMENTAL CONSULTING SERVICES, INC.**

**Bulk Sampling Form**

Stop at First Positive     24 Hour turn around     Rush turn around (4 Hours)  
 Do Not Layer Samples

CLIENT <i>Kimberly Clark</i>	PROJECT NO. <i>2069218 Am</i>		
PROJECT ID <i>Blk. 19</i>	DATE <i>11/26/18</i>	PAGE <i>3</i>	OF <i>4</i>
PROJECT LOCATION <i>2000 E. Orange Ave, Fullerton, CA</i>	INSPECTOR <i>A. Sanchez</i>		

GRP. NO.	SAMP. NO.	MATERIAL DESCRIPTION	LOCATION OF SAMPLE	QTY	% POS
15	43	white dry	1st Fl. Locker Room - East end		
↓	44	ceiling tile	2nd Fl. Break Room - N.E. end		
↓	45	↓	2nd Fl. Office #4 - east end		
16	46	gray linoleum	1st Fl. Break Room - west end		
↓	47	↓	↓ - North end		
↓	48	↓	↓ - South end		
17	49	yellow linoleum	1st Fl. Break Room - west end		
↓	50	glue	↓ - North end		
↓	51	↓	↓ - South end		
18	52	Brn. linoleum	2nd Fl. Locker Room - east end		
↓	53	↓	↓ - west end		
↓	54	↓	1st Fl. Locker Room - east end		
19	55	yellow/white linoleum	2nd Fl. Locker Room - east end		
↓	56	glue	↓ - west end		
↓	57	↓	1st Fl. Locker Room - East end		
20	58	yellow ceiling	1st Fl. Locker Room - East end		
↓	59	insulation	2nd Fl. Break Room - N.E. End		
↓	60	↓	2nd Fl. Office #4 - East end		
21	61	white Drywall	2nd Fl. office #4 - east end		
↓	62	↓	1st Fl. Break Room - east end		
↓	63	↓	2nd Fl. Janitor's closet - west end		

Notes:



**SECTION 2  
SURVEY SUMMARY**

**LEAD XRF SURVEY RESULTS  
BUILDING 19**

**Phase 2 - Fullerton Mill - 2069218 AS  
2001 East Orangethorpe Avenue  
Fullerton, California**

The list materials and their components where Lead Based Paint (LBP) was detected at or in excess of the HUD/EPA standards of 1.0 mg/cm<sup>2</sup> (Los Angeles County has established a more stringent standard for lead-based paint at 0.7mg/cm<sup>2</sup>) by XRF method which is listed in the table below. All XRF readings below the regulatory defined action level are considered negative and all readings at and above these levels are considered positive.

Shot #	Unit	Room Tested	Wall	Color	Component	Substrate	Quantity	Paint Condition	Result	Neg/Pos
01	Bldg. 19	Storage	North	White	Wall	Drywall	450 SF	Intact	0.00	Negative
02	Bldg. 19	Storage	East	White	Wall	Ceramic	900 SF	Intact	0.01	Negative
03	Bldg. 19	Storage	East	Blue	Door Frame	Metal	2 Each	Intact	0.10	Negative
<b>04</b>	<b>Bldg. 19</b>	<b>Storage</b>	<b>East</b>	<b>Blue</b>	<b>Sliding Door</b>	<b>Metal</b>	<b>2 Each</b>	<b>Intact</b>	<b>4.10</b>	<b>Positive</b>
05	Bldg. 19	Storage	East	White	Sliding Door Frame	Metal	2 Each	Intact	0.10	Negative
06	Bldg. 19	Storage	East	White	Column	Concrete	6 Each	Intact	0.01	Negative
07	Bldg. 19	Storage	North	White	Wall	Block	450 SF	Intact	0.01	Negative
08	Bldg. 19	Storage	West	White	Electrical Panel	Metal	1 Each	Intact	0.01	Negative
09	Bldg. 19	Storage	West	White	Door Frame	Metal	1 Each	Intact	0.01	Negative
10	Bldg. 19	Storage	West	Blue	Door	Metal	1 Each	Intact	0.01	Negative
11	Bldg. 19	Storage	West	Tan	Wall	Concrete	30 SF	Intact	0.01	Negative
<b>12</b>	<b>Bldg. 19</b>	<b>Storage</b>	<b>West</b>	<b>White</b>	<b>Ceiling I-Beam</b>	<b>Metal</b>	<b>9 Each</b>	<b>Intact</b>	<b>10.1</b>	<b>Positive</b>
13	Bldg. 19	Storage	West	White	Ceiling Pipe	Metal	1 Each	Intact	0.01	Negative
14	Bldg. 19	Men's Restroom	North	Blue	Door Frame	Metal	1 Each	Intact	0.01	Negative
15	Bldg. 19	Men's Restroom	North	Blue	Door	Metal	1 Each	Intact	0.01	Negative
16	Bldg. 19	Men's Restroom	North	Tan	4"x4" Wall Tile	Ceramic	384 SF	Intact	0.01	Negative

**SECTION 2**  
**SURVEY SUMMARY**

**LEAD XRF SURVEY RESULTS**  
**BUILDING 19**

**Phase 2 - Fullerton Mill - 2069218 AS**  
**2001 East Orangethorpe Avenue**  
**Fullerton, California**

The list materials and their components where Lead Based Paint (LBP) was detected at or in excess of the HUD/EPA standards of 1.0 mg/cm<sup>2</sup> (Los Angeles County has established a more stringent standard for lead-based paint at 0.7mg/cm<sup>2</sup>) by XRF method which is listed in the table below. All XRF readings below the regulatory defined action level are considered negative and all readings at and above these levels are considered positive.

Shot #	Unit	Room Tested	Wall	Color	Component	Substrate	Quantity	Paint Condition	Result	Neg/Pos
17	Bldg. 19	Men's Restroom	North	Tan	4"x4" Base Wall Tile	Ceramic	48 SF	Intact	0.05	Negative
18	Bldg. 19	Men's Restroom	North	White	Sink	Ceramic	3 Each	Intact	0.05	Negative
19	Bldg. 19	Men's Restroom	North	White	Urinal	Ceramic	2 Each	Intact	0.01	Negative
20	Bldg. 19	Men's Restroom	North	White	Toilet	Ceramic	2 Each	Intact	0.05	Negative
21	Bldg. 19	Men's Restroom	North	Tan	Partition	Metal	2 Each	Intact	0.00	Negative
22	Bldg. 19	Men's Restroom	East	Brown	1'x1' Floor Tile	Ceramic	135 SF	Intact	0.00	Negative
23	Bldg. 19	Men's Restroom	East	White	Ceiling	Drywall	135 SF	Intact	0.00	Negative
24	Bldg. 19	Men's Restroom	North	White	Ceiling Vent	Metal	1 Each	Intact	0.00	Negative
25	Bldg. 19	Women's Restroom	South	Blue	Door Frame	Metal	1 Each	Intact	0.05	Negative
26	Bldg. 19	Women's Restroom	South	Blue	Door	Metal	1 Each	Intact	0.01	Negative
27	Bldg. 19	Women's Restroom	South	Tan	4"x4" Wall Tile	Ceramic	384 SF	Intact	0.05	Negative
28	Bldg. 19	Women's Restroom	South	Tan	4"x4" Base Wall Tile	Ceramic	48 SF	Intact	0.01	Negative
29	Bldg. 19	Women's Restroom	South	White	Sink	Ceramic	3 Each	Intact	0.01	Negative
30	Bldg. 19	Women's Restroom	South	White	Toilet	Ceramic	3 Each	Intact	0.01	Negative
31	Bldg. 19	Women's Restroom	South	Orange	Partition	Metal	3 Each	Intact	0.11	Negative
32	Bldg. 19	Women's Restroom	East	White	Ceiling	Drywall	135 SF	Intact	0.00	Negative

**SECTION 2**  
**SURVEY SUMMARY**

**LEAD XRF SURVEY RESULTS**  
**BUILDING 19**

**Phase 2 - Fullerton Mill - 2069218 AS**  
**2001 East Orangethorpe Avenue**  
**Fullerton, California**

The list materials and their components where Lead Based Paint (LBP) was detected at or in excess of the HUD/EPA standards of 1.0 mg/cm<sup>2</sup> (Los Angeles County has established a more stringent standard for lead-based paint at 0.7mg/cm<sup>2</sup>) by XRF method which is listed in the table below. All XRF readings below the regulatory defined action level are considered negative and all readings at and above these levels are considered positive.

Shot #	Unit	Room Tested	Wall	Color	Component	Substrate	Quantity	Paint Condition	Result	Neg/Pos
33	Bldg. 19	Women's Restroom	East	White	Ceiling Vent	Metal	1 Each	Intact	0.00	Negative
34	Bldg. 19	Women's Restroom	East	Brown	1'x1' Floor Tile	Ceramic	48 SF	Intact	0.00	Negative
35	Bldg. 19	Breakroom	North	White	Wall	Concrete	360 SF	Intact	0.00	Negative
36	Bldg. 19	Breakroom	North	Blue	Door Frame	Metal	2 Each	Intact	0.00	Negative
37	Bldg. 19	Breakroom	North	Blue	Door	Metal	2 Each	Intact	0.00	Negative
38	Bldg. 19	Breakroom	North	White	Column	Drywall	4 Each	Intact	0.00	Negative
39	Bldg. 19	Breakroom	East	Blue	Window Frame	Metal	2 Each	Intact	0.00	Negative
40	Bldg. 19	Warehouse	North	White	Wall	Concrete	200 SF	Intact	0.00	Negative
<b>41</b>	<b>Bldg. 19</b>	<b>Warehouse</b>	<b>North</b>	<b>Blue</b>	<b>Stair Frame</b>	<b>Metal</b>	<b>2 Each</b>	<b>Intact</b>	<b>1.00</b>	<b>Positive</b>
42	Bldg. 19	Warehouse	North	Blue	Stairs	Metal	2 Each	Intact	0.00	Negative
43	Bldg. 19	Warehouse	North	Yellow	Stair Rail	Metal	2 Each	Intact	0.30	Negative
44	Bldg. 19	Warehouse	North	Yellow	Barrier	Metal	45 LF	Intact	0.00	Negative
<b>45</b>	<b>Bldg. 19</b>	<b>Warehouse</b>	<b>North</b>	<b>Yellow</b>	<b>Floor</b>	<b>Concrete</b>	<b>456 LF</b>	<b>Intact</b>	<b>2.80</b>	<b>Positive</b>
46	Bldg. 19	Warehouse	North	Blue	Door Frame	Metal	1 Each	Intact	0.00	Negative
47	Bldg. 19	Warehouse	North	Blue	Door	Wood	1 Each	Intact	0.00	Negative
<b>48</b>	<b>Bldg. 19</b>	<b>Warehouse</b>	<b>North</b>	<b>Blue</b>	<b>Stair Brace</b>	<b>Metal</b>	<b>2 Each</b>	<b>Intact</b>	<b>1.00</b>	<b>Positive</b>

**SECTION 2  
SURVEY SUMMARY**

**LEAD XRF SURVEY RESULTS  
BUILDING 19**

**Phase 2 - Fullerton Mill - 2069218 AS  
2001 East Orangethorpe Avenue  
Fullerton, California**

The list materials and their components where Lead Based Paint (LBP) was detected at or in excess of the HUD/EPA standards of 1.0 mg/cm<sup>2</sup> (Los Angeles County has established a more stringent standard for lead-based paint at 0.7mg/cm<sup>2</sup>) by XRF method which is listed in the table below. All XRF readings below the regulatory defined action level are considered negative and all readings at and above these levels are considered positive.

Shot #	Unit	Room Tested	Wall	Color	Component	Substrate	Quantity	Paint Condition	Result	Neg/Pos
49	Bldg. 19	Warehouse	North	White	Wall	Concrete	24,240 SF	Intact	0.01	Negative
50	Bldg. 19	Warehouse	North	Brown	Door Frame	Metal	4 Each	Intact	0.01	Negative
51	Bldg. 19	Warehouse	North	Brown	Door	Metal	4 Each	Intact	0.01	Negative
52	Bldg. 19	Warehouse	North	Red	Water Pipe	Metal	456 LF	Intact	0.00	Negative
<b>53</b>	<b>Bldg. 19</b>	<b>Warehouse</b>	<b>North</b>	<b>Yellow</b>	<b>Column</b>	<b>Metal</b>	<b>20 Each</b>	<b>Intact</b>	<b>6.80</b>	<b>Positive</b>
<b>54</b>	<b>Bldg. 19</b>	<b>Warehouse</b>	<b>North</b>	<b>White</b>	<b>I-Beam</b>	<b>Metal</b>	<b>10 Each</b>	<b>Intact</b>	<b>3.80</b>	<b>Positive</b>
<b>55</b>	<b>Bldg. 19</b>	<b>Warehouse</b>	<b>East</b>	<b>Red</b>	<b>I-Beam</b>	<b>Metal</b>	<b>10 Each</b>	<b>Intact</b>	<b>3.80</b>	<b>Positive</b>
<b>56</b>	<b>Bldg. 19</b>	<b>Warehouse</b>	<b>East</b>	<b>Red</b>	<b>Column</b>	<b>Metal</b>	<b>4 Each</b>	<b>Intact</b>	<b>3.80</b>	<b>Positive</b>
57	Bldg. 19	Warehouse	East	Tan	Ceiling	Metal	68,400 SF	Intact	0.01	Negative
<b>58</b>	<b>Bldg. 19</b>	<b>Warehouse</b>	<b>East</b>	<b>Tan</b>	<b>I-Beam</b>	<b>Metal</b>	<b>6,840 SF</b>	<b>Intact</b>	<b>3.80</b>	<b>Positive</b>
<b>59</b>	<b>Bldg. 19</b>	<b>Warehouse</b>	<b>East</b>	<b>Tan</b>	<b>Angle Bracket</b>	<b>Metal</b>	<b>6,840 SF</b>	<b>Intact</b>	<b>6.80</b>	<b>Positive</b>
60	Bldg. 19	Warehouse	East	Tan	Pipe	Metal	684 LF	Intact	0.01	Negative
61	Bldg. 19	Warehouse	North	Brown	Stair Frame	Metal	2 Each	Intact	0.01	Negative
62	Bldg. 19	Warehouse	North	Brown	Staircase	Metal	2 Each	Intact	0.01	Negative
63	Bldg. 19	Warehouse	North	Yellow	Stair Rail	Metal	2 Each	Intact	0.01	Negative
64	Bldg. 19	Warehouse	North	Blue	Wall	Concrete	624 SF	Intact	0.00	Negative



**SECTION 2**  
**SURVEY SUMMARY**

**LEAD XRF SURVEY RESULTS**  
**BUILDING 19**

**Phase 2 - Fullerton Mill - 2069218 AS**  
**2001 East Orangethorpe Avenue**  
**Fullerton, California**

The list materials and their components where Lead Based Paint (LBP) was detected at or in excess of the HUD/EPA standards of 1.0 mg/cm<sup>2</sup> (Los Angeles County has established a more stringent standard for lead-based paint at 0.7mg/cm<sup>2</sup>) by XRF method which is listed in the table below. All XRF readings below the regulatory defined action level are considered negative and all readings at and above these levels are considered positive.

Shot #	Unit	Room Tested	Wall	Color	Component	Substrate	Quantity	Paint Condition	Result	Neg/Pos
<b>65</b>	<b>Bldg. 19</b>	<b>Warehouse</b>	<b>North</b>	<b>Tan</b>	<b>Platform Frame</b>	<b>Metal</b>	<b>1 Each</b>	<b>Intact</b>	<b>4.90</b>	<b>Positive</b>
66	Bldg. 19	Warehouse	North	Yellow	Platform Rail	Metal	1 Each	Intact	0.01	Negative
67	Bldg. 19	Warehouse	North	Brown	Door Frame	Metal	2 Each	Intact	0.00	Negative
68	Bldg. 19	Warehouse	North	Brown	Door	Metal	2 Each	Intact	0.00	Negative
69	Bldg. 19	Warehouse	East	Yellow	Shoot Ladder Rail	Metal	1 Each	Intact	0.00	Negative
70	Bldg. 19	Warehouse	East	White	Shoot Ladder	Metal	1 Each	Intact	0.00	Negative
71	Bldg. 19	Warehouse Locker	North	White	Wall	Concrete	176 SF	Intact	0.00	Negative
72	1 <sup>st</sup> Floor	Warehouse 1 Locker	North	Tan	Wall	Concrete	176 SF	Intact	0.00	Negative
73	1 <sup>st</sup> Floor	Refrigerant Area	West	White	Wall	Concrete	680 SF	Intact	0.00	Negative
<b>74</b>	<b>1<sup>st</sup> Floor</b>	<b>Refrigerant Area</b>	<b>South</b>	<b>White</b>	<b>Sliding Door</b>	<b>Metal</b>	<b>2 Each</b>	<b>Intact</b>	<b>6.80</b>	<b>Positive</b>
75	1 <sup>st</sup> Floor	Refrigerant Area	South	Orange	Floor	Concrete	5 SF	Intact	0.01	Negative
76	1 <sup>st</sup> Floor	Refrigerant Area	North	Tan	Wall	Concrete	96 SF	Intact	0.00	Negative
77	1 <sup>st</sup> Floor	Refrigerant Area	North	Blue	Door Frame	Metal	1 Each	Intact	0.00	Negative
78	1 <sup>st</sup> Floor	Refrigerant Area	North	Blue	Door	Metal	1 Each	Intact	0.00	Negative
79	1 <sup>st</sup> Floor	Refrigerant Area	West	Red	Shoot Ladder	Metal	2 Each	Intact	0.01	Negative
80	1 <sup>st</sup> Floor	Refrigerant Area	West	White	Ceiling	Metal	576 SF	Intact	0.08	Negative

**SECTION 2  
SURVEY SUMMARY**

**LEAD XRF SURVEY RESULTS  
BUILDING 19**

**Phase 2 - Fullerton Mill - 2069218 AS  
2001 East Orangethorpe Avenue  
Fullerton, California**

The list materials and their components where Lead Based Paint (LBP) was detected at or in excess of the HUD/EPA standards of 1.0 mg/cm<sup>2</sup> (Los Angeles County has established a more stringent standard for lead-based paint at 0.7mg/cm<sup>2</sup>) by XRF method which is listed in the table below. All XRF readings below the regulatory defined action level are considered negative and all readings at and above these levels are considered positive.

Shot #	Unit	Room Tested	Wall	Color	Component	Substrate	Quantity	Paint Condition	Result	Neg/Pos
<b>81</b>	<b>1<sup>st</sup> Floor</b>	<b>Refrigerant Area</b>	<b>West</b>	<b>White</b>	<b>Ceiling I-Beam</b>	<b>Metal</b>	<b>144 SF</b>	<b>Intact</b>	<b>6.80</b>	<b>Positive</b>
82	1 <sup>st</sup> Floor	Refrigerant Area	West	White	Pipe	Metal	576 LF	Intact	0.01	Negative
83	1 <sup>st</sup> Floor	Refrigerant Area	West	Green	Machine	Metal	3 Each	Intact	0.01	Negative
84	2 <sup>nd</sup> Floor	Office Area Hallway	West	Tan	Wall	Drywall	11,752 SF	Intact	0.00	Negative
85	2 <sup>nd</sup> Floor	Office Area Hallway	West	Brown	Door Frame	Metal	23 Each	Intact	0.00	Negative
86	2 <sup>nd</sup> Floor	Office Area Hallway	West	Brown	Door	Metal	23 Each	Intact	0.00	Negative
87	2 <sup>nd</sup> Floor	Office 1	West	Brown	Window Frame	Metal	11 Each	Intact	0.00	Negative
88	Bldg. 19	Office 2	West	White	Window Frame	Metal	12 Each	Intact	0.00	Negative
89	Bldg. 19	Office 2	West	White	Door Frame	Metal	4 Each	Intact	0.00	Negative
90	Bldg. 19	Warehouse 2	North	White	Wall	Concrete	26,480 SF	Intact	0.00	Negative
<b>91</b>	<b>Bldg. 19</b>	<b>Warehouse 2</b>	<b>North</b>	<b>Blue</b>	<b>Sliding Door</b>	<b>Wood</b>	<b>1 Each</b>	<b>Intact</b>	<b>4.80</b>	<b>Positive</b>
92	Bldg. 19	Warehouse 2	North	Yellow	Floor	Concrete	1,324 LF	Intact	0.01	Negative
93	Bldg. 19	Warehouse 2	West	Yellow	Barrier	Metal	1,324 LF	Intact	0.00	Negative
94	Bldg. 19	Warehouse 2	North	White	Ceiling	Metal	89,83 SF	Intact	0.00	Negative
<b>95</b>	<b>Bldg. 19</b>	<b>Warehouse 2</b>	<b>North</b>	<b>White</b>	<b>Ceiling I-Beam</b>	<b>Metal</b>	<b>8,983 SF</b>	<b>Intact</b>	<b>4.90</b>	<b>Positive</b>
<b>96</b>	<b>Bldg. 19</b>	<b>Warehouse 2</b>	<b>North</b>	<b>White</b>	<b>Ceiling Angle Bracket</b>	<b>Metal</b>	<b>8,983 SF</b>	<b>Intact</b>	<b>5.60</b>	<b>Positive</b>

**SECTION 2**  
**SURVEY SUMMARY**

**LEAD XRF SURVEY RESULTS**  
**BUILDING 19**

**Phase 2 - Fullerton Mill - 2069218 AS**  
**2001 East Orangethorpe Avenue**  
**Fullerton, California**

The list materials and their components where Lead Based Paint (LBP) was detected at or in excess of the HUD/EPA standards of 1.0 mg/cm<sup>2</sup> (Los Angeles County has established a more stringent standard for lead-based paint at 0.7mg/cm<sup>2</sup>) by XRF method which is listed in the table below. All XRF readings below the regulatory defined action level are considered negative and all readings at and above these levels are considered positive.

Shot #	Unit	Room Tested	Wall	Color	Component	Substrate	Quantity	Paint Condition	Result	Neg/Pos
97	Bldg. 19	Warehouse 2	North	White	Pipe	Metal	653 LF	Intact	0.00	Negative
98	Bldg. 19	Warehouse 2	North	Red	Pipe	Metal	653 LF	Intact	0.00	Negative
<b>99</b>	<b>Bldg. 19</b>	<b>Warehouse 2</b>	<b>South</b>	<b>Red</b>	<b>I-Beam</b>	<b>Metal</b>	<b>200 SF</b>	<b>Intact</b>	<b>5.60</b>	<b>Positive</b>
100	Bldg. 19	Warehouse 2	South	White	Duct	Metal	2,612 SF	Intact	0.01	Negative
<b>101</b>	<b>Bldg. 19</b>	<b>Warehouse 2</b>	<b>South</b>	<b>Yellow</b>	<b>Column</b>	<b>Metal</b>	<b>30 Each</b>	<b>Intact</b>	<b>5.90</b>	<b>Positive</b>

**SECTION 2  
SURVEY SUMMARY**

**LEAD XRF SURVEY RESULTS  
BUILDING 20**

**Phase 2 - Fullerton Mill - 2069218 AS  
2001 East Orangethorpe Avenue  
Fullerton, California**

The list materials and their components where Lead Based Paint (LBP) was detected at or in excess of the HUD/EPA standards of 1.0 mg/cm<sup>2</sup> (Los Angeles County has established a more stringent standard for lead-based paint at 0.7mg/cm<sup>2</sup>) by XRF method which is listed in the table below. All XRF readings below the regulatory defined action level are considered negative and all readings at and above these levels are considered positive.

Shot #	Unit	Room Tested	Wall	Color	Component	Substrate	Quantity	Paint Condition	Result	Neg/Pos
01	1 <sup>st</sup> Floor	Warehouse	North	White	Wall	Concrete	20,550 SF	Intact	0.00	Negative
<b>02</b>	<b>1<sup>st</sup> Floor</b>	<b>Warehouse</b>	<b>North</b>	<b>White</b>	<b>I-Beam</b>	<b>Metal</b>	<b>1,000 SF</b>	<b>Intact</b>	<b>6.80</b>	<b>Positive</b>
03	1 <sup>st</sup> Floor	Warehouse	North	White	Ceiling	Metal	41,810 SF	Intact	0.01	Negative
<b>04</b>	<b>1<sup>st</sup> Floor</b>	<b>Warehouse</b>	<b>North</b>	<b>White</b>	<b>Ceiling I-Beam</b>	<b>Metal</b>	<b>4,181 SF</b>	<b>Intact</b>	<b>6.90</b>	<b>Positive</b>
05	1 <sup>st</sup> Floor	Warehouse	North	Red	Pipe	Metal	1,000 SF	Intact	0.01	Negative
<b>06</b>	<b>1<sup>st</sup> Floor</b>	<b>Warehouse</b>	<b>North</b>	<b>White</b>	<b>Ceiling Angle Bracket</b>	<b>Metal</b>	<b>41,810 SF</b>	<b>Intact</b>	<b>6.80</b>	<b>Positive</b>
07	1 <sup>st</sup> Floor	Warehouse	East	White	Pipe	Metal	1,000 SF	Intact	0.01	Negative
08	1 <sup>st</sup> Floor	Warehouse	East	Yellow	Panel	Metal	1 Each	Intact	0.01	Negative
<b>09</b>	<b>1<sup>st</sup> Floor</b>	<b>Warehouse</b>	<b>East</b>	<b>Yellow</b>	<b>Bollard</b>	<b>Metal</b>	<b>1,000 SF</b>	<b>Intact</b>	<b>9.60</b>	<b>Positive</b>
10	1 <sup>st</sup> Floor	Warehouse	East	Brown	Door	Metal	4 Each	Intact	0.01	Negative
11	1 <sup>st</sup> Floor	Warehouse	East	Tan	Door Frame	Metal	4 Each	Intact	0.01	Negative
12	1 <sup>st</sup> Floor	Warehouse	East	Blue	Sliding Door Frame	Metal	6 Each	Intact	0.10	Negative
<b>13</b>	<b>1<sup>st</sup> Floor</b>	<b>Warehouse</b>	<b>East</b>	<b>Blue</b>	<b>Sliding Door</b>	<b>Metal</b>	<b>6 Each</b>	<b>Intact</b>	<b>1.70</b>	<b>Positive</b>
14	1 <sup>st</sup> Floor	Warehouse	East	Red	Floor	Concrete	100 SF	Intact	0.07	Negative
<b>15</b>	<b>1<sup>st</sup> Floor</b>	<b>Warehouse</b>	<b>East</b>	<b>Yellow</b>	<b>Floor</b>	<b>Concrete</b>	<b>100 LF</b>	<b>Intact</b>	<b>9.60</b>	<b>Positive</b>
16	1 <sup>st</sup> Floor	Warehouse	West	White	Floor	Concrete	100 LF	Intact	0.07	Negative

**SECTION 2**  
**SURVEY SUMMARY**

---

**LEAD XRF SURVEY RESULTS**  
**BUILDING 20**

**Phase 2 - Fullerton Mill - 2069218 AS**  
**2001 East Orangethorpe Avenue**  
**Fullerton, California**

The list materials and their components where Lead Based Paint (LBP) was detected at or in excess of the HUD/EPA standards of 1.0 mg/cm<sup>2</sup> (Los Angeles County has established a more stringent standard for lead-based paint at 0.7mg/cm<sup>2</sup>) by XRF method which is listed in the table below. All XRF readings below the regulatory defined action level are considered negative and all readings at and above these levels are considered positive.

Shot #	Unit	Room Tested	Wall	Color	Component	Substrate	Quantity	Paint Condition	Result	Neg/Pos
17	1 <sup>st</sup> Floor	Warehouse	South	Blue	Door Frame	Metal	12 Each	Intact	0.00	Negative
18	1 <sup>st</sup> Floor	Warehouse	South	Blue	Door	Metal	12 Each	Intact	0.00	Negative



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509335  
**Samples Submitted:** 78  
**Sample Collection Date:** 11/20/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #21  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 1 of 20

### TEST DATA

**Laboratory ID#:** 1509335-001      **Client Sample #:** 1

**Sample Material and Location:** White Drywall 1st Floor Hallway - North End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 95% Non-Fibrous Material  
5% Cellulose

**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509335-002      **Client Sample #:** 2

**Sample Material and Location:** White Drywall 2nd Floor Open Work Area - East End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 95% Non-Fibrous Material  
5% Cellulose

**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509335-003      **Client Sample #:** 3

**Sample Material and Location:** White Drywall 3rd Floor R/R - South End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 95% Non-Fibrous Material  
5% Cellulose

**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509335-004      **Client Sample #:** 4

**Sample Material and Location:** White Joint Compound 1st Floor Hallway - North End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509335  
**Samples Submitted:** 78  
**Sample Collection Date:** 11/20/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #21  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 2 of 20

### TEST DATA

**Laboratory ID#:** 1509335-005      **Client Sample #:** 5

**Sample Material and Location:** White Joint Compound 2nd Floor Open Work Area - East End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):** .  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509335-006      **Client Sample #:** 6

**Sample Material and Location:** White Joint Compound 3rd Floor R/R - South End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):** .  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509335-007      **Client Sample #:** 7

**Sample Material and Location:** Gray 4" Covebase 1st Floor Hallway - South End

**Sample Characteristics:** Gray Smooth Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):** .  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509335-008      **Client Sample #:** 8

**Sample Material and Location:** Gray 4" Covebase 2nd Floor Open Work Area - East End

**Sample Characteristics:** Gray Smooth Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):** .  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509335  
**Samples Submitted:** 78  
**Sample Collection Date:** 11/20/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #21  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 3 of 20

### TEST DATA

---

**Laboratory ID#:** 1509335-009      **Client Sample #:** 9

**Sample Material and Location:** Gray 4" Covebase 2nd Floor Office 18 - S.W. End

**Sample Characteristics:** Gray Smooth Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509335-010      **Client Sample #:** 10

**Sample Material and Location:** Brown/Tan Covebase Glue 1st Floor Hallway - South End

**Sample Characteristics:** Brown Tan Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509335-011      **Client Sample #:** 11

**Sample Material and Location:** Brown/Tan Covebase Glue 2nd Floor Open Work Area - East End

**Sample Characteristics:** Brown Tan Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509335-012      **Client Sample #:** 12

**Sample Material and Location:** Brown/Tan Covebase Glue 2nd Floor Office 18 - S.W. End

**Sample Characteristics:** Brown Tan Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected





## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509335  
**Samples Submitted:** 78  
**Sample Collection Date:** 11/20/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #21  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 4 of 20

### TEST DATA

---

**Laboratory ID#:** 1509335-013      **Client Sample #:** 13

**Sample Material and Location:** Brown 4" Covebase 1st Floor Facilities Conference Room - East End

**Sample Characteristics:** Brown Gray Smooth Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509335-014      **Client Sample #:** 14

**Sample Material and Location:** Brown 4" Covebase 1st Floor Facilities Conference Room - West End

**Sample Characteristics:** Brown Gray Smooth Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509335-015      **Client Sample #:** 15

**Sample Material and Location:** Brown 4" Covebase 1st Floor T.C. Main Conference Room - West End

**Sample Characteristics:** Brown Gray Smooth Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509335-016      **Client Sample #:** 16

**Sample Material and Location:** Brown/Tan Covebase Glue 1st Floor Facilities Conference Room - East End

**Sample Characteristics:** Brown Tan Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509335  
**Samples Submitted:** 78  
**Sample Collection Date:** 11/20/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #21  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 5 of 20

### TEST DATA

**Laboratory ID#:** 1509335-017      **Client Sample #:** 17

**Sample Material and Location:** Brown/Tan Covebase Glue 1st Floor Facilities Conference Room - West End

**Sample Characteristics:** Brown Tan Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509335-018      **Client Sample #:** 18

**Sample Material and Location:** Brown/Tan Covebase Glue 1st Floor T.C. Main Conference Room - West End

**Sample Characteristics:** Brown Tan Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509335-019      **Client Sample #:** 19

**Sample Material and Location:** Black 4" Covebase 3rd Floor Env. File Office #2 - South End

**Sample Characteristics:** Black Gray Smooth Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509335-020      **Client Sample #:** 20

**Sample Material and Location:** Black 4" Covebase 2nd Floor Hallway - South End

**Sample Characteristics:** Black Gray Smooth Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509335  
**Samples Submitted:** 78  
**Sample Collection Date:** 11/20/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #21  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 6 of 20

### TEST DATA

**Laboratory ID#:** 1509335-021      **Client Sample #:** 21

**Sample Material and Location:** Black 4" Covebase Stairwell 1st Floor - South End

**Sample Characteristics:** Black Gray Smooth Homogenous

**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**

**Analyst:** Dennis Liu      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509335-022      **Client Sample #:** 22

**Sample Material and Location:** Brown/Tan Covebase Glue 3rd Floor Env. File Office #2 - South End

**Sample Characteristics:** Beige Non-Fibrous Homogenous

**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**

**Analyst:** Dennis Liu      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509335-023      **Client Sample #:** 23

**Sample Material and Location:** Brown/Tan Covebase Glue 2nd Floor Hallway - South End

**Sample Characteristics:** Brown Tan Non-Fibrous Homogenous

**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**

**Analyst:** Dennis Liu      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509335-024      **Client Sample #:** 24

**Sample Material and Location:** Brown/Tan Covebase Glue Stairwell 1st Floor - South End

**Sample Characteristics:** Brown Tan Non-Fibrous Homogenous

**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**

**Analyst:** Dennis Liu      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509335  
**Samples Submitted:** 78  
**Sample Collection Date:** 11/20/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #21  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 7 of 20

### TEST DATA

**Laboratory ID#:** 1509335-025      **Client Sample #:** 25

**Sample Material and Location:** White 2' x 4' Ceiling Tile 1st Floor Open Office Area - Center

**Sample Characteristics:** White Gray Fibrous Inhomogenous  
**Misc. Components Observed:** 55% Non-Fibrous Material  
5% Fibrous Glass  
40% Cellulose

**Asbestos Observed (%):** **Total Asbestos (%)** None Detected  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/27/2018

### TEST DATA

**Laboratory ID#:** 1509335-026      **Client Sample #:** 26

**Sample Material and Location:** White 2' x 4' Ceiling Tile 2nd Floor Open Work Area Center

**Sample Characteristics:** White Gray Fibrous Inhomogenous  
**Misc. Components Observed:** 55% Non-Fibrous Material  
5% Fibrous Glass  
40% Cellulose

**Asbestos Observed (%):** **Total Asbestos (%)** None Detected  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/27/2018

### TEST DATA

**Laboratory ID#:** 1509335-027      **Client Sample #:** 27

**Sample Material and Location:** White 2' x 4' Ceiling Tile 3rd Floor Env. File Office #2 - Center

**Sample Characteristics:** White Gray Fibrous Inhomogenous  
**Misc. Components Observed:** 55% Non-Fibrous Material  
5% Fibrous Glass  
40% Cellulose

**Asbestos Observed (%):** **Total Asbestos (%)** None Detected  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/27/2018

### TEST DATA

**Laboratory ID#:** 1509335-028      **Client Sample #:** 28

**Sample Material and Location:** Yellow Carpet Glue under Blue Carpet 1st Floor 2 - South End

**Sample Characteristics:** Yellow Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):** **Total Asbestos (%)** None Detected  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/27/2018



**Analytical Report**

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509335  
**Samples Submitted:** 78  
**Sample Collection Date:** 11/20/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #21  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 8 of 20

**TEST DATA**

---

**Laboratory ID#:** 1509335-029                      **Client Sample #:** 29

**Sample Material and Location:** Yellow Carpet Glue under Blue Carpet 1st Floor 3 - West End

**Sample Characteristics:** Yellow Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu                      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

**TEST DATA**

---

**Laboratory ID#:** 1509335-030                      **Client Sample #:** 30

**Sample Material and Location:** Yellow Carpet Glue under Blue Carpet 1st Floor 5 - West End

**Sample Characteristics:** Yellow Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu                      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

**TEST DATA**

---

**Laboratory ID#:** 1509335-031                      **Client Sample #:** 31

**Sample Material and Location:** Light Gray/Blue 12 x 12 Floor Tile 1st Floor Facilities Conference Room - N.W. End

**Sample Characteristics:** Grey Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu                      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

**TEST DATA**

---

**Laboratory ID#:** 1509335-032                      **Client Sample #:** 32

**Sample Material and Location:** Light Gray/Blue 12 x 12 Floor Tile 2nd Floor Open Work Area - East End

**Sample Characteristics:** Grey Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu                      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509335  
**Samples Submitted:** 78  
**Sample Collection Date:** 11/20/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #21  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 9 of 20

### TEST DATA

---

**Laboratory ID#:** 1509335-033      **Client Sample #:** 33

**Sample Material and Location:** Light Gray/Blue 12 x 12 Floor Tile 2nd Floor Office 18 - S.W. End

**Sample Characteristics:** Grey Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509335-034      **Client Sample #:** 34

**Sample Material and Location:** Yellow/Gray Floor Tile Glue 1st Floor Facilities Conference Room - N.W. End

**Sample Characteristics:** Brown Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509335-035      **Client Sample #:** 35

**Sample Material and Location:** Yellow/Gray Floor Tile Glue 2nd Floor Open Work Area - East End

**Sample Characteristics:** Yellow Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509335-036      **Client Sample #:** 36

**Sample Material and Location:** Yellow/Gray Floor Tile Glue 2nd Floor Office 18 - S.W. End

**Sample Characteristics:** Yellow Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509335  
**Samples Submitted:** 78  
**Sample Collection Date:** 11/20/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #21  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 10 of 20

### TEST DATA

**Laboratory ID#:** 1509335-037 **Client Sample #:** 37

**Sample Material and Location:** Offwhite Floor Tile under Light Gray/Blue 12 x 12 F.T. 1st Floor Facilities Conference Room - N.W.

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509335-038 **Client Sample #:** 38

**Sample Material and Location:** Offwhite Floor Tile under Light Gray/Blue 12 x 12 F.T. 2nd Floor Open Work Area - East End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509335-039 **Client Sample #:** 39

**Sample Material and Location:** Offwhite Floor Tile under Light Gray/Blue 12 x 12 F.T. 2nd Floor Office 18 - S.W. End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509335-040 **Client Sample #:** 40

**Sample Material and Location:** Black Floor Tile Mastic 1st Floor Facilities Conference Room - N.W. End

**Sample Characteristics:** Black Non-Fibrous Homogenous  
**Misc. Components Observed:** 95% Non-Fibrous Material  
**Asbestos Observed (%):** Chrysotile 5%  
**Analyst:** Dennis Liu **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** 5%



**Analytical Report**

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509335  
**Samples Submitted:** 78  
**Sample Collection Date:** 11/20/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #21  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 11 of 20

**TEST DATA**

---

**Laboratory ID#:** 1509335-041                      **Client Sample #:** 41

**Sample Material and Location:** Black Floor Tile Mastic 2nd Floor Open Work Area - East End

**Sample Characteristics:** Black Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu                      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

**TEST DATA**

---

**Laboratory ID#:** 1509335-042                      **Client Sample #:** 42

**Sample Material and Location:** Black Floor Tile Mastic 2nd Floor Office 18 - S.W. End

**Sample Characteristics:** Black Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu                      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

**TEST DATA**

---

**Laboratory ID#:** 1509335-043                      **Client Sample #:** 43

**Sample Material and Location:** Gray w/Streaks 12 x 12 Floor Tile 1st Floor Office 9 - West End

**Sample Characteristics:** Grey Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu                      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

**TEST DATA**

---

**Laboratory ID#:** 1509335-044                      **Client Sample #:** 44

**Sample Material and Location:** Gray w/Streaks 12 x 12 Floor Tile Env. File Office #1 - West End

**Sample Characteristics:** Grey Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu                      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected





## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509335  
**Samples Submitted:** 78  
**Sample Collection Date:** 11/20/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #21  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 12 of 20

### TEST DATA

**Laboratory ID#:** 1509335-045      **Client Sample #:** 45

**Sample Material and Location:** Gray w/Streaks 12 x 12 Floor Tile Env. File Office #2 - South End

**Sample Characteristics:** Grey Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509335-046      **Client Sample #:** 46

**Sample Material and Location:** Yellow Floor Tile Glue 1st Floor Office 9 - West End

**Sample Characteristics:** Yellow Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509335-047      **Client Sample #:** 47

**Sample Material and Location:** Yellow Floor Tile Glue Env. File Office #1 - West End

**Sample Characteristics:** Yellow Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509335-048      **Client Sample #:** 48

**Sample Material and Location:** Yellow Floor Tile Glue Env. File Office #2 - South End

**Sample Characteristics:** Yellow Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected



**Analytical Report**

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509335  
**Samples Submitted:** 78  
**Sample Collection Date:** 11/20/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #21  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 13 of 20

**TEST DATA**

---

**Laboratory ID#:** 1509335-049                      **Client Sample #:** 49

**Sample Material and Location:** Tan w/Brown Streaks 12 x 12 Floor Tile Print Room- South End

**Sample Characteristics:** Tan Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu                      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)**    **None Detected**

**TEST DATA**

---

**Laboratory ID#:** 1509335-049L1                      **Client Sample #:** 49

**Sample Material and Location:** Mastic Print Room- South End

**Sample Characteristics:** Black Non-Fibrous Homogenous  
**Misc. Components Observed:** 95% Non-Fibrous Material  
**Asbestos Observed (%):** Chrysotile                      5%  
**Analyst:** Dennis Liu                      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)**                      **5%**

**TEST DATA**

---

**Laboratory ID#:** 1509335-050                      **Client Sample #:** 50

**Sample Material and Location:** Tan w/Brown Streaks 12 x 12 Floor Tile Hallway - South End

**Sample Characteristics:** Tan Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu                      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)**    **None Detected**

**TEST DATA**

---

**Laboratory ID#:** 1509335-050L1                      **Client Sample #:** 50

**Sample Material and Location:** Mastic Hallway - South End

**Sample Characteristics:** Black Non-Fibrous Homogenous  
**Misc. Components Observed:** 95% Non-Fibrous Material  
**Asbestos Observed (%):** Chrysotile                      5%  
**Analyst:** Dennis Liu                      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)**                      **5%**



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509335  
**Samples Submitted:** 78  
**Sample Collection Date:** 11/20/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #21  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 14 of 20

### TEST DATA

**Laboratory ID#:** 1509335-051 **Client Sample #:** 51

**Sample Material and Location:** Tan w/Brown Streaks 12 x 12 Floor Tile Office #5 - North End

**Sample Characteristics:** Tan Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509335-051L1 **Client Sample #:** 51

**Sample Material and Location:** Mastic Office #5 - North End

**Sample Characteristics:** Black Non-Fibrous Homogenous  
**Misc. Components Observed:** 95% Non-Fibrous Material  
**Asbestos Observed (%):** Chrysotile 5%  
**Analyst:** Dennis Liu **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** 5%

### TEST DATA

**Laboratory ID#:** 1509335-052 **Client Sample #:** 52

**Sample Material and Location:** Black Floor Tile Mastic Print Room- South End

**Sample Characteristics:** Black Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509335-053 **Client Sample #:** 53

**Sample Material and Location:** Black Floor Tile Mastic Hallway - South End

**Sample Characteristics:** Black Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509335  
**Samples Submitted:** 78  
**Sample Collection Date:** 11/20/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #21  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 15 of 20

### TEST DATA

---

**Laboratory ID#:** 1509335-054      **Client Sample #:** 54

**Sample Material and Location:** Black Floor Tile Mastic Office #5 - North End

**Sample Characteristics:** Black Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509335-055      **Client Sample #:** 55

**Sample Material and Location:** Brown 12 x 12 Floor Tile Print Room - West End

**Sample Characteristics:** Brown Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509335-056      **Client Sample #:** 56

**Sample Material and Location:** Brown 12 x 12 Floor Tile Stairwell 2nd Floor - North End

**Sample Characteristics:** Brown Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509335-057      **Client Sample #:** 57

**Sample Material and Location:** Brown 12 x 12 Floor Tile Stairwell 3rd Floor - West End

**Sample Characteristics:** Brown Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected



**Analytical Report**

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509335  
**Samples Submitted:** 78  
**Sample Collection Date:** 11/20/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #21  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 16 of 20

**TEST DATA**

---

**Laboratory ID#:** 1509335-058                      **Client Sample #:** 58

**Sample Material and Location:** Black/Brown Floor Tile Mastic Print Room - West End

**Sample Characteristics:** Brown Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu                      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

**TEST DATA**

---

**Laboratory ID#:** 1509335-059                      **Client Sample #:** 59

**Sample Material and Location:** Black/Brown Floor Tile Mastic Stairwell 2nd Floor - North End

**Sample Characteristics:** Brown Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu                      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

**TEST DATA**

---

**Laboratory ID#:** 1509335-060                      **Client Sample #:** 60

**Sample Material and Location:** Black/Brown Floor Tile Mastic Stairwell 3rd Floor - West End

**Sample Characteristics:** Brown Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu                      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

**TEST DATA**

---

**Laboratory ID#:** 1509335-061                      **Client Sample #:** 61

**Sample Material and Location:** Yellow Carpet Glue under Gray Carpet Stairwell 1st Floor - East End

**Sample Characteristics:** Yellow Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu                      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509335  
**Samples Submitted:** 78  
**Sample Collection Date:** 11/20/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #21  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 17 of 20

### TEST DATA

---

**Laboratory ID#:** 1509335-062      **Client Sample #:** 62

**Sample Material and Location:** Yellow Carpet Glue under Gray Carpet Stairwell 1st Floor - Center

**Sample Characteristics:** Yellow Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509335-063      **Client Sample #:** 63

**Sample Material and Location:** Yellow Carpet Glue under Gray Carpet Stairwell 1st Floor - West End

**Sample Characteristics:** Yellow Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509335-064      **Client Sample #:** 64

**Sample Material and Location:** Gray/Blue 12 x 12 Floor Tile 1st Floor Break Room - North End

**Sample Characteristics:** Grey Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509335-065      **Client Sample #:** 65

**Sample Material and Location:** Gray/Blue 12 x 12 Floor Tile 1st Floor T.C. Main Conference Room - East End

**Sample Characteristics:** Grey Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509335  
**Samples Submitted:** 78  
**Sample Collection Date:** 11/20/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #21  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 18 of 20

### TEST DATA

**Laboratory ID#:** 1509335-066      **Client Sample #:** 66

**Sample Material and Location:** Gray/Blue 12 x 12 Floor Tile 1st Floor T.C. Main Conference Room - N.W. End

**Sample Characteristics:** Grey Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509335-067      **Client Sample #:** 67

**Sample Material and Location:** Yellow Floor Tile Glue 1st Floor Break Room - North End

**Sample Characteristics:** Yellow Gray Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509335-068      **Client Sample #:** 68

**Sample Material and Location:** Yellow Floor Tile Glue 1st Floor T.C. Main Conference Room - East End

**Sample Characteristics:** Yellow Gray Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509335-069      **Client Sample #:** 69

**Sample Material and Location:** Yellow Floor Tile Glue 1st Floor T.C. Main Conference Room - N.W. End

**Sample Characteristics:** Yellow Gray Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509335  
**Samples Submitted:** 78  
**Sample Collection Date:** 11/20/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #21  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 19 of 20

### TEST DATA

**Laboratory ID#:** 1509335-070 **Client Sample #:** 70

**Sample Material and Location:** White Pipe Wrap Warehouse - West End

**Sample Characteristics:** White Fibrous Inhomogenous  
**Misc. Components Observed:** 50% Non-Fibrous Material  
10% Fibrous Glass  
40% Cellulose

**Asbestos Observed (%):**  
**Analyst:** Dennis Liu **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509335-071 **Client Sample #:** 71

**Sample Material and Location:** White Pipe Wrap Warehouse - Center North End

**Sample Characteristics:** White Fibrous Inhomogenous  
**Misc. Components Observed:** 50% Non-Fibrous Material  
10% Fibrous Glass  
40% Cellulose

**Asbestos Observed (%):**  
**Analyst:** Dennis Liu **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509335-072 **Client Sample #:** 72

**Sample Material and Location:** White Pipe Wrap Warehouse - East End

**Sample Characteristics:** White Fibrous Inhomogenous  
**Misc. Components Observed:** 50% Non-Fibrous Material  
10% Fibrous Glass  
40% Cellulose

**Asbestos Observed (%):**  
**Analyst:** Dennis Liu **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509335-073 **Client Sample #:** 73

**Sample Material and Location:** Yellow Pipe Insulation Warehouse - West End

**Sample Characteristics:** Yellow Fibrous Homogenous  
**Misc. Components Observed:** 3% Non-Fibrous Material  
97% Fibrous Glass

**Asbestos Observed (%):**  
**Analyst:** Dennis Liu **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected





## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509335  
**Samples Submitted:** 78  
**Sample Collection Date:** 11/20/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #21  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 20 of 20

### TEST DATA

**Laboratory ID#:** 1509335-074      **Client Sample #:** 74

**Sample Material and Location:** Yellow Pipe Insulation Warehouse - Center North End

**Sample Characteristics:** Yellow Fibrous Homogenous  
**Misc. Components Observed:** 3% Non-Fibrous Material  
97% Fibrous Glass

**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509335-075      **Client Sample #:** 75

**Sample Material and Location:** Yellow Pipe Insulation Warehouse - East End

**Sample Characteristics:** Yellow Fibrous Homogenous  
**Misc. Components Observed:** 3% Non-Fibrous Material  
97% Fibrous Glass

**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/28/2018

**Total Asbestos (%)** None Detected

Samples were analyzed by Calibrated Visual Estimation (CVE). Analyses by CVE have a detection limit of 1% asbestos by relative area and may not be consistently reliable below this limit or for asbestos with fiber diameter thinner than the resolving capacity of PLM without further analysis by another independent method. A test result of less than (<) 1% by CVE means asbestos was observed in the sample but is visually estimated to be below the reportable limit of 1%. The laboratory references interim method EPA 600/M4-82-020 (Interim Method) for fiber identification, 400 point counts, and composite reporting. EPA method 600/R-93/116 is referenced for analysis of non-insulation materials, sub-layers, expanded and modified point counts, CVE and subsequent data reporting. Samples containing distinct layers that can be reliably separated are analyzed and reported as separate unless requested in writing. The test data presented apply only to the items submitted. Count for samples submitted is indicative of total layers observed and may vary from actual analysis for positive stop requests. ATEL, LLC is a NIST-NVLAP and CA-ELAP Accredited laboratory (ID# 201073-0 and #2971, respectively). This report must not be reproduced, unless in its entirety, without the written consent of ATEL, LLC. Per NIST-NVLAP 150 Annex A: This report shall not be used to claim product certification, approval or endorsement by NVLAP, NIST, or any agency of the federal government.

Unless indicated, samples were received in acceptable condition. Sample retention time is 30 days from issuing this report unless requested otherwise.

**Analyst Signature:**  -Dennis Liu

**Approved Signatory:**  -Chris Turton

**Reported On:** 11/28/2018



1509335

Analytical Services Request v.112414

Pg 1 of 1

Asbestos Laboratory

**Your Contact Information**

Company Name (if by company): H2 Environmental Consulting Services, Inc.  
 Personal/Company Address: 13122 6th Street, Chino, CA 91710  
 Contact Person: Amy De Santiago  
 Contact Information: Main: 909-628-0369 E-Mail: labresults@h2env.com  
 Mobile: - Fax: 909-613-5845  
 How should we send your result Verbal  Verbal  E-mail  Fax

*\*If verbal results are requested, you must also select a second form of delivery.*

**Project Information**

Project Name: Kimberly Clark  
 Project #: 2069218AS  
 Project Location: 2001 E Orange Harbor Ave Fullerton, CA - Bldg # 21  
 PO#: \_\_\_\_\_ Claim# \_\_\_\_\_  
 Date Sampled: 11/20/18 Time Sampled: 11AM

**Analytical Type(s) Requested**

Asbestos in Bulk Materials, EPA 600/R-93/116, 600/M4-82-020  
 Routine, Calibrated Visual Estimation   
 Point Count: 400pts   
 1000pts   
 Gravimetric Reduction (72hr Minimum)   
 Fiber Count in Sampling Cartridge (25mm MCE)  
 Asbestos-like, NIOSH 7400 A Rules   
 Rotometer Calibration (Low and High Flow Rotometers)

**Turnaround Time\***

\*Business Hrs: 0800-1700 Mon-Fri.

Rush 3 Business Hrs\*   
 8 Business Hrs\*   
 Expedited 24 Business Hrs   
 Routine 48 Business Hrs   
 72 Business Hrs   
 Standard 5 Business Days

\*3hr TAT: Samples must be submitted by 2pm for same day results

\*8hr TAT: Samples must be submitted by 9am for same day results

Special Instructions: \_\_\_\_\_


**Sample Information**

Sample ID #	Description/Material Type	Location	Flow Rate	Start Time	Stop Time	Volume (L)
	Please See Attached					

For more samples, please continue onto supplemental form. Page # indication in upper-right-hand of form.

**Chain of Custody**

Relinquished By: Albert Encin Date and Time: 11/20/18 11AM  
 Received By: \_\_\_\_\_ Date and Time: \_\_\_\_\_  
 Relinquished By: Christina Date and Time: \_\_\_\_\_  
 Received By: \_\_\_\_\_ Date and Time: 11/27/18 2:50pm



**ENVIRONMENTAL CONSULTING SERVICES, INC.**


**Bulk Sampling Form**

Stop at First Positive 
  24 Hour turn around 
  Rush turn around (4 Hours) 
  Do Not Layer Samples

CLIENT <i>Kimberly Clark</i>	PROJECT NO. <i>2069218AS</i>
PROJECT ID <i>Bldg# 21</i>	DATE <i>11/20/18</i>
PROJECT LOCATION <i>2001 E. Orange Ave., Fullerton, CA</i>	INSPECTOR <i>A. Sanchez, J. Ortiz</i>
	PAGE <i>1</i> OF <i>4</i>

GRP. NO.	SAMP. NO.	MATERIAL DESCRIPTION	LOCATION OF SAMPLE	QTY	% POS
01	01	white Drywall	1st Flr. Hallway - North end		
	02	↓	2nd Flr. open work area - East end		
	03	↓	3rd Flr. R/R - South end		
02	04	white joint	1st Flr. Hallway - North end		
	05	↓	2nd Flr. open work area - East end		
	06	↓	3rd Flr. R/R - South end		
03	07	Grey 4" concrete	1st Flr. Hallway - South end		
	08	↓	2nd Flr. open work area - East end		
	09	↓	2nd Flr. office 18 - S.W. end		
04	10	Ben. TAN concrete	1st Flr. Hallway - South end		
	11	↓	2nd Flr. open work area - East end		
	12	↓	2nd Flr. office 18 - S.W. end		
05	13	Ben. TAN concrete	1st Flr. Conf. Rm. - East end		
	14	↓	1st Flr. Conf. Rm. - West end		
	15	↓	1st Flr. Conf. Rm. - West end		
06	16	Ben. TAN concrete	1st Flr. Conf. Rm. - East end		
	17	↓	1st Flr. Conf. Rm. - West end		
	18	↓	1st Flr. Conf. Rm. - West end		
07	19	Black 4" concrete	3rd Flr. cov. file office 2 - South end		
	20	↓	2nd Flr. Hallway - South end		
	21	↓	Stairwell 1st Flr. South end		

Notes:



**H2 ENVIRONMENTAL CONSULTING SERVICES, INC.**


**Bulk Sampling Form**

Stop at First Positive  
  24 Hour turn around  
  Rush turn around (4 Hours)  
 Do Not Layer Samples

CLIENT <i>Kimberly Clark</i>	PROJECT NO. <i>206921845</i>	
PROJECT ID <i>Bldg #21</i>	DATE <i>11/20/18</i>	PAGE OF <i>2 4</i>
PROJECT LOCATION <i>2001 E. Orange Avenue Eastchester, CA</i>	INSPECTOR <i>A. Sanchez, J. Cortez</i>	

GRP. NO.	SAMP. NO.	MATERIAL DESCRIPTION	LOCATION OF SAMPLE	QTY	% POS
08	22	<sup>TAN</sup> Br. A Greenburg	3rd flr. env. file office #2 - <sup>South</sup> end		
↓	23	glue ↓	2nd flr. hallway - South end		
	24	↓	Stairwell 1st flr. - South end		
09	25	white 2x4	1st flr. open office area center		
↓	26	ceiling tile	2nd flr. open work area: center		
↓	27	↓	2nd flr. env. file office #2 - center		
10	28	Yellow Carpet	1st flr. 2 - South end		
↓	29	glue ↓	1st flr. 3 - west end		
↓	30	Under Blue carpet	1st flr. 5 - west end		
11	31	light gray/Blue 12x12	1st flr. Facilities conf. room - N.W. end		
↓	32	floor tile	2nd flr. open work area - East end		
↓	33	↓	2nd flr. office #18 - S.W. end		
12	34	Yellow/gray floor	1st flr. Facilities conf. room - NW end		
↓	35	tile glue	2nd flr. open work area - east end		
↓	36	↓	2nd flr. office #18 - S.W. end		
13	37	off-white floor tile	1st flr. Facilities conf. room - NW end		
↓	38	under light gray/Blue	2nd flr. open work area - east end		
↓	39	12x12 F.T.	2nd flr. office #18 - S.W. end		
14	40	Blue floor tile mosaic	1st flr. Facilities conf. room - NW end		
↓	41	↓	2nd flr. open work area - east end		
↓	42	↓	2nd flr. office #18 - S.W. end		

Notes:



**ENVIRONMENTAL CONSULTING SERVICES, INC.**

**Bulk Sampling Form**

Stop at First Positive  
  24 Hour turn around  
  Rush turn around (4 Hours)  
 Do Not Layer Samples

CLIENT <i>Kimberly Clark</i>	PROJECT NO. <i>206921843</i>
PROJECT ID <i>Bldg # 21</i>	DATE <i>11/20/18</i> PAGE <i>3</i> OF <i>4</i>
PROJECT LOCATION <i>2001 E. Orange Ave. Fullerton, CA</i>	INSPECTOR <i>A. Sanchez J. Valdez</i>

GRP. NO.	SAMP. NO.	MATERIAL DESCRIPTION	LOCATION OF SAMPLE	QTY	% POS
15	43	gray w/strakes	off. #11 - west end		
↓	44	12x12 floor tile	env. file office #11 - west end		
↓	45	↓	env. file office #12 - south end		
16	46	yellow floor tile	off. #11 - west end		
↓	47	glue ↓	env. file office #11 - west end		
↓	48	↓	env. file office #12 - south end		
17	49	TAN w/Ben. Strakes	print room - south end		
↓	50	12x12 floor tile ↓	Hallway - south end		
↓	51	↓	OFF. #15 - north end		
18	52	Blk floor mosaic	print room - south end		
↓	53	↓	Hallway - south end		
↓	54	↓	OFF. #15 - north end		
19	55	Ben 12x12 Floor	print room - west end		
↓	56	t-l-	Stairwell 2nd flr - north end		
↓	57		Stairwell 3rd flr - west end		
20	58	Blk/Ben. Floor tile	print room - west end		
↓	59	mosaic ↓	Stairwell 2nd flr - north end		
↓	60	↓	stairwell 3rd flr - west end		
21	61	yellow carpet glue	Stairwell 1st flr - east end		
↓	62	under gray carpet	↓ - center		
↓	63	↓	↓ - west end		

Notes:



**ENVIRONMENTAL CONSULTING SERVICES, INC.**

**Bulk Sampling Form**

Stop at First Positive  24 Hour turn around  Rush turn around (4 Hours)  
 Do Not Layer Samples

CLIENT: <i>Kimberly Clark</i>		PROJECT NO. <i>2069218AS</i>	
PROJECT ID: <i>Bldg # 21</i>		DATE: <i>11/20/18</i>	PAGE OF: <i>4 4</i>
PROJECT LOCATION: <i>2001 E. Orange Harbor Ave, Fullerton, CA</i>		INSPECTOR: <i>A. Sanchez, J. Ortiz</i>	

GRP. NO.	SAMP. NO.	MATERIAL DESCRIPTION	LOCATION OF SAMPLE	QTY	% POS
22	64	<i>Gray / Blue Duff</i>	<i>1st Flr. Break Room - North end</i>		
↓	65	<i>Flour</i>	<i>1st Flr. T.C. main Cor. Area - East end</i>		
↓	66		<i>1st Flr. - N.W. end</i>		
23	67	<i>Yellow Flour like</i>	<i>1st Flr. Break Room - North end</i>		
↓	68	<i>Glue</i>	<i>1st Flr. T.C. main Cor. Area - East end</i>		
↓	69		<i>1st Flr. - N.W. end</i>		
24	70	<i>white ? in wrap</i>	<i>wrap house - West end</i>		
↓	71		<i>Center North end</i>		
↓	72		<i>West end</i>		
25	73	<i>Yellow ? in</i>	<i>wrap house - West end</i>		
↓	74	<i>Insulation</i>	<i>23 - Center North end</i>		
↓	75		<i>East end</i>		
		<i>DXIF #1</i>			
		<i>23x23</i>			
		<i>XX</i>			
			<i>E</i>		
			<i>N ← S</i>		
			<i>W</i>		

Notes:

**SECTION 2  
SURVEY SUMMARY**

**LEAD XRF SURVEY RESULTS  
BUILDING 21**

**Phase 2 - Fullerton Mill - 2069218 AS  
2001 East Orangethorpe Avenue  
Fullerton, California**

The list materials and their components where Lead Based Paint (LBP) was detected at or in excess of the HUD/EPA standards of 1.0 mg/cm<sup>2</sup> (Los Angeles County has established a more stringent standard for lead-based paint at 0.7mg/cm<sup>2</sup>) by XRF method which is listed in the table below. All XRF readings below the regulatory defined action level are considered negative and all readings at and above these levels are considered positive.

Shot #	Unit	Room Tested	Wall	Color	Component	Substrate	Quantity	Paint Condition	Result	Neg/Pos
01	2 <sup>nd</sup> Floor	Open Office Area	North	White	Wall	Drywall	1,504 SF	Intact	0.01	Negative
02	2 <sup>nd</sup> Floor	Open Office Area	North	Blue	Door Frame	Metal	3 Each	Intact	0.00	Negative
03	2 <sup>nd</sup> Floor	Open Office Area	North	Bare	Door	Wood	3 Each	Intact	0.00	Negative
04	2 <sup>nd</sup> Floor	Open Office Area	East	Blue	Door Frame	Metal	22 Each	Intact	0.00	Negative
05	2 <sup>nd</sup> Floor	Open Office Area	East	Blue	Door	Wood	22 Each	Intact	0.00	Negative
06	2 <sup>nd</sup> Floor	Open Office Area	East	White	Wall	Wood	1,008 SF	Intact	0.02	Negative
07	2 <sup>nd</sup> Floor	Open Office Area	West	Brown	Door Frame	Metal	536 SF	Intact	0.00	Negative
08	2 <sup>nd</sup> Floor	Open Office Area	East	White	Column	Drywall	3 Each	Intact	0.05	Negative
09	2 <sup>nd</sup> Floor	Staircase	South	Brown	Stair Frame	Metal	4 Each	Intact	0.02	Negative
10	2 <sup>nd</sup> Floor	Staircase	South	Brown	Stair Rail	Metal	4 Each	Intact	0.01	Negative
11	2 <sup>nd</sup> Floor	Staircase	South	Tan	Wall	Drywall	180 SF	Intact	0.01	Negative
12	3 <sup>rd</sup> Floor	Open Area	West	White	Wall	Drywall	3,990 SF	Intact	0.00	Negative
13	3 <sup>rd</sup> Floor	Open Area	West	Brown	Door Frame	Metal	7 Each	Intact	0.00	Negative
14	3 <sup>rd</sup> Floor	Open Area	West	Bare	Door	Wood	14 Each	Intact	0.00	Negative
15	3 <sup>rd</sup> Floor	Open Area	West	Blue	Door	Metal	3 Each	Intact	0.00	Negative
16	3 <sup>rd</sup> Floor	Open Area	West	White	Ceiling	Metal	5,264 SF	Intact	0.00	Negative

**SECTION 2  
SURVEY SUMMARY**

**LEAD XRF SURVEY RESULTS  
BUILDING 21**

**Phase 2 - Fullerton Mill - 2069218 AS  
2001 East Orangethorpe Avenue  
Fullerton, California**

The list materials and their components where Lead Based Paint (LBP) was detected at or in excess of the HUD/EPA standards of 1.0 mg/cm<sup>2</sup> (Los Angeles County has established a more stringent standard for lead-based paint at 0.7mg/cm<sup>2</sup>) by XRF method which is listed in the table below. All XRF readings below the regulatory defined action level are considered negative and all readings at and above these levels are considered positive.

Shot #	Unit	Room Tested	Wall	Color	Component	Substrate	Quantity	Paint Condition	Result	Neg/Pos
17	3 <sup>rd</sup> Floor	Open Area	West	White	Angle Bracket	Metal	5,264 SF	Intact	0.01	Negative
18	3 <sup>rd</sup> Floor	Open Area	West	White	Duct	Metal	200 SF	Intact	0.00	Negative
19	3 <sup>rd</sup> Floor	Open Area	West	White	Wall	Concrete	832 SF	Intact	0.00	Negative
20	3 <sup>rd</sup> Floor	Open Area	East	Tan	Wall	Drywall	832 SF	Intact	0.00	Negative
21	3 <sup>rd</sup> Floor	Open Area	West	White	Wall	Wood	20 SF	Intact	0.00	Negative
22	3 <sup>rd</sup> Floor	Open Area	South	White	Door Frame	Wood	1 Each	Intact	0.00	Negative
23	3 <sup>rd</sup> Floor	Open Area	West	Red	Fire Alarm Box	Metal	2 Each	Intact	0.28	Negative
24	3 <sup>rd</sup> Floor	Electrical Room	West	Red	Wall	Concrete	5 SF	Intact	0.00	Negative
25	3 <sup>rd</sup> Floor	Electrical Room	West	Yellow	Shoot Ladder	Metal	1 Each	Intact	0.00	Negative
26	3 <sup>rd</sup> Floor	Electrical Room	West	Yellow	Platform Wall	Metal	1 Each	Intact	0.00	Negative
27	3 <sup>rd</sup> Floor	Electrical Room	West	Brown	Platform	Metal	1 Each	Intact	0.00	Negative
28	3 <sup>rd</sup> Floor	Electrical Room	North	Brown	Door Frame	Metal	3 Each	Intact	0.00	Negative
29	3 <sup>rd</sup> Floor	Electrical Room	North	Brown	Door	Wood	3 Each	Intact	0.00	Negative
<b>30</b>	<b>3<sup>rd</sup> Floor</b>	<b>Electrical Room</b>	<b>North</b>	<b>Green</b>	<b>Shelf</b>	<b>Metal</b>	<b>2 Each</b>	<b>Intact</b>	<b>1.80</b>	<b>Positive</b>
31	3 <sup>rd</sup> Floor	Electrical Room	North	White	Ceiling	Metal	1,095 SF	Intact	0.01	Negative
32	3 <sup>rd</sup> Floor	Electrical Room	North	White	Pipe	Metal	1,095 SF	Intact	0.01	Negative



**SECTION 2  
SURVEY SUMMARY**

**LEAD XRF SURVEY RESULTS  
BUILDING 21**

**Phase 2 - Fullerton Mill - 2069218 AS  
2001 East Orangethorpe Avenue  
Fullerton, California**

The list materials and their components where Lead Based Paint (LBP) was detected at or in excess of the HUD/EPA standards of 1.0 mg/cm<sup>2</sup> (Los Angeles County has established a more stringent standard for lead-based paint at 0.7mg/cm<sup>2</sup>) by XRF method which is listed in the table below. All XRF readings below the regulatory defined action level are considered negative and all readings at and above these levels are considered positive.

Shot #	Unit	Room Tested	Wall	Color	Component	Substrate	Quantity	Paint Condition	Result	Neg/Pos
33	3 <sup>rd</sup> Floor	Electrical Room	North	White	Duct	Metal	111 SF	Intact	0.01	Negative
34	3 <sup>rd</sup> Floor	Electrical Room	North	Grey	Wall	Concrete	4,460 SF	Intact	0.00	Negative
35	3 <sup>rd</sup> Floor	Electrical Room	West	Grey	Electrical Panel	Metal	2 Each	Intact	0.01	Negative
36	3 <sup>rd</sup> Floor	Office	North	Tan	Ceiling	Drywall	270 SF	Intact	0.00	Negative
37	3 <sup>rd</sup> Floor	Office	North	Tan	Wall	Drywall	1,200 SF	Intact	0.00	Negative
38	2 <sup>nd</sup> Floor	Hallway	North	Blue	Stair Frame	Metal	2 Each	Intact	0.00	Negative
39	2 <sup>nd</sup> Floor	Hallway	North	Blue	Stairwell	Metal	2 Each	Intact	0.00	Negative
40	1 <sup>st</sup> Floor	Open Office Area	South	Teal	Door Frame	Metal	3 Each	Intact	0.00	Negative
41	1 <sup>st</sup> Floor	Open Office Area	South	Teal	Door	Metal	1 Each	Intact	0.00	Negative
42	1 <sup>st</sup> Floor	Open Office Area	North	Blue	Door Frame	Metal	6 Each	Intact	0.00	Negative
43	1 <sup>st</sup> Floor	Open Office Area	East	Blue	Door	Wood	6 Each	Intact	0.00	Negative
44	1 <sup>st</sup> Floor	Open Office Area	East	Blue	Wall	Drywall	2,384 SF	Intact	0.00	Negative
45	1 <sup>st</sup> Floor	Open Office Area	South	Teal	Stair Frame	Metal	1 Each	Intact	0.00	Negative
46	1 <sup>st</sup> Floor	Open Office Area	South	Teal	Stair Rail	Metal	1 Each	Intact	0.00	Negative
47	1 <sup>st</sup> Floor	Hallway 1	North	Teal	Stair Rail	Metal	2 Each	Intact	0.05	Negative
48	1 <sup>st</sup> Floor	Hallway 1	North	Teal	Door Frame	Metal	2 Each	Intact	0.00	Negative

**SECTION 2**  
**SURVEY SUMMARY**

**LEAD XRF SURVEY RESULTS**  
**BUILDING 21**

**Phase 2 - Fullerton Mill - 2069218 AS**  
**2001 East Orangethorpe Avenue**  
**Fullerton, California**

The list materials and their components where Lead Based Paint (LBP) was detected at or in excess of the HUD/EPA standards of 1.0 mg/cm<sup>2</sup> (Los Angeles County has established a more stringent standard for lead-based paint at 0.7mg/cm<sup>2</sup>) by XRF method which is listed in the table below. All XRF readings below the regulatory defined action level are considered negative and all readings at and above these levels are considered positive.

Shot #	Unit	Room Tested	Wall	Color	Component	Substrate	Quantity	Paint Condition	Result	Neg/Pos
49	1 <sup>st</sup> Floor	Hallway 1	West	Teal	Door	Wood	2 Each	Intact	0.00	Negative
50	1 <sup>st</sup> Floor	Hallway 1	West	White	Ceiling	Drywall	250 SF	Intact	0.00	Negative
51	1 <sup>st</sup> Floor	Hallway 2	West	Blue	Wall	Concrete	280 SF	Intact	0.00	Negative
52	1 <sup>st</sup> Floor	Hallway 2	West	White	Wall	Concrete	5,550 SF	Intact	0.00	Negative
53	1 <sup>st</sup> Floor	Hallway 2	West	Teal	Door Frame	Metal	4 Each	Intact	0.00	Negative
54	1 <sup>st</sup> Floor	Hallway 2	West	Teal	Door	Metal	4 Each	Intact	0.00	Negative
55	1 <sup>st</sup> Floor	Hallway 2	South	Red	Hydrant Pipe	Metal	1 Each	Intact	0.04	Negative
56	1 <sup>st</sup> Floor	Hallway 2	East	Red	Electrical Panel	Metal	1 Each	Intact	0.00	Negative
57	1 <sup>st</sup> Floor	Hallway 2	East	White	Ceiling	Metal	720 SF	Intact	0.00	Negative
58	1 <sup>st</sup> Floor	Men's Restroom	North	Teal	Door Frame	Metal	1 Each	Intact	0.00	Negative
59	1 <sup>st</sup> Floor	Men's Restroom	North	Teal	Door	Metal	1 Each	Intact	0.00	Negative
60	1 <sup>st</sup> Floor	Men's Restroom	East	White	Wall	Drywall	248 SF	Intact	0.00	Negative
61	1 <sup>st</sup> Floor	Men's Restroom	East	Blue	6"x6" Wall Tile	Ceramic	124 SF	Intact	0.05	Negative
62	1 <sup>st</sup> Floor	Men's Restroom	East	Gray	6"x6" Wall Tile	Ceramic	124 SF	Intact	0.00	Negative
63	1 <sup>st</sup> Floor	Men's Restroom	East	White	Urinal	Ceramic	2 Each	Intact	0.02	Negative
64	1 <sup>st</sup> Floor	Men's Restroom	East	White	Toilet	Ceramic	3 Each	Intact	0.00	Negative

**SECTION 2  
SURVEY SUMMARY**

**LEAD XRF SURVEY RESULTS  
BUILDING 21**

**Phase 2 - Fullerton Mill - 2069218 AS  
2001 East Orangethorpe Avenue  
Fullerton, California**

The list materials and their components where Lead Based Paint (LBP) was detected at or in excess of the HUD/EPA standards of 1.0 mg/cm<sup>2</sup> (Los Angeles County has established a more stringent standard for lead-based paint at 0.7mg/cm<sup>2</sup>) by XRF method which is listed in the table below. All XRF readings below the regulatory defined action level are considered negative and all readings at and above these levels are considered positive.

Shot #	Unit	Room Tested	Wall	Color	Component	Substrate	Quantity	Paint Condition	Result	Neg/Pos
65	1 <sup>st</sup> Floor	Men's Restroom	East	Gray	Partition	Metal	5 Each	Intact	0.00	Negative
66	1 <sup>st</sup> Floor	Men's Restroom	East	Gray	6"x6" Floor Tile	Ceramic	110 SF	Intact	0.00	Negative
67	1 <sup>st</sup> Floor	Men's Restroom	East	Blue	6"x6" Floor Tile	Ceramic	110 SF	Intact	0.00	Negative
68	1 <sup>st</sup> Floor	Men's Restroom	East	White	Ceiling	Drywall	220 SF	Intact	0.00	Negative
69	1 <sup>st</sup> Floor	Women's Restroom	North	Teal	Door Frame	Metal	1 Each	Intact	0.00	Negative
70	1 <sup>st</sup> Floor	Women's Restroom	North	Teal	Door	Wood	1 Each	Intact	0.00	Negative
71	1 <sup>st</sup> Floor	Women's Restroom	North	White	Wall	Drywall	248 SF	Intact	0.00	Negative
72	1 <sup>st</sup> Floor	Women's Restroom	North	Blue	6"x6" Wall Tile	Ceramic	124 SF	Intact	0.05	Negative
73	1 <sup>st</sup> Floor	Women's Restroom	North	Gray	6"x6" Wall Tile	Ceramic	124 SF	Intact	0.05	Negative
74	1 <sup>st</sup> Floor	Women's Restroom	East	White	Sink	Ceramic	3 Each	Intact	0.02	Negative
75	1 <sup>st</sup> Floor	Women's Restroom	West	White	Toilet	Ceramic	5 Each	Intact	0.01	Negative
76	1 <sup>st</sup> Floor	Women's Restroom	West	Gray	Partition	Metal	5 Each	Intact	0.00	Negative
77	1 <sup>st</sup> Floor	Women's Restroom	West	White	Ceiling	Drywall	22 SF	Intact	0.00	Negative
78	1 <sup>st</sup> Floor	Women's Restroom	West	Gray	6"x6" Floor Tile	Ceramic	124 SF	Intact	0.00	Negative
79	1 <sup>st</sup> Floor	Women's Restroom	West	Blue	6"x6" Floor Tile	Ceramic	124 SF	Intact	0.00	Negative
80	1 <sup>st</sup> Floor	Men's Restroom	West	White	Sink	Ceramic	2 Each	Intact	0.00	Negative

**SECTION 2**  
**SURVEY SUMMARY**

**LEAD XRF SURVEY RESULTS**  
**BUILDING 21**

**Phase 2 - Fullerton Mill - 2069218 AS**  
**2001 East Orangethorpe Avenue**  
**Fullerton, California**

The list materials and their components where Lead Based Paint (LBP) was detected at or in excess of the HUD/EPA standards of 1.0 mg/cm<sup>2</sup> (Los Angeles County has established a more stringent standard for lead-based paint at 0.7mg/cm<sup>2</sup>) by XRF method which is listed in the table below. All XRF readings below the regulatory defined action level are considered negative and all readings at and above these levels are considered positive.

Shot #	Unit	Room Tested	Wall	Color	Component	Substrate	Quantity	Paint Condition	Result	Neg/Pos
81	Bldg. 21	Warehouse	East	White	Wall	Concrete	31,260 SF	Intact	0.00	Negative
82	Bldg. 21	Warehouse	East	Red	Wall	Concrete	10 SF	Intact	0.05	Negative
83	Bldg. 21	Warehouse	South	Red	Hydrant Pipe	Metal	2 Each	Intact	0.00	Negative
84	Bldg. 21	Warehouse	South	Teal	Stair Frame	Metal	1 Each	Intact	0.00	Negative
85	Bldg. 21	Warehouse	South	Teal	Stair Rail	Metal	1 Each	Intact	0.00	Negative
86	Bldg. 21	Warehouse	South	Teal	Door Frame	Metal	6 Each	Intact	0.00	Negative
87	Bldg. 21	Warehouse	South	Teal	Door	Metal	6 Each	Intact	0.00	Negative
<b>88</b>	<b>Bldg. 21</b>	<b>Warehouse</b>	<b>South</b>	<b>Teal</b>	<b>Sliding Door</b>	<b>Metal</b>	<b>1 Each</b>	<b>Intact</b>	<b>4.80</b>	<b>Positive</b>
89	Bldg. 21	Warehouse	South	Teal	Sliding Door Frame	Metal	1 Each	Intact	0.04	Negative
<b>90</b>	<b>Bldg. 21</b>	<b>Warehouse</b>	<b>North</b>	<b>Yellow</b>	<b>Guard Rail</b>	<b>Metal</b>	<b>4 Each</b>	<b>Intact</b>	<b>6.80</b>	<b>Positive</b>
<b>91</b>	<b>Bldg. 21</b>	<b>Warehouse</b>	<b>North</b>	<b>Yellow</b>	<b>Shoot Ladder</b>	<b>Metal</b>	<b>6 Each</b>	<b>Intact</b>	<b>1.80</b>	<b>Positive</b>
92	Bldg. 21	Warehouse	North	Yellow	Shoot Ladder Rail	Metal	6 Each	Intact	0.08	Negative
<b>93</b>	<b>Bldg. 21</b>	<b>Warehouse</b>	<b>North</b>	<b>White</b>	<b>Platform</b>	<b>Metal</b>	<b>4 Each</b>	<b>Intact</b>	<b>6.80</b>	<b>Positive</b>
94	Bldg. 21	Warehouse	North	Yellow	Platform Guard Rail	Metal	Each	Intact	0.01	Negative
95	Bldg. 21	Warehouse	North	White	Support Beam	Metal	8 Each	Intact	0.27	Negative
<b>96</b>	<b>Bldg. 21</b>	<b>Warehouse</b>	<b>North</b>	<b>White</b>	<b>I-Beam</b>	<b>Metal</b>	<b>12 Each</b>	<b>Intact</b>	<b>8.70</b>	<b>Positive</b>

**SECTION 2**  
**SURVEY SUMMARY**

**LEAD XRF SURVEY RESULTS**  
**BUILDING 21**

**Phase 2 - Fullerton Mill - 2069218 AS**  
**2001 East Orangethorpe Avenue**  
**Fullerton, California**

The list materials and their components where Lead Based Paint (LBP) was detected at or in excess of the HUD/EPA standards of 1.0 mg/cm<sup>2</sup> (Los Angeles County has established a more stringent standard for lead-based paint at 0.7mg/cm<sup>2</sup>) by XRF method which is listed in the table below. All XRF readings below the regulatory defined action level are considered negative and all readings at and above these levels are considered positive.

Shot #	Unit	Room Tested	Wall	Color	Component	Substrate	Quantity	Paint Condition	Result	Neg/Pos
97	1 <sup>st</sup> Floor	Warehouse	East	White	Ceiling	Metal	40,470 SF	Intact	0.01	Negative
<b>98</b>	<b>1<sup>st</sup> Floor</b>	<b>Warehouse</b>	<b>East</b>	<b>White</b>	<b>Ceiling I-Beam</b>	<b>Metal</b>	<b>20 Each</b>	<b>Intact</b>	<b>4.80</b>	<b>Positive</b>
99	1 <sup>st</sup> Floor	Warehouse	East	White	Pipe	Metal	1,563 LF	Intact	0.01	Negative
100	1 <sup>st</sup> Floor	Warehouse	East	White	Duct	Metal	521 SF	Intact	0.02	Negative
101	1 <sup>st</sup> Floor	Warehouse	East	Yellow	Floor Bracket	Metal	2,084 SF	Intact	0.00	Negative
102	1 <sup>st</sup> Floor	Office 9	West	White	Wall	Concrete	3,008 SF	Intact	0.00	Negative
103	1 <sup>st</sup> Floor	Tissue Breakroom	South	White	Wall	Drywall	720 SF	Intact	0.00	Negative
104	1 <sup>st</sup> Floor	Janitor's Closet	West	White	Wall	Drywall	80 SF	Intact	0.00	Negative
105	1 <sup>st</sup> Floor	Janitor's Closet	West	Tan	Wall	FRP	80 SF	Intact	0.00	Negative
106	1 <sup>st</sup> Floor	Janitor's Closet	West	Tan	3"x3" Floor Tile	Ceramic	25 SF	Intact	0.00	Negative
107	1 <sup>st</sup> Floor	Janitor's Closet	West	White	Ceiling	Drywall	25 SF	Intact	0.00	Negative
<b>108</b>	<b>1<sup>st</sup> Floor</b>	<b>Warehouse</b>	<b>West</b>	<b>White</b>	<b>Ceiling Angle Bracket</b>	<b>Metal</b>	<b>40,470 SF</b>	<b>Intact</b>	<b>6.80</b>	<b>Positive</b>

**SECTION 2  
SURVEY SUMMARY**

**LEAD XRF SURVEY RESULTS  
BUILDING 22**

**Phase 2 - Fullerton Mill - 2069218 AS  
2001 East Orangethorpe Avenue  
Fullerton, California**

The list materials and their components where Lead Based Paint (LBP) was detected at or in excess of the HUD/EPA standards of 1.0 mg/cm<sup>2</sup> (Los Angeles County has established a more stringent standard for lead-based paint at 0.7mg/cm<sup>2</sup>) by XRF method which is listed in the table below. All XRF readings below the regulatory defined action level are considered negative and all readings at and above these levels are considered positive.

Shot #	Unit	Room Tested	Wall	Color	Component	Substrate	Quantity	Paint Condition	Result	Neg/Pos
01	Interior	Storage	North	White	Wall	Metal	3,570 SF	Intact	0.00	Negative
02	Interior	Storage	North	Red	I-Beam	Metal	1,000 SF	Intact	0.00	Negative
03	Interior	Storage	North	White	Door	Metal	2 Each	Intact	0.00	Negative
04	Interior	Storage	North	Blue	Door Frame	Metal	2 Each	Intact	0.13	Negative
<b>05</b>	<b>Interior</b>	<b>Storage</b>	<b>North</b>	<b>Yellow</b>	<b>Bollard Rail</b>	<b>Metal</b>	<b>100 SF</b>	<b>Intact</b>	<b>1.00</b>	<b>Positive</b>
06	Exterior	Storage	North	White	Wall	Metal	3,570 SF	Intact	0.00	Negative
07	Exterior	Storage	North	White	Door Frame	Metal	2 Each	Intact	0.00	Negative
08	Exterior	Storage	North	White	Door	Metal	2 Each	Intact	0.01	Negative

**SECTION 2  
SURVEY SUMMARY**

**LEAD XRF SURVEY RESULTS  
BUILDING 25**

**Phase 2 - Fullerton Mill - 2069218 AS  
2001 East Orangethorpe Avenue  
Fullerton, California**

The list materials and their components where Lead Based Paint (LBP) was detected at or in excess of the HUD/EPA standards of 1.0 mg/cm<sup>2</sup> (Los Angeles County has established a more stringent standard for lead-based paint at 0.7mg/cm<sup>2</sup>) by XRF method which is listed in the table below. All XRF readings below the regulatory defined action level are considered negative and all readings at and above these levels are considered positive.

Shot #	Unit	Room Tested	Wall	Color	Component	Substrate	Quantity	Paint Condition	Result	Neg/Pos
01	Interior	Warehouse Storage 2	North	White	Door Frame	Metal	4 Each	Intact	0.00	Negative
02	Interior	Warehouse Storage 2	North	White	Door	Metal	4 Each	Intact	0.00	Negative
03	Interior	Warehouse Storage 2	North	White	I-Beam	Metal	1,000 SF	Intact	0.00	Negative
04	Interior	Warehouse Storage 2	North	Tan	I-Beam	Metal	1,000 SF	Intact	0.00	Negative
05	Interior	Warehouse Storage 2	North	Tan	Angle Bracket	Metal	8,280 SF	Intact	0.00	Negative
06	Interior	Warehouse Storage 2	North	Tan	Panel Cage	Metal	2 Each	Intact	0.00	Negative
07	Interior	Warehouse Storage 2	North	Tan	Wall	Metal	2 Each	Intact	0.00	Negative
08	Interior	Warehouse Storage 2	North	Blue	Wall	Metal	3,870 SF	Intact	0.00	Negative
<b>09</b>	<b>Interior</b>	<b>Warehouse Storage 2</b>	<b>North</b>	<b>Yellow</b>	<b>Floor</b>	<b>Concrete</b>	<b>100 LF</b>	<b>Intact</b>	<b>6.80</b>	<b>Positive</b>
10	Interior	Warehouse Storage 2	East	White	Rollup Door	Metal	2 Each	Intact	0.00	Negative
11	Interior	Warehouse Storage 2	East	White	Rollup Door Frame	Metal	2 Each	Intact	0.00	Negative
12	Interior	Warehouse Storage 2	East	Red	I-Beam	Metal	1 Each	Intact	0.00	Negative
13	Interior	Warehouse Storage 2	East	Red	Floor	Concrete	15 SF	Intact	0.00	Negative
14	Interior	Warehouse Storage 2	East	Yellow	Bollard	Metal	100 SF	Intact	0.00	Negative
15	Interior	Warehouse Storage 2	West	White	Wall	Wood	3,870 SF	Intact	0.00	Negative
16	Exterior	Warehouse Storage 2	West	White	Plywood	Wood	1 Each	Intact	0.00	Negative

**SECTION 2  
SURVEY SUMMARY**

**LEAD XRF SURVEY RESULTS  
BUILDING 25**

**Phase 2 - Fullerton Mill - 2069218 AS  
2001 East Orangethorpe Avenue  
Fullerton, California**

The list materials and their components where Lead Based Paint (LBP) was detected at or in excess of the HUD/EPA standards of 1.0 mg/cm<sup>2</sup> (Los Angeles County has established a more stringent standard for lead-based paint at 0.7mg/cm<sup>2</sup>) by XRF method which is listed in the table below. All XRF readings below the regulatory defined action level are considered negative and all readings at and above these levels are considered positive.

Shot #	Unit	Room Tested	Wall	Color	Component	Substrate	Quantity	Paint Condition	Result	Neg/Pos
17	Exterior	Warehouse Storage	West	White	Wall	Metal	6,336 SF	Intact	0.00	Negative
18	Exterior	Warehouse Storage	West	Gray	Panel	Metal	1 Each	Intact	0.00	Negative
<b>19</b>	<b>Exterior</b>	<b>Warehouse Storage</b>	<b>West</b>	<b>Yellow</b>	<b>Bollard</b>	<b>Metal</b>	<b>7 Each</b>	<b>Intact</b>	<b>6.80</b>	<b>Positive</b>
20	Exterior	Warehouse Storage	West	White	Post	Metal	8 Each	Intact	0.00	Negative
21	Exterior	Warehouse Storage	West	White	Patio Ceiling	Metal	2,000 SF	Intact	0.00	Negative
22	Exterior	Warehouse Storage	West	White	Ceiling I-Beam	Metal	1,000 SF	Intact	0.00	Negative
<b>23</b>	<b>Exterior</b>	<b>Warehouse Storage</b>	<b>West</b>	<b>Yellow</b>	<b>Bollard Rail</b>	<b>Metal</b>	<b>50 SF</b>	<b>Intact</b>	<b>2.20</b>	<b>Positive</b>
24	Exterior	Warehouse Storage	West	Yellow	Curb Side	Asphalt	100 SF	Intact	0.00	Negative
25	Exterior	Warehouse Storage	South	White	Gable Vent	Metal	10 Each	Intact	0.00	Negative
26	Exterior	Warehouse Storage	South	Red	Pipe	Metal	2 Each	Intact	0.00	Negative
27	Exterior	Warehouse Storage	West	Yellow	Floor	Asphalt	100 LF	Intact	0.00	Negative





## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509333  
**Samples Submitted:** 24  
**Sample Collection Date:** 11/21/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #28  
**Project Location:** 2001 E. Orangethorpe  
Fullerton, CA

**Page:** 1 of 7

### TEST DATA

---

**Laboratory ID#:** 1509333-001      **Client Sample #:** 1

**Sample Material and Location:** White Drywall Work Shop - West End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 95% Non-Fibrous Material  
5% Cellulose

**Asbestos Observed (%):**      **Date Analyzed:** 11/27/2018      **Total Asbestos (%)** None Detected  
**Analyst:** Dennis Liu

### TEST DATA

---

**Laboratory ID#:** 1509333-002      **Client Sample #:** 2

**Sample Material and Location:** White Drywall Computer Training Room - South End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 95% Non-Fibrous Material  
5% Cellulose

**Asbestos Observed (%):**      **Date Analyzed:** 11/27/2018      **Total Asbestos (%)** None Detected  
**Analyst:** Dennis Liu

### TEST DATA

---

**Laboratory ID#:** 1509333-003      **Client Sample #:** 3

**Sample Material and Location:** White Drywall Storage Closet #1 - South End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 95% Non-Fibrous Material  
5% Cellulose

**Asbestos Observed (%):**      **Date Analyzed:** 11/27/2018      **Total Asbestos (%)** None Detected  
**Analyst:** Dennis Liu

### TEST DATA

---

**Laboratory ID#:** 1509333-004      **Client Sample #:** 4

**Sample Material and Location:** White Joint Compound Work Shop - West End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**      **Date Analyzed:** 11/27/2018      **Total Asbestos (%)** None Detected  
**Analyst:** Dennis Liu



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509333  
**Samples Submitted:** 24  
**Sample Collection Date:** 11/21/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #28  
**Project Location:** 2001 E. Orangethorpe  
Fullerton, CA

**Page:** 2 of 7

### TEST DATA

**Laboratory ID#:** 1509333-005      **Client Sample #:** 5

**Sample Material and Location:** White Joint Compound Computer Training Room - South End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509333-006      **Client Sample #:** 6

**Sample Material and Location:** White Joint Compound Storage Closet #1 - South End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509333-007      **Client Sample #:** 7

**Sample Material and Location:** White 2' x 4' Ceiling Tile Computer Training Room - North End

**Sample Characteristics:** Beige White Fibrous Inhomogenous  
**Misc. Components Observed:** 55% Non-Fibrous Material  
5% Fibrous Glass  
40% Cellulose

**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509333-008      **Client Sample #:** 8

**Sample Material and Location:** White 2' x 4' Ceiling Tile Lobby - South End

**Sample Characteristics:** Beige White Fibrous Inhomogenous  
**Misc. Components Observed:** 55% Non-Fibrous Material  
5% Fibrous Glass  
40% Cellulose

**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509333  
**Samples Submitted:** 24  
**Sample Collection Date:** 11/21/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #28  
**Project Location:** 2001 E. Orangethorpe  
Fullerton, CA

**Page:** 3 of 7

### TEST DATA

---

**Laboratory ID#:** 1509333-009      **Client Sample #:** 9

**Sample Material and Location:** White 2' x 4' Ceiling Tile Hallway - East End

**Sample Characteristics:** Beige White Fibrous Inhomogenous  
**Misc. Components Observed:** 55% Non-Fibrous Material  
5% Fibrous Glass  
40% Cellulose

**Asbestos Observed (%):**      **Total Asbestos (%)** None Detected  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/27/2018

### TEST DATA

---

**Laboratory ID#:** 1509333-010      **Client Sample #:** 10

**Sample Material and Location:** Gray 4" Covebase Workshop - West End

**Sample Characteristics:** Grey Smooth Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**      **Total Asbestos (%)** None Detected  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/27/2018

### TEST DATA

---

**Laboratory ID#:** 1509333-011      **Client Sample #:** 11

**Sample Material and Location:** Gray 4" Covebase Computer Training Room - South End

**Sample Characteristics:** Grey Smooth Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**      **Total Asbestos (%)** None Detected  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/27/2018

### TEST DATA

---

**Laboratory ID#:** 1509333-012      **Client Sample #:** 12

**Sample Material and Location:** Gray 4" Covebase Storage Closet #1 - South End

**Sample Characteristics:** Grey Smooth Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**      **Total Asbestos (%)** None Detected  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/27/2018



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509333  
**Samples Submitted:** 24  
**Sample Collection Date:** 11/21/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #28  
**Project Location:** 2001 E. Orangethorpe  
Fullerton, CA

**Page:** 4 of 7

### TEST DATA

---

**Laboratory ID#:** 1509333-013      **Client Sample #:** 13

**Sample Material and Location:** Tan Covebase Glue Workshop - West End

**Sample Characteristics:** Tan Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**

**Analyst:** Dennis Liu

**Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509333-014      **Client Sample #:** 14

**Sample Material and Location:** Tan Covebase Glue Computer Training Room - South End

**Sample Characteristics:** Tan Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**

**Analyst:** Dennis Liu

**Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509333-015      **Client Sample #:** 15

**Sample Material and Location:** Tan Covebase Glue Storage Closet #1 - South End

**Sample Characteristics:** Tan Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**

**Analyst:** Dennis Liu

**Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509333-016      **Client Sample #:** 16

**Sample Material and Location:** Yellow Carpet Glue under Blue Carpet Computer Training Room - South End

**Sample Characteristics:** Yellow Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**

**Analyst:** Dennis Liu

**Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509333  
**Samples Submitted:** 24  
**Sample Collection Date:** 11/21/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #28  
**Project Location:** 2001 E. Orangethorpe  
Fullerton, CA

**Page:** 5 of 7

### TEST DATA

---

**Laboratory ID#:** 1509333-017      **Client Sample #:** 17

**Sample Material and Location:** Yellow Carpet Glue under Blue Carpet Lobby - North End

**Sample Characteristics:** Yellow Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509333-018      **Client Sample #:** 18

**Sample Material and Location:** Yellow Carpet Glue under Blue Carpet New Training Room - S.E. End

**Sample Characteristics:** Yellow Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509333-019      **Client Sample #:** 19

**Sample Material and Location:** Blue/Gray Floor Tile Office #1 - South End

**Sample Characteristics:** Grey Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509333-020      **Client Sample #:** 20

**Sample Material and Location:** Blue/Gray Floor Tile Hallway - West End

**Sample Characteristics:** Grey Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected



**Analytical Report**

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509333  
**Samples Submitted:** 24  
**Sample Collection Date:** 11/21/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #28  
**Project Location:** 2001 E. Orangethorpe  
Fullerton, CA

**Page:** 6 of 7

**TEST DATA**

---

**Laboratory ID#:** 1509333-021 **Client Sample #:** 21

**Sample Material and Location:** Blue/Gray Floor Tile Storage Closet #3 - East End

**Sample Characteristics:** Grey Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

**TEST DATA**

---

**Laboratory ID#:** 1509333-022 **Client Sample #:** 22

**Sample Material and Location:** Yellow Floor Tile Glue Office #1 - South End

**Sample Characteristics:** Yellow Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

**TEST DATA**

---

**Laboratory ID#:** 1509333-023 **Client Sample #:** 23

**Sample Material and Location:** Yellow Floor Tile Glue Hallway - West End

**Sample Characteristics:** Yellow Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected

**TEST DATA**

---

**Laboratory ID#:** 1509333-024 **Client Sample #:** 24

**Sample Material and Location:** Yellow Floor Tile Glue Storage Closet #3 - East End

**Sample Characteristics:** Yellow Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu **Date Analyzed:** 11/27/2018

**Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509333  
**Samples Submitted:** 24  
**Sample Collection Date:** 11/21/2018  
**Laboratory Receipt Date:** 11/27/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Bldg #28  
**Project Location:** 2001 E. Orangethorpe  
Fullerton, CA

**Page:** 7 of 7

Samples were analyzed by Calibrated Visual Estimation (CVE). Analyses by CVE have a detection limit of 1% asbestos by relative area and may not be consistently reliable below this limit or for asbestos with fiber diameter thinner than the resolving capacity of PLM without further analysis by another independent method. A test result of less than (<) 1% by CVE means asbestos was observed in the sample but is visually estimated to be below the reportable limit of 1%. The laboratory references interim method EPA 600/M4-82-020 (Interim Method) for fiber identification, 400 point counts, and composite reporting. EPA method 600/R-93/116 is referenced for analysis of non-insulation materials, sub-layers, expanded and modified point counts, CVE and subsequent data reporting. Samples containing distinct layers that can be reliably separated are analyzed and reported as separate unless requested in writing. The test data presented apply only to the items submitted. Count for samples submitted is indicative of total layers observed and may vary from actual analysis for positive stop requests. ATEL, LLC is a NIST-NVLAP and CA-ELAP Accredited laboratory (ID# 201073-0 and #2971, respectively). This report must not be reproduced, unless in its entirety, without the written consent of ATEL, LLC. Per NIST-NVLAP 150 Annex A: This report shall not be used to claim product certification, approval or endorsement by NVLAP, NIST, or any agency of the federal government.

Unless indicated, samples were received in acceptable condition. Sample retention time is 30 days from issuing this report unless requested otherwise.

Analyst Signature:

A handwritten signature in black ink, appearing to read "Dennis Liu".

-Dennis Liu

Approved Signatory:


A handwritten signature in black ink, appearing to read "Chris Turton".

-Chris Turton

Reported On: 11/28/2018







**H2 ENVIRONMENTAL CONSULTING SERVICES, INC.**

**Bulk Sampling Form**

Stop at First Positive   
  24 Hour turn around   
  Rush turn around (4 Hours)  
 Do Not Layer Samples

CLIENT Kimberly Clark		PROJECT NO. 2069218 AS	
PROJECT ID Bldg #128		DATE 11/21/18	PAGE 1 OF 2
PROJECT LOCATION 2001 E. Orangehurst, Fullerton, CA 92831		INSPECTOR A. Sanchez, J. Ortiz	

GRP. NO.	SAMP. NO.	MATERIAL DESCRIPTION	LOCATION OF SAMPLE	QTY	% POS
01	01	white Drywall	workshop - west end	7.5000	
↓	02	↓	computer training room - south end	↓	
	03	↓	storage closet #19 - south end	↓	
02	04	white joint	workshop - west end	7.5000	
↓	05	compound	computer training room - south end	↓	
	06	↓	storage closet #19 - south end	↓	
03	07	white zxy	computer training room - north end	3.5000	
↓	08	ceiling tile	lobby - south end	↓	
	09	↓	hallway - east end	↓	
04	10	gray 4" composite	workshop - west end	7.5000	
↓	11	↓	computer training room - south end	↓	
	12	↓	storage closet #19 - south end	↓	
05	13	tan composite glass	workshop - west end	7.5000	
↓	14	↓	computer training room - south end	↓	
	15	↓	storage closet #19 - south end	↓	
06	16	yellow carpet	computer training room - south end	2.4000	
↓	17	glass	lobby - north end	↓	
	18	under blue carpet	new training room - S.E. end	↓	
07	19	Blue Gray 12x12 Floor	office #19 - south end	1.0000	
↓	20	tile	hallway - west end	↓	
	21	↓	storage closet #19 - east end	↓	

Notes:



**SECTION 2**  
**SURVEY SUMMARY**

**LEAD XRF SURVEY RESULTS**  
**BUILDING 28**

**Phase 2 - Fullerton Mill - 2069218 AS**  
**2001 East Orangethorpe Avenue**  
**Fullerton, California**

The list materials and their components where Lead Based Paint (LBP) was detected at or in excess of the HUD/EPA standards of 1.0 mg/cm<sup>2</sup> (Los Angeles County has established a more stringent standard for lead-based paint at 0.7mg/cm<sup>2</sup>) by XRF method which is listed in the table below. All XRF readings below the regulatory defined action level are considered negative and all readings at and above these levels are considered positive.

Shot #	Unit	Room Tested	Wall	Color	Component	Substrate	Quantity	Paint Condition	Result	Neg/Pos
01	Bldg. 28	New Training Room	East	Blue	Door Frame	Metal	2 Each	Intact	0.00	Negative
02	Bldg. 28	New Training Room	East	Blue	Door	Metal	2 Each	Intact	0.00	Negative
03	Bldg. 28	New Training Room	East	Blue	Wall	Drywall	2,400 SF	Intact	0.00	Negative
04	Bldg. 28	New Training Room	West	White	Door Frame	Metal	4 Each	Intact	0.00	Negative
05	Bldg. 28	Hallway	East	White	Door Frame	Metal	8 Each	Intact	0.00	Negative
06	Bldg. 28	Hallway	East	White	Wall	Drywall	4,672 SF	Intact	0.00	Negative
07	Bldg. 28	Hallway	North	Blue	Door Frame	Metal	1 Each	Intact	0.00	Negative
08	Bldg. 28	Hallway	North	Blue	Door	Metal	2 Each	Intact	0.00	Negative
09	Bldg. 28	Storage Room 1	North	White	Ceiling	Drywall	199 SF	Intact	0.00	Negative
10	Bldg. 28	Storage Room 1	North	White	Wall	Drywall	920 SF	Intact	0.00	Negative
11	Bldg. 28	Men's Restroom	South	White	Door Frame	Metal	1 Each	Intact	0.00	Negative
12	Bldg. 28	Men's Restroom	South	Bare	Door	Wood	1 Each	Intact	0.00	Negative
13	Bldg. 28	Men's Restroom	South	White	Wall	Drywall	184 SF	Intact	0.00	Negative
14	Bldg. 28	Men's Restroom	South	Gray	6"x6" Wall Tile	Ceramic	92 SF	Intact	0.00	Negative
15	Bldg. 28	Men's Restroom	South	Blue	6"x6" Wall Tile	Ceramic	92 SF	Intact	0.00	Negative
16	Bldg. 28	Men's Restroom	West	White	Sink	Ceramic	2 Each	Intact	0.00	Negative

**SECTION 2  
SURVEY SUMMARY**

**LEAD XRF SURVEY RESULTS  
BUILDING 28**

**Phase 2 - Fullerton Mill - 2069218 AS  
2001 East Orangethorpe Avenue  
Fullerton, California**

The list materials and their components where Lead Based Paint (LBP) was detected at or in excess of the HUD/EPA standards of 1.0 mg/cm<sup>2</sup> (Los Angeles County has established a more stringent standard for lead-based paint at 0.7mg/cm<sup>2</sup>) by XRF method which is listed in the table below. All XRF readings below the regulatory defined action level are considered negative and all readings at and above these levels are considered positive.

Shot #	Unit	Room Tested	Wall	Color	Component	Substrate	Quantity	Paint Condition	Result	Neg/Pos
17	Bldg. 28	Men's Restroom	West	White	Urinal	Ceramic	2 Each	Intact	0.01	Negative
18	Bldg. 28	Men's Restroom	West	White	Toilet	Ceramic	2 Each	Intact	0.01	Negative
19	Bldg. 28	Men's Restroom	West	Blue	Partition	Metal	2 Each	Intact	0.00	Negative
20	Bldg. 28	Men's Restroom	West	White	Ceiling	Drywall	120 SF	Intact	0.00	Negative
21	Bldg. 28	Men's Restroom	West	Grey	6"x6" Floor Tile	Ceramic	60 SF	Intact	0.00	Negative
22	Bldg. 28	Men's Restroom	West	Blue	6"x6" Floor Tile	Ceramic	60 SF	Intact	0.00	Negative
23	Bldg. 28	Men's Restroom	North	Tan	Wall	FRP	112 SF	Intact	0.00	Negative
24	Bldg. 28	Janitor's Closet	North	White	3"x6" Wall base Tile	Ceramic	14 SF	Intact	0.00	Negative
25	Bldg. 28	Janitor's Closet	North	White	3"x3" Floor Tile	Ceramic	10 SF	Intact	0.00	Negative
26	Bldg. 28	Women's Restroom	South	White	Door Frame	Metal	1 Each	Intact	0.00	Negative
27	Bldg. 28	Women's Restroom	South	Bare	Door	Wood	1 Each	Intact	0.00	Negative
28	Bldg. 28	Women's Restroom	South	White	Wall	Drywall	184 SF	Intact	0.00	Negative
29	Bldg. 28	Women's Restroom	South	Gray	6"x6" Wall Tile	Ceramic	92 SF	Intact	0.00	Negative
30	Bldg. 28	Women's Restroom	South	Blue	6"x6" Wall Tile	Ceramic	92 SF	Intact	0.00	Negative
31	Bldg. 28	Women's Restroom	East	White	Sink	Ceramic	3 Each	Intact	0.00	Negative
32	Bldg. 28	Women's Restroom	East	White	Toilet	Ceramic	3 Each	Intact	0.00	Negative

**SECTION 2**  
**SURVEY SUMMARY**

**LEAD XRF SURVEY RESULTS**  
**BUILDING 28**

**Phase 2 - Fullerton Mill - 2069218 AS**  
**2001 East Orangethorpe Avenue**  
**Fullerton, California**

The list materials and their components where Lead Based Paint (LBP) was detected at or in excess of the HUD/EPA standards of 1.0 mg/cm<sup>2</sup> (Los Angeles County has established a more stringent standard for lead-based paint at 0.7mg/cm<sup>2</sup>) by XRF method which is listed in the table below. All XRF readings below the regulatory defined action level are considered negative and all readings at and above these levels are considered positive.

Shot #	Unit	Room Tested	Wall	Color	Component	Substrate	Quantity	Paint Condition	Result	Neg/Pos
33	Bldg. 28	Women's Restroom	East	Blue	Partition	Metal	3 Each	Intact	0.00	Negative
34	Bldg. 28	Women's Restroom	East	White	Ceiling	Drywall	120 SF	Intact	0.00	Negative
35	Bldg. 28	Women's Restroom	East	Gray	6"x6" Floor Tile	Ceramic	60 SF	Intact	0.00	Negative
36	Bldg. 28	Women's Restroom	East	Blue	6"x6" Floor Tile	Ceramic	60 SF	Intact	0.00	Negative



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
 Chino, CA 91710

**Project ID:** 2069218AM  
**Project Name:** Kimberly Clark - Stores Storage/Office Area 2  
**Project Location:** 2001 E. Orangethorpe Ave.  
 Fullerton, CA

**Report Number:** 1509362  
**Samples Submitted:** 33  
**Sample Collection Date:** 11/27/2018  
**Laboratory Receipt Date:** 11/29/2018

**Page:** 1 of 9

### TEST DATA

---

**Laboratory ID#:** 1509362-001      **Client Sample #:** 1

**Sample Material and Location:** Brown 4" Covebase Office #1 - East End

**Sample Characteristics:** Black Smooth Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/29/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509362-002      **Client Sample #:** 2

**Sample Material and Location:** Brown 4" Covebase Office #1 - North End

**Sample Characteristics:** Black Smooth Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/29/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509362-003      **Client Sample #:** 3

**Sample Material and Location:** Brown 4" Covebase Office #1 - South End

**Sample Characteristics:** Black Smooth Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/29/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509362-004      **Client Sample #:** 4

**Sample Material and Location:** Tan Covebase Glue Office #1 - East End

**Sample Characteristics:** Tan Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/29/2018

**Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
 Chino, CA 91710

**Project ID:** 2069218AM  
**Project Name:** Kimberly Clark - Stores Storage/Office Area 2  
**Project Location:** 2001 E. Orangethorpe Ave.  
 Fullerton, CA

**Report Number:** 1509362  
**Samples Submitted:** 33  
**Sample Collection Date:** 11/27/2018  
**Laboratory Receipt Date:** 11/29/2018

**Page:** 2 of 9

### TEST DATA

**Laboratory ID#:** 1509362-005      **Client Sample #:** 5

**Sample Material and Location:** Tan Covebase Glue Office #1 - North End

**Sample Characteristics:** Tan Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**

**Analyst:** Dennis Liu      **Date Analyzed:** 11/29/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509362-006      **Client Sample #:** 6

**Sample Material and Location:** Tan Covebase Glue Office #1 - South End

**Sample Characteristics:** Tan Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**

**Analyst:** Dennis Liu      **Date Analyzed:** 11/29/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509362-007      **Client Sample #:** 7

**Sample Material and Location:** Offwhite w/Tan 12 x 12 Floor Tile Office #1 - East End

**Sample Characteristics:** Off-White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**

**Analyst:** Dennis Liu      **Date Analyzed:** 11/29/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509362-008      **Client Sample #:** 8

**Sample Material and Location:** Offwhite w/Tan 12 x 12 Floor Tile Office #1 - North End

**Sample Characteristics:** Off-White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**

**Analyst:** Dennis Liu      **Date Analyzed:** 11/29/2018

**Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
 Chino, CA 91710

**Project ID:** 2069218AM  
**Project Name:** Kimberly Clark - Stores Storage/Office Area 2  
**Project Location:** 2001 E. Orangethorpe Ave.  
 Fullerton, CA

**Report Number:** 1509362  
**Samples Submitted:** 33  
**Sample Collection Date:** 11/27/2018  
**Laboratory Receipt Date:** 11/29/2018

**Page:** 3 of 9

### TEST DATA

---

**Laboratory ID#:** 1509362-009      **Client Sample #:** 9

**Sample Material and Location:** Offwhite w/Tan 12 x 12 Floor Tile Office #1 - South End

**Sample Characteristics:** Off-White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/29/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509362-010      **Client Sample #:** 10

**Sample Material and Location:** Yellow Floor Tile Glue Office #1 - East End

**Sample Characteristics:** Yellow Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/29/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509362-011      **Client Sample #:** 11

**Sample Material and Location:** Yellow Floor Tile Glue Office #1 - North End

**Sample Characteristics:** Yellow Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/29/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509362-012      **Client Sample #:** 12

**Sample Material and Location:** Yellow Floor Tile Glue Office #1 - South End

**Sample Characteristics:** Yellow Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/29/2018

**Total Asbestos (%)** None Detected





## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
 Chino, CA 91710  
**Project ID:** 2069218AM  
**Project Name:** Kimberly Clark - Stores Storage/Office Area 2  
**Project Location:** 2001 E. Orangethorpe Ave.  
 Fullerton, CA

**Report Number:** 1509362  
**Samples Submitted:** 33  
**Sample Collection Date:** 11/27/2018  
**Laboratory Receipt Date:** 11/29/2018

**Page:** 4 of 9

### TEST DATA

---

**Laboratory ID#:** 1509362-013      **Client Sample #:** 13  
**Sample Material and Location:** White 12" x 12" Ceiling Tile Office #1 - N.E. End  
**Sample Characteristics:** Brown White Fibrous Inhomogenous  
**Misc. Components Observed:** 58% Non-Fibrous Material  
 2% Fibrous Glass  
 40% Cellulose  
**Asbestos Observed (%):**      **Date Analyzed:** 11/29/2018      **Total Asbestos (%)** None Detected  
**Analyst:** Dennis Liu

### TEST DATA

---

**Laboratory ID#:** 1509362-014      **Client Sample #:** 14  
**Sample Material and Location:** White 12" x 12" Ceiling Tile Office #1 - East End  
**Sample Characteristics:** Brown White Fibrous Inhomogenous  
**Misc. Components Observed:** 58% Non-Fibrous Material  
 2% Fibrous Glass  
 40% Cellulose  
**Asbestos Observed (%):**      **Date Analyzed:** 11/29/2018      **Total Asbestos (%)** None Detected  
**Analyst:** Dennis Liu

### TEST DATA

---

**Laboratory ID#:** 1509362-015      **Client Sample #:** 15  
**Sample Material and Location:** White 12" x 12" Ceiling Tile Office #1 - S.E. End  
**Sample Characteristics:** Brown White Fibrous Inhomogenous  
**Misc. Components Observed:** 58% Non-Fibrous Material  
 2% Fibrous Glass  
 40% Cellulose  
**Asbestos Observed (%):**      **Date Analyzed:** 11/29/2018      **Total Asbestos (%)** None Detected  
**Analyst:** Dennis Liu

### TEST DATA

---

**Laboratory ID#:** 1509362-016      **Client Sample #:** 16  
**Sample Material and Location:** Brown Ceiling Tile Mastic Office #1 - N.E. End  
**Sample Characteristics:** Brown Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**      **Date Analyzed:** 11/29/2018      **Total Asbestos (%)** None Detected  
**Analyst:** Dennis Liu



**Analytical Report**

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
 Chino, CA 91710  
  
**Project ID:** 2069218AM  
**Project Name:** Kimberly Clark - Stores Storage/Office Area 2  
**Project Location:** 2001 E. Orangethorpe Ave.  
 Fullerton, CA

**Report Number:** 1509362  
**Samples Submitted:** 33  
**Sample Collection Date:** 11/27/2018  
**Laboratory Receipt Date:** 11/29/2018

**Page:** 5 of 9

**TEST DATA**

---

**Laboratory ID#:** 1509362-017                      **Client Sample #:** 17

**Sample Material and Location:** Brown Ceiling Tile Mastic Office #1 - East End

**Sample Characteristics:** Brown Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu                      **Date Analyzed:** 11/29/2018

**Total Asbestos (%)** None Detected

**TEST DATA**

---

**Laboratory ID#:** 1509362-018                      **Client Sample #:** 18

**Sample Material and Location:** Brown Ceiling Tile Mastic Office #1 - S.E. End

**Sample Characteristics:** Brown White Fibrous Inhomogenous  
**Misc. Components Observed:** 60% Non-Fibrous Material  
 40% Cellulose  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu                      **Date Analyzed:** 11/29/2018

**Total Asbestos (%)** None Detected

**TEST DATA**

---

**Laboratory ID#:** 1509362-019                      **Client Sample #:** 19

**Sample Material and Location:** White Drywall behind 12 x 12 C.T. Office #1 - N.E. End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 95% Non-Fibrous Material  
 5% Cellulose  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu                      **Date Analyzed:** 11/29/2018

**Total Asbestos (%)** None Detected

**TEST DATA**

---

**Laboratory ID#:** 1509362-020                      **Client Sample #:** 20

**Sample Material and Location:** White Drywall behind 12 x 12 C.T. Office #1 - East End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 95% Non-Fibrous Material  
 5% Cellulose  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu                      **Date Analyzed:** 11/29/2018

**Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
 Chino, CA 91710

**Project ID:** 2069218AM  
**Project Name:** Kimberly Clark - Stores Storage/Office Area 2  
**Project Location:** 2001 E. Orangethorpe Ave.  
 Fullerton, CA

**Report Number:** 1509362  
**Samples Submitted:** 33  
**Sample Collection Date:** 11/27/2018  
**Laboratory Receipt Date:** 11/29/2018

**Page:** 6 of 9

### TEST DATA

---

**Laboratory ID#:** 1509362-021      **Client Sample #:** 21

**Sample Material and Location:** White Drywall behind 12 x 12 C.T. Office #1 - S.E. End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 95% Non-Fibrous Material  
 5% Cellulose

**Asbestos Observed (%):**      **Date Analyzed:** 11/29/2018      **Total Asbestos (%)** None Detected  
**Analyst:** Dennis Liu

### TEST DATA

---

**Laboratory ID#:** 1509362-022      **Client Sample #:** 22

**Sample Material and Location:** White 2' x 4' Ceiling Tile Stores Storage - North End

**Sample Characteristics:** Brown White Fibrous Inhomogenous  
**Misc. Components Observed:** 58% Non-Fibrous Material  
 2% Fibrous Glass  
 40% Cellulose

**Asbestos Observed (%):**      **Date Analyzed:** 11/29/2018      **Total Asbestos (%)** None Detected  
**Analyst:** Dennis Liu

### TEST DATA

---

**Laboratory ID#:** 1509362-023      **Client Sample #:** 23

**Sample Material and Location:** White 2' x 4' Ceiling Tile Stores Storage - Center

**Sample Characteristics:** Brown White Fibrous Inhomogenous  
**Misc. Components Observed:** 58% Non-Fibrous Material  
 2% Fibrous Glass  
 40% Cellulose

**Asbestos Observed (%):**      **Date Analyzed:** 11/29/2018      **Total Asbestos (%)** None Detected  
**Analyst:** Dennis Liu

### TEST DATA

---

**Laboratory ID#:** 1509362-024      **Client Sample #:** 24

**Sample Material and Location:** White 2' x 4' Ceiling Tile Stores Storage - South End

**Sample Characteristics:** Brown White Fibrous Inhomogenous  
**Misc. Components Observed:** 58% Non-Fibrous Material  
 2% Fibrous Glass  
 40% Cellulose

**Asbestos Observed (%):**      **Date Analyzed:** 11/29/2018      **Total Asbestos (%)** None Detected  
**Analyst:** Dennis Liu





## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
 Chino, CA 91710

**Project ID:** 2069218AM  
**Project Name:** Kimberly Clark - Stores Storage/Office Area 2  
**Project Location:** 2001 E. Orangethorpe Ave.  
 Fullerton, CA

**Report Number:** 1509362  
**Samples Submitted:** 33  
**Sample Collection Date:** 11/27/2018  
**Laboratory Receipt Date:** 11/29/2018

**Page:** 8 of 9

### TEST DATA

---

**Laboratory ID#:** 1509362-029      **Client Sample #:** 29

**Sample Material and Location:** White Ductwork Wrap Warehouse - East End

**Sample Characteristics:** White Fibrous Inhomogenous  
**Misc. Components Observed:** 20% Non-Fibrous Material  
 80% Cellulose

**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/29/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509362-030      **Client Sample #:** 30

**Sample Material and Location:** White Ductwork Wrap Warehouse - South End

**Sample Characteristics:** White Fibrous Inhomogenous  
**Misc. Components Observed:** 20% Non-Fibrous Material  
 80% Cellulose

**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/29/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509362-031      **Client Sample #:** 31

**Sample Material and Location:** Brown Ductwork Insulation Warehouse - North End

**Sample Characteristics:** Brown Fibrous Inhomogenous  
**Misc. Components Observed:** 10% Non-Fibrous Material  
 80% Fibrous Glass  
 10% Cellulose

**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/29/2018

**Total Asbestos (%)** None Detected

### TEST DATA

---

**Laboratory ID#:** 1509362-032      **Client Sample #:** 32

**Sample Material and Location:** Brown Ductwork Insulation Warehouse - East End

**Sample Characteristics:** Brown Fibrous Inhomogenous  
**Misc. Components Observed:** 10% Non-Fibrous Material  
 80% Fibrous Glass  
 10% Cellulose

**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/29/2018

**Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
 Chino, CA 91710

**Project ID:** 2069218AM  
**Project Name:** Kimberly Clark - Stores Storage/Office Area 2  
**Project Location:** 2001 E. Orangethorpe Ave.  
 Fullerton, CA

**Report Number:** 1509362  
**Samples Submitted:** 33  
**Sample Collection Date:** 11/27/2018  
**Laboratory Receipt Date:** 11/29/2018

**Page:** 9 of 9

### TEST DATA

**Laboratory ID#:** 1509362-033      **Client Sample #:** 33

**Sample Material and Location:** Brown Ductwork Insulation Warehouse - South End

**Sample Characteristics:** Brown Fibrous Inhomogenous  
**Misc. Components Observed:** 10% Non-Fibrous Material  
 80% Fibrous Glass  
 10% Cellulose

**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 11/29/2018

**Total Asbestos (%)** None Detected

Samples were analyzed by Calibrated Visual Estimation (CVE). Analyses by CVE have a detection limit of 1% asbestos by relative area and may not be consistently reliable below this limit or for asbestos with fiber diameter thinner than the resolving capacity of PLM without further analysis by another independent method. A test result of less than (<) 1% by CVE means asbestos was observed in the sample but is visually estimated to be below the reportable limit of 1%. The laboratory references interim method EPA 600/M4-82-020 (Interim Method) for fiber identification, 400 point counts, and composite reporting. EPA method 600/R-93/116 is referenced for analysis of non-insulation materials, sub-layers, expanded and modified point counts, CVE and subsequent data reporting. Samples containing distinct layers that can be reliably separated are analyzed and reported as separate unless requested in writing. The test data presented apply only to the items submitted. Count for samples submitted is indicative of total layers observed and may vary from actual analysis for positive stop requests. ATEL, LLC is a NIST-NVLAP and CA-ELAP Accredited laboratory (ID# 201073-0 and #2971, respectively). This report must not be reproduced, unless in its entirety, without the written consent of ATEL, LLC. Per NIST-NVLAP 150 Annex A: This report shall not be used to claim product certification, approval or endorsement by NVLAP, NIST, or any agency of the federal government.


Unless indicated, samples were received in acceptable condition. Sample retention time is 30 days from issuing this report unless requested otherwise.

**Analyst Signature:**  -Dennis Liu

**Approved Signatory:**  -Chris Turton

**Reported On:** 11/30/2018





# ENVIRONMENTAL CONSULTING SERVICES, INC.

## Bulk Sampling Form

Stop at First Positive   
  24 Hour turn around   
  Rush turn around (4 Hours)  
 Do Not Layer Samples

CLIENT <i>Kimberly Clark</i>	PROJECT NO. <i>2069218A</i>
PROJECT ID <i>Bldg. Storage Storage/ Office Area 2</i>	DATE <i>11/27/18</i>
PROJECT LOCATION <i>2001 E. Orange Avenue, Fullerton, CA</i>	PAGE OF <i>1 2</i>
INSPECTOR <i>A. Sanchez</i>	

GRP. NO.	SAMP. NO.	MATERIAL DESCRIPTION	LOCATION OF SAMPLE	QTY	% POS
01	01	Bra. 4" Combs	Office #1 - East end	44 Lit.	
↓	02	↓	↓ - North end	↓	
↓	03	↓	↓ - South end	↓	
02	04	TAN Combs	Office #1 - East end	44 Lit.	
↓	05	↓	↓ - North end	↓	
↓	06	↓	↓ - South end	↓	
03	07	offwhite w/TAN	Office #1 - East end	120 p	
↓	08	↓	↓ - North end	↓	
↓	09	↓	↓ - South end	↓	
04	10	yellow floor	Office #1 - East end	120 p	
↓	11	↓	↓ - North end	↓	
↓	12	↓	↓ - South end	↓	
05	13	white 12x12	Office #1 - N.E. end	120 p	
↓	14	↓	↓ - East end	↓	
↓	15	↓	↓ - S.E. end	↓	
06	16	Bra. ceiling tile	Office #1 - N.E. end	120 p	
↓	17	↓	↓ - East end	↓	
↓	18	↓	↓ - S.E. end	↓	
07	19	white Downall	Office #1 - N.E. end	120 p	
↓	20	↓	↓ - East end	↓	
↓	21	↓	↓ - S.E. end	↓	

Notes:





**SECTION 2  
SURVEY SUMMARY**

**LEAD XRF SURVEY RESULTS  
STORES STORAGE/OFFICE AREA 2**

**Phase 2 - Fullerton Mill - 2069218 AS  
2001 East Orangethorpe Avenue  
Fullerton, California**

The list materials and their components where Lead Based Paint (LBP) was detected at or in excess of the HUD/EPA standards of 1.0 mg/cm<sup>2</sup> (Los Angeles County has established a more stringent standard for lead-based paint at 0.7mg/cm<sup>2</sup>) by XRF method which is listed in the table below. All XRF readings below the regulatory defined action level are considered negative and all readings at and above these levels are considered positive.

Shot #	Unit	Room Tested	Wall	Color	Component	Substrate	Quantity	Paint Condition	Result	Neg/Pos
01	B10	Stores Storage	West	White	Wall	Concrete	1,000 SF	Intact	0.00	Negative
02	B10	Stores Storage	West	White	I-Beam	Metal	100 SF	Intact	0.02	Negative
03	B10	Stores Storage	West	White	Wall	Wood	300 SF	Intact	0.00	Negative
04	B10	Stores Storage	West	Gray	Wall	Wood	100 SF	Intact	0.00	Negative
05	B10	Stores Storage	West	Blue	Wall	Wood	100 SF	Intact	0.00	Negative
06	B10	Stores Storage	West	Blue	Door	Wood	1 Each	Intact	0.00	Negative
07	B10	Stores Storage	West	Blue	Door Frame	Wood	1 Each	Intact	0.01	Negative
08	B10	Stores Storage	North	Gray	Door	Metal	5 Each	Intact	0.03	Negative
09	B10	Stores Storage	North	Gray	Door Frame	Metal	5 Each	Intact	0.01	Negative
10	B10	Stores Storage	East	Gray	Roll Up Door	Metal	1 Each	Intact	0.02	Negative
11	B10	Stores Storage	East	White	Roll Up Door Frame	Metal	1 Each	Intact	0.01	Negative
12	B10	Stores Storage	East	Yellow	Bollards	Metal	2 Each	Intact	0.07	Negative
13	B10	Stores Storage	North	Gray	Door	Metal	2 Each	Intact	0.01	Negative
14	B10	Warehouse	North	Gray	Door Frame	Metal	2 Each	Intact	0.02	Negative
<b>15</b>	<b>B10</b>	<b>Warehouse</b>	<b>North</b>	<b>Brown</b>	<b>Sliding Door</b>	<b>Metal</b>	<b>3 Each</b>	<b>Intact</b>	<b>10.10</b>	<b>Positive</b>
16	B10	Warehouse	North	Brown	Sliding Door Frame	Metal	3 Each	Intact	0.10	Negative

**SECTION 2  
SURVEY SUMMARY**

**LEAD XRF SURVEY RESULTS  
STORES STORAGE/OFFICE AREA 2**

**Phase 2 - Fullerton Mill - 2069218 AS  
2001 East Orangethorpe Avenue  
Fullerton, California**

The list materials and their components where Lead Based Paint (LBP) was detected at or in excess of the HUD/EPA standards of 1.0 mg/cm<sup>2</sup> (Los Angeles County has established a more stringent standard for lead-based paint at 0.7mg/cm<sup>2</sup>) by XRF method which is listed in the table below. All XRF readings below the regulatory defined action level are considered negative and all readings at and above these levels are considered positive.

Shot #	Unit	Room Tested	Wall	Color	Component	Substrate	Quantity	Paint Condition	Result	Neg/Pos
17	B10	Warehouse	East	Red	I-Beam	Metal	100 SF	Intact	0.27	Negative
18	B10	Warehouse	East	White	I-Beam	Metal	1,000 SF	Intact	0.01	Negative
<b>19</b>	<b>B10</b>	<b>Warehouse</b>	<b>East</b>	<b>White</b>	<b>Wall</b>	<b>Metal</b>	<b>2,380 SF</b>	<b>Intact</b>	<b>4.00</b>	<b>Positive</b>
20	B10	Warehouse	East	Red	Fire Hose Cabinet	Metal	1 Each	Intact	0.00	Negative
21	B10	Warehouse	East	Red	Floor	Concrete	100 SF	Intact	0.00	Negative
22	B10	Warehouse	East	White	Ceiling	Metal	13,923 SF	Intact	0.01	Negative
<b>23</b>	<b>B10</b>	<b>Warehouse</b>	<b>East</b>	<b>White</b>	<b>Ceiling I-Beam</b>	<b>Metal</b>	<b>13,923 SF</b>	<b>Intact</b>	<b>3.10</b>	<b>Positive</b>
<b>24</b>	<b>B10</b>	<b>Warehouse</b>	<b>East</b>	<b>White</b>	<b>Cross Beam</b>	<b>Metal</b>	<b>13,923 SF</b>	<b>Intact</b>	<b>2.80</b>	<b>Positive</b>
25	B10	Warehouse	North	Yellow	Floor	Concrete	100 SF	Intact	0.00	Negative
26	B10	Warehouse	East	White	Ceiling Pipe	Metal	300 LF	Intact	0.00	Negative

**SECTION 2  
SURVEY SUMMARY**

**LEAD XRF SURVEY RESULTS  
HARDROLL AREA**

**Phase 2 - Fullerton Mill - 2069218 AS  
2001 East Orangethorpe Avenue  
Fullerton, California**

The list materials and their components where Lead Based Paint (LBP) was detected at or in excess of the HUD/EPA standards of 1.0 mg/cm<sup>2</sup> (Los Angeles County has established a more stringent standard for lead-based paint at 0.7mg/cm<sup>2</sup>) by XRF method which is listed in the table below. All XRF readings below the regulatory defined action level are considered negative and all readings at and above these levels are considered positive.

Shot #	Unit	Room Tested	Wall	Color	Component	Substrate	Quantity	Paint Condition	Result	Neg/Pos
01	B10	Hardroll Area	North	Yellow	Floor	Concrete	800 LF	Intact	0.00	Negative
02	B10	Hardroll Area	North	White	Floor	Concrete	800 LF	Intact	0.00	Negative
03	B10	Hardroll Area	North	Green	Floor	Concrete	20 SF	Intact	0.00	Negative
04	B10	Hardroll Area	North	Blue	Floor	Concrete	10 LF	Intact	0.00	Negative
05	B10	Hardroll Area	North	White	Wall	Concrete	3,000 SF	Intact	0.00	Negative
06	B10	Hardroll Area	North	White	I-Beam	Metal	1,000 SF	Intact	0.01	Negative
<b>07</b>	<b>B10</b>	<b>Hardroll Area</b>	<b>East</b>	<b>Red</b>	<b>I-Beam</b>	<b>Metal</b>	<b>300 SF</b>	<b>Intact</b>	<b>5.30</b>	<b>Positive</b>
<b>08</b>	<b>B10</b>	<b>Hardroll Area</b>	<b>West</b>	<b>Yellow</b>	<b>I-Beam</b>	<b>Metal</b>	<b>300 SF</b>	<b>Intact</b>	<b>4.90</b>	<b>Positive</b>
09	B10	Hardroll Area	East	Gray	Door	Metal	2 Each	Intact	0.50	Negative
<b>10</b>	<b>B10</b>	<b>Hardroll Area</b>	<b>East</b>	<b>Gray</b>	<b>Door Frame</b>	<b>Metal</b>	<b>2 Each</b>	<b>Intact</b>	<b>3.30</b>	<b>Positive</b>
11	B10	Hardroll Area	East	Gray	Sliding Door	Metal	2 Each	Intact	0.11	Negative
<b>12</b>	<b>B10</b>	<b>Hardroll Area</b>	<b>East</b>	<b>Gray</b>	<b>Sliding Door Frame</b>	<b>Metal</b>	<b>2 Each</b>	<b>Intact</b>	<b>7.10</b>	<b>Positive</b>
13	B10	Hardroll Area	East	White	Ceiling	Metal	7,800 SF	Intact	0.01	Negative
14	B10	Hardroll Area	East	White	Ceiling I-Beam	Metal	7,800 SF	Intact	0.04	Negative
15	B10	Hardroll Area	East	White	Crossbeam	Metal	7,800 SF	Intact	0.01	Negative
<b>16</b>	<b>B10</b>	<b>Hardroll Area</b>	<b>East</b>	<b>Yellow</b>	<b>Bollards</b>	<b>Metal</b>	<b>4 Each</b>	<b>Intact</b>	<b>4.70</b>	<b>Positive</b>



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
 Chino, CA 91710

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - North Gate Fire Pump House  
**Project Location:** 2001 E. Orangethorpe Ave  
 Fullerton, CA

**Report Number:** 1509514  
**Samples Submitted:** 3  
**Sample Collection Date:** 12/7/2018  
**Laboratory Receipt Date:** 12/7/2018

**Page:** 1 of 1

### TEST DATA

**Laboratory ID#:** 1509514-001      **Client Sample #:** 1

**Sample Material and Location:** White Caulking on Wall Fire Pump Room - North End

**Sample Characteristics:** Grey Smooth Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 12/7/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509514-002      **Client Sample #:** 2

**Sample Material and Location:** White Caulking on Wall Fire Pump Room - S.E. End End

**Sample Characteristics:** Grey Smooth Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 12/7/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509514-003      **Client Sample #:** 3

**Sample Material and Location:** White Caulking on Wall Fire Pump Room - S.W. End End

**Sample Characteristics:** Grey Smooth Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Dennis Liu      **Date Analyzed:** 12/7/2018

**Total Asbestos (%)** None Detected

Samples were analyzed by Calibrated Visual Estimation (CVE). Analyses by CVE have a detection limit of 1% asbestos by relative area and may not be consistently reliable below this limit or for asbestos with fiber diameter thinner than the resolving capacity of PLM without further analysis by another independent method. A test result of less than (<) 1% by CVE means asbestos was observed in the sample but is visually estimated to be below the reportable limit of 1%. The laboratory references interim method EPA 600/M4-82-020 (Interim Method) for fiber identification, 400 point counts, and composite reporting. EPA method 600/R-93/116 is referenced for analysis of non-insulation materials, sub-layers, expanded and modified point counts, CVE and subsequent data reporting. Samples containing distinct layers that can be reliably separated are analyzed and reported as separate unless requested in writing. The test data presented apply only to the items submitted. Count for samples submitted is indicative of total layers observed and may vary from actual analysis for positive stop requests. ATEL, LLC is a NIST-NVLAP and CA-ELAP Accredited laboratory (ID# 201073-0 and #2971, respectively). This report must not be reproduced, unless in its entirety, without the written consent of ATEL, LLC. Per NIST-NVLAP 150 Annex A: This report shall not be used to claim product certification, approval or endorsement by NVLAP, NIST, or any agency of the federal government.

Unless indicated, samples were received in acceptable condition. Sample retention time is 30 days from issuing this report unless requested otherwise.

**Analyst Signature:**

-Dennis Liu

**Approved Signatory:**

-Chris Turton

**Reported On:** 12/8/2018



1509514

Analytical Services Request v.112414

Pg 1 of 1

Asbestos Laboratory

**Your Contact Information**

Company Name (if by company): H2 Environmental Consulting Services, Inc.

Personal/Company Address: 13122 6th Street, Chino, CA 91710

Contact Person: Amy De Santiago

Contact Information: Main: 909-628-0369 E-Mail: labresults@h2env.com

Mobile: \_\_\_\_\_ Fax: 909-613-5845

How should we send your result? Verbal  Verbal  E-mail  Fax

*\*If verbal results are requested, you must also select a second form of delivery.*

**Project Information**

Project Name: Kimberly Clark

Project #: 2069218 AS

Project Location: 2001 E Orange Avenue Anaheim Fullerton, CA - Bldg N. h2c Fire Pump House

PO#: \_\_\_\_\_ Claim#: \_\_\_\_\_

Date Sampled: 12/7/18 Time Sampled: 11am

Analytical Type(s) Requested	Turnaround Time*
<b>Asbestos in Bulk Materials</b> EPA 600/R-93/116, 600/M4-82-020 Routine, Calibrated Visual Estimation <input checked="" type="checkbox"/> Point Count: 400pts <input type="checkbox"/> 1000pts <input type="checkbox"/> Gravimetric Reduction (72hr Minimum) <input type="checkbox"/>	*Business Hrs: 0800-1700 Mon-Fri. Rush 3 Business Hrs* <input type="checkbox"/> 8 Business Hrs* <input type="checkbox"/> Expedited 24 Business Hrs <input checked="" type="checkbox"/> Routine 48 Business Hrs <input type="checkbox"/> 72 Business Hrs <input type="checkbox"/> Standard 5 Business Days <input type="checkbox"/>
<b>Fiber Count in Sampling Cartridge (25mm MCE)</b> Asbestos-like, NIOSH 7400 A Rules <input type="checkbox"/>	*3hr TAT: Samples must be submitted by 2pm for same day results *8hr TAT: Samples must be submitted by 9am for same day results
<b>Rotometer Calibration (Low and High Flow Rotometers)</b> <input type="checkbox"/>	
<b>Special Instructions:</b> _____	

**Sample Information**

Sample ID #	Description/Material Type	Location	Flow Rate	Start Time	Stop Time	Volume (L)
	Please See Attached					

For more samples, please continue onto supplemental form. Page # Indication in upper-right-hand of form.

**Chain of Custody**

Relinquished By: _____	Date <u>and</u> Time: _____
Received By: _____	Date <u>and</u> Time: _____
Relinquished By: _____	Date <u>and</u> Time: _____
Received By: <u>[Signature]</u>	Date <u>and</u> Time: <u>12/7/18 3:40</u>



**SECTION 2  
SURVEY SUMMARY**

**LEAD XRF SURVEY RESULTS  
NORTH GATE FIRE PUMP ROOM**

**Phase 2 - Fullerton Mill - 2069218 AS  
2001 East Orangethorpe Avenue  
Fullerton, California**

The list materials and their components where Lead Based Paint (LBP) was detected at or in excess of the HUD/EPA standards of 1.0 mg/cm<sup>2</sup> (Los Angeles County has established a more stringent standard for lead-based paint at 0.7mg/cm<sup>2</sup>) by XRF method which is listed in the table below. All XRF readings below the regulatory defined action level are considered negative and all readings at and above these levels are considered positive.

Shot #	Unit	Room Tested	Wall	Color	Component	Substrate	Quantity	Paint Condition	Result	Neg/Pos
01	Exterior	North Gate Fire Pump	East	Red	Box	Metal	1 Each	Intact	0.00	Negative
02	Exterior	North Gate Fire Pump	East	Red	Pipe	Metal	100 LF	Intact	0.01	Negative
<b>03</b>	<b>Exterior</b>	<b>North Gate Fire Pump</b>	<b>East</b>	<b>White</b>	<b>Water Tank</b>	<b>Metal</b>	<b>2 Each</b>	<b>Intact</b>	<b>7.30</b>	<b>Positive</b>
<b>04</b>	<b>Exterior</b>	<b>North Gate Fire Pump</b>	<b>West</b>	<b>Yellow</b>	<b>Shoot Ladder</b>	<b>Metal</b>	<b>2 Each</b>	<b>Intact</b>	<b>8.40</b>	<b>Positive</b>
05	Exterior	North Gate Fire Pump	West	White	Water Tank Mount	Metal	2 Each	Intact	0.01	Negative
06	Exterior	North Gate Fire Pump	West	Yellow	Floor	Asphalt	20 LF	Intact	0.01	Negative
07	Exterior	North Gate Fire Pump	West	White	Floor	Asphalt	10 LF	Intact	0.00	Negative
08	Interior	North Gate Fire Pump	West	Red	Pipe	Metal	100 LF	Intact	0.00	Negative
09	Interior	North Gate Fire Pump	West	Gray	Post	Metal	6 Each	Intact	0.00	Negative
10	Interior	North Gate Fire Pump	North	Yellow	Floor	Concrete	50 SF	Intact	0.00	Negative
11	Interior	North Gate Fire Pump	East	Blue	Pipe	Metal	2 Each	Intact	0.00	Negative
12	Interior	North Gate Fire Pump	East	Gray	Door Frame	Metal	1 Each	Intact	0.00	Negative
13	Interior	North Gate Fire Pump	East	Gray	Door	Metal	1 Each	Intact	0.00	Negative
14	Interior	North Gate Fire Pump	East	Orange	Machine	Metal	1 Each	Intact	0.00	Negative
15	Interior	North Gate Fire Pump	East	Gray	Floor	Concrete	750 SF	Intact	0.00	Negative
16	Interior	North Gate Fire Pump	East	Gray	I-Beam	Gray	2 Each	Intact	0.00	Negative





## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
 Chino, CA 91710

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Guard Shack North Gate  
**Project Location:** 2001 E. Orangethorpe Ave  
 Fullerton, CA

**Report Number:** 1509520  
**Samples Submitted:** 18  
**Sample Collection Date:** 12/7/2018  
**Laboratory Receipt Date:** 12/7/2018

**Page:** 1 of 5

### TEST DATA

**Laboratory ID#:** 1509520-001 **Client Sample #:** 1

**Sample Material and Location:** White 2' x 4' Ceiling Tile Guard Shack - West End

**Sample Characteristics:** White Gray Fibrous Inhomogenous  
**Misc. Components Observed:** 60% Non-Fibrous Material  
 10% Fibrous Glass  
 30% Cellulose

**Asbestos Observed (%):**  
**Analyst:** Chris Turton **Date Analyzed:** 12/7/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509520-002 **Client Sample #:** 2

**Sample Material and Location:** White 2' x 4' Ceiling Tile Guard Shack - North End

**Sample Characteristics:** White Gray Fibrous Inhomogenous  
**Misc. Components Observed:** 60% Non-Fibrous Material  
 10% Fibrous Glass  
 30% Cellulose

**Asbestos Observed (%):**  
**Analyst:** Chris Turton **Date Analyzed:** 12/7/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509520-003 **Client Sample #:** 3

**Sample Material and Location:** White 2' x 4' Ceiling Tile Guard Shack - East End

**Sample Characteristics:** White Grey Fibrous Inhomogenous  
**Misc. Components Observed:** 60% Non-Fibrous Material 35% Cellulose  
 10% Fibrous Glass  
 30% Cellulose

**Asbestos Observed (%):**  
**Analyst:** Chris Turton **Date Analyzed:** 12/7/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509520-004 **Client Sample #:** 4

**Sample Material and Location:** Black 4" Covebase Guard Shack - North End

**Sample Characteristics:** Black Gray Smooth Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material

**Asbestos Observed (%):**  
**Analyst:** Chris Turton **Date Analyzed:** 12/7/2018

**Total Asbestos (%)** None Detected



**Analytical Report**

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
 Chino, CA 91710  
  
**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Guard Shack North Gate  
**Project Location:** 2001 E. Orangethorpe Ave  
 Fullerton, CA

**Report Number:** 1509520  
**Samples Submitted:** 18  
**Sample Collection Date:** 12/7/2018  
**Laboratory Receipt Date:** 12/7/2018

**Page:** 2 of 5

**TEST DATA**

---

**Laboratory ID#:** 1509520-005                      **Client Sample #:** 5

**Sample Material and Location:** Black 4" Covebase Guard Shack - East End

**Sample Characteristics:** Black Grey Smooth Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton                      **Date Analyzed:** 12/7/2018

**Total Asbestos (%)** None Detected

**TEST DATA**

---

**Laboratory ID#:** 1509520-006                      **Client Sample #:** 6

**Sample Material and Location:** Black 4" Covebase Guard Shack - South End

**Sample Characteristics:** Black Gray Smooth Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton                      **Date Analyzed:** 12/7/2018

**Total Asbestos (%)** None Detected

**TEST DATA**

---

**Laboratory ID#:** 1509520-007                      **Client Sample #:** 7

**Sample Material and Location:** White Covebase Glue Guard Shack - North End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton                      **Date Analyzed:** 12/7/2018

**Total Asbestos (%)** None Detected

**TEST DATA**

---

**Laboratory ID#:** 1509520-008                      **Client Sample #:** 8

**Sample Material and Location:** White Covebase Glue Guard Shack - East End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton                      **Date Analyzed:** 12/7/2018

**Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
 Chino, CA 91710

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Guard Shack North Gate  
**Project Location:** 2001 E. Orangethorpe Ave  
 Fullerton, CA

**Report Number:** 1509520  
**Samples Submitted:** 18  
**Sample Collection Date:** 12/7/2018  
**Laboratory Receipt Date:** 12/7/2018

**Page:** 3 of 5

### TEST DATA

**Laboratory ID#:** 1509520-009      **Client Sample #:** 9

**Sample Material and Location:** White Covebase Glue Guard Shack - South End

**Sample Characteristics:** White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 12/7/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509520-010      **Client Sample #:** 10

**Sample Material and Location:** Gray 12 x 12 Floor Tile Guard Shack - North End

**Sample Characteristics:** Gray Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 12/7/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509520-011      **Client Sample #:** 11

**Sample Material and Location:** Gray 12 x 12 Floor Tile Guard Shack - East End

**Sample Characteristics:** Gray Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 12/7/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509520-012      **Client Sample #:** 12

**Sample Material and Location:** Gray 12 x 12 Floor Tile Guard Shack - South End

**Sample Characteristics:** Gray Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 12/7/2018

**Total Asbestos (%)** None Detected



## Analytical Report

Asbestos Identification in Bulk Materials  
by Polarized Light Microscopy

**Client Name:** H2 Environmental Consulting Services  
**Client Address:** 13122 6th Street  
Chino, CA 91710

**Report Number:** 1509520  
**Samples Submitted:** 18  
**Sample Collection Date:** 12/7/2018  
**Laboratory Receipt Date:** 12/7/2018

**Project ID:** 2069218AS  
**Project Name:** Kimberly Clark - Guard Shack North Gate  
**Project Location:** 2001 E. Orangethorpe Ave  
Fullerton, CA

**Page:** 4 of 5

### TEST DATA

**Laboratory ID#:** 1509520-013      **Client Sample #:** 13

**Sample Material and Location:** Offwhite Floor Tile under Gray Floor Tile Guard Shack - North End

**Sample Characteristics:** Off-White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 12/7/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509520-014      **Client Sample #:** 14

**Sample Material and Location:** Offwhite Floor Tile under Gray Floor Tile Guard Shack - East End

**Sample Characteristics:** Off-White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 12/7/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509520-015      **Client Sample #:** 15

**Sample Material and Location:** Offwhite Floor Tile under Gray Floor Tile Guard Shack - South End

**Sample Characteristics:** Off-White Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 12/7/2018

**Total Asbestos (%)** None Detected

### TEST DATA

**Laboratory ID#:** 1509520-016      **Client Sample #:** 16


**Sample Material and Location:** Gray/Yellow Floor Tile Glue Guard Shack - North End

**Sample Characteristics:** Gray Yellow Non-Fibrous Homogenous  
**Misc. Components Observed:** 100% Non-Fibrous Material  
**Asbestos Observed (%):**  
**Analyst:** Chris Turton      **Date Analyzed:** 12/7/2018

**Total Asbestos (%)** None Detected







**H2 ENVIRONMENTAL CONSULTING SERVICES, INC.**

**Bulk Sampling Form**

Stop at First Positive     24 Hour turn around     Rush turn around (4 Hours)  
 Do Not Layer Samples

CLIENT Kimberly Clark	PROJECT NO. 2069218AS		
PROJECT ID Guard Shack Nookin Gut	DATE 12/7/18	PAGE 1	OF 1
PROJECT LOCATION 2001 E. Orange thorns Ave, Fullerton, CA	INSPECTOR A. Sanchez		

GRP. NO.	SAMP. NO.	MATERIAL DESCRIPTION	LOCATION OF SAMPLE	QTY	% POS
01	01	white 2x4'	Guard shack - west end	110φ	
	02	ceiling tiles	↓ - north end	↓	
	03	↓	↓ - east end	↓	
02	04	Blk 4" concrete	Guard shack - north end	426LF	
	05	↓	↓ - east end	↓	
	06	↓	↓ - south end	↓	
03	07	white concrete	Guard shack - north end	426LF	
	08	glue ↓	Guard shack - east end	↓	
	09	↓	↓ - south end	↓	
04	10	gray 12x12 Floor	Guard shack - north end	110φ	
	11	tile ↓	↓ - east end	↓	
	12	↓	↓ - south end	↓	
05	13	off-white Floor tile	Guard shack - north end	110φ	
	14	under gray Floor tile	↓ - east end	↓	
	15	↓	↓ - south end	↓	
06	16	gray/yellow Floor tile	Guard shack - north end	110φ	
	17	glue ↓	↓ - east end	↓	
	18	↓	↓ - south end	↓	

Notes:

**SECTION 2  
SURVEY SUMMARY**

**LEAD XRF SURVEY RESULTS  
NORTH GATE GUARD SHACK**

**Phase 2 - Fullerton Mill - 2069218 AS  
2001 East Orangethorpe Avenue  
Fullerton, California**

The list materials and their components where Lead Based Paint (LBP) was detected at or in excess of the HUD/EPA standards of 1.0 mg/cm<sup>2</sup> (Los Angeles County has established a more stringent standard for lead-based paint at 0.7mg/cm<sup>2</sup>) by XRF method which is listed in the table below. All XRF readings below the regulatory defined action level are considered negative and all readings at and above these levels are considered positive.

Shot #	Unit	Room Tested	Wall	Color	Component	Substrate	Quantity	Paint Condition	Result	Neg/Pos
01	Exterior	Guard Shack	North	White	Wall	Concrete	336 SF	Intact	0.00	Negative
02	Exterior	Guard Shack	North	White	Pipe	Metal	1 Each	Intact	0.00	Negative
03	Exterior	Guard Shack	North	Brown	Wall	Wood	120 SF	Intact	0.00	Negative
04	Exterior	Guard Shack	North	Brown	Edge Metal	Metal	42 LF	Intact	0.00	Negative
<b>05</b>	<b>Exterior</b>	<b>Guard Shack</b>	<b>North</b>	<b>Yellow</b>	<b>Bollard</b>	<b>Metal</b>	<b>4 Each</b>	<b>Intact</b>	<b>2.20</b>	<b>Positive</b>
06	Exterior	Guard Shack	North	Yellow	Floor	Asphalt	20 LF	Intact	0.00	Negative
07	Interior	Guard Shack	East	Yellow	Floor	Concrete	5 LF	Intact	0.00	Negative
08	Interior	Guard Shack	East	White	Wall	Concrete	256 SF	Intact	0.00	Negative
09	Interior	Guard Shack	East	Tan	Window Frame	Metal	4 Each	Intact	0.00	Negative
10	Exterior	Guard Shack	East	Red	Floor	Asphalt	15 SF	Intact	0.00	Negative
11	Exterior	Guard Shack	North	Tan	A/C Bracket	Metal	2 Each	Intact	0.00	Negative



**SECTION 2  
SURVEY SUMMARY**

**LEAD XRF SURVEY RESULTS  
ACACIA NORTHWEST FIRE PUMP BUILDING**

**Phase 2 - Fullerton Mill - 2069218 AS  
2001 East Orangethorpe Avenue  
Fullerton, California**

The list materials and their components where Lead Based Paint (LBP) was detected at or in excess of the HUD/EPA standards of 1.0 mg/cm<sup>2</sup> (Los Angeles County has established a more stringent standard for lead-based paint at 0.7mg/cm<sup>2</sup>) by XRF method which is listed in the table below. All XRF readings below the regulatory defined action level are considered negative and all readings at and above these levels are considered positive.

Shot #	Unit	Room Tested	Wall	Color	Component	Substrate	Quantity	Paint Condition	Result	Neg/Pos
<b>01</b>	<b>Interior</b>	<b>Fire Pump Bldg.</b>	<b>South</b>	<b>Blue</b>	<b>Door</b>	<b>Metal</b>	<b>2 Each</b>	<b>Intact</b>	<b>2.10</b>	<b>Positive</b>
<b>02</b>	<b>Interior</b>	<b>Fire Pump Bldg.</b>	<b>South</b>	<b>White</b>	<b>Door Frame</b>	<b>Metal</b>	<b>2 Each</b>	<b>Intact</b>	<b>6.80</b>	<b>Positive</b>
<b>03</b>	<b>Interior</b>	<b>Fire Pump Bldg.</b>	<b>South</b>	<b>White</b>	<b>I-Beam</b>	<b>Metal</b>	<b>6 Each</b>	<b>Intact</b>	<b>5.70</b>	<b>Positive</b>
04	Interior	Fire Pump Bldg.	South	White	Wall	Metal	480 SF	Intact	0.01	Negative
05	Interior	Fire Pump Bldg.	South	White	Ceiling	Metal	221 SF	Intact	0.01	Negative
<b>06</b>	<b>Interior</b>	<b>Fire Pump Bldg.</b>	<b>South</b>	<b>White</b>	<b>Ceiling I-Beam</b>	<b>Metal</b>	<b>100 SF</b>	<b>Intact</b>	<b>6.70</b>	<b>Positive</b>
07	Interior	Fire Pump Bldg.	South	Green	Pipe	Metal	5 LF	Intact	0.00	Negative
08	Interior	Fire Pump Bldg.	South	Yellow	Floor Threshold	Concrete	3 LF	Intact	0.00	Negative
09	Interior	Fire Pump Bldg.	East	Blue	Pipe	Metal	10 LF	Intact	0.00	Negative
10	Interior	Fire Pump Bldg.	East	Yellow	Machine	Metal	1 Each	Intact	0.00	Negative
11	Interior	Fire Pump Bldg.	East	Red	Machine	Metal	1 Each	Intact	0.00	Negative
12	Interior	Fire Pump Bldg.	West	Red	Panel	Metal	1 Each	Intact	0.00	Negative
<b>13</b>	<b>Exterior</b>	<b>Fire Pump Bldg.</b>	<b>South</b>	<b>Blue</b>	<b>Door Frame</b>	<b>Metal</b>	<b>2 Each</b>	<b>Intact</b>	<b>6.20</b>	<b>Positive</b>
<b>14</b>	<b>Exterior</b>	<b>Fire Pump Bldg.</b>	<b>South</b>	<b>Blue</b>	<b>Door</b>	<b>Metal</b>	<b>2 Each</b>	<b>Intact</b>	<b>2.20</b>	<b>Positive</b>
<b>15</b>	<b>Exterior</b>	<b>Fire Pump Bldg.</b>	<b>South</b>	<b>White</b>	<b>I-Beam</b>	<b>Metal</b>	<b>4 Each</b>	<b>Intact</b>	<b>6.60</b>	<b>Positive</b>
16	Exterior	Fire Pump Bldg.	South	White	Wall	Metal	480 SF	Intact	0.00	Negative

**SECTION 2  
SURVEY SUMMARY**

**LEAD XRF SURVEY RESULTS  
OUTFALL SAMPLE ROOM**

**Phase 2 - Fullerton Mill - 2069218 AS  
2001 East Orangethorpe Avenue  
Fullerton, California**

The list materials and their components where Lead Based Paint (LBP) was detected at or in excess of the HUD/EPA standards of 1.0 mg/cm<sup>2</sup> (Los Angeles County has established a more stringent standard for lead-based paint at 0.7mg/cm<sup>2</sup>) by XRF method which is listed in the table below. All XRF readings below the regulatory defined action level are considered negative and all readings at and above these levels are considered positive.

Shot #	Unit	Room Tested	Wall	Color	Component	Substrate	Quantity	Paint Condition	Result	Neg/Pos
01	Exterior	Outfall Sample Room	South	White	Pipe	Metal	1 Each	Intact	0.00	Negative
02	Exterior	Outfall Sample Room	South	Yellow	Channel	Concrete	1 Each	Intact	0.00	Negative
03	Exterior	Outfall Sample Room	South	Green	Platform	Metal	1 Each	Intact	0.00	Negative
04	Exterior	Outfall Sample Room	East	White	Wall	Wood	208 SF	Intact	0.00	Negative
05	Exterior	Outfall Sample Room	East	Blue	Door Frame	Wood	1 Each	Intact	0.00	Negative
06	Exterior	Outfall Sample Room	East	Blue	Window Frame	Wood	4 Each	Intact	0.00	Negative
07	Exterior	Outfall Sample Room	East	Yellow	Baseboard	Wood	3 SF	Intact	0.00	Negative
08	Exterior	Outfall Sample Room	North	Yellow	Pipe	Metal	1 Each	Intact	0.00	Negative
09	Interior	Outfall Sample Room	East	White	Ceiling	Wood	42 SF	Intact	0.00	Negative
10	Interior	Outfall Sample Room	East	Blue	Floor	Wood	42 SF	Intact	0.00	Negative
11	Interior	Outfall Sample Room	East	Blue	Door	Wood	1 Each	Intact	0.00	Negative
12	Exterior	Outfall Sample Room	East	Blue	Door	Wood	1 Each	Intact	0.00	Negative